



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52128479 06	COVER, FR BUMPER LH	1.00	\$28.10	25.00	\$21.08	Replace	Replace
		52127479 07	COVER, FR BUMPER RH	1.00	\$28.10	25.00	\$21.08	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace
		75310470 60	EMBLEM ASSY FRONT	1.00	\$87.10	25.00	\$65.32	Replace	Replace
		53112472 40	GRILLE, RADIATOR	1.00	\$165.00	25.00	\$123.75	Replace	Replace
		52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace
		53395470 40	SEAL, HOOD TO FR END	1.00	\$24.40	25.00	\$18.30	Replace	Replace
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.72	Replace	Replace
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$78.90	25.00	\$59.18	Replace	Replace
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.72	Replace	Replace
		52021471 10	REINFORCEMENT FRONT UPPER	1.00	\$691.10	25.00	\$518.33	Replace	Replace
		52618470 90	ABSORBER, FR BUMPER LOWER	1.00	\$117.00	25.00	\$87.75	Replace	Replace
		52132470 10	REINFORCEMENT FRONT LOWER	1.00	\$238.50	25.00	\$178.88	Replace	Replace
		52103470 10	EXTENSION SUBASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		52102470 20	EXTENSION SUBASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check
		81220470 20	LAMP ASSY, FOG, LH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		81210470 20	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given
		53301471 10	HOOD SUB-ASSY	1.00	\$936.40	25.00	\$702.30	Replace	Replace
		53341470 40	INSULATOR, HOOD	0.00	\$393.90	0.00	\$0.00	Replace	Not Given
		90467090 50	INSULATOR, HOOD CLIP	0.00	\$2.30	0.00	\$0.00	Replace	Not Given
		53420471 30	HINGE ASSY, HOOD, LH	1.00	\$57.00	25.00	\$42.75	Replace	Replace
		53410471 30	HINGE ASSY, HOOD, RH	1.00	\$57.00	25.00	\$42.75	Replace	Replace
		53510471 40	LOCK ASSY, HOOD	1.00	\$131.10	25.00	\$98.32	Replace	Replace
		53630470 90	CABLE ASSY, HOOD	0.00	\$53.20	0.00	\$0.00	Replace	Not Given
		75536470 20	MOULDING LH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		75535470 20	MOULDING RH	0.00	\$83.30	0.00	\$0.00	Replace	Not Given
		581014E 959	WINDSCREEN FRONT GLASS SUB-ASSY	1.00	\$1,626.40	25.00	\$1,219.80	Replace	Replace
		75533470 70	WINDSCREEN FRONT MOULDING, TOP FRONT	1.00	\$44.00	25.00	\$33.00	Replace	Replace
			SEALANT W/SCREEN	2.00	\$37.00	0.00	\$74.00	Replace	Replace
		55708472 30	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$666.90	0.00	\$0.00	Replace	Not Given
		55754470 70	WIPER GARNISH SHIELD, COWL WATER, LH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given
		55753470 90	WIPER GARNISH SHIELD, COWL WATER, RH	0.00	\$18.90	0.00	\$0.00	Replace	Not Given
		61014470 10	PILLAR, FRONT BODY, LH	0.00	\$339.40	0.00	\$0.00	Replace	Check
		60118470 20	COVER SUB-ASSY, FRONT PILLAR, UPR LH	0.00	\$96.90	0.00	\$0.00	Replace	Check
		88790261 00	THERMISTOR ASSY	0.00	\$68.00	0.00	\$0.00	Replace	Check
		53289470 72	COVER, RADIATOR	0.00	\$227.80	0.00	\$0.00	Replace	Check

964.70

MIS
MIS
MC
BR
MIS
OR
OR
MIS
OR
TN
OR
OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR

OR



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		53205479 00	SUPPORT S/A UPPER	1.00	\$364.90	25.00	\$273.67	Replace	Replace
		53028470 10	SUPPORT SUB-ASSY LOWER	0.00	\$397.40	0.00	\$0.00	Replace	Check
		53203479 01	SUPPORT S/A LH	0.00	\$237.00	0.00	\$0.00	Replace	Check
		53202479 01	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Check
		53217470 30	BRACE, HOOD LOCK SUPPORT	0.00	\$76.20	0.00	\$0.00	Replace	Check
		53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Check
		53213470 50	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Check
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		81145476 91	UNIT, HEADLAMP, RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		81056476 90	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Check
		86510470 50	HORN ASSY, HIGH	0.00	\$112.80	0.00	\$0.00	Replace	Check
		86520470 30	HORN ASSY, LOW	0.00	\$112.80	0.00	\$0.00	Replace	Check
		88460103 20	AIR CON CONDENSER ASSY	0.00	\$1,317.70	0.00	\$0.00	Replace	Check
		88710471 60	TUBE & ACCESSORY	0.00	\$574.40	0.00	\$0.00	Replace	Check
		88703470 80	HOSE SUB-ASSY, DISCHARGE	0.00	\$337.10	0.00	\$0.00	Replace	Check
			COOLANT	0.00	\$12.30	0.00	\$0.00	Replace	Check
		16592370 20	GUIDE, RADIATOR AIR	0.00	\$93.90	0.00	\$0.00	Replace	Check
		16594370 10	GUIDE, RADIATOR AIR, UPPER	0.00	\$44.70	0.00	\$0.00	Replace	Check
		16595370 50	GUIDE, RADIATOR AIR, LH	0.00	\$56.80	0.00	\$0.00	Replace	Check
		16593370 40	GUIDE, RADIATOR AIR, RH	0.00	\$54.60	0.00	\$0.00	Replace	Check
		16400373 10	RADIATOR ASSY	0.00	\$1,841.10	0.00	\$0.00	Replace	Check
		90480400 21	GROMMET (FOR RADIATOR LOWER SUPPORT)	0.00	\$12.70	0.00	\$0.00	Replace	Check
		16523370 10	CUSHION, (FOR RADIATOR UPPER SUPPORT)	0.00	\$9.80	0.00	\$0.00	Replace	Check
		16361370 60	FAN RADIATOR, LH	0.00	\$181.80	0.00	\$0.00	Replace	Check
		16361370 70	FAN RADIATOR, RH	0.00	\$233.00	0.00	\$0.00	Replace	Check
		16711371 60	FAN SHROUD RADIATOR	0.00	\$219.30	0.00	\$0.00	Replace	Check
		16363370 60	MOTOR, COOLING FAN, LH	0.00	\$543.50	0.00	\$0.00	Replace	Check
		16363361 60	MOTOR, COOLING FAN, RH	0.00	\$443.40	0.00	\$0.00	Replace	Check
		16571372 10	HOSE, RADIATOR, NO.1	0.00	\$42.60	0.00	\$0.00	Replace	Check
		16572372 10	HOSE, RADIATOR, NO.2	0.00	\$40.20	0.00	\$0.00	Replace	Check
		164A237 012	TANK, RESERVE SEALED W/O CAP	0.00	\$127.00	0.00	\$0.00	Replace	Check
		16261371 50	HOSE, WATER BYPASS NO.1	0.00	\$37.40	0.00	\$0.00	Replace	Check
		16264371 20	HOSE, WATER BYPASS NO.2	0.00	\$37.40	0.00	\$0.00	Replace	Check
		16267370 60	HOSE, WATER BYPASS NO.3	0.00	\$20.10	0.00	\$0.00	Replace	Check
		16281371 00	HOSE, WATER BYPASS NO.4	0.00	\$13.20	0.00	\$0.00	Replace	Check
		16296370 10	HOSE, WATER BYPASS NO.8	0.00	\$37.90	0.00	\$0.00	Replace	Check

8077.7