



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		16268371 00	PIPE, WATER BYPASS, NO.1	0.00	\$11.00	0.00	\$0.00	Replace	Check X N/A
		16268371 20	PIPE, WATER BYPASS, NO.2	0.00	\$11.00	0.00	\$0.00	Replace	Check X N/A
		16279370 20	PIPE, WATER BYPASS, NO.3	0.00	\$56.40	0.00	\$0.00	Replace	Check X N/A
		16577370 90	PIPE, RADIATOR	0.00	\$32.90	0.00	\$0.00	Replace	Check X N/A
		16573370 20	HOSE, RADIATOR, NO.3	0.00	\$29.60	0.00	\$0.00	Replace	Check X N/A
		16282370 90	HOSE, WATER BYPASS, NO.5	0.00	\$13.20	0.00	\$0.00	Replace	Check X N/A
		16278370 20	PIPE, WATER BYPASS, NO.5	0.00	\$51.80	0.00	\$0.00	Replace	Check X N/A
		16283370 21	HOSE, WATER BYPASS, NO.6	0.00	\$13.20	0.00	\$0.00	Replace	Check X N/A
		G904047 040	INVERTER WATER PUMP ASSY	0.00	\$432.00	0.00	\$0.00	Replace	Check X N/A
		G922E47 010	HOSE, HV WATER PUMP INLET	0.00	\$37.90	0.00	\$0.00	Replace	Check X N/A
		G922F47 010	HOSE, HV WATER PUMP OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check X N/A
		G91H047 011	TANK ASSY, INVERTER RESERVE	0.00	\$371.30	0.00	\$0.00	Replace	Check X N/A
		G922A47 010	HOSE, INVERTER COOLING INLET	0.00	\$43.10	0.00	\$0.00	Replace	Check X N/A
		G922C47 010	HOSE, INVERTER COOLING OUTLET	0.00	\$29.60	0.00	\$0.00	Replace	Check X N/A
		G922H47 010	HOSE, INVERTER RADIATOR INLET	0.00	\$40.70	0.00	\$0.00	Replace	Check X N/A
		G125A47 010	COOLER, MOTOR COOLING	0.00	\$249.10	0.00	\$0.00	Replace	Check X N/A
		821H247 010	WIRE, AIR CONDITIONER	0.00	\$445.70	0.00	\$0.00	Replace	Check X N/A
		8211147J 21	WIRE, ENGINE ROOM MAIN	0.00	\$6,138.00	0.00	\$0.00	Replace	Check X N/A
		28800371 30	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Check X N/A
		74404470 30	CLAMP SUB-ASSY, BATTERY	0.00	\$41.40	0.00	\$0.00	Replace	Check X N/A
		74482470 10	CLAMP, BATTERY, NO.2	0.00	\$43.30	0.00	\$0.00	Replace	Check X N/A
		82621470 20	COVER, FUSIBLE LINK	0.00	\$28.30	0.00	\$0.00	Replace	Check X N/A
		8262047090	BLOCK ASSY, FUSIBLE LINK	0.00	\$99.80	0.00	\$0.00	Replace	Check X N/A
		8267147040	BLOCK, JUNCTION	0.00	\$15.80	0.00	\$0.00	Replace	Check X N/A
		2885037070	SENSOR ASSY, BATTERY STATE	0.00	\$256.80	0.00	\$0.00	Replace	Check X N/A
		2885937030	HOLDER, BATTERY CURRENT SENSOR	0.00	\$11.70	0.00	\$0.00	Replace	Check X N/A
		17751371 10	INLET, AIR CLEANER, NO.1	0.00	\$130.50	0.00	\$0.00	Replace	Check X N/A
		17752371 21	INLET, AIR CLEANER, NO.2	0.00	\$93.90	0.00	\$0.00	Replace	Check X N/A
		17753370 10	INLET, AIR CLEANER, NO.3	0.00	\$35.30	0.00	\$0.00	Replace	Check X N/A
		17893371 30	RESONATOR, INTAKE AIR	0.00	\$14.90	0.00	\$0.00	Replace	Check X N/A
		17771370 20	BRACKET, AIR CLEANER	0.00	\$26.90	0.00	\$0.00	Replace	Check X N/A
		17700373 30	AIR CLEANER ASSY	0.00	\$956.20	0.00	\$0.00	Replace	Check X N/A
		90904060 08	TUBE, UNION (FOR AIR CLEANER HOSE)	0.00	\$19.40	0.00	\$0.00	Replace	Check X N/A
		5710147070	MEMBER SUB-ASSY, FR RH	0.00	\$2,012.70	0.00	\$0.00	Replace	Check X N/A
		5710247090	MEMBER SUB-ASSY, FR LH	0.00	\$1,959.50	0.00	\$0.00	Replace	Check X N/A
		8531947170	WIPER WASHER INLET	0.00	\$55.40	0.00	\$0.00	Replace	Check X N/A

1542280



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 22/05/2019

User ID : ZhiYangPhua

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8531547160	WIPER WASHER JAR	0.00	\$183.60	?	\$0.00	Replace	Check X N/A
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair X R
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace X R
		53807470 20	SEAL SUB-ASSY, RH	1.00	\$50.20	25.00	\$37.65	Replace	Replace X R
		53875470 70	LINER, FR FENDER, RH	0.00	\$196.40	?	\$0.00	Replace	Replace X R
		5370147111	APRON SUB-ASSY, FRONT FENDER, RH	0.00	\$944.20	?	\$0.00	Replace	Check X N/A
		53802471 00	FENDER SUB-ASSY, FR, LH	1.00	\$933.10	25.00	\$699.83	Replace	Replace X R
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace X R
		53828470 70	PROTECTOR, FR FENDER LH	0.00	\$90.40	?	\$0.00	Replace	Check X N/A
		53808470 20	SEAL SUB-ASSY, LH	0.00	\$50.20	?	\$0.00	Replace	Check X N/A
		53876471 10	LINER, FR FENDER, LH	1.00	\$194.30	25.00	\$145.73	Replace	Replace X R
		53852470 41	PAD, FR WHEEL LH	0.00	\$57.70	?	\$0.00	Replace	Check X R
		53702471 01	APRON SUB-ASSY, FRONT FENDER, LH	0.00	\$944.20	?	\$0.00	Replace	Check X R
		67002471 62	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair X R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace X R
		8861047040	CHECK ASSY, FRONT DOOR	0.00	\$153.50	0.00	\$0.00	Replace	Not Given X N/A
		6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$82.10	0.00	\$0.00	Replace	Not Given X N/A
		6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$92.10	0.00	\$0.00	Replace	Not Given X N/A
Total					\$72,456.40		\$27,173.83		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2468.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: