

Vehicle number	FC2366U
Make / Model	VESPA/PX150
Chassis number	476995
Accident date	21 May 2019
Reference	1905-70

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT FENDER	310.00 <i>ky</i>
1	FRONT LH FORK ASSY	550.00 <i>X</i>
1	FRONT RH FORK ASSY	55.00 <i>?</i>
1	STEERING HEADCROWM	210.00 <i>?</i>
1	STEERING STEM UNDERBRACKET	150.00 <i>?</i>
1	STEERING STEM BEARING	120.00 <i>?</i>
1	REAR RH FENDER	450.00 <i>dd ✓</i>
		1845.00
	Less 10%	184.50
	Subtotal	1660.50
	Balance C/F	1660.50
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	1660.50
1	FRONT NUMBER PLATE	60.00 <i>X</i>
	Subtotal	60.00
	Balance C/F	1720.50
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	1720.50
	TO KNOCK, STRAIGHTEN CHASSIS, BODY BALANCING AND REPLACE DAMAGE	500.00 <i>200</i>
	TO REMOVE/REFIT, REPLACE FRONT FORK TUDES	250.00 <i>/20</i>
	SPRAY PAINTING	380.00 <i>200</i>
	Subtotal	1130.00
	Grand total	2850.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Taufik 97495749
'WP'
23/5/19 @ 3:50pm
03 days
Resurvey after repair
Taufik e Manto on