

INS. CASE OWNER:

Add.

CC 4, 111 1900 9151

Khai's

LAC
IDAC

Surveyor:

RAML

DOI:

ASSIGNMENT

23/5/19

Date / Time:

23/5/19

Registered in Merimen:

23/5/19

Pre-assessment / CCL / FTE

Insured Vehicle No.:

SH 89812

Claim No.:

Name of Insured:

VPL

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

21/5/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SFX 7006 R

INSRS:

WSP:

Tel:

Liability:

RMKS:

Sng Ah Tee

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SFX 7006 R, X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mute/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

29/09/19

- 900K CABLET WANDER. → MK

10/11/19

- File → type mandale

19/11/19

- file → SUE to send BV.

11/12/19

- File pass to MK to close.

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Aa

If NO or B 28, Ass. Lip:

Repair Cost:

S\$

6420.00

COLD W/ STOP WAD

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

1120.00

(days)

Loss of Income (LOI):

S\$

(3 x days)

LOR only ☐ LOU only ☒

S\$

7.45

LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

120.00

(e.g. Tow / Independent)

Legal Cost

S\$

Total:

S\$

7667.45

Global Sum S\$:

1) Claim status: ☒ Mute/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

\$50.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7667.45

Name 1:

Sng Ah Tee Motor & Panel Service Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Signature: *Pamela*

REF:


ASSIGNMENT

COE XPRY: 2020/04

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SFX 7006R**
 at Workshop m/s: **SNA AH.TEE**
 of: **PIONEER RD NORTH**
 Insured: **111**
 Policy No.: _____
 Claims No.: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **26500**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **12** days Res.: Yes or No
 Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SFX 7006R** Yr Regn: **2010** / **OUT**
 Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **HONDA STREAM 1.8 LA** C.C: **1754**
 Colour: **RED** A/C: Insured / Std / NI / NA
 Sp. Reading: **287596** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **JHAKN6860AC200120**

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Normal / Jammed / Leaked / Burnt or

Brake: ☒ Normal / Jammed / Leaked / Burnt or

Modi: Nil / ☒ Rim / STD A/Rim or

Tyre Size: F: **205/65R15**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **CONTINENTAL**

Front: _____ Rear: _____
 R/Bal: **6** mm R/Bal: **6** mm
 L/Bal: **6** mm L/Bal: **6** mm
 D.O.A: **21/05/19** D.O.I: **23/05/19**

Survey held at **SNA AH.TEE**

Des. of Damages: Frt / Rear ☒ O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit 6k
	US \$ 6000 (Reel # 8443.44/586).
	MV: \$ 26500.00 (est)
	LTA: \$ 20025.00 (est)
	NV: \$ 6775.00 (est)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

repair limit \$6k

EST/QUOTE NO. SQ004940

DATE 23/05/2019

ACCIDENT DATE: 21/05/2019

VEHICLE NO: SFX7006R

CHASSIS/ENG.NO: JHMRN6860AC200120

VEHICLE MODEL: HONDA STREAM

CLAIM NO:

POLICY NO:

REMARK 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER DE	635.60	20	508.48	508.48/
2	1	PC	FRT BUMPER SIDE RETAINER(RH) rec	12.40	20	9.92	9.92/
3	10	PC	FRT BUMPER CLIPS rec	3.90	20	3.12	31.20/
4	1	PC	FRT FENDER RH bt	486.20	20	388.96	388.96/
5	1	PC	FRT FENDER INNERSHIELD RH DE	82.70	20	66.16	66.16/
6	10	PC	FRT FENDER INNERSHIELD CLIPS rec	3.50	20	2.80	28.00/
7	1	PC	FRT FENDER INNER PANEL RH repair	90.90	20	72.72	72.72 R
8	1	PC	FRT HEADLAMP RH scr	595.70	20	476.56	476.56/
9	1	PC	FRT HEADLAMP LOWER BRACKET RH ? x sue	36.50	20	29.20	29.20 X
10	1	PC	FRT DOOR RH bt	860.00	20	688.00	688.00/
11	2	PC	FRT DOOR HINGE RH bt	35.40	20	28.32	56.64/
12	1	PC	FRT DOOR CHECKER(RH) ? x sue	36.90	20	29.52	29.52 X
13	1	PC	FRT DOOR LOCK RH bt	217.10	20	173.68	173.68/
14	1	PC	FRT SIDE MIRROR ASSY RH repair	436.40	20	349.12	349.12 R
15	1	PC	FRT DOOR GLASS OUTER MOULDING R rec	80.50	20	64.40	64.40/
16	1	PC	FRT DOOR GLASS RUN CHANNEL RH ? x sue	90.90	20	72.72	72.72 X
17	1	PC	FRT DOOR GLASS REGULATOR MOTOR ? x sue	391.90	20	313.52	313.52 X
18	1	PC	FRT DOOR INNER TRIM BOARD RH ? x sue	636.00	20	508.80	508.80 X
19	10	PC	FRT DOOR INNER TRIM BOARD CLIP rec	4.50	20	3.60	36.00/
20	1	PC	FRT QUARTER GLASS MOULDING RH rec	38.90	20	31.12	31.12/

SAM

PAGE: 1 of 4

2659.12

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE: 23/05/2019

ACCIDENT DATE: 21/05/2019

VEHICLE NO: SFX7006R

CHASSIS/ENG.NO: JHMRN6860AC200120

VEHICLE MODEL: HONDA STREAM

CLAIM NO:

POLICY NO:

REMARK: 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	FRT DOOR FRAME STICKER RH <i>na</i>	46.10	20	36.88	36.88 /
22	1	PC	FRT DOOR OUTER HANDLE RH <i>X su</i>	112.40	20	89.92	89.92 X
23	1	PC	SIDE PANEL RH <i>bt</i>	220.70	20	176.56	176.56 /
24	1	PC	REAR DOOR RH <i>bt</i>	811.20	20	648.96	648.96 /
25	2	PC	REAR DOOR HINGE RH <i>X su</i>	38.90	20	31.12	62.24 X
26	1	PC	REAR DOOR LOCK RH <i>X su</i>	194.70	20	155.76	155.76 X
27	1	PC	REAR DOOR FRAME STICKER RH <i>na</i>	38.70	20	30.96	30.96 /
28	1	PC	REAR DOOR GLASS REGULATOR MOTO <i>X su</i>	428.40	20	342.72	342.72 X
29	1	PC	REAR FENDER RH <i>repair</i>	925.30	20	740.24	740.24 /
30	10	PC	REAR FENDER INNER SHIELD CLIP <i>X su</i>	3.50	20	2.80	28.00 X
31	1	PC	REAR BUMPER <i>su</i>	640.90	20	512.72	512.72 /
32	1	PC	REAR BUMPER SIDE RETAINER RH <i>na</i>	20.80	20	16.64	16.64 /
33	1	PC	REAR FENDER GLASS MOULDING RH <i>X su</i>	60.00	20	48.00	48.00 X
34	1	PC	FRT RIM 15" <i>su</i>	660.20	20	528.16	30090 528.16 /
35	1	PC	FRT SHOCK ABSORBER RH <i>bt</i>	286.90	20	229.52	229.52 /
36	1	PC	FRT WHEEL HUB RH <i>bt</i>	249.70	20	199.76	199.76 /
37	1	PC	FRT WHEEL BEARING RH <i>na</i>	121.60	20	97.28	97.28 /
38	1	PC	FRT KNUCKLE ARM RH <i>bt</i>	267.40	20	213.92	213.92 /
39	1	PC	FRT LOWER ARM RH <i>bt</i>	328.20	20	262.56	262.56 /
40	1	PC	FRT TIE ROD RH <i>? bt</i>	85.10	20	68.08	68.08 /
41	1	PC	FRT TIE ROD END RH <i>? bt</i>	56.20	20	44.96	44.96 /

SAM

PAGE: 2 of 4

2538.80

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE : 23/05/2019

ACCIDENT DATE : 21/05/2019

VEHICLE NO : SFX7006R

CHASSIS/ENG.NO : JHMRN6860AC200120

VEHICLE MODEL : HONDA STREAM

CLAIM NO :

POLICY NO :

REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
42	1	PC	FRT DRIVE SHAFT ? <i>ksu</i>	996.90	20	797.52	797.52 X
43	1	PC	FRT STABILIZER LINK RH ? <i>ksu</i>	68.40	20	54.72	54.72 X
44	1	PC	REAR RIM 15" <i>sen</i>	660.20	20	528.16	300 <i>1/2</i> 528.16 ✓
45	1	PC	REAR WHEEL HUB BEARING(RH) ? <i>ksu</i>	380.60	20	304.48	304.48 X

SUB-TOTAL: 10,153.44

\$5097.92

** SPECIAL NETT PRICE **

1	1	PC	FRT QUARTER GLASS SEALANT <i>sen</i>	40.00		40.00	20 40.00
2	1	PC	REAR FENDER GLASS SEALANT <i>X sen</i>	40.00		40.00	X 40.00
3	1	PC	FRT TYRE RH (205/65R15) <i>sen</i>	250.00	<i>\$175</i>	250.00	70% 250.00
4	1	PC	REAR TYRE RH (205/65R15) <i>sen</i>	250.00	<i>\$175</i>	250.00	70% 250.00

SUB-TOTAL 580.00

\$370 + \$600
sniff

** WORK LABOUR **

TO CHECK WIRING	30.00	30.00
TO REMOVE & REFIX RR FENDER GLS	100.00	<i>12X</i> 100.00
TO REMOVE & REFIX FRT QUARTER GLS	100.00	<i>50</i> 100.00
TO TRANSFER FRT & RR DOOR GLS	50.00	<i>60</i> 100.00
TO DO WHEEL ALIGNMENT	80.00	<i>60</i> 80.00
TO REPAIR & REFIX UNDERCARRIAGE	400.00	<i>200</i> 400.00

SAM

PAGE: 3 of 4

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE 23/05/2019

ACCIDENT DATE: 21/05/2019

VEHICLE NO: SFX7006R

CHASSIS/ENG.NO: JHMRN6860AC200120

VEHICLE MODEL: HONDA STREAM

CLAIM NO:

POLICY NO:

REMARK: 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO KNOCK, WELD, REMOVE & FIX ON ABOVE PARTS	1400.00		1200	1,400.00
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	1500.00		1400	1,500.00
			SUB-TOTAL				3,710.00

Issue
Hp 90010068
12 days
4/s
23/05/19 @ 1610
Repairing after repair
Repair limit 6K
=

total \$9067.92
less 7% = \$7264.33
x \$7250/-
Long Sun
Unit 6k
on
3/10/2019

SAM

PAGE: 4 of 4

SUB-TOTAL: S\$ 14,443.44
ADD 7% GST. S\$ 1,011.04
GRAND TOTAL: S\$ 15,454.48

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004940

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE : 23/05/2019
ACCIDENT DATE : 21/05/2019
VEHICLE NO : SFX7006R
CHASSIS/ENG.NO : JHMRN6860AC200120
VEHICLE MODEL : HONDA STREAM
CLAIM NO :
POLICY NO :
REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER <i>DI</i>	635.60 ✓	20	508.48	508.48 ✓
2	1	PC	FRT BUMPER SIDE RETAINER(RH) <i>new</i>	12.40 ✓	20	9.92	9.92
3	10	PC	FRT BUMPER CLIPS <i>new</i>	3.90 ✓	20	3.12	31.20
4	1	PC	FRT FENDER RH <i>bt</i>	486.20 ✓	20	388.96	388.96
5	1	PC	FRT FENDER INNERSHIELD RH <i>DE</i>	82.70 ✓	20	66.16	66.16
6	10	PC	FRT FENDER INNERSHIELD CLIPS <i>new</i>	3.50 ✓	20	2.80	28.00
7	1	PC	FRT FENDER INNER PANEL RH <i>repair</i>	90.90 X	20	72.72	72.72
8	1	PC	FRT HEADLAMP RH <i>scu</i>	595.70 ✓	20	476.56	476.56
9	1	PC	FRT HEADLAMP LOWER BRACKET RH ?	36.50 X	20	29.20	29.20
10	1	PC	FRT DOOR RH <i>bt</i>	860.00 ✓	20	688.00	688.00
11	2	PC	FRT DOOR HINGE RH <i>bt</i>	35.40 ✓	20	28.32	56.64
12	1	PC	FRT DOOR CHECKER(RH) ?	36.90 X	20	29.52	29.52
13	1	PC	FRT DOOR LOCK RH <i>bt</i>	217.10 ✓	20	173.68	173.68
14	1	PC	FRT SIDE MIRROR ASSY RH <i>repair</i>	436.40 X	20	349.12	349.12
15	1	PC	FRT DOOR GLASS OUTER MOULDING R <i>new</i>	80.50 ✓	20	64.40	64.40
16	1	PC	FRT DOOR GLASS RUN CHANNEL RH ?	90.90 X	20	72.72	72.72
17	1	PC	FRT DOOR GLASS REGULATOR MOTOR ?	391.90 X	20	313.52	313.52
18	1	PC	FRT DOOR INNER TRIM BOARD RH ?	636.00 ✓	20	508.80	508.80
19	10	PC	FRT DOOR INNER TRIM BOARD CLIP <i>new</i>	4.50 ✓	20	3.60	36.00
20	1	PC	FRT QUARTER GLASS MOULDING RH <i>new</i>	38.90 ✓	20	31.12	31.12

SAM

PAGE: 1 of 4

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004940

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT : 62238122

FAX NO: 62244174

DATE : 23/05/2019

ACCIDENT DATE : 21/05/2019

VEHICLE NO : SFX7006R

CHASSIS/ENG.NO : JHMRN6860AC200120

VEHICLE MODEL : HONDA STREAM

CLAIM NO :

POLICY NO :

REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	FRT DOOR FRAME STICKER RH <i>new</i>	46.10	20	36.88	36.88
22	1	PC	FRT DOOR OUTER HANDLE RH <i>X</i>	112.40	20	89.92	89.92
23	1	PC	SIDE PANEL RH <i>bt</i>	220.70	20	176.56	176.56
24	1	PC	REAR DOOR RH <i>bt</i>	811.20	20	648.96	648.96
25	2	PC	REAR DOOR HINGE RH <i>X</i>	38.90	20	31.12	62.24
26	1	PC	REAR DOOR LOCK RH <i>X</i>	194.70	20	155.76	155.76
27	1	PC	REAR DOOR FRAME STICKER RH <i>new</i>	38.70	20	30.96	30.96
28	1	PC	REAR DOOR GLASS REGULATOR MOTO <i>X</i>	428.40	20	342.72	342.72
29	1	PC	REAR FENDER RH <i>repair</i>	925.30	20	740.24	740.24
30	10	PC	REAR FENDER INNERSHIELD CLIP <i>X</i>	3.50	20	2.80	28.00
31	1	PC	REAR BUMPER <i>sea</i>	640.90	20	512.72	512.72
32	1	PC	REAR BUMPER SIDE RETAINER RH <i>new</i>	20.80	20	16.64	16.64
33	1	PC	REAR FENDER GLASS MOULDING RH <i>X</i>	60.00	20	48.00	48.00
34	1	PC	FRT RIM 15" <i>sea</i>	660.20	20	528.16	<i>300 \$/u</i> 528.16
35	1	PC	FRT SHOCKABSORBER RH <i>bt</i>	286.90	20	229.52	229.52
36	1	PC	FRT WHEEL HUB RH <i>bt</i>	249.70	20	199.76	199.76
37	1	PC	FRT WHEEL BEARING RH <i>new</i>	121.60	20	97.28	97.28
38	1	PC	FRT KNUCKLE ARM RH <i>bt</i>	267.40	20	213.92	213.92
39	1	PC	FRT LOWER ARM RH <i>bt</i>	328.20	20	262.56	262.56
40	1	PC	FRT TIE ROD RH <i>?</i>	85.10	20	68.08	68.08
41	1	PC	FRT TIE ROD END RH <i>?</i>	56.20	20	44.96	44.96

SAM

PAGE: 2 of 4

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004940

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

DATE : 23/05/2019
ACCIDENT DATE : 21/05/2019
VEHICLE NO : SFX7006R
CHASSIS/ENG.NO : JHMRN6860AC200120
VEHICLE MODEL : HONDA STREAM
CLAIM NO :
POLICY NO :
REMARK : 7006INDIA TP AGST SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
42	1	PC	FRT DRIVE SHAFT ?X	996.90	20	797.52	797.52
43	1	PC	FRT STABILIZER LINK RH ?	68.40	20	54.72	54.72
44	1	PC	REAR RIM 15" sun	660.20	20	528.16	300 1/2 528.16
45	1	PC	REAR WHEEL HUB BEARING(RH) ?X	380.60	20	304.48	304.48

SUB-TOTAL: 10,153.44

** SPECIAL NETT PRICE **

1	1	PC	FRT QUARTER GLASS SEALANT no	40.00		40.00	20 40.00
2	1	PC	REAR FENDER GLASS SEALANT X	40.00		40.00	X 40.00
3	1	PC	FRT TYRE RH (205/65R15) cut	250.00		250.00	70 250.00
4	1	PC	REAR TYRE RH (205/65R15) sun	250.00		250.00	70 250.00

SUB-TOTAL 580.00

** WORK LABOUR **

TO CHECK WIRING	30.00	30.00	/
TO REMOVE & REFIX RR FENDER GLS	100.00	X	100.00
TO REMOVE & REFIX FRT QUARTER GLS	100.00	50	100.00
TO TRANSFER FRT & RR DOOR GLS	50.00	60	100.00
TO DO WHEEL ALIGNMENT	80.00	60	80.00
TO REPAIR & REFIX UNDERCARRIAGE	400.00	200	400.00

SAM

PAGE: 3 of 4

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004940

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE : 23/05/2019
ACCIDENT DATE : 21/05/2019
VEHICLE NO : SFX7006R
CHASSIS/ENG.NO : JHMRN6860AC200120
VEHICLE MODEL : HONDA STREAM
CLAIM NO :
POLICY NO :
REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	1400.00		1200	1,400.00
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	1500.00		1400	1,500.00
			SUB-TOTAL				3,710.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Issue
Hp 90010068
12 days
L/S
23/05/19 @ 1610
Resurvey after repair
Repair limit 6K

SAM

PAGE: 4 of 4

SUB-TOTAL : S\$ 14,443.44
ADD 7% GST. S\$ 1,011.04
GRAND TOTAL : S\$ 15,454.48

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 4554B

Vehicle Details

Vehicle No.: SFX7006R
Vehicle to be Exported: No
Intended Deregistration Date: 24 May 2019
Vehicle Make: HONDA
Vehicle Model: STREAM 1.8L AUTO
Primary Colour: Red
Manufacturing Year: 2009
Engine No.: R18A13860120
Chassis No.: JHMRN6860AC200120
Maximum Power Output: 103.0 kW (138 bhp)
Open Market Value: \$25,509.00
Original Registration Date: 20 Oct 2010
First Registration Date: 20 Oct 2010
Transfer Count: 0
Actual ARF Paid: \$25,509.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 19 Oct 2020
PARF Rebate Amount: \$14,029.00

Intended COE Rebate Details

COE Expiry Date: 19 Oct 2020
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$42,801.00
COE Rebate Amount: \$5,996.00
Total Rebate Amount: \$20,025.00

The information contained herein is correct as at 23 May 2019

OK

26,500
20025

6,475

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Thursday, 23 May 2019 11:35 AM
To: SAMANTHA TAN; Sundari Nagarajan - III; admin-d@lkkauto.com
Cc: Zuhaidah Samsuri
Subject: RE: Accident involved with our client's vehicle SFX7006R and your insured SH8981Z on 21/05/2019
Attachments: SFX7006R_21052019.pdf

11.43am @ 23/5/19
person @ Joyce
vehicle in
Sua @ Panel

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SFX7006R and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: SAMANTHA TAN [mailto:sam@sngahtee.com]
Sent: 23 May, 2019 9:53 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: Lalitha Krishnan - III <lalitha@iii.com.sg>
Subject: RE: Accident Involved with our client's vehicle SFX7006R and your insured SH8981Z on 21/05/2019

Hi,

Kindly arrange LKK to survey the vehicle.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>

From: Motor Claim - III <motorclaim@iii.com.sg>

Sent: Thursday, 23 May 2019 9:15 AM

To: SAMANTHA TAN <sam@sngahtee.com>

Cc: Lalitha Krishnan - III <lalitha@iii.com.sg>

Subject: RE: Accident involved with our client's vehicle SFX7006R and your insured SH8981Z on 21/05/2019

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: SAMANTHA TAN [<mailto:sam@sngahtee.com>]

Sent: 22 May, 2019 5:11 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: Lalitha Krishnan - III <lalitha@iii.com.sg>

Subject: : Accident involved with our client's vehicle SFX7006R and your insured SH8981Z on 21/05/2019

Hi All,

We refer to the above and wish to check liability for this case.

Hope to hear from you soon.

Thank you.

Best Regards

Samantha Tan | sam@sngahtee.com



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	23 May 2019 19:04	Cim Dtl Modified	Claimant's Name: -> TEO SIEW LAN. Claimant's ID: -> S7534554B.	[A] HOW MEI KWAN
2	23 May 2019 19:04	Cim Veh Model Changed	(201726) HONDA STREAM 1.8 L (A).	[A] HOW MEI KWAN
3	23 May 2019 19:04	Cim Created	Reg No: SFX7006R, Acct Date: 2019/05/21. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ). Workshop: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	[A] HOW MEI KWAN
4	23 May 2019 19:04	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	23 May 2019 19:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/03	[A] HOW MEI KWAN
6	23 May 2019 19:04	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] HOW MEI KWAN
7	23 May 2019 19:04	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	23 May 2019 19:04	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] HOW MEI KWAN
9	29 May 2019 09:55	Adj Mandate Request	Cur.Req:0.00;PODS LIABILITY: 100% REMARKS: BOLA 41 - OID with stop line	[A] VIC ALPEH
10	29 May 2019 16:11	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/06/03	[I] Zuhaidah Bte Samsuri
11	29 May 2019 16:11	Adj Mandate Set	Approved:0.00,	[I] Zuhaidah Bte Samsuri
12	01 Nov 2019 11:08	Adj Rpt Initiated		[A] HUEY YON
13	01 Nov 2019 11:08	Cim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD, Insured ID: -> 199303821R.	[A] HUEY YON
14	01 Nov 2019 11:08	Cim Dtl Modified	JPJ Reg. Date: -> 2010/10/20.	[A] HUEY YON
15	01 Nov 2019 11:08	Cim Details Notified		[A] HUEY YON
16	02 Nov 2019 13:44	Adj Mandate Request	Cur.Req:7667.45;PODS Liability: 100% *Quantum: (a)CORw/GST: \$6,420.00 + (b)LO U(14days x \$80.00): \$1,120.00+ (c)LTA/GIA search fee: \$7.45 +(d)Towing Fee:\$120.00= Total: \$7,667.45 *Vehicle Model: Honda Stream (1799cc)*MV:\$26,500.00(est) less LTA Reb	[A] CHEW HSIAD TONG

Date From



Date To



Audit Type None



Go

ACTIVITY

[29/05/2019 09:55] VIC ALPEH:

Adj Mandate Request Cur.Req:0.00;PODS LIABILITY: 100% REMARKS: BOLA 41 - OID with stop line

[29/05/2019 09:54] VIC ALPEH:

FILE REVIEWED. OID reported crossing the junction with stop line. TP on main road. Seek liability mandate to III by merimen.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2331327	01 Nov 2019 11:08:33	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFX7006R	SH8981Z	11.77

Print Received Message

This mail is associated with :

***SFX7006R (MCT19050592)**

[SH8981Z]

TP

TEO SIEW LAN

May 21 2019 3:00PM

[COMFORT TRANSPORTATION PTE LTD]

Sng Ah Tee Motor & Panel Service Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 04/11/2019 15:21 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7667.45) - SFX7006R - Claim Handler: Zuhaidah Bte Samsuri

Approved:7667.45:Request TP WS to issue Tax invoice for Repairs in III's favour

Hsiao Tong (LKKAUTO)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Monday, 18 November 2019 3:12 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: Your Ref: SFX7006R *Our Ref: CC4/III19009131/R1pa3 [ACCIDENT INVOLVING SH 8981Z(III) AND SFX 7006R ON 21/05/2019]

Hi Xiao tong

we confirm the offer as proposed. Pls forward us DV.
Thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Hsiao Tong (LKKAUTO)
Sent: Monday, November 18, 2019 9:05 AM
To: Sharon Sng <sharon@sngahtee.com>
Subject: Your Ref: SFX7006R *Our Ref: CC4/III19009131/R1pa3 [ACCIDENT INVOLVING SH 8981Z(III) AND SFX 7006R ON 21/05/2019]

Your Ref: **SFX7006R** Without Prejudice
Our Ref: CC4/III19009131/R1pa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SH 8981Z(III) AND SFX 7006R ON 21/05/2019

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair (w/GST)	\$ 6,420.00
2. Loss of Use (14days x \$80.00)	\$ 1,120.00
3. LTA/ GIA Search Fee	\$ 7.45
4. Towing Fee	\$ 120.00
Total	\$ 7,667.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt	S\$6,000.00 Edit Estimates	S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	TEO SIEW LAN, ID: S7534554B								
Vehicle Reg. No.:	SFX7006R	Date of Loss:	21/05/2019 15:00 - :59 [103 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19050592	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SH8981Z	Policy No. (Claimant):	5104777983						
		Excess:							
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (04/11/2019): Alert - Adj Mandate Approved (S\$7667.45) - SFX7006R - Claim Handler: Zuhaidah Bt... - III_SG (29/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SFX7006R - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFX7006R (MCT19050592)
[SH8981Z]
TP
TEO SIEW LAN
May 21 2019 3:00PM
[COMFORT TRANSPORTATION PTE LTD]
Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	02/11/19 13:37	Odometer Reading					Load JPG	☒	
2	02/11/19 13:37	Chassis Number					Load JPG	☒	
3	02/11/19 13:37	General View					Load JPG	☒	
4	02/11/19 13:37	General View					Load JPG	☒	
5	02/11/19 13:37	General View					Load JPG	☒	
6	02/11/19 13:37	General View					Load JPG	☒	
7	02/11/19 13:37	General View					Load JPG	☒	
8	02/11/19 13:37	General View					Load JPG	☒	
9	02/11/19 13:37	General View					Load JPG	☒	
10	02/11/19 13:37	General View					Load JPG	☒	
11	02/11/19 13:37	General View					Load JPG	☒	
12	02/11/19 13:37	General View					Load JPG	☒	
13	02/11/19 13:37	General View					Load JPG	☒	
14	02/11/19 13:37	General View					Load JPG	☒	
15	02/11/19 13:37	General View					Load JPG	☒	
16	02/11/19 13:37	General View					Load JPG	☒	
17	02/11/19 13:37	General View					Load JPG	☒	
18	02/11/19 13:37	General View					Load JPG	☒	
19	02/11/19 13:37	General View					Load JPG	☒	
20	02/11/19 13:37	General View					Load JPG	☒	
21	02/11/19 13:37	General View					Load JPG	☒	
22	02/11/19 13:37	General View					Load JPG	☒	
23	02/11/19 13:37	General View					Load JPG	☒	
24	02/11/19 13:37	General View					Load JPG	☒	
25	02/11/19 13:37	General View					Load JPG	☒	
26	02/11/19 13:37	General View					Load JPG	☒	
27	02/11/19 13:37	General View					Load JPG	☒	
28	02/11/19 13:37	General View					Load JPG	☒	
29	02/11/19 13:37	General View					Load JPG	☒	
30	02/11/19 13:37	General View					Load JPG	☒	
31	02/11/19 13:37	General View					Load JPG	☒	
32	02/11/19 13:37	General View					Load JPG	☒	
33	02/11/19 13:37	General View					Load JPG	☒	
34	02/11/19 13:37	General View					Load JPG	☒	
35	02/11/19 13:37	General View					Load JPG	☒	
36	02/11/19 13:37	General View					Load JPG	☒	
37	02/11/19 13:37	General View					Load JPG	☒	
38	02/11/19 13:37	General View					Load JPG	☒	
39	02/11/19 13:37	General View					Load JPG	☒	
40	02/11/19 13:37	General View					Load JPG	☒	
41	02/11/19 13:37	General View					Load JPG	☒	
42	02/11/19 13:37	General View					Load JPG	☒	
43	02/11/19 13:37	General View					Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	02/11/19 13:37	General View	 Load JPG	☒
45	02/11/19 13:37	General View	 Load JPG	☒
46	02/11/19 13:37	General View	 Load JPG	☒
47	02/11/19 13:37	General View	 Load JPG	☒
48	02/11/19 13:37	General View	 Load JPG	☒
49	02/11/19 13:37	General View	 Load JPG	☒
50	02/11/19 13:37	General View	 Load JPG	☒
51	02/11/19 13:37	General View	 Load JPG	☒
52	02/11/19 13:37	General View	 Load JPG	☒
53	02/11/19 13:37	General View	 Load JPG	☒
54	02/11/19 13:37	General View	 Load JPG	☒
55	02/11/19 13:37	General View	 Load JPG	☒
56	02/11/19 13:37	General View	 Load JPG	☒
57	02/11/19 13:37	General View	 Load JPG	☒
58	02/11/19 13:37	General View	 Load JPG	☒
59	02/11/19 13:37	General View	 Load JPG	☒
60	02/11/19 13:37	General View	 Load JPG	☒
61	02/11/19 13:37	General View	 Load JPG	☒
62	02/11/19 13:37	General View	 Load JPG	☒
63	02/11/19 13:37	General View	 Load JPG	☒
64	02/11/19 13:37	General View	 Load JPG	☒
65	02/11/19 13:37	General View	 Load JPG	☒
66	02/11/19 13:37	General View	 Load JPG	☒
67	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
68	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
69	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
70	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
71	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
72	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
73	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
74	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
75	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
76	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
77	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
78	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
79	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
80	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
81	02/11/19 13:37	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/05/19 19:05	ACKNOWLEDGEMENT EMAIL TO III DD 23.05.2019	 Load PDF	
2	23/05/19 19:05	TP GIA REPORT	 Load PDF	
3	26/05/19 09:56	TP ESTIMATE-MARKED	 Load PDF	
4	02/11/19 13:38	LOD	 Load PDF	
5	02/11/19 13:38	Authorisation to Act	 Load PDF	
6	02/11/19 13:38	Workshop Invoice	 Load PDF	
7	02/11/19 13:38	LTA Search Fee	 Load PDF	
8	02/11/19 13:38	Towing Fee	 Load PDF	
9	02/11/19 13:42	PARF_COE REBATE	 Load PDF	
10	16/12/19 11:24	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	24/05/19 08:24	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19009131/R1PA3Q2

Date: 16/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0015
Claimant	
Vehicle No : SFX7006R	Insured Vehicle No : SH8981Z
Date of Loss: 21/05/2019	Nature of Claim: TP Claim No: MCT19050592

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFX7006R	Engine No:	R18A13860120
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN6860AC200120
Reg. Date:	20/10/2010 (Man. Year: 2009)	Odometer:	287596 km
Colour:	Red		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,733.44	6,067.92	4,665.52	43.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	3,000.00	710.00	19.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,443.44	9,067.92	5,375.52	37.22
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	14,443.44	6,000.00	8,443.44	58.46
+ GST 7.00/7.00% (S\$)	1,011.04	420.00	591.04	58.46
Nett Amount (S\$)	15,454.48	6,420.00	9,034.48	58.46
+ Loss of Use (14.0 x S\$80.00/day) (S\$)		1,120.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		7,667.45		

INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	23/05/2019 Inspected At:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
		Blk 3 Pioneer Road North, #01-18
		Singapore 628457
Estimated Period of Repair:	12.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$26,500.00(est) less LTA Rebate: \$20,025.00(est) = Nett Value :\$6,475.00(est)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFX7006R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	635.60 FL	*635.60 FL
2	1		*FRT BUMPER SIDE RETAINER (RH)	Necessary	12.40 FL	*12.40 FL
3	10		*FRT BUMPER CLIPS	Necessary	39.00 FL	*39.00 FL
4	1		*FRT FENDER RH	Bent	486.20 FL	*486.20 FL
5	1		*FRT FENDER INNERSHIELD RH	Deformed	82.70 FL	*82.70 FL
6	10		*FRT FENDER INNERSHIELD CLIPS	Necessary	35.00 FL	*35.00 FL
7	1		*FRT FENDER INNER PANEL RH	Repair	90.90 FL	*- FL
8	1		*FRT HEADLAMP RH	Scratched	595.70 FL	*595.70 FL
9	1		*FRT HEADLAMP LOWER BRACKET RH	Serviceable	36.50 FL	*- FL
10	1		*FRT DOOR RH	Bent	860.00 FL	*860.00 FL
11	2		*FRT DOOR HINGE RH	Bent	70.80 FL	*70.80 FL
12	1		*FRT DOOR CHECKER (RH)	Serviceable	36.90 FL	*- FL
13	1		*FRT DOOR LOCK RH	Bent	217.10 FL	*217.10 FL
14	1		*FRT SIDE MIRROR ASSY RH	Repair	436.40 FL	*- FL
15	1		*FRT DOOR GLASS OUTER MOULDING	Necessary	80.50 FL	*80.50 FL
16	1		*FRT DOOR GLASS RUN CHANNEL RH	Serviceable	90.90 FL	*- FL
17	1		*FRT DOOR GLASS REGULATOR MOTOR	Serviceable	391.90 FL	*- FL
18	1		*FRT DOOR INNER TRIM BOARD RH	Serviceable	636.00 FL	*- FL
19	10		*FRT DOOR INNER TRIM BOARD CLIP	Necessary	45.00 FL	*45.00 FL
20	1		*FRT QUARTER GLASS MOULDING RH	Necessary	38.90 FL	*38.90 FL
21	1		*FRT DOOR FRAME STICKER RH	Necessary	46.10 FL	*46.10 FL
22	1		*FRT DOOR OUTER HANDLE RH	Serviceable	112.40 FL	*- FL
23	1		*SIDE PANEL RH	Bent	220.70 FL	*220.70 FL
24	1		*REAR DOOR RH	Bent	811.20 FL	*811.20 FL
25	2		*REAR DOOR HINGE RH	Serviceable	77.80 FL	*- FL
26	1		*REAR DOOR LOCK RH	Serviceable	194.70 FL	*- FL
27	1		*REAR DOOR FRAME STICKER RH	Necessary	38.70 FL	*38.70 FL
28	1		*REAR DOOR GLASS REGULATOR MOTOR	Serviceable	428.40 FL	*- FL
29	1		*REAR FENDER RH	Repair	925.30 FL	*- FL
30	10		*REAR FENDER INNERSHIELD CLIP	Not Necessary	35.00 FL	*- FL
31	1		*REAR BUMPER	Scratched	640.90 FL	*640.90 FL
32	1		*REAR BUMPER SIDE RETAINER RH	Necessary	20.80 FL	*20.80 FL
33	1		*REAR FENDER GLASS MOULDING RH	Serviceable	60.00 FL	*- FL
34	1		*FRT RIM 15	Scratched	528.16 FS	*300.00 FS
35	1		*FRT SHOCK ABSORBER RH	Bent	286.90 FL	*286.90 FL
36	1		*FRT WHEEL HUB RH	Bent	249.70 FL	*249.70 FL
37	1		*FRT WHEEL BEARING RH	Necessary	121.60 FL	*121.60 FL
38	1		*FRT KNUCKLE ARM RH	Bent	267.40 FL	*267.40 FL
39	1		*FRT LOWER ARM RH	Bent	328.20 FL	*328.20 FL
40	1		*FRT TIE ROD RH	Bent	85.10 FL	*85.10 FL
41	1		*FRT TIE ROD END RH	Bent	56.20 FL	*56.20 FL
42	1		*FRT DRIVE SHAFT	Serviceable	996.90 FL	*- FL
43	1		*FRT STABILIZER LINK RH	Serviceable	68.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR RIM 15	Scratched	528.16 FS	*300.00 FS
45	1		*REAR WHEEL HUB BEARING (RH)	Serviceable	380.60 FL	*- FL
46	1		*FRT QUARTER GLASS SEALANT	Necessary	40.00 FS	*20.00 FS
47	1		*REAR FENDER GLASS SEALANT	Not Necessary	40.00 FS	*- FS
48	1		*FRT TYRE RH (205/65R15) (70%)	Cut	250.00 FS	*175.00 FS
49	1		*REAR TYRE RH (205/65R15) (70%)	Scratched	250.00 FS	*175.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					13,007.72	7,342.40
- List Item Discount on L Items 20.00/20.00% (S\$)					2,274.28	1,274.48
Total Parts (S\$)					10,733.44	6,067.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	30.00	30.00
2	TO REMOVE & REFIX RR FENDER GLS	New	100.00	0.00
3	TO REMOVE & REFIX FRT QUARTER GLS	New	100.00	50.00
4	TO TRANSFER FRT & RR DOOR GLS	New	100.00	60.00
5	TO DO WHEEL ALIGNMENT	New	80.00	60.00
6	TO REPAIR & REFIX UNDERCARRIAGE	New	400.00	200.00
7	TO KNOCK ,WELD ,REMOVE & FIX ON ABOVE PARTS	New	1,400.00	1,200.00
8	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,500.00	1,400.00
Gross Labour Cost (S\$)			3,710.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >