

H3170 RML

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

Repair Unit \$6k

EST/QUOTE NO. SQ004940

DATE 23/05/2019

ACCIDENT DATE: 21/05/2019

VEHICLE NO: SFX7006R

CHASSIS/ENG.NO: JHMRN6860AC200120

VEHICLE MODEL: HONDA STREAM

CLAIM NO:

POLICY NO:

REMARK 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER <i>bt</i>	635.60	20	508.48	508.48/
2	1	PC	FRT BUMPER SIDE RETAINER(RH) <i>rec</i>	12.40	20	9.92	9.92/
3	10	PC	FRT BUMPER CLIPS <i>rec</i>	3.90	20	3.12	31.20/
4	1	PC	FRT FENDER RH <i>bt</i>	486.20	20	388.96	388.96/
5	1	PC	FRT FENDER INNERSHIELD RH <i>DE</i>	82.70	20	66.16	66.16/
6	10	PC	FRT FENDER INNERSHIELD CLIPS <i>rec</i>	3.50	20	2.80	28.00/
7	1	PC	FRT FENDER INNER PANEL RH <i>repair</i>	90.90	20	72.72	72.72 R
8	1	PC	FRT HEADLAMP RH <i>scr</i>	595.70	20	476.56	476.56/
9	1	PC	FRT HEADLAMP LOWER BRACKET RH <i>? xscr</i>	36.50	20	29.20	29.20 X
10	1	PC	FRT DOOR RH <i>bt</i>	860.00	20	688.00	688.00/
11	2	PC	FRT DOOR HINGE RH <i>bt</i>	35.40	20	28.32	56.64/
12	1	PC	FRT DOOR CHECKER(RH) <i>? xscr</i>	36.90	20	29.52	29.52 X
13	1	PC	FRT DOOR LOCK RH <i>bt</i>	217.10	20	173.68	173.68/
14	1	PC	FRT SIDE MIRROR ASSY RH <i>repair</i>	436.40	20	349.12	349.12 R
15	1	PC	FRT DOOR GLASS OUTER MOULDING R <i>xscr</i>	80.50	20	64.40	64.40/
16	1	PC	FRT DOOR GLASS RUN CHANNEL RH <i>? xscr</i>	90.90	20	72.72	72.72 X
17	1	PC	FRT DOOR GLASS REGULATOR MOTOR <i>? xscr</i>	391.90	20	313.52	313.52 X
18	1	PC	FRT DOOR INNER TRIM BOARD RH <i>? xscr</i>	636.00	20	508.80	508.80 X
19	10	PC	FRT DOOR INNER TRIM BOARD CLIP <i>rec</i>	4.50	20	3.60	36.00/
20	1	PC	FRT QUARTER GLASS MOULDING RH <i>rec</i>	38.90	20	31.12	31.12/

SAM

PAGE: 1 of 4

2559.14

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION:

CONTACT: 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE 23/05/2019

ACCIDENT DATE : 21/05/2019

VEHICLE NO : SFX7006R

CHASSIS/ENG.NO : JHMRN6860AC200120

VEHICLE MODEL : HONDA STREAM

CLAIM NO :

POLICY NO :

REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
21	1	PC	FRT DOOR FRAME STICKER RH <i>new</i>	46.10	20	36.88	36.88 /
22	1	PC	FRT DOOR OUTER HANDLE RH <i>X</i>	112.40	20	89.92	89.92 X
23	1	PC	SIDE PANEL RH <i>bt</i>	220.70	20	176.56	176.56 /
24	1	PC	REAR DOOR RH <i>bt</i>	811.20	20	648.96	648.96 /
25	2	PC	REAR DOOR HINGE RH <i>X</i>	38.90	20	31.12	62.24 X
26	1	PC	REAR DOOR LOCK RH <i>X</i>	194.70	20	155.76	155.76 X
27	1	PC	REAR DOOR FRAME STICKER RH <i>new</i>	38.70	20	30.96	30.96 /
28	1	PC	REAR DOOR GLASS REGULATOR MOTO <i>X</i>	428.40	20	342.72	342.72 X
29	1	PC	REAR FENDER RH <i>repair</i>	925.30	20	740.24	740.24 /
30	10	PC	REAR FENDER INNER SHIELD CLIP <i>X</i>	3.50	20	2.80	28.00 X
31	1	PC	REAR BUMPER <i>sc</i>	640.90	20	512.72	512.72 /
32	1	PC	REAR BUMPER SIDE RETAINER RH <i>new</i>	20.80	20	16.64	16.64 /
33	1	PC	REAR FENDER GLASS MOULDING RH <i>X</i>	60.00	20	48.00	48.00 X
34	1	PC	FRT RIM 15" <i>sc</i>	660.20	20	528.16	300% 528.16
35	1	PC	FRT SHOCK ABSORBER RH <i>bt</i>	286.90	20	229.52	229.52 /
36	1	PC	FRT WHEEL HUB RH <i>bt</i>	249.70	20	199.76	199.76 /
37	1	PC	FRT WHEEL BEARING RH <i>new</i>	121.60	20	97.28	97.28 /
38	1	PC	FRT KNUCKLE ARM RH <i>bt</i>	267.40	20	213.92	213.92 /
39	1	PC	FRT LOWER ARM RH <i>bt</i>	328.20	20	262.56	262.56 /
40	1	PC	FRT TIE ROD RH <i>? bt</i>	85.10	20	68.08	68.08 /
41	1	PC	FRT TIE ROD END RH <i>? bt</i>	56.20	20	44.96	44.96 /

SAM

PAGE: 2 of 4

2538.80

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE : 23/05/2019

ACCIDENT DATE : 21/05/2019

VEHICLE NO : SFX7006R

CHASSIS/ENG.NO : JHMRN6860AC200120

VEHICLE MODEL : HONDA STREAM

CLAIM NO :

POLICY NO :

REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
42	1	PC	FRT DRIVE SHAFT ? <i>you</i>	996.90	20	797.52	797.52 X
43	1	PC	FRT STABILIZER LINK RH ? <i>you</i>	68.40	20	54.72	54.72 X
44	1	PC	REAR RIM 15" <i>you</i>	660.20	20	528.16	300 <i>you</i> 528.16 ✓
45	1	PC	REAR WHEEL HUB BEARING(RH) ? <i>you</i>	380.60	20	304.48	304.48 X

SUB-TOTAL: 10,153.44

\$5097.91

** SPECIAL NETT PRICE **

1	1	PC	FRT QUARTER GLASS SEALANT <i>you</i>	40.00		40.00	20 40.00
2	1	PC	REAR FENDER GLASS SEALANT <i>X</i>	40.00		40.00	X 40.00
3	1	PC	FRT TYRE RH (205/65R15) <i>you</i>	250.00	<i>\$175</i>	250.00	70% 250.00
4	1	PC	REAR TYRE RH (205/65R15) <i>you</i>	250.00	<i>\$175</i>	250.00	70% 250.00

SUB-TOTAL 580.00

\$370 + \$600
SWIFT

** WORK LABOUR **

TO CHECK WIRING	30.00	30.00	✓
TO REMOVE & REFIX RR FENDER GLS	100.00	100.00	<i>100</i> X
TO REMOVE & REFIX FRT QUARTER GLS	100.00	100.00	<i>50</i> ✓
TO TRANSFER FRT & RR DOOR GLS	50.00	100.00	<i>60</i> ✓
TO DO WHEEL ALIGNMENT	80.00	80.00	<i>60</i> ✓
TO REPAIR & REFIX UNDERCARRIAGE	400.00	400.00	<i>200</i> ✓

SAM

PAGE: 3 of 4

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司
SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

EST/QUOTE NO. SQ004940

DATE : 23/05/2019
ACCIDENT DATE : 21/05/2019
VEHICLE NO : SFX7006R
CHASSIS/ENG.NO : JHMRN6860AC200120
VEHICLE MODEL : HONDA STREAM
CLAIM NO :
POLICY NO :
REMARK : 7006INDIA TP AGST
SH8981Z

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
			TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	1400.00			1,400.00 1200
			TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	1500.00			1,500.00 1400
			SUB-TOTAL				3,710.00

Issue
Hp 90010068
12 days
L/S
23/05/19 @ 1610
Removal after repair
Repair limit 6K

total \$9067.92
less 70% = \$2720.33
x \$7250/-
Lump sum
Unit 6K
Chm on
3/10/2019

SAM

PAGE: 4 of 4

SUB-TOTAL : S\$ 14,443.44
ADD 7% GST. S\$ 1,011.04
GRAND TOTAL : S\$ 15,454.48

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.