

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 04 Jun 2019

Preliminary Advice

Insured Vehicle No	: SLC3736H		
TP Vehicle No	: SHC483D	Accident Date	: 20/05/2019
Make	: TOYOTA PRIUS	Assignment Date	: 24/05/2019
Date of Inspection	: 24/05/2019	Est. Duration of Repair	: 24/05/2019
Inspection At	: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front, o/s front & o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,061.76
Revised Amount	:S\$	14,523.35
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,523.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.