



Section A - Accident Details

Registration Number	SHF348X
Case Reference Number	TAX/05/19/2081
Registration Date	14/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	GOH HUAT ANTONIE
Type of Accident	Head to Rear
Accident Date and Time	20/5/2019 11:15 AM
Accident Reported Date and Time	21/5/2019 9:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101568
Special Instruction to ARC, if any	TP
Prepared Date and Time	23/5/2019 10:20 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Top View

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$500.00
Total Spray Cost	\$1,836.00	\$400.00
Total Spare Part Cost	\$6,170.40	\$1,400.72
Total Other Cost	\$920.00	\$80.00
TOTAL COST	\$10,190.40	\$2,380.72 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	23/05/2019 11:30 AM	23/05/2019 1:44 PM
Signature		
Remarks		p/p repair, photo before paint.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0139	Invoice Number	
Quotation Date	13.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RR END PANEL	\$250.00	\$100.00
TO REPAIR REAR PORTION	\$1,014.00	\$400.00
Total Labour	\$1,264.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00
TO RESPRAY SPOILER	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,836.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$920.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52565479 00	FILLER, RR BUMPER, RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
		52566479 00	FILLER, RR BUMPER, LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Check

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park EA, Singapore 757195
FAX Number : 63655592
Estimator Telephone Number : 69662622
Accident Reporting Number : 68662672

Date Generated : 14/05/2019
User ID : PehHuan

		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
	58398470	COVER, REAR FLOOR	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	50	UNDER, RH							
	66259470	COVER, REAR FLOOR	0.00	\$222.80	0.00	\$0.00	Replace	Check	X
	10	UNDER CENTER							
	58399470	COVER, REAR FLOOR	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	30	UNDER, LH							
	67005474	TAIL GATE PANEL SUB-	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
	40	ASSY, BACK DOOR							
	76801471	TAIL GATE BACK DOOR	1.00	\$891.20	100.00	\$0.00	Replace	Repair	X
	10A1	OUTSIDE GARNISH SUB-							
	56117501	TAIL GATE DAM, BACK	0.00	\$27.90	0.00	\$0.00	Replace	Not Given	X
	40	DOOR GLASS UPPER							
	75571470	TAIL GATE MOULDING	0.00	\$29.70	0.00	\$0.00	Replace	Not Given	X
	10	GLASS, BACK DOOR							
	75574470	TAIL GATE MOULDING	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
	40	LOWER GLASS, BACK							
	75573471	TAIL GATE MOULDING	0.00	\$29.90	0.00	\$0.00	Replace	Not Given	X
	10	LOWER GLASS, BACK							
	75575470	TAIL GATE MOULDING	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X
	51	LOWER GLASS, BACK							
		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
	75403480	EMBLEM SUB-ASSY REAR	0.00	\$46.30	0.00	\$0.00	Replace	Not Given	X
	10								
	75441470	NAME PLATE (HYBRID),	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
	90	LUGGAGE COMPARTMENT							
	75442471	NAME PLATE (PRIUS),	1.00	\$52.30	25.00	\$39.23	Replace	Replace	X
	30	LUGGAGE COMPARTMENT							
		STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	X
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	X
	67881470	TAIL GATE	0.00	\$360.70	0.00	\$0.00	Replace	Not Given	X
	50	WEATHERSTRIP, BACK							
	64718470	END PANEL, COVER,	0.00	\$47.00	0.00	\$0.00	Replace	Not Given	X
	80C0	DECK TRIM SERVICE							
	64716471	END PANEL, COVER,	0.00	\$122.80	0.00	\$0.00	Replace	Not Given	X
	30C0	DECK TRIM, REAR							
	76085479	SPOILER SUB-ASSY, REAR	0.00	\$1,322.10	0.00	\$0.00	Replace	Not Given	X
	16								
	81006470	LAMP SET, STOP CENTER	0.00	\$186.50	0.00	\$0.00	Replace	Not Given	X
	30								
	52159479	COVER, RR BUMPER	1.00	\$423.90	25.00	\$317.93	Replace	Replace	X
	13	ASSY							
	52023470	REAR BUMPER	0.00	\$318.80	0.00	\$0.00	Replace	Check	X
	30	REINFORCEMENT							
	52462470	PAD, RR BUMPER, RH &	2.00	\$3.80	25.00	\$5.70	Replace	Replace	X
	30	LH, 1							
	52462470	PAD, RR BUMPER, RH &	2.00	\$3.80	25.00	\$5.70	Replace	Replace	X
	20	LH, 2							
	52462470	PAD, RR BUMPER, RH &	2.00	\$3.80	25.00	\$5.70	Replace	Replace	X
	10	LH, 3							
	52575470	RETAINER, RR BUMPER,	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
	40	RH							
	52576470	RETAINER, RR BUMPER,	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X
	40	LH							
	52453470	GUARD, RR BUMPER,	1.00	\$558.30	25.00	\$418.73	Replace	Replace	X
	10	LOWER							
	52169470	COVER, GUARD RR	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
	20	BUMPER LOWER							
Total				\$7,538.70		\$1,161.62			

1400.72
+ 500.00
+ 480.00
2380.72

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470	REAR BUMPER	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		30	REINFORCEMENT						
Total					318.80		239.10		



Case Details

Case Reference Number : TAX/05/19/2081
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHF348X

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6968-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 20/05/2019 03:15 AM
 Vehicle Age(In Months) : 17

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation					Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)			Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93		Replace	0	0	Not Give	un X
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93		Replace	0	0	Not Give	un X
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00		Replace	2	120.00	Replace	hel /
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00		Replace	1	180.00	Replace	shorted /
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	529.80	529.80	25.00	472.35		Replace	0	0	Check	X NM
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00		Replace	0	0	Check	X NM
One Time Key In	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13		Replace	0	0	Not Give	X un
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95		Replace	0	0	Check	X NM
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73		Replace	0	0	Not Give	X un
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20		Replace	0	0	Not Give	X un

Total Spare Part Cost 5,931.30

Lump Sum Discount (%) 0.00

Final Spare Part Cost 1,159.42

Surveyor Total 1,161.58

Lump Sum Dis (%) 0

Final Sur Total 1,161.58

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	* X R
One Time Key In	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	55.80	25.00	41.85	Replace	0	0	Not Give	* X nu
One Time Key In	Main			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	29.70	25.00	22.27	Replace	0	0	Not Give	* }
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give	* }
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	1	29.90	29.90	25.00	22.42	Replace	0	0	Not Give	* }
One Time Key In	Main			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	* } nu X
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give	* }
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	0	0	Not Give	* }
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / nec
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	* / nec
One Time Key In	Main			STICKER SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / nec
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / nec
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	0	0	Not Give	* X nu
One Time Key In	Main			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	47.00	25.00	35.25	Replace	0	0	Not Give	* X nu
One Time Key In	Main			END PANEL, COVER, DECK TRIM, REAR	1	122.80	122.80	25.00	92.10	Replace	0	0	Not Give	* X nu

Total Spare Part Cost 5,931.30

Surveyor Total 1,161.58

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 1,159.42

Final Sur Total 1,161.58

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0	Not Give	X mh
One Time Key In	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	0	0	Not Give	X mh
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	/CUT
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	X MH
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/nel
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/nel
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	/nel
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	X mh
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Not Give	X mh
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	/DEF
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Not Give	X mh
Total Spare Part Cost									5,931.30	Surveyor Total 1,161.58				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									1,159.42	Final Sur Total 1,161.58				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			1,656.00	300.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0	
3	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0	
4	Main	TO RESPRAY REAR PANEL	180.00	0	
5	Main	TO RESPRAY TAIL GATE	378.00	0	
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
7	Main	TO RESPRAY SPOILER	180.00	0	
Total:			1,856.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20 <i>APC</i>	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0	
3	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30 <i>APC</i>	
4	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
5	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
6	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	120.00	30 <i>APC</i>	
7	Main	TO WASH AND VACUUM	80.00	0	
8	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			920.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,159.42	1,161.58
Total Labour Cost	1,014.00	400.00
Total Spray Painting	1,556.00	300.00
Other	920.00	80.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Overall Total	4,749.42	1,941.58
Lump Sum Repair Option		
Lump Sum Total	0.00	1,941.58
Surveyor Approved Amount		1,941.58
No of Repair Days*	6	3
Remarks		p/p repair, photo before paint.
Surveyor Name		Hwee Jie
Signature		
Survey Date	23/05/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

REQUEST FOR SUPPLYMENT PARTS

Contractor:		WEGA ENGINEERING PTE LTD	
Accident Case Number	TAX/05/19/2081	Date of Collection	23/5/19
Vehicle No	SHP 348X	Date of Request	24/5/19
Vehicle Model	TOYOTA PRINCE 4	Number of Days to Extend (if any)	1 DAYS.

S/N	Part Number	Part Description	Quantity	Unit Price
	0981,82,83,84	Rear Bumper Reinforcement		\$318.80 ✓ BT 23910/
	0985,86,87	To Repair End Panel		\$290.00 \$100
		To Respray End Panel		\$180.00 \$100

<<<Please submit photographs for damaged parts>>>

I, (Name) CHIA

(Position)

Do solemnly and sincerely declare that Supplementary Parts are raised for replacement for the aforesaid vehicle.

.....

Signature of person making this declaration
(To be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission