

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 412D**AAD1905-184***Not Notarized*
*Resurvey B4 paint**\$1207.96*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

SHD 412D

VF1ABL15AUC283291

RENAULT

LATITUDE

22.5.19

III

14/11/2016

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel)TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH
28	1	BOOT HINGE LH
29	1	BOOT HINGE RH
30	1	BOOT INNER TRIM

LIST

\$	<i>N</i>	1,108.46	<i>X</i>
\$	<i>nd/cu</i>	768.84	<i>X</i>
\$	<i>Sn</i>	113.47	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>Sn</i>	135.97	
\$	<i>Sn</i>	44.99	
\$	<i>Sn</i>	43.61	
\$	<i>N</i>	777.52	
\$	<i>N</i>	225.95	
\$	<i>N</i>	225.95	
\$	<i>N</i>	1,471.77	
\$	<i>Sn</i>	404.56	
\$	<i>Sn</i>	552.55	<i>X</i>
\$	<i>N</i>	986.70	
\$	<i>Sn</i>	552.55	
\$	<i>N</i>	986.70	
\$	<i>N</i>	2,872.68	
\$	<i>Sn</i>	470.06	
\$	<i>Sn</i>	323.05	
\$	<i>Sn</i>	493.35	
\$	<i>Sn</i>	493.35	
\$	<i>na</i>	225.36	
\$	<i>na</i>	225.36	
\$	<i>Sn</i>	276.08	
\$	<i>Sn</i>	276.08	
\$	<i>N</i>	367.84	
\$	<i>N</i>	367.84	
\$	<i>Sn</i>	586.45	

Trans-cab Auto Services Pte Ltd

AAD1905-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 412D

31	1	BOOT SWITCH	\$	Sn	168.13	X
32	1	BOOT LOCK	\$	nn	202.67	X
33	1	BOOT LOCK CATCH	\$	nn	74.40	X

TOTAL \$ 16,046.87**10% \$ 1,604.69****\$ 14,442.19****Special Nett**

1	1SET	PARKING AID	\$	Sn	700.00	
2	1SET	REAR BUMPER CLIP	\$	nn	66.00	
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
10	1	REAR BOOT ADVERTISEMENT STICKER	\$	nn	300.00	X
11	1	REAR BUMPER ADVERTISEMENT STICKER	\$	nn	300.00	100%nn
12	1	REAR LH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
13	1	REAR RH FENDER ADVERTISEMENT STICKER	\$	nn	300.00	X
14	2	REAR WINDSCREEN SEALANT	\$	nn	80.00	
15	1	WINDSCREEN MOULDING	\$	nn	100.00	
16	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
17	1	EXHAUST MOUNTING REAR	\$	nn	17.82	
18	1	TAILLAMP CLIP LH	\$	nn	5.00	
19	1	TAILLAMP CLIP RH	\$	nn	5.00	
20	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
21	1	BOOT INNER TRIM CLIP	\$	nn	45.00	

TOTAL \$ 2,524.02**TOTAL PARTS \$ 16,966.21****LABOUR**

To Check Electrical Lighting Concerned. \$ nn 170.00 X

To transfer of tire, rim and on wheel balancing. \$ nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-184**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 412D

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00 X
To reinstall rear bumper parking sensor.	\$	nn 170.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,500.00 10d
Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 22d
To repair and realign rear exhaust pipe.	\$	nn 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and replace corporate sticker	\$	330.00 3d
TOTAL	\$	12,050.00
Over All Total	\$	29,016.21
PART BY PART (REPAIR DAY)		10 DAYS
		1 day

LKK Auto Consultants hence notify

the Repairs of the vehicle

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be confirmed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: