



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park E4, Singapore 757705
 FAX Number : 63685592
 Estimator Telephone Number : 68662623
 Accident Reporting Number : 68662672

Date Generated : 12/06/2019
 User ID : CatherineLee

Khanchina

Section A - Accident Details

Registration Number	SMB326X
Case Reference Number	BUS/05/19/5035
Registration Date	1/11/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Murugan Raja
Type of Accident	Side Swipe
Accident Date and Time	14/5/2019 2:28 PM
Accident Reported Date and Time	14/5/2019 5:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101637
Special Instruction to ARC, if any	Bus left mirror cover broken. TP: YM3446M (China Taiping)
Prepared Date and Time	22/5/2019 7:24 PM
Chassis Number	WMAA22Z25C7001459
Mileage	
Work Shop	
Repair Completion Date and Time	

L/S \$2400/ 1day.

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$1,863.07	\$1,863.07
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,825.07	\$2,390.07
Lump Sum Total	\$0.00	1.0
Number of Repair Days	2.0	Hwee jie
Prepared / Adjusted By	Jeong Choon Hwee	23/05/2019 12:11 PM
ARC / Surveyor Sign Off Date	22/05/2019 7:28 PM	x
Signature		
Remarks		L/S REPAIR. AFTER PAINT PHOTO

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 12/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL FRONT VIEW MIRROR LH	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$432.00	\$262.00
Total Spray Painting & Panel Beating	\$432.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010159	BODY LH	4001M01-ACCE466	MIRROR,VIEW:FRONT,LH,FOR MAN	1.00	\$1,903.30	10.00	\$1,712.97	Replace	Replace
6010160	BODY LH	4001M01-ACCE468	ARM,MIRROR VIEW:FRONT,LH,FOR MAN	1.00	\$684.30	10.00	\$615.87	Replace	Replace
Total					\$2,587.60		\$2,328.84		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: