



poh kin

樹發汽車修理廠 SHU FATT AUTO WORKS

SKS 8455M

D-11

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK pw Sh-quo
23rd May 2019
TP-20

SKS 8455 M HONDA HR-V

Spare Parts	1	Left fit tender. <i>bt</i>	88
	1	Left fit fender cowling <i>X</i>	588.20
	1	Set left fit fender cowling clips. <i>new</i>	98.20 <i>X</i>
	1	Left fit fender arch garnish. <i>new</i>	35.00
	1	Set left fit fender arch garnish clips. <i>new</i>	160.20
	1	Left wing mirror. <i>scr</i>	35.00
	1	Left wing mirror cover. <i>repair</i>	495.20
	1	Fit bumper <i>X RX</i>	49.20 <i>X</i>
	1	Set fit bumper clips. <i>X</i>	459.20 <i>X</i>
			42.00 <i>X</i>

Less 20%
1962.20
392.44

Labour

To knock straighten left fit wheel house, left fit door pillar, fit inner panel, fit lower panel, fit side panel, renew left fit fender, fit bumper, wing mirror and assembly
To respray damaged parts

1569.76
~~760.00~~ *350*

900.00 *500*

3229.76

Goodyear 215/55R17
MR.HRU1830FP000089
77887

Rasul
HP 9001068

4 days

4/5

18/06/19 @ 1155

Revy after repair

Surveyed on 18/6/19 @ 11:55 am

Parts: 1313.60
-20%: (262.72)
1050.88
Labour: 850.00
900.88
-20%: (180.18)
720.70

4/5 = 1500

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: