



樹發汽車修理廠 SHU FATT AUTO WORKS

0-11

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Our Ref: WSK/jw/SF-quo
23rd May 2019
TP-20

SKS 8455 M HONDA HR-V

		S\$
Spare Parts	1 Left fnt fender. <i>bt ✓</i>	588.20
	1 Left fnt fender cowling <i>x</i>	98.20
	1 Set left fnt fender cowling clips. <i>new ✓</i>	35.00
	1 Left fnt fender arch garnish. <i>sc ✓</i>	160.20
	1 Set left fnt fender arch garnish clips. <i>new ✓</i>	35.00
	1 Left wing mirror. <i>scr ✓</i>	495.20
	1 Left wing mirror cover. <i>repair</i>	49.20
	1 Fnt bumper. <i>x</i>	459.20
	1 Set fnt bumper clips. <i>x</i>	42.00

		1962.20
	Less 20%	392.44

		1569.76
Labour	To knock, straighten left fnt wheel house, left fnt door pillar, fnt inner panel, fnt lower panel, fnt side panel, renew left fnt fender, fnt bumper, wing mirror and assembly.	760.00 <i>350</i>
	To respray damaged parts.	900.00 <i>500</i>

		3229.76
		=====

Goodyear 215/55R17
MRHRU1830FP000089
77887

Rasul
Hp 9001068
4 days
L/S
18/06/19 @ 1155
Reev after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: