

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0666/2019/DY
Date : 24-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle No. : **YN 5082 K**

EQ Insurance Company Limited

22 Gemmill Lane

Singapore 069257

Motor Claims Dept

Tel: 6223 9433 - Fax: 6223 4190

Owner's Name : Mr. Suresh s/o Nagarajan
Address : Blk 308B Ang Mo Kio Ave 1
#06-397
Singapore 562308
Telephone : HP +65 91870015
Type of Claim : Third Party Claims
Policy No. : 5103460854
Vehicle No : **SLB 8491 K** ✓
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Apr-16
Engine No : CVN 005052
Chassis No : WAUZZZF42GA038570
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-May-19
Place of Accident : Church Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLB 8491 K

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,800.00 1400
3	To respray front bumper and rhs front fender.	\$ 1,800.00 1400
4	To remove and renew rhs front rim and alignment.	S/N \$ 280.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 4,432.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLB 8491 K

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT BUMPER <i>del</i>	\$ 1,946.00	✓
2	FRONT BUMPER FIXING PARTS <i>green</i>	\$ 258.00	X
3	FRONT BUMPER AIR GUIDE - RH <i>green</i>	\$ 56.00	X
4	FRONT BUMPER GUIDE SECTION - RH ?	\$ 34.00	?
5	FRONT FENDER - RH <i>Distorted</i>	\$ 700.00	✓
6	FRONT FENDER CLOSING ELEMENT - RH ?	\$ 45.00	?
7	FRONT FENDER BRACE - RH <i>Bent</i>	\$ 107.00	✓
8	FRONT FENDER BRACKET - RH	\$ 32.00	✓
9	FRONT FENDER RIVET - RH <i>in</i>	\$ 36.00	✓
10	FRONT WHEEL HOUSING LINER - RH ?	\$ 220.00	?
11	FRONT WHEEL SPOILER - RH <i>green</i>	\$ 66.00	X
12	FRONT WHEEL SPOILER TRIM - RH <i>green</i>	\$ 33.00	X
13	FRONT TYRE RIM - RH <i>cut</i>	\$ 629.00	✓
14	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		:	\$ 4,562.00
TOTAL LABOUR CHARGES			\$ 4,432.00
GRAND TOTAL			<u>\$ 8,994.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lij
Surveyed Date : 28/05/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : xoe authorised, 05 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant