

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt	S\$600.00 Edit Estimates	S\$600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Prestige Premium Lease Pte Ltd , Co. Reg. No.: 201408247E									
Main Claimant: TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K									
Vehicle Reg. No.:	SHB9905A	Date of Loss:	21/05/2019 10:00 - :59 [68 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8586968016SG	Policy/Cover Note No.:	1700074680 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKL1528U	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (06/08/2019): Re: No OI GIA Report - AIG_SG (06/08/2019): Re: Request For OI GIA Report - AIG_SG (06/06/2019): Re: No OI GIA Report - AIG_SG (27/05/2019): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB9905A (8586968016SG)**
[SKL1528U]
TP
TRANS-CAB SERVICES PTE LTD
May 21 2019 10:00AM
[Prestige Premium Lease Pte Ltd]
Trans-cab Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	06/08/19 11:30	Accident Statement From: SC - Reg. No: SKL1528U, Claimant: PRESTIGE PREMIUM LEASE PTE LTD	1	Load HTM
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	30/05/19 16:27	General View	1	Load JPG ☒
2	30/05/19 16:27	General View	1	Load JPG ☒
3	30/05/19 16:27	General View	1	Load JPG ☒
4	30/05/19 16:27	General View	1	Load JPG ☒
5	30/05/19 16:27	General View	1	Load JPG ☒
6	30/05/19 16:27	General View	1	Load JPG ☒
7	30/05/19 16:27	General View	1	Load JPG ☒
8	30/05/19 16:27	General View	1	Load JPG ☒
9	30/05/19 16:27	Odometer Reading	1	Load JPG ☒
10	30/05/19 16:27	General View	1	Load JPG ☒
11	30/05/19 16:27	Chassis Number	1	Load JPG ☒
Documentation				
			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/05/19 16:53	TP ESTIMATE- MARKED	1	Load PDF
2	24/05/19 16:53	TP GIA REPORT	1	Load PDF
3	28/05/19 10:58	Non reporting letter	1	Load PDF
4	12/12/19 14:01	LETTER TO OI	1	Load PDF
5	21/07/20 11:27	Authorisation to Act	1	Load PDF
6	21/07/20 11:27	LOD	1	Load PDF
7	21/07/20 11:27	LTA SEARCH	1	Load PDF
8	21/07/20 11:27	Release Voucher	1	Load PDF
9	21/07/20 11:27	RENTAL MILEAGE	1	Load PDF
10	21/07/20 11:27	RENTAL RECEIPT	1	Load PDF
11	21/07/20 11:27	WORKSHOP INVOICE	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKL1528U (Insd veh)	Model:	RENAULT LATITUDE 2.0 D DCI
	SHB9905A (TP veh)		(A)
Date of Accident:	21/05/2019		

Global Sum Settlement	:	[X]	Yes	[]	No	
Repair Estimate	:	\$				26,446.32
Final Repair Cost	:	\$				1,000.00
Loss of Use	:	\$				2.50 days at \$50.00 per day
Rental (if any)	:	\$				2.5 days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				1,000.00

Is Third Party Workshop GIA Registered?		[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Trans-Cab Auto Services Pte Ltd	: \$	1,000.00
2)		: \$	
3)		: \$	
4)		: \$	
5)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

21 Jul
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG19009172/KKA3S2**Date:** 21/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700074680
Claimant Vehicle No :	SHB9905A	Insured Vehicle No :	SKL1528U
Date of Loss:	21/05/2019	Nature of Claim:	TP
		Claim No:	8586968016SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9905A	Engine No:	M9R8839C000448
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC273459
Reg. Date:	30/08/2013 (Man. Year: 2013)	Odometer:	619697 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,826.19	400.00	15,426.19	97.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,890.00	360.00	8,530.00	95.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,716.19	760.00	23,956.19	96.93
Approved Total (Overridden) (S\$)		600.00		
(S\$)	24,716.19	600.00	24,116.19	97.57
+ GST 7.00/7.00% (S\$)	1,730.13	42.00	1,688.13	97.57
Nett Amount (S\$)	26,446.32	642.00	25,804.32	97.57
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$95.04/day) (S\$)		237.60		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,012.05		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment:	23/05/2019	
Date Inspected:	23/05/2019	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
2	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*- FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
19	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
28	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
29	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
30	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
31	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
32	1		*BOOT LOCK	Repair	202.67 FL	*- FL
33	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
34	1		*SET PARKING AID	Scratched	700.00 FS	*400.00 FS
35	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
36	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
37	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
38	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
39	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
40	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
41	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
42	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
43	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
44	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
45	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
46	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
47	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
48	1		*REAR WINDSCREEN INNER SPONGE INNER SEALSPONGE	Not Necessary	100.00 FS	*- FS
49	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
50	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
51	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
52	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 17,430.88 **400.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 1,604.69 0.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	15,826.19 400.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	0.00
2	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR.	New	170.00	60.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	3,000.00	220.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	3,000.00	80.00
9	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	New	170.00	0.00
10	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	New	170.00	0.00
11	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	0.00
14	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
Gross Labour Cost (\$\$)			8,890.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >