

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9905A**AAD1905-183***Not Authorized*
L1Bry &

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHB 9905A
VF1ABL15AUC273459
RENAULT
LATITUDE
21.5.19
AIG
30/8/2013

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>11</i>	1,108.46
2	1	BUMPER LOWER REAR	\$	<i>12</i>	768.84
3	1	BUMPER BRACKET CTR REAR	\$	<i>12</i>	113.47
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>12</i>	135.97
5	1	BUMPER RETAINER RH REAR	\$	<i>12</i>	44.99
6	1	BUMPER REFLECTOR RH	\$	<i>12</i>	43.61
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>12</i>	135.97
8	1	BUMPER RETAINER LH REAR	\$	<i>12</i>	44.99
9	1	BUMPER REFLECTOR LH	\$	<i>12</i>	43.61
10	1	BUMPER BEAM REAR	\$	<i>11</i>	777.52
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>11</i>	225.95
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>11</i>	225.95
13	1	OUTER PANEL REAR (End Panel)	\$	<i>11</i>	1,471.77
14	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>12</i>	404.56
15	1	TAILLAMP RH	\$	<i>12</i>	552.55
16	1	TAILLAMP PANEL RH	\$	<i>11</i>	986.70
17	1	TAILLAMP LH	\$	<i>12</i>	552.55
18	1	TAILLAMP PANEL LH	\$	<i>11</i>	986.70
19	1	BOOT REAR	\$	<i>11</i>	2,872.68
20	1	BOOT FINISHER	\$	<i>12</i>	470.06
21	1	BOOT WHEATERSTRIP	\$	<i>12</i>	323.05
22	1	BOOT REFLECTOR LAMP LH	\$	<i>12</i>	493.35
23	1	BOOT REFLECTOR LAMP RH	\$	<i>12</i>	493.35
24	1	BOOT BADGE 'RENAULT'	\$	<i>11</i>	225.36
25	1	BOOT BADGE	\$	<i>11</i>	225.36
26	1	BOOT STRUT LH	\$	<i>12</i>	276.08
27	1	BOOT STRUT RH	\$	<i>12</i>	276.08
28	1	BOOT HINGE LH	\$	<i>11</i>	367.84
29	1	BOOT HINGE RH	\$	<i>11</i>	367.84

Trans-cab Auto Services Pte Ltd**AAD1905-183**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9905A

30	1	BOOT INNER TRIM	\$	586.45	X
31	1	BOOT SWITCH	\$	168.13	X
32	1	BOOT LOCK	\$	202.67	X
33	1	BOOT LOCK CATCH	\$	74.40	X
TOTAL			\$	16,046.87	
10%			\$	1,604.69	
			\$	14,442.19	

Special Nett

1	1SET	PARKING AID	\$	700.00	PER 4000
2	1SET	REAR BUMPER CLIP	\$	66.00	} X
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	
10	1	BOOT STICKER "Trans-cab"	\$	30.00	
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
TOTAL			\$	1,384.02	

TOTAL PARTS \$ 15,826.21**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-183**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9905A

To reinstall rear bumper parking sensor.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	✓
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	✓
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	801
To repair and realign rear exhaust pipe.	\$	170.00	✓
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	✓
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	✓
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	✓
To check steering geometry and computer wheel alignment	\$	220.00	✓
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	✓
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	✓

TOTAL \$ 8,890.00**Over All Total \$ 24,716.21****LUMP SUM (REPAIR DAY)****10-DAYS***1 day*LKK Auto Consultancy Sdn Bhd
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: