

15/02/19

INS. CASE OWNER:

CC 4/AIG1900 9180

LKK:
IDAC:

Surveyor:

MURCHIS

DOI:

ASSIGNMENT

26/5/19


Date / Time:

22/5/19

Registered in Merimen:

26/5/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 8036

Name of Insured:

LEE WAI

Insured Tel No.:

HP:

96682779

Excess Sec II :SS

D.O.A.:

15/5/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

300458398454

Policy No.:

20042778

Make / Model:

TOYOTA

Place of Accident:

PIE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

GBF 4565E

INSRS:
WSP:
Tel:
Liability:
RMKS:Think
oneINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE / PIC
15/5/19 - 8	Non-Reporting ltr (1st):	
15/5/19 - 8	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by: CKS
Repair Cost: 45 \$56,800	(8 days) Reduction: 49 %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: 25-10-19	Confirm with MICHAEL	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No.:	If NO or B 28. Ass. Lia:
Repair Cost: nil		101 FILTER/OVERTAKE
Loss of Rental (LOR): \$5 -	(0 days)	(6 LOR INTO TWO LOR)
Loss of Use (LOU): \$5 120.00	(5 90 x 8 days)	
Loss of Income (LOI): \$5 -	(5 x days)	
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	\$5 2.00	
Medical:	\$5 -	
Disbursement:	\$5 -	(e.g. Tow/ Independent)
Legal Cost	\$5 -	
Total:	\$5 7,998.00	Global Sum \$5:
FINAL PAYMENT Date/Time: 25-10-19	Confirm with MICHAEL	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	\$5 7,998.00	Name 1: THINK ONE AUTO CARE PIE LTD
Payee 2: (Strike if N.A.)	\$5 -	Name 2:
Payee 3: (Strike if N.A.)	\$5 -	Name 3:

Surveyor

REF: AIG

e

ASSIGNMENT

From:

Date: 28.5.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBF 4565E

at Workshop m/s Think One Autocare
of 1018 Dafu Ave 2

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3.00p.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

"up" 47A 17443

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF 4565E

Yr Regn:

10/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

Toyota Hiace

C.C

2982

Colour

Orange

A/C:

Insured / Std / NI / NA

Sp. Reading

102 25.8

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KDM 2015023774

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

17/5/19

D.O.I.

28/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

43 : +6.800 (RED: +6.422.75 49%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

not Admin
Mar
28/5/19
2/5 # 6800/
Poh
Ech phd Abing

GBF4565E Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	Dis S 1,260.00
2	1	Rear bumper left bracket	S S 86.00
3	1	Rear bumper inner beam	S S 287.00
4	1	Rear bumper step garnish	S S 296.00
5	1	Rear tailgate assy	S S 1,862.00
6	1	Rear tailgate lock mechanism	S S 266.00
7	1	Rear tailgate lock catch	S S 62.00
8	2	Rear tailgate hinges	S S 162.00
9	2	Rear tailgate damper	S S 375.00
10	1	Rear tailgate weatherstrip	S S 288.00
11	1	Rear tailgate inner board	S S 190.00
12	1	Rear tailgate centre logo	S S 68.00
13	1	Rear tailgate windscreen glass moulding	S S 295.00
14	1	Rear tailgate lock actuator	S S 189.00
15	1	Rear tailgate outer garnish	S S 176.00
16	1	Rear tailgate lock cylinder	S S 191.00
17	1	Rear left taillamp	S S 785.00
18	1	Rear left taillamp lower panel	S S 109.00
19	1	Rear left fender panel assy	S S 6,800.00
20	1	Rear left air duct	S S 96.00
21	1	Rear left lower side panel	S S 580.00
22	1	Rear end lower panel	S S 1,274.00
Less 25%			S 15,697.00
			S 3,924.25
			S 11,772.75

7214.5
262
8411.17

Special Nett Items

1	10	Rear bumper clips	S S 50.00
2	12	Rear tailgate inner board clips	S S 30.00
3	4	Rear tailgate outer garnish clips	S S 20.00
4	1	Rear tailgate '70km/h' sticker	S S 30.00
5	1set	Rear tailgate company advertisement sticker	S S 250.00
6	1	Rear end lower panel sealant	S S 100.00
7	1	Rear view camera	S S 300.00
8	2	Rear bumper reverse sensor	S S 250.00
9	1	Rear left fender panel sealant	S S 80.00
10	1	Rear left lower side panel sealant	S S 80.00
11	1	Rear windscreen glass sealant	S S 80.00
12	1	Rear left quarter glass sealant	S S 100.00
13	1	Rear no plate	S S 80.00
			S 1,450.00

600

Total Parts

S 13,222.75

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBF4565E Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear, rear left affected area and replace rear and rear left damaged parts.	S 1,400.00	1200
2	To putty and spray painting rear and rear left portion.	S 1,400.00	900
3	To check rear lighting and wiring.	S 50.00	30
4	To remove and install rear tailgate lock mechanism.	S 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	S 150.00	X
6	To apply anti rust proofing to rear and rear left affected area.	S 120.00	100
7	To remove and install rear windscreen glass to facilitate the repair.	S 140.00	100
8	To remove and install rear bumper reverse sensor.	S 80.00	50
9	To remove and install rear view camera.	S 80.00	50
10	To remove and install rear left quarter glass.	S 100.00	80
11	Towing service.	S 100.00	X

Total labour : S 3,700.00

Total parts : S 13,222.75

Total labour : S 3,700.00

Total repair cost : S 16,922.75

2420
S31.17

not Arant
Mar
28/5/18
2/5/18
Poh
Teh phd Ahlowe

GBF4565E Toyota Hiace

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy	D.S \$ 1,260.00
2	1	Rear bumper left bracket	Sp \$ 86.00
3	1	Rear bumper inner beam	\$ 287.00 ?
4	1	Rear bumper step garnish	NS \$ 296.00 X
5	1	Rear tailgate assy	body \$ 1,862.00
6	1	Rear tailgate lock mechanism	rod/br \$ 266.00
7	1	Rear tailgate lock catch	11 \$ 62.00 X
8	2	Rear tailgate hinges	11 \$ 162.00 X
9	2	Rear tailgate damper	11 \$ 375.00 X
10	1	Rear tailgate weatherstrip	\$ 288.00 ?
11	1	Rear tailgate inner board	\$ 190.00 ?
12	1	Rear tailgate centre logo	ru \$ 68.00
13	1	Rear tailgate windscreen glass moulding	NS \$ 295.00 X
14	1	Rear tailgate lock actuator	11 \$ 189.00 X
15	1	Rear tailgate outer garnish	11 \$ 176.00 X
16	1	Rear tailgate lock cylinder	11 \$ 191.00 X
17	1	Rear left taillamp	cu \$ 785.00
18	1	Rear left taillamp lower panel	D.S \$ 109.00
19	1	Rear left fender panel assy	body/suc \$ 6,800.00
20	1	Rear left air duct	D.S \$ 96.00
21	1	Rear left lower side panel	body \$ 580.00
22	1	Rear end lower panel	body \$ 1,274.00
			\$ 15,697.00
Less 25%			\$ 3,924.25
			\$ 11,772.75

Special Nett Items

1	10	Rear bumper clips	ru \$ 50.00
2	12	Rear tailgate inner board clips	ru \$ 30.00
3	4	Rear tailgate outer garnish clips	11 \$ 20.00 X
4	1	Rear tailgate '70km/h' sticker	ru \$ 30.00
5	1set	Rear tailgate company advertisement sticker	ru \$ 250.00 150
6	1	Rear end lower panel sealant	ru \$ 100.00 X
7	1	Rear view camera	11 \$ 300.00 X
8	2	Rear bumper reverse sensor	cu \$ 250.00 200
9	1	Rear left fender panel sealant	ru \$ 80.00 50
10	1	Rear left lower side panel sealant	11 \$ 80.00 X
11	1	Rear windscreen glass sealant	ru \$ 80.00 40
12	1	Rear left quarter glass sealant	ru \$ 100.00 50
13	1	Rear no plate	11 \$ 80.00 X
			\$ 1,450.00

Total Parts

\$ 13,222.75

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

GBF4565E Toyota Hiace

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear, rear left affected area and replace rear and rear left damaged parts.	\$ 1,400.00	1200
2	To putty and spray painting rear and rear left portion.	\$ 1,400.00	900
3	To check rear lighting and wiring.	\$ 50.00	30
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00	X
6	To apply anti rust proofing to rear and rear left affected area.	\$ 120.00	100
7	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	100
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	\$ 80.00	
10	To remove and install rear left quarter glass.	\$ 100.00	80
11	Towing service.	\$ 100.00	X
Total labour :		\$ 3,700.00	

Total parts : \$ 13,222.75

Total labour : \$ 3,700.00

Total repair cost : \$ 16,922.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No unauthorised alterations allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5609M
Vehicle Details	
Vehicle No.:	GBF4565E
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2637846
Chassis No.:	KDH2015023774
Maximum Power Output:	-
Open Market Value:	\$35,251.00
Original Registration Date:	27 Oct 2016
First Registration Date:	27 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$1,763.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$23,553.00
COE Rebate Amount:	\$17,443.00
Total Rebate Amount:	\$17,443.00

The information contained herein is correct as at 29 May 2019

OK

PRE-REPAIR INSPECTION REQUEST – GBF4565E vs SLE803G (OI) on D.O.A.: 17/05/2019

From: Hor, Yinrul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 5/23/2019 10:40:10 AM
Attachments:  SAS2604894.pdf

Hi,

Please refer to the enclosed request from **Think One Autocare Pte Ltd**.

Claim no : 3004585982SG003
Case Owner : KIAN MENG CHAN

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Marcus Chua** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: karentan@thinkone.com.sg [mailto:karentan@thinkone.com.sg]
Sent: Thursday, May 23, 2019 10:30 AM
To: Hor, Yinrul
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLE803G AND GBF4565E ON 17/05/2019

Hi Yinrul,

We shall proceed with LKK Auto Consultants Pte Ltd, Marcus Chua.

From: Hor, Yinrul
Sent: Thu, 23 May 2019 02:21:30 +0000
To: Karen Tan
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLE803G AND GBF4565E ON 17/05/2019

Without Prejudice

Your Reference : GBF4565E
Our Reference : 3004585982SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd

Veh Out.

Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
*Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Yinrul.Hor@aig.com | www.aig.sg

From: Karen Tan [mailto:karentan@thinkone.com.sg]

Sent: Thursday, May 23, 2019 10:09 AM

To: ClaimsDocManagement

Subject: [EXTERNAL] RE: GBF4565E & SLE803G ACCIDENT DATED ON 17.05.2019

Importance: High

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Mdm,

I would like to arrange a surveyor for GBF4565E. As my client is claiming against your insured SLE803G for the above mention accident.

Thank you.

Karen Tan

Claim Advisor

Think One Autocare Pte Ltd

No.18 Defu Avenue 2

Singapore 539522

HP : 9128 8488

DID : 6844 3300 FAX : 6842 4988

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 May 2019 Edit Reg		23 May 2019 00:00 Edit Adj Rpt	S\$6,800.00 Edit Estimates	S\$6,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LEE WAH, ID: S0013068J		
Main Claimant:	THINK ONE LEASING PTE LTD, Co. Reg. No.: 201115609M		
Vehicle Reg. No.:	GBF4565E	Date of Loss:	17/05/2019 16:00 - :59 [30 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 3004585982SG	Policy/Cover Note No.:	2100472938 (Comprehensive)
Vehicle Reg. No. (Insured):	SLE803G	Policy No. (Claimant):	5107728339
		Excess:	
Repairer:	Think One Autocare Pte Ltd (HQ) No. 18 Defu Avenue 2, 539522 Ubi - Tel: 68443300		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 04/06/2019]		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF4565E (3004585982SG)**
[SLE803G]

TP
















































THINK ONE LEASING PTE LTD

May 17 2019 4:00PM

[LEE WAH]

Think One Autocare Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	<input checked="" type="checkbox"/>
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Thumbnail	Print
			1	Edit
Photos/Images				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page	<input checked="" type="checkbox"/>
1	28/05/19 19:08	Chassis Number	Thumbnail	Print
2	28/05/19 19:08	Odometer Reading	1	Load JPG
3	28/05/19 19:09	General View	1	Load JPG
4	28/05/19 19:09	General View	1	Load JPG
5	28/05/19 19:09	General View	1	Load JPG
6	28/05/19 19:09	General View	1	Load JPG
7	28/05/19 19:09	General View	1	Load JPG
8	28/05/19 19:09	General View	1	Load JPG
9	28/05/19 19:09	General View	1	Load JPG
10	28/05/19 19:09	General View	1	Load JPG
11	28/05/19 19:09	General View	1	Load JPG
12	28/05/19 19:09	General View	1	Load JPG
13	28/05/19 19:09	General View	1	Load JPG
14	28/05/19 19:09	General View	1	Load JPG
15	28/05/19 19:09	General View	1	Load JPG
16	28/05/19 19:09	General View	1	Load JPG
17	28/05/19 19:09	General View	1	Load JPG
18	28/05/19 19:09	General View	1	Load JPG
19	28/05/19 19:09	General View	1	Load JPG
20	28/05/19 19:09	General View	1	Load JPG
21	28/05/19 19:09	General View	1	Load JPG
22	28/05/19 19:09	General View	1	Load JPG
23	28/05/19 19:09	General View	1	Load JPG
24	28/05/19 19:09	General View	1	Load JPG
25	28/05/19 19:09	General View	1	Load JPG
26	28/05/19 19:09	General View	1	Load JPG
27	28/05/19 19:09	General View	1	Load JPG
28	28/05/19 19:09	General View	1	Load JPG
29	28/05/19 19:09	General View	1	Load JPG
30	28/05/19 19:09	General View	1	Load JPG
31	28/05/19 19:09	General View	1	Load JPG
32	28/05/19 19:09	General View	1	Load JPG
33	28/05/19 19:09	General View	1	Load JPG
34	28/05/19 19:09	General View	1	Load JPG
35	28/05/19 19:09	General View	1	Load JPG
36	28/05/19 19:09	General View	1	Load JPG
37	28/05/19 19:09	General View	1	Load JPG

Letters/Correspondences			1 per page ▼	☑
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/05/19 19:09	General View	 Load JPG	☑
39	28/05/19 19:09	General View	 Load JPG	☑
40	28/05/19 19:09	General View	 Load JPG	☑
41	28/05/19 19:09	General View	 Load JPG	☑
42	28/05/19 19:09	General View	 Load JPG	☑
43	28/05/19 19:09	General View	 Load JPG	☑
44	28/05/19 19:09	General View	 Load JPG	☑
45	28/05/19 19:09	General View	 Load JPG	☑
46	28/05/19 19:09	General View	 Load JPG	☑
47	28/05/19 19:09	General View	 Load JPG	☑
48	28/05/19 19:09	General View	 Load JPG	☑
49	28/05/19 19:09	General View	 Load JPG	☑
50	28/05/19 19:09	General View	 Load JPG	☑
51	28/05/19 19:09	General View	 Load JPG	☑
52	28/05/19 19:09	General View	 Load JPG	☑
53	28/05/19 19:09	General View	 Load JPG	☑
54	28/05/19 19:09	General View	 Load JPG	☑
55	28/05/19 19:09	General View	 Load JPG	☑
56	28/05/19 19:09	General View	 Load JPG	☑
57	28/05/19 19:09	General View	 Load JPG	☑
58	28/05/19 19:09	General View	 Load JPG	☑
59	28/05/19 19:09	General View	 Load JPG	☑
60	28/05/19 19:09	General View	 Load JPG	☑
61	28/05/19 19:09	General View	 Load JPG	☑
62	28/05/19 19:09	General View	 Load JPG	☑
63	28/05/19 19:09	General View	 Load JPG	☑
64	28/05/19 19:09	General View	 Load JPG	☑
65	28/05/19 19:09	General View	 Load JPG	☑
66	28/05/19 19:09	General View	 Load JPG	☑
67	28/05/19 19:09	General View	 Load JPG	☑
68	28/05/19 19:09	General View	 Load JPG	☑
69	28/05/19 19:09	General View	 Load JPG	☑
70	28/05/19 19:09	General View	 Load JPG	☑
71	28/05/19 19:09	General View	 Load JPG	☑
72	28/05/19 19:09	General View	 Load JPG	☑
73	28/05/19 19:09	General View	 Load JPG	☑
74	28/05/19 19:09	General View	 Load JPG	☑
75	28/05/19 19:09	General View	 Load JPG	☑
76	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
77	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
78	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
79	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
80	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
81	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
82	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
83	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
84	11/06/19 07:45	Reinspection Photo	 Load JPG	☑
85	11/06/19 07:45	Reinspection Photo	Load JPG	☑
86	11/06/19 07:45	Reinspection Photo	Load JPG	☑
87	11/06/19 07:45	Reinspection Photo	Load JPG	☑
88	11/06/19 07:45	Reinspection Photo	Load JPG	☑
89	11/06/19 07:45	Reinspection Photo	Load JPG	☑
90	11/06/19 07:45	Reinspection Photo	Load JPG	☑

Letters/Correspondences			1 per page	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
91	11/06/19 07:45	Reinspection Photo	1 Load JPG	✓
92	11/06/19 07:45	Reinspection Photo	i Load JPG	✓
Documentation			1 per page	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/05/19 15:52	EMAIL FROM AIG DD 23052019	i Load PDF	
2	24/05/19 15:52	TP GIA REPORT	i Load PDF	
3	22/07/19 11:58	EMAIL TO OI	i Load PDF	
4	04/11/19 11:54	LOD	i Load PDF	
5	04/11/19 11:54	AUTHORISATION TO ACT	i Load PDF	
6	04/11/19 11:54	RELEASE VOUCHER	i Load PDF	
7	04/11/19 11:54	WORKSHOP INVOICE	i Load PDF	
8	04/11/19 11:54	GIA SEARCH	i Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/05/19 12:11	OI GIA REPORT	i Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE803G (Insd veh)	Model:	TOYOTA HIACE 3.0 D DX (M)
	GBF4565E (TP veh)		
Date of Accident:	17/05/2019		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		18,107.34
Final Repair Cost	:	\$		7,276.00
Loss of Use	:	\$		720.00
Rental (if any)	:	\$		8.00 days at \$90.00 per day
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		days
	:	\$		
Final Settlement Sum	:	\$		7,998.00

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Think One Autocare Pte Ltd	:	\$ 7,988.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

04 Nov
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009180/UEB3S2
Date: 04/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100472938
Claimant Vehicle No: GBF4565E Insured Vehicle No: SLE803G
Date of Loss: 17/05/2019 Nature of Claim: TP Claim No: 3004585982SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4565E**
Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2637846
Reg. Date: 27/10/2016 (Man. Year: 2016) Chassis No: KDH2015023774
Colour: Orange Odometer: 102958 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Bearway 6 mm Rear Left Side: Bearway 6 mm
Front Right Side: Bearway 6 mm Rear Right Side: Bearway 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	13,222.75	6,011.17	7,211.58	54.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,520.00	1,180.00	31.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,922.75	8,531.17	8,391.58	49.59
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	16,922.75	6,800.00	10,122.75	59.82
+ GST 7.00/7.00% (S\$)	1,184.59	476.00	708.59	59.82
Nett Amount (S\$)	18,107.34	7,276.00	10,831.34	59.82
+ Loss of Use (8.0 x S\$90.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,998.00		

INSPECTION

Date of Assignment: 23/05/2019
Date Inspected: 28/05/2019 Inspected At: Think One Autocare Pte Ltd (HQ)
Estimated Period of Repair: 8.0 days No. 18 Defu Avenue 2
Singapore 539522

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and

11/4/2019

Adjuster Report

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Distorted	1,260.00 FL	*596.20 FL
2	1		*REAR BUMPER LEFT BRACKET	Bent	86.00 FL	*86.00 FL
3	1		*REAR BUMPER INNER BEAM	Bent	287.00 FL	*287.00 FL
4	1		*REAR BUMPER STEP GARNISH	No such part	296.00 FL	*- FL
5	1		*REAR TAILGATE ASSY	Badly Dented	1,862.00 FL	*1,862.00 FL
6	1		*REAR TAILGATE LOCK MECHANISM	Dented / Jammed	266.00 FL	*266.00 FL
7	1		*REAR TAILGATE LOCK CATCH	Not Necessary	62.00 FL	*- FL
8	2		*REAR TAILGATE HINGES	Not Necessary	162.00 FL	*- FL
9	2		*REAR TAILGATE DAMPER	Not Necessary	375.00 FL	*- FL
10	1		*REAR TAILGATE WEATHERSTRIP	Twisted	288.00 FL	*288.00 FL
11	1		*REAR TAILGATE INNER BOARD	Not Necessary	190.00 FL	*- FL
12	1		*REAR TAILGATE CENTRE LOGO	Necessary	68.00 FL	*68.00 FL
13	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	No such part	295.00 FL	*- FL
14	1		*REAR TAILGATE LOCK ACTUATOR	Not Necessary	189.00 FL	*- FL
15	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	176.00 FL	*- FL
16	1		*REAR TAILGATE LOCK CYLINDER	Not Necessary	191.00 FL	*- FL
17	1		*REAR LEFT TAILLAMP	Cracked	785.00 FL	*338.50 FL
18	1		*REAR LEFT TAILLAMP LOWER PANEL	Distorted	109.00 FL	*109.00 FL
19	1		*REAR LEFT FENDER PANEL ASSY	Badly Dented / Buckled	6,800.00 FL	*2,115.10 FL
20	1		*REAR LEFT AIR DUCT	Distorted	96.00 FL	*65.50 FL
21	1		*REAR LEFT LOWER SIDE PANEL	Badly Dented	580.00 FL	*345.50 FL
22	1		*REAR END LOWER PANEL	Badly Dented	1,274.00 FL	*788.10 FL
23	10		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	12		*REAR TAILGATE INNER BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
25	4		*REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
26	1		*REAR TAILGATE 70KM/H STICKER	Necessary	30.00 FS	*30.00 FS
27	1		*SET REAR TAILGATE COMPANY ADVERTISEMENT STICKER	Necessary	250.00 FS	*150.00 FS
28	1		*REAR END LOWER PANEL SEALANT	Not Necessary	100.00 FS	*- FS
29	1		*REAR VIEW CAMERA	Not Necessary	300.00 FS	*- FS
30	2		*REAR BUMPER REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
31	1		*REAR LEFT FENDER PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
32	1		*REAR LEFT LOWER SIDE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
33	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR LEFT QUARTER GLASS SEALANT	Necessary	100.00 FS	*50.00 FS
35	1		*REAR NO PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 17,147.00 7,814.90
 - List Item Discount on L Items 25.00/25.00% (S\$) 3,924.25 1,803.73

Total Parts (S\$) 13,222.75 6,011.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR, REAR LEFT AFFECTED AREA AND REPLACE REAR AND REAR LEFT DAMAGED PARTS.	New	1,400.00	1,200.00
2	TO PUTTY AND SPRAY PAINTING REAR AND REAR LEFT PORTION.	New	1,400.00	900.00
3	TO CHECK REAR LIGHTING AND WIRING.	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM.	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	New	150.00	0.00
6	TO APPLY ANTI RUST PROOFING TO REAR AND REAR LEFT AFFECTED AREA.	New	120.00	100.00
7	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR.	New	140.00	100.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.	New	80.00	50.00
9	TO REMOVE AND INSTALL REAR VIEW CAMERA.	New	80.00	0.00
10	TO REMOVE AND INSTALL REAR LEFT QUARTER GLASS.	New	100.00	80.00
11	TOWING SERVICE.	New	100.00	0.00
Gross Labour Cost (\$\$)			3,700.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >