

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

AIG

Owner : Tay Wei Liang

Accident Date : 18-May-19

Vehicle No : FBK 7891 S

Vehicle Model : Honda PCX 150

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
1	Front fender	\$ Cur 165.00 ✓
1	Front fork assy	\$ Dange 780.00 ✗
1	Front sport rim	\$ R 350.00 ✗
1	Front brake disc	\$ 17 180.00 ✗
1	Front rim shaft	\$ 17 52.00 ✗
1	Windshield	\$ 512 248.00 ✓
1	Headlamp -LED	\$ 1ne 550.00 ✓
1	Side mirror -L/H	\$ Bro 176.00 ✓
1	Handle-bar	\$ Bel 98.00 ✓
1	Handle-bar balancer	\$ 512 80.00 ✓
1	Hand grip (1 set)	\$ 1ne 35.00 ✓
1	Brake lever -L/H	\$ 512 38.00 ✓
1	Footstep panel -L/H	\$ Cur 185.00 ✓
1	Rear footrest -L/H	\$ Cur 60.00 ✓
1	Fairing cover set	\$ 1ne 985.00 ✓
1	Horn	\$ 17 50.00 ✗
1	Engine cover	\$ 1ne 350.00 ✓
1	Air filter box cover	\$ Cur 150.00 ✓
1	Main stand	\$ Bel 145.00 ✓
1	Side stand	\$ Bel 95.00 ✓
		\$ 4,772.00
Less 10%		\$ 477.20
		\$ 4,294.80

Not Allowed
n/a
2/3 \$3300/
4 day
wh/m/o Alhaz
24/5/19

3360

Special Nett Items

1	Number plate (1 set)	\$	Net	28.00	10
1	Rear box	\$	cut	250.00	200
1	Rear box bracket	\$	Net	100.00	—
2	Fork oils	\$	Net	30.00	—
2	Fork oil seals	\$	Net	56.00	—
1	Steering cone (1 set)	\$	11	120.00	✓
1	E.R.P IU	\$	11	170.00	X
1	"PCX 150" emblem	\$	Net	70.00	✓
		\$		824.00	

<u>S/No.</u>	<u>Labour</u>				
1	To provide towing service.	\$		50.00	✓
2	To check wiring and reset headlamp focusing	\$	11	80.00	X
3	To provide labour.	\$		380.00	300
4	To respray painting.	\$		800.00	400
		\$		1,310.00	

Grand Total**\$ 6,428.80**

4280


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: