

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

LUMENS AUTO PTE LTD
8 KAKI BUKIT AVENUE 4
05-25 PREMIER @ KAKI BIKIT
Singapore 415875

24th MAY 2019

TP ALG.
Vic

Accident date: 23rd MAY 2019

Estimated repair cost for vehicle no: SMG2620G Toyota PRIUS

S/n	Qty	Items	U/price	Amount
1	1	Front Windscreen <i>Shattered</i>		\$1,250.00 ✓
3	1	Front windscreen moulding <i>new</i>		\$289.40 158
5	1	Front windscreen rubber <i>new</i>		\$236.50 X
6	1	Front windscreen ERP sticker <i>new</i>		\$30.00 20(SN)
7	1	Front Wiper Panel <i>new</i>		\$485.00 X
8	1	Front wiper garnish <i>new</i>		\$564.40 358
9	1	Front wiper garnish rubber <i>new</i>		\$131.75 X
10	1	front wiper <i>best</i>		\$98.00 ✓
11	6	Front wiper garnish clips <i>new</i>	\$12.90	\$77.40 20
12	1	front dashboard	\$0.00	\$0.00
13	1	Front dashboard <i>new</i>		\$964.00 ✓
14	1	Front dashboard panel <i>new</i>		\$469.00 X
16	1	Front Bonnet <i>Repair</i>		\$1,150.00 X

Subtotal :- \$5,742.45

Labour charges

Gum

\$50.00 ✓

To remove & re-fix front windscreen

~~\$150.00~~ 120

to Remove & install front dashboard

670

~~\$280.00~~ 200

Panel beating

~~\$400.00~~ 100

Spray painting

~~\$400.00~~ 200

subtotal:- \$1,280.00

Total:- \$7,022.45

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2823.75

2/5: 2250

0529