

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 846R

MAKE :

MODEL : HYUNDAI i40

AXA
FRONT LEFT

DATE 24/5/2019 12:57

(FZ)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille			\$ 1,110.10
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Grille (LH)			\$ 93.60
	Front Bumper Bracket (LH)			\$ 24.60
	SUB TOTAL			\$ 2,280.50
	LESS 20%			\$ 456.10
	DISCOUNTED TOTAL			\$ 1,824.40
	Labour Charge			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	TOTAL LABOUR			\$ 600.00
	ESTIMATE TOTAL			\$ 2,424.40

✓ SCR XR ✓ SCR ?

150 200

NA2 CLK
24/5/19 1600
LIS
2 DAYS
CHECK ITEMS (PHOTOS)
AFTER REPAIR (PHOTOS)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.