MSG19004448 Gtd302-1 (xin quo Qiray) ASSICTANTENT TOTTE

111ne 7cm

MCS Auto

SLQ 5152E 6296 9939

1100 Scringoun 28795104MCX 4 Form Hos

586695

Make of Vehi O first's Decade

2 um brough

1101 01/03/2019 13/3/11

CA FREY FREE FREE STREET Date/Time 12-54pm@12/3/19 Beautiful

Interest

Pale/Time

Action/Instructions () (stipped)

\$950, 20 ays. (Red: 2050; 68%)

RECEIVED 2 0 JUN 2019

instille OC		CERTIFICATION	1	C0331	(-2
		VSSIGNMLN		12 N	1
From	13	3/19	FBD1541D		
Estimated Cost		Type M.Ca	MCycle / Bus / Van / L	.orry / Taxi / Prime Move	27.1
OD (TP) WS / TP RES / O	D RES / EVA / INV / MV	Truc	k / Trailer or	7.24	0.0
To Inspect Vehicle No	FBD 1541D	Make	Gamana	T135 CO Insured IS	135
at Workshop m/s	MCS AUTO	Colour			
of 11.0	MCS Auto o Sennguan R	d Sp Reading	7/920	T/Radio: Insured / S	td / NI /
Insured	O	Eng/No	6-V2	221.10	
Policy No.		C/No	5 X P 20 8		
Claims No.			Grod / Fair / Poor / Burn		
Sum Insured	Excess		o Ger / Jammed / Leaked		
(Client's Record)			Order / Jammed / Leaker		
Make of Veh		Modi to) / S/Rim / STD A/Rim		
		Tyre Size	F: 80/9	10-11	
(Policy Condition)			R: 90/8	80-17	
Remark. The veh had com	/ V	N/S D/S BS (DUN)	EXNOVA I GY I FS I LIZA	A / MIC / OHTSU / PIR / S	UMI/
repair at the time	e of inspection.	10,011	OKO or		
Bal or Market Value		Front		Rear	
IDAC Accident Rport	Consistent? : Yes or	No R/Bal.	(mm	R/Bal 5	
GIA / PR Seen	Consistent? Yes or	No L'Bal	mm	L/Bal	
Est Repairs 2	days Res Yes or	No D.O.A		DOI 13-0	3 -
Lum Sum: 20		No Survey held	t at W	>	5
CA / REV / REP. /	24 HRS 140	Des. of Dar	mages (rt) Rear / O/S	S / N/9 / U/C / Roofto	p or
Date Date		ehicle IN / OUT			
	son Contacted	The U/O	C / Chassis frame / Bo	dy Structure affected du	e to coll
\$10	00 - \$ 2000				
Cate/Time File Pass to 7	: Preli. Report	Days Of R		Summy Face	120
Date/Time File Return 107	: Final Report	Resurvey	No. of Trip: —	Survey Fee Transportation	110
the same of the sa		Add Fee: Site	Insp (\$	V 20 - 181 13	
		Inte	ryew (\$	Y + 1	

Nivitha (LKK Auto)

From:

Irene Tan <irene_tan@sq.msiq-asia.com>

Sent:

Thursday, 23 May 2019 7:32 PM

To:

Veron Chen (LKKAuto); Shiau Chan (LKKAuto); Denise Tay (LKKAuto); Shirley Hiew

(LKK Auto)

Cc:

Admin-D (LKKAuto); Olivia Lau (LKKAuto)

Subject:

Please prepare your paper survey report on FBD1541D; Our claim no.: 586695/IT

Importance:

High

URGENT

Good evening Veron,

We refer to your PRI report dated 1.4.19.

Please upload your paper survey report asap before the 3rd party's law firm issues a writ of summons.

Irene Tan

Senior Executive, Motor Claims Services

D: +65 6594 2541 |F: +65 6225 7402 | Irene_tan@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg










A Member of MS&AD INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148 reg no: 53058468m Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference

: KAAS/TA/5443/1541/TP/03.19

Invoice No.

: 5443

Date

: 28 April 2019

To: AV One FM & Engineering Pte Ltd

c/o 1100 Serangoon Road Singapore 328195

INVOICE	
PARTICULARS	AMOUNT
Vehicle No. : FBD 1541D Make/Model : Yamaha T135 Inspection of Vehicle	
Appraisal Report	
✓ 28 Colored Photographs ✓ Transport charges	SGD 368.00
Re-inspection	
Others (Specify)	SGD 368.00

Dollars: Three Hundred and Sixty-Eight Only

(Cheque should be crossed and make payable to " Kelvin Automotive Appraising Services ")

Kelvin Automotive Appraising Services



6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148

reg no: 53058468m

Claim Reference : Insured Vehicle No. : Thirty Party Veh No. : Officer-In-Charge : -

Our Reference Date : KAAS/TA/5443/1541/TP/03.19

: 28 April 2019

To: AV One FM & Engineering Pte Ltd

c/o 1100 Serangoon Road Singapore 328195

VEHICLE APPRAISAL REPORT

Name of Workshop

: MCS Auto

Place of inspection

: 1100 Serangoon Road, Singapore 328195

T135

Date of Assignment

: 06 March 2019

Date of Accident

: 01 March 2019

Date of Inspection

: 06 March 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.

: FBD 1541D

Chassis Frame No.

: 5YP208649

Make / Model

: Yamaha

Engine No. (Logcard)

: 5YP208649

Year of Manufacture/Reg

: 2008

Odometer Reading

: 71,920 KM

Colour

: Blue

Class / Type

: Motorcycle

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition

: Good

Paintwork

: Good

Market Value

.

Scrap Value

92.....

CONDITION OF TYRES ON VEHICLE

Make/Size

Thread Balance

Front

DUNLOP 80 / 90 - 17 M/C

8 mm


Rear

DUNLOP 80 / 90 - 17 M/C

8 mm

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

^{*}The above is an estimate of the remaining life of the tyre thread in millimeters




6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148 reg no: 53058468m Our Reference Vehicle Number : KAAS/TA/5443/1541/TP/03.19

: FBD 1541D

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's	Revised
				Estimate	Amount
		LIST ITEMS:-	The second secon	The last a Constitution of the last and the	
1	1 pc	front fender	Broken	\$ 75.00	\$ 75.00
2	1 pair	front fork assy	Bent	\$ 514.00	\$ Pepcir × 514:00
3	1 pc	front fairing	Deformed	\$ 352.00	\$ 352.00
4	1 pc	headlight	Scratched	\$ 95.00	
5	1 pc	front head fairing	Deformed	\$ 196.00	
6	1 pair	wing mirror	Scratched	\$ 76.00	\$ 76.00
7	1 pc	handlebar	Bent	\$ 62.00	
8	1 pc 1 pc	n/s clutch lever basket tray	Scratched	\$ 19.00	
10	1 pc	rider foot rest bar	Deformed Bent	\$ 95.00 \$ 38.00	- 1 A / 1
11	1 pair	rider foot rest	Scratched	\$ 25.00	\$ X 38.00 \$ 25.00
12	1 pair	pillion rider footrest bracket	Unconfirmed	\$ 96.00	Not Affected
13	1 pair	pillion rider footrest	Scratched	\$ 55.00	\$ 27.5 55.00
14	1 pc	n/s gear pedal	Bent	\$ 67.00	\$ AN × 67.00
		148.5			7
		Less 10% 19% : 670.95		\$ 1,765.00	\$ 1,669.00
		Less 10% 1 % 1 670.95			\$ 166.90
		1		\$ 1,765.00	\$ 1,502.10
		1		1,703.00	φ 1,502.10
		SPECIAL NETT ITEMS:-			
15	1 pc	front no. plate - sticker	Manager		\$ 15 2500
16	1 set	rear box (w/ support bracket)	Necessary Scratched	\$ 30.00 \$ 180.00	20.00
17	1 pc	wheel rim	Scratched	\$ 400.00	\$ (40 1.86.00
18	1 pc	tyre @50% depreciation	Scratched	\$ 350.00	\$ 175.00
				\$ 960.00	\$ 780.00
					155
			1		
		1			
		As a constant of the second of	Sub - Total	\$ 2,725.00	\$ 2,282.10



6 tampines st 73, #01-03, singapore 528825 tel: 6746 2118 fax: 6746 1148 reg no: 53058468m

Our Reference Vehicle Number

: KAAS/TA/5443/1541/TP/03.19 *

: FBD 1541D

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's		Revise	ed
				Estimate		Amou	nt
		B/F		\$ 2,725.00	\$	7	2,282.10
		LABOUR & OTHER CHARGES:-					
1		To dismantle and repair damaged parts		\$ 900.00	\$	150	800.00
2		To check wiring and rewire		\$ 100.00	\$	NNX	80.00
3		To realign front fork		\$ 200.00	\$	60	180.00
. 4		To apply anti-rust		\$ 100.00	\$	\times MM	80.00
5		To putty and spray-paint of affected areas		\$ 350.00	\$	150	300.00
				\$ 1,650.00	\$, 1	,440.00
						360	
		21.05			1		
		118595					
		118595					
		P					
		de Es			19.00		
					Bay		
						PAUL POSE	
			Sub - Total	\$ 4,375.00	\$	3,72	2.10

6 tampines st 73, #01-03, singapore 528825

tel: 6746 2118 fax: 6746 1148


reg no: 53058468m

Our Reference Vehicle Number : KAAS/TA/5443/1541/TP/03.19

: FBD 1541D

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered Diagonally to the RH Side from rear to front; right to left; portion of the vehicle.







(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs

MCS Auto

4,375.00

We have adjusted the cost to

3,722.10 and the repairer has agreed to undertake the repairs at a

Contract Lump Sum of

\$

3,000.00 to a acceptable quality and standards.

However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of

working days.

28 photographs were taken at the time of static inspection.

This report is strictly done in a Without Prejudice Basis.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No.

5443

for our services rendered and

we thank you for engaging our services.

KELVIN TEO

PRINCIPAL SURVEYOR

Licensed Automotive Appraiser

Nitec in Automotive Technology

Cert. Crash Investigation & Reconstruction

Dip MS

MSAAA, AM SAE-A

TERRENCE HONG SENIOR SURVEYOR

Dip Engineering (SP) DECC

Certs Automotive Technology (NP)

Cert. Crash Investigation & Reconstruction

Cert SCI (General Insurance)

AMSAAA, AM SAE-A

NOTE: This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.

1100 Serangoon Road Singapore 328195 Company Registration No. 53126812L Email: mcs.auto@yahoo.com.sg

Date: 08 May 2019

AV One FM & Engineering Pte Ltd 1100 Serangoon Road Singapore 328195

FINAL REPAIR COSTS

VEHICLE NO: FBD1541D (YAMAHA T135)

Repair costs of vehicle no. FBD1541D as per the surveyor's report KELVIN AUTOMOTIVE APPRAISING SERVICES (attached herewith) dated 28 Apr 2019 \$3,000.00 LUMP SUM

SINGAPORE DOLLARS : THREE THOUSAND ONLY


































































Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case N	otified	Est Submitted	Adj Assigned	Adj Rpt	Ad	j Submitted	Ins Auth'ed	Status	
Main 0	5 Mar 2019		12 Mar 2019 11:08 Edit Adj Rpt	S\$950.		950.00 /iew Rpt		Pending for Report Cancel Ca	
М	ain	R	eference		laim Details		Documents		Show All
CLAIM SUB							by insurer]		
Insured:	SKYWAY	MOTOR PTE LTD	, Co. Reg. No.: 19	9904194N,	Email: SAND	OY@SKYWAY.	COM.SG		
Main Claimant:	AV ONE F	M & ENGINEERI	NG PTE LTD, Co.	Reg. No.:	201200331D				
Vehicle Reg. No.:	FBD154	BD1541D					9 22:00 - :59 hs and 17 Days Fr	om LTA Reg Da	te (Man Yr)]
Claim Type:	TP / 586	695			Policy/Cover Note No.:		1CX (Comprehensi 08/08/2018 - 07/0		
Vehicle Reg. No. (Insured):	SLQ5152				Policy No. (Claimant):				
					Excess:	S\$1,000.00)		
Repairer:	Mcs Auto	(HQ) 1100 Serai	ngoon Rd, 328195 S	erangoon -	Tel: 6296993	9			
Handling Insurer:	MSIG Ins	urance (Singapo	ore) Pte. Ltd. (HQ)	- Tel: +65	6827 7888	. [Handled by	Irene Tan Gek I	ng - 6594 2541]
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561	[Handled by	XING GUO Q	IANG] [Final	Rpt due 27/	05/2019]
Driver/Custo dian (Insured):			/ Male) , NRIC: S						
Adj Asg. Remarks:		: DISAGREED / to arrange for su	LIABILITY 100% Ple irvey .	ase appoin	LKK AUTO to	conduct the s	survey . Kindly cor	ntact the works	nop directly
ASSOCIATE	D MAIL RE	CEIVED					Vie	w All Comp	ose Case Mai
MSIG_SG	(23/05/2019): Report Send	Back Alerts - FBD:	541D (TP)				
ALL ASSOC	IATED TAS	ks⊟				View All S	Search Tasks C	reate New Task	Complet
Due Date	Priority	Type Tasi	Group Subject	t Hand	ler Assig	ned By	Completed On	Created (n Done

Claim Documents

*FBD1541D (586695)

[SLQ5152E]

TP

AV ONE FM & ENGINEERING PTE LTD

Mar 1 2019 10:00PM

[SKYWAY MOTOR PTE LTD]

Mcs Auto

Ass	essment Reports		1 per page	~
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/03/19 13:39	Accident Statement Addm. #1 From:SC - Reg. No: SLQ5152E, Claimant: SKYWAY MOTOR PTE LTD	1 Load HTM	
Pho	otos/Images		3 per page	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	-
1	14/03/19 09:31	General View	1 Load JPG	✓
2	14/03/19 09:31	General View	Load JPG	✓
3	14/03/19 09:31	General View	1 Load JPG	✓
4	14/03/19 09:31	General View	1 Load JPG	V
5	14/03/19 09:31	General View	Load JPG	☑
6	14/03/19 09:31	General View	Load JPG	V
7	14/03/19 09:31	General View	1 Load JPG	V
8	14/03/19 09:31	General View	1 Load JPG	~
9	14/03/19 09:31	General View	1 Load JPG	4
10	14/03/19 09:31	General View	1 Load JPG	~
11	14/03/19 09:31	General View	1 Load JPG	V
12	14/03/19 09:31	General View	1 Load JPG	V
13	14/03/19 09:31	General View	1 Load JPG	V
14	14/03/19 09:31	General View	1 Load JPG	V
15	14/03/19 09:31	General View	1 Load JPG	~
16	14/03/19 09:31	General View	1 Load JPG	V
17	14/03/19 09:31	General View	1 Load JPG	V
18	14/03/19 09:31	General View	1 Load JPG	V
19	14/03/19 09:31	General View	1 Load JPG	V
20	14/03/19 09:31	General View	1 Load JPG	V
21	14/03/19 09:31	General View	Load JPG	V
22	14/03/19 09:31	General View	Load JPG	V
23	14/03/19 09:31	General View	Load JPG	V
24	14/03/19 09:31	General View	1 Load JPG	V
25	14/03/19 09:31	General View	1 Load JPG	V
26	14/03/19 09:31	General View	1 Load JPG	V
27	14/03/19 09:31	General View	1 Load JPG	V
28	14/03/19 09:31	General View	1 Load JPG	V
29	14/03/19 09:31	General View	1 Load JPG	V
30	14/03/19 09:31	General View	1 Load JPG	V
31	14/03/19 09:31	General View	Load JPG	V
32	14/03/19 09:31	General View	■ Load JPG	V
33	14/03/19 09:31	General View	■ Load JPG	V

Ass	essment Reports		1 per p	page 🗸	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	14/03/19 09:31	General View	0	Load JPG	V
35	14/03/19 09:31	General View	0	Load JPG	V
36	14/03/19 09:31	General View	0	Load JPG	V
37	14/03/19 09:31	General View	0	Load JPG	V
38	14/03/19 09:31	General View	0	Load JPG	V
39	14/03/19 09:31	General View	0	Load JPG	V
40	14/03/19 09:31	General View	0	Load JPG	V
41	14/03/19 09:31	General View	0	Load JPG	V
42	14/03/19 09:31	General View	0	Load JPG	V
43	14/03/19 09:31	General View	0	Load JPG	V
44	14/03/19 09:31	General View	0	Load JPG	V
45	14/03/19 09:31	General View	0	Load JPG	V
46	14/03/19 09:31	General View	0	Load JPG	V
47	14/03/19 09:31	General View	0	Load JPG	V
48	14/03/19 09:31	General View	0	Load JPG	V
49	14/03/19 09:31	General View	0	Load JPG	V
50	14/03/19 09:32	Odometer Reading	0	Load JPG	V
51	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
52	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
53	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
54	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
55	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
56	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
57	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
58	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
59	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
60	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
61	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
62	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
63	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
64	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
65	25/03/19 11:25	Photographs of Damaged Parts	0	Load JPG	V
1000		Photographs of Damaged Parts	0	Load JPG	V
66	25/03/19 11:25	Priotographs of Damageu Parts		Load 31 O	CEL
Doc	cumentation		1 per	page 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Prin
1	05/03/19 13:39	TPD FBD1541D - GIA REPORT From:SC - Reg. No: SLQ5152E, Claimant: SKYWAY MOTOR PTE LTD	0	Load PDF	
2	23/05/19 19:16	LOD with accident report	0	Load PDF	
3	23/05/19 19:16	survey report with final repair invoice	0	Load PDF	
4	23/05/19 19:17	survey pictures	0	Load PDF	
5	23/05/19 19:32	our instruction to LKK to upload paper survey report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	21/06/19 08:50	Colour Photo	Ð	Load PDF	
2	21/06/19 08:50	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG19004448/GTD3E2-1

Date:

21/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28795104MCX

Claimant Vehicle FBD1541D

Insured Vehicle No:

SLQ5152E

No: Date of Loss:

01/03/2019

Nature of Claim:

TP

Claim No: 586695

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

FBD1541D

Make & Model:

YAMAHA T135, 135cc (A) 12/11/2008 (Man. Year: 2008) Engine No:

5YP208649

Reg. Date: Colour:

Blue

Chassis No: Odometer:

5YP208649 71920 km

Engine Capacity: Market Value/New Car Price:

135 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable): Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

Yes

CONDITION OF TYRES

Front Tyre Size:

80/90-17

Rear Tyre Size:

90/80-17

Front Left Side:

Dunlop 5 mm

Rear Left Side:

Dunlop 5 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,725.00	825.95	1,899.05	69.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	360.00	1,290.00	78.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,375.00	1,185.95	3,189.05	72.89
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	4,375.00	950.00	3,425.00	78.29

INSPECTION

Date of Assignment:

12/03/2019

Date Inspected:

13/03/2019

Inspected At:

Mcs Auto (HQ)

1100 Serangoon Rd Singapore 328195

Estimated Period of Repair:

3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source	:	(Last Synchronised: 21 Jun 2019)
Parts:	N/A	YAMAHA T135 135cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted,	no print-code for FBD1541D)
Validity:		es are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info	: Items/values n	ot in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Broken	75.00 F	*75.00 FL
2	1		*PAIR FRONT FORK ASSY	Repair	514.00 F	*-FL
3	1		*FRONT FAIRING	Deformed	352.00 F	*352.00 FL
4	1		*HEADLIGHT	Not Necessary	95.00 F	*-FL
5	1		*FRONT HEAD FAIRING	Deformed	196.00 F	*196.00 FL
6	1		*PAIR WING MIRROR	Scratched	76.00 F	*76.00 FL
7	1		*HANDLEBAR	Not Necessary	62.00 F	*-FL
8	1		*N/S CLUTCH LEVER	Scratched	19.00 F	*19.00 FL
9	1		*BASKET TRAY	Not Necessary	95.00 F	*-FL
10	1		*RIDER FOOT REST BAR	Not Necessary	38.00 F	*-FL
11	1		*PAIR RIDER FOOT REST	Not Necessary	25.00 F	*-FL
12	1		*PAIR PILLION RIDER FOOTREST BRACKET	Not Affected	96.00 F	*-FL
13	1		*PAIR PILLION RIDER FOOTREST	Scratched	55.00 F	*27.50 FL
14	1		*N/S GEAR PEDAL	Not Necessary	67.00 F	*-FL
15	1		*FRONT NO. PLATE - STICKER	Necessary	30.00 FS	*15.00 FS
16	1		*SET REAR BOX (W/SUPPORT BRACKET)	Scratched	180.00 FS	*140.00 FS
17	1		*WHEEL RIM	Not Necessary	400.00 FS	*-FS
18	1		*TYRE	Not Necessary	350.00 FS	*-FS
F=Fr	anchise	part. S=Spcf	Nett. L=ListItemDisc.	2010 TO 1010 NO 000 DOWNSON	54.50-05-05-00-00-0	F. P. S. Colombia T. Colombia
				Sub Total (S\$)	2,725.00	900.50
			- List Item Discount on L Item	is 0.00/10.00% (S\$)	0.00	74.55
				Total Parts (S\$)	2,725.00	825.95

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO DISMANTLE AND REPAIR DAMAGED PARTS	New	900.00	150.00
2	TO CHECK WIRING AND REWIRE	New	100.00	0.00
3	TO REALIGN FRONT FORK	New	200.00	60.00
4	TO APPLY ANTI-RUST	New	100.00	0.00
5	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS	New	350.00	150.00
	Gross Labour Cost (S\$)		1,650.00	360.00
	Report was unsubmitted du	ing this print-out		

< END OF ESTIMATES >