

INS. CASE OWNER:

CC 4, RM 1900 9248, Kalas

LAN: IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT 24/5/19

Date / Time:

24/5/19

Registered in Merimen:

27/5/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

68F 6097B

Name of Insured:

ADAME ADAMAE PTE

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Excess Sec II :SS

D.O.A:

24/05/2019

Place of Accident:

Is driver the owner? (YES /)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SGA 1188 y



INSRS: WSP: Tel: Liability: RMKS:

Cheng Hoe



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time

SGA 1188 y, x: 68F 6097B. 11/11/19 9:00/9:00/14 : DOA: 24/5/19

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

> 20/5/19

17/3/2020 - FILE PASS TO HMMU TO CLOSE

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 19/7/2020

Confirm with: Jme

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost: (w/65%)

SS 4358.58

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 600.00 (\$ 100 x 6 days)

Loss of Income (LOI):

SS -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS 8.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

Total:

SS 4966.58

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 4966.58

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP \$320

COPY SENT 17/3/2020

ASS. REC. BY:

REF: AG1


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Cheng Hoe
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGA11884 Yr Regn: 08, 18
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Fit Hybrid cc 1496
 Colour: M. Pink AC: Insured / Std / NI / NA
 Sp. Reading: 24994 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GP5 . 3415782
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 2 mm Rear R/Bal. 2 mm
 L/Bal. 2 mm L/Bal. 2 mm
 D.O.A. 24/5/19 D.O.I. 24/5/19
 Survey held at _____
 Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>
	<u>P/P - \$4073.44 (Red \$1043.76 / 202)</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) _____
 Date/Time, File Return to?
 2) _____

Report Format :
 Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____
 Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 Fixins _____
 Others _____
 TOTAL _____

Kd
 Athi Kenneth

Cheng Hoe Motor Pte Ltd

804 1019, Yunnan Industrial Park, A 011-174-382, Singapore 748751
 TEL: 67556142 (YIB) FAX: 67557719 (YIB) Email: chmotor@chenghoe.com.sg
 GST: 2000011581 RCD NO: 201001188

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department
 WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 24/05/2019
 TP Veh Reg No: GBF6097B

Estimate No: ES1991547/AMK
 Date: 24 May 2019
 Policy No: 5103456065 DC
 Veh Reg No: SGA1188Y
 Make/Model: HONDA FIT 1.5 A
 HYBRID
 Chassis No: GP57415782
 Engine No: LEB6070466
 Reg. Date: 30/08/2018

Not Authorized
 Resurvey By paint

5045

Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	652.70	1 PC	652.70	✓
2 REAR BUMPER CLIP	3.90	5 PC	19.50	✓
3 REAR TAIL GATE	880.40	1 PC	880.40	✓
4 TAILGATE INNER RUBBER	42.20	1 PC	42.20	✓
5 TAILGATE INNER LOCK	157.50	1 PC	157.50	XX
6 TAILGATE EMBLEM TIT	35.00	1 PC	35.00	✓
7 TAILGATE EMBLEM HYBRID	79.50	1 PC	79.50	✓
8 TAILGATE OUTER CHROME MOULDING	256.00	1 PC	256.00	XX
9 TAILGATE WINDSCREEN GLASS	1050.00	1 PC	1050.00	✓
10 TAILGATE WINDSCREEN GLASS MOULDING	135.80	1 SET	135.80	✓
11 REAR END PANEL	390.00	1 PC	390.00	XX
			2941.30	
			Less 20% 588.26	
			2353.44	
Special Net				
12 REVERSE SENSOR	200.00	1 SET	200.00	✓
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
14 REAR WINDSCREEN GLASS TINTED FILM	250.00	1 PC	250.00	1800 420
			490.00	
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 L.A	120.00	✓
16 REMOVE & REFIX REVERSE CAMERA RESET & REPOSITION	40.00	1 PC	40.00	✓
17 REMOVE & REFIX REAR BUMPER, TAIL LAMP, TAIL GATE & ATTACHMENTS, CUT, WELD & RENEW REAR END PANEL, SMOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	500.00	1 L.A	500.00	500 ✓
18 PUTTY & RESPRAY REAR BUMPER, TAIL GATE & SPOILER, REAR END PANEL, REAR FENDER, AFFECTED AREAS	700.00	1 L.A	700.00	600 ✓
19 RESPROOFING		1 L.A		700 ✓
			1,670.00	1300 ✓

PARTS: 2353.44
 LABOUR: 420
 L: 1300
 4073.44 ✓ ok
 PIP: 4073.44
 PLS CHECK & CONFIRM

OKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Viahun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST 201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 24/05/2019

TP Veh Reg No: GBF6097B

Estimate No: ES1991547/AMK

Date: 24 May 2019

Policy No: 5103456065 DC

Veh Reg No: SGA1188Y

Make/Model: HONDA FIT 1.5 A
 HYBRID

Chassis No: GP53415782

Engine No: LEB6070466

Reg. Date: 30/08/2018

Not Authorized
Resurvey By paint

Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	652.70	1 PC	652.70	✓
2 REAR BUMPER CLIP	3.90	5 PC	19.50	✓
3 REAR TAILGATE	880.40	1 PC	880.40	✓
4 TAILGATE INNER RUBBER	92.30	1 PC	92.30	?
5 TAILGATE INNER LOCK	157.50	1 PC	157.50	?
6 TAILGATE EMBLEM 'FIT'	35.00	1 PC	35.00	✓
7 TAILGATE EMBLEM 'HYBRID'	75.50	1 PC	75.50	✓
8 TAILGATE OUTER CHROME MOULDING	256.60	1 PC	256.60	?
9 TAILGATE WINDSCREEN GLASS	1,050.60	1 PC	1,050.60	✓
10 TAILGATE WINDSCREEN GLASS MOULDING	135.80	1 SET	135.80	✓
11 REAR END PANEL	390.60	1 PC	390.60	?
			3,746.50	
		Less 20%	749.30	2,997.20
Special Net				
12 REVERSE SENSOR	200.00	1 SET	200.00	✓
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
14 REAR WINDSCREEN GLASS TINTED FILM	250.00	1 PC	250.00	✓
			490.00	490.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
17 REMOVE & REFIX REAR BUMPER, TAILLAMP, TAILGATE & ATTACHMENTS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	700.00	1 LA	700.00	?
18 PUTTY & RESPRAY REAR BUMPER, TAILGATE & SPOILER, REAR END PANEL, REAR FENDERS & ALL AFFECTED AREAS	700.00	1 LA	700.00	600
19 RUSTPROOFING		1 LA	60.00	?
			1,630.00	1,630.00

Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES1991547/AMK
Date: 24 May 2019
Policy No: 5103456065 DC
Veh Reg No: SGA1188Y
Make/Model: HONDA FIT 1.5 A
HYBRID
Chassis No: GP53415782
Engine No: LEB6070466
Reg. Date: 30/08/2018

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 24/05/2019
TP Veh Reg No: GBF6097B

Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 5,117.20
			Add GST @ 7%	358.20
			Total Amount Payable	<u>SS 5,475.40</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

PRE-REPAIR INSPECTION REQUEST – SGA1188Y vs GBF6097B (OI) on D.O.A.: 24/05/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 5/24/2019 1:23:12 PM

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd (AMK)**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: chmamk@singnet.com.sg [mailto:chmamk@singnet.com.sg]
Sent: Friday, May 24, 2019 12:21 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; chmamk@singnet.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF6097B AND SGA1188Y ON 24/05/2019

Hi Mr Hor,

Our Selection as follow :

- Kenneth Kong (LKK Auto Consultants Pte Ltd)

* P/S : Please assist to expedite on survey arrangement for today is a Friday and this vehicle is a driving tuition car (claiming loss of income).

Thank you.

Vek lu.

Rgds

Dorlyn Li

Cheng Hoe Motor Pte Ltd (AMK)

Tel : 64812001

From: Hor, Yinrul
Sent: Fri, 24 May 2019 03:41:38 +0000
To: chmamk@singnet.com.sg
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF6097B AND SGA1188Y ON 24/05/2019

Without Prejudice

Your Reference : SGA1188Y
Our Reference : GBF6097B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinrul.Hor@aig.com | www.aig.sg

From: Cheng Hoe Motor Pte Ltd (AMK) [mailto:chmamk@singnet.com.sg]
Sent: Friday, May 24, 2019 10:53 AM
To: Chan, Yoke Shi; Cheng Hoe Motor Pte Ltd
Cc: Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; MohdFitri.Hassim@aig.com; Mithoosingh, Aashweenjeetkaur
Subject: [EXTERNAL] Repair Survey (Single Joint Expert) -SGA1188Y doa 24/05/19 (Yr Insured GBF6097B)

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

OUR CLIENT – SGA1188Y
DOA - 24/05/2019 @ 0900HRS
YOUR INSURED : GBF6097B (HORME HARDWARE PTE LTD)

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
Dorlyn Li
Cheng Hoe Motor Pte Ltd
Tel :64812001
Fax : 64821296

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details			
Vehicle No.:	SGA1188Y		
Vehicle Type:	L10 - For Instruction Motor Car		
Vehicle Attachment 1:	No Attachment		
Vehicle Scheme:	Normal		
Vehicle Make:	HONDA		
Vehicle Model:	FIT 1.5 HYBRID AUTO		
Chassis No.:	GP53415782		
Propellant:	Petrol-Electric		
Engine No.:	LEB6070466		
Motor No.:	H11651485		
Engine Capacity:	1496 cc		
Power Rating:	22.0 kW		
Maximum Power Output:	101.0 kW (135 bhp)		
Maximum Laden Weight:	1335 kg		
Unladen Weight:	1080 kg		
Year Of Manufacture:	2018		
Original Registration Date:	30 Aug 2018		
Lifespan Expiry Date:	-		
COE Category:	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium:	\$32,429.00		
COE Expiry Date:	29 Aug 2028		
Road Tax Expiry Date:	29 Aug 2019		
PARF Eligibility Expiry Date:	29 Aug 2028		
Inspection Due Date:	29 Aug 2019		
Intended Transfer Date:	24 May 2019		
CO2 Emission:	82.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$10,000.00		
CO Emission:	0.046000 (g/km)		
HC Emission:	0.014000 (g/km)		
NOx Emission:	0.004000 (g/km)		
PM Emission:	0.300000 (mg/km)		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST	GST Amount	Amount After GST
	(S\$)	(S\$)	(S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 May 2019 Edit Reg		24 May 2019 00:00 Edit Adj Rpt	S\$4,073.44 Edit Estimates	S\$4,073.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: HORME HARDWARE PTE LTD , Co. Reg. No.: 201226640D									
Main Claimant: SONG KONG BENG , ID: S11301008									
Vehicle Reg. No.:	SGA1188Y	Date of Loss:	24/05/2019 00:00 - :59 [8 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4768220174SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	GBF6097B	Policy No. (Claimant):	S10345606SDC						
Excess:									
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGA1188Y (4768220174SG)**
[GBF6097B]
TP
SONG KONG BENG
May 24 2019 12:00AM
[HORME HARDWARE PTE LTD]
Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Documentation										1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	27/05/19 12:01	ACKNOWLEDGEMENT EMAIL TO AIG DD 24.05.2019							Load PDF		
2	27/05/19 12:01	EMAIL FROM AIG DD 24.05.2019							Load PDF		
3	27/05/19 13:19	TP GIA REPORT							Load PDF		
4	27/05/19 19:50	TP ESTIMATE - MARKED							Load PDF		
5	18/03/20 09:14	WORKSHOP INVOICE							Load PDF		
6	18/03/20 09:14	AUTHORISATION TO ACT FORM							Load PDF		
7	18/03/20 09:14	Release Voucher							Load PDF		
8	18/03/20 09:14	LTA SEARCH							Load PDF		
9	18/03/20 09:14	LOD							Load PDF		
10	18/03/20 09:14	LETTER TO OI							Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	28/05/19 12:48	OI GIA REPORT							Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBF6097B (Insd veh)	Model:	HONDA FIT 1.5 HYBRID (A)
	SGA1188Y (TP veh)		
Date of Accident:	24/05/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	5,475.40	
Final Repair Cost	:	\$	4,358.58	
Loss of Use	:	\$	600.00	6.00 days at \$100.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	8.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	4,966.58	

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/~~No~~—BOLA Scenario No: 27

BOLA Liability: 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Cheng Hoe Motor Pte Ltd	\$ 4,966.58
2)		\$
3)		\$

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

18 Mar
2020
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009248/KDA3Q2
Date: 18/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant
Vehicle No : SGA1188Y **Insured Vehicle No :** GBF6097B
Date of Loss: 24/05/2019 **Nature of Claim:** TP **Claim No:** 4768220174SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGA1188Y**
 Make & Model: HONDA FIT, 1.5 HYBRID (A) Engine No: LEB6070466
 Reg. Date: 30/08/2018 (Man. Year: 2018) Chassis No: GP53415782
 Colour: Metallic Pink Odometer: 24994 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,487.20	2,773.44	713.76	20.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,300.00	330.00	20.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,117.20	4,073.44	1,043.76	20.40
+ GST 7.00/7.00% (S\$)	358.20	285.14	73.06	20.40
Nett Amount (S\$)	5,475.40	4,358.58	1,116.82	20.40
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,966.58		

INSPECTION

Date of Assignment: 24/05/2019
 Date Inspected: 24/05/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	652.70 FL	*652.70 FL
2	5		*REAR BUMPER CLIP	Necessary	19.50 FL	*19.50 FL
3	1		*REAR TAILGATE	Bent	880.40 FL	*880.40 FL
4	1		*TAILGATE INNER RUBBER	Cut	92.30 FL	*92.30 FL
5	1		*TAILGATE EMBLEM FIT	Necessary	35.00 FL	*35.00 FL
6	1		*TAILGATE INNER LOCK	Repair	157.50 FL	*- FL
7	1		*TAILGATE EMBLEM HYBRID	Necessary	75.50 FL	*75.50 FL
8	1		*TAILGATE OUTER CHROME MOULDING	Serviceable	256.60 FL	*- FL
9	1		*TAILGATE WINDSCREEN GLASS	Shattered	1,050.60 FL	*1,050.60 FL
10	1		*SET TAILGATE WINDSCREEN GLASS MOULDING	Necessary	135.80 FL	*135.80 FL
11	1		*REAR END PANEL	Repair	390.60 FL	*- FL
12	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS
13	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
14	1		*REAR WINDSCREEN GLASS TINTED FILM	Necessary	250.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,236.50	3,361.80
- List Item Discount on L Items 20.00/20.00% (S\$)	749.30	588.36
Total Parts (S\$)	3,487.20	2,773.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REVERSE CAMERA RESET & REPOSITION	New	50.00	50.00
3	REMOVE & REFIX REAR BUMPER ,TAILLAMP ,TAILGATE & ATTACHMENTS TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR FENDER & REALIGN THE SAME	New	700.00	500.00
4	PUTTY & RESPRAY REAR BUMPER ,TAILGATE & SPOILER ,REAR END PANEL ,REAR FENDERS & ALL AFFECTED AREAS	New	700.00	600.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (S\$)			1,630.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >