

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000
 ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG/AMK
 Claim Type: Third Party
 Accident Date: 24/05/2019
 TP Veh Reg No: GBF6097B

Estimate No: ES1991547/AMK

Date: 24 May 2019

Policy No: 5103456065 DC

Veh Reg No: **SGA1188Y**

Make/Model: HONDA FIT 1.5 A
 HYBRID

Chassis No: GP53415782

Engine No: LEB6070466

Reg. Date: 30/08/2018

Not Authored
Resurvey By paint

Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	<i>Bu</i> 652.70	1 PC	652.70	✓
2 REAR BUMPER CLIP	<i>nu</i> 3.90	5 PC	19.50	✓
3 REAR TAILGATE	880.40	1 PC	<i>Bu</i> 880.40	✓
4 TAILGATE INNER RUBBER	92.30	1 PC	92.30	?
5 TAILGATE INNER LOCK	157.50	1 PC	157.50	?
6 TAILGATE EMBLEM 'FIT'	35.00	1 PC	<i>nu</i> 35.00	-
7 TAILGATE EMBLEM 'HYBRID'	75.50	1 PC	<i>nu</i> 75.50	-
8 TAILGATE OUTER CHROME MOULDING	256.60	1 PC	256.60	?
9 TAILGATE WINDSCREEN GLASS	<i>Shattered</i> 1,050.60	1 PC	1,050.60	✓
10 TAILGATE WINDSCREEN GLASS MOULDING	135.80	1 SET	<i>nu</i> 135.80	-
11 REAR END PANEL	390.60	1 PC	390.60	?
			3,746.50	
		Less 20%	749.30	2,997.20
Special Net				
12 REVERSE SENSOR	200.00	1 SET	<i>nd</i> 200.00	✓
13 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>nu</i> 40.00	✓
14 REAR WINDSCREEN GLASS TINTED FILM	250.00	1 PC	<i>nu</i> 250.00	<i>1800</i>
			490.00	490.00
Labour				
15 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
16 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
17 REMOVE & REFIX REAR BUMPER, TAILLAMP, TAILGATE & ATTACHMENTS; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	700.00	1 LA	700.00	?
18 PUTTY & RESPRAY REAR BUMPER, TAILGATE & SPOILER, REAR END PANEL, REAR FENDERS & ALL AFFECTED AREAS	700.00	1 LA	700.00	<i>600</i>
19 RUSTPROOFING		1 LA	60.00	?
			1,630.00	1,630.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO.201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 24/05/2019
TP Veh Reg No: GBF6097B

Estimate No: ES1991547/AMK
Date: 24 May 2019
Policy No: 5103456065 DC
Veh Reg No: SGA1188Y
Make/Model: HONDA FIT 1.5 A
HYBRID
Chassis No: GP53415782
Engine No: LEB6070466
Reg. Date: 30/08/2018

Estimate Repair Cost to Vehicle No :SGA1188Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 5,117.20
			Add GST @ 7%	358.20
			Total Amount Payable	<u>S\$ 5,475.40</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE