

ASS. REC. BY:

REF: CS/CTI14009253/Rqd3n2

Special Instruction:

Surveyor: \_\_\_\_\_

**ASSIGNMENT (Office)**

From (Person): Chong Boon Sen of CTI Date/Time: 27/5/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS7722L Insured: GBJ 2061J

at Workshop m/s: Auto Checks Tel: 9192 8963

of No. 1 Bukit Batok Crescent #02-HO WCE BA Plaza

Policy No: DMCVSN19039719000 Claim No: SNM190002367

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 24/5/19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 27/5 Person Contacted: Louis Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	GBJ 2061J - X	
	SLS 7722L - X	
04/6/19 @	10.27am loan finalised with Louis final fig \$1291.81, 2 days. Chrg. \$10815.19, 89% @	



## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 27 May 2019 9:43 AM  
**To:** louisongautowheels@yahoo.com  
**Cc:** assignments  
**Subject:** RE: OUR REF: SNM19D202367 / ACCIDENT INVOLVED WITH VEHICLE SKS7722L AND GBJ2061J (TP) ON 24.5.19 ALONG SERANGOON NORTH AVE TURNING RIGHT TO YIO CHU KANG

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

### **Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Louis Ong [mailto:louisongautowheels@yahoo.com]  
**Sent:** Monday, 27 May, 2019 9:32 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: OUR REF: SNM19D202367 / ACCIDENT INVOLVED WITH VEHICLE SKS7722L AND GBJ2061J (TP) ON 24.5.19 ALONG SERANGOON NORTH AVE TURNING RIGHT TO YIO CHU KANG

Hi Boonsen,

We would like LKK to conduct the survey.

Vehicle is in.

Survey at No 1 BukitBatok Crescent #02-40 WCEGA PLAZA

Meanwhile, can advise us the liability.

Thanks

Auto Wheels Motorworks PTE LTD  
Louis Ong  
91928963

On Mon, 27 May 2019 at 9:30, Chong Boon Sen  
<[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

## Chong Boon Sen

Claims Executive

Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](http://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

**Shiau Chan (LKKAuto)**

---

**From:** Rasul (LKKAuto)  
**Sent:** Tuesday, 4 June 2019 10:27 AM  
**To:** Louis Ong  
**Cc:** Shiau Chan (LKKAuto)  
**Subject:** RE: Finalize for vehicle SLS7722L part by part \$1,291.81 with 2 repair days

Hi Louis,

Finalised amount confirmed

Best Regards,

**Rasul** | Assessor

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Rasul@lkkauto.com](mailto:Rasul@lkkauto.com) | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

---

**From:** Louis Ong [<mailto:louisongautowheels@yahoo.com>]  
**Sent:** Friday, 31 May, 2019 8:56 AM  
**To:** Rasul (LKKAuto)  
**Cc:** SUR  
**Subject:** Finalize for vehicle SLS7722L part by part \$1,291.81 with 2 repair days

Hi Rasul,

The above attachment is the after paint and finalize.

Can help to finalize for vehicle SLS7722L part by part \$1,291.81 with 2 repair days.

No Supplementary.

Thanks

Auto Wheels Motorworks PTE LTD  
Louis Ong  
91928963



Address BLK 603A PUNGGOL ROAD #05-10  
 Postcode 821603  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: TEO HOCK LYE  
 GENDER: MALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

KINDLY REFER TO SKETCH PLAN.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GBJ2061J  
 Vehicle Make/Model/Colour TOYOTA  
 Details Of Properties PRIVATE CAR  
 Vehicle Category ANAND RAJ S/O KANAN  
 Name of Driver S9537814E  
 NRIC/Passport Number 94249643  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)


SKETCH PLAN

IMPORTANT NOTICE

1. Please report immediately the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may show insurer's willingness to repeal policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (as insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurer, lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of
  - (i) processing, handling and for dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

  
 Policyholder's Signature  
 Date & Time: 24/5

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC / ID No:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling on Simpson St and stopped at cross junction road. C/S 722L came from back on my vehicle back.

Important:

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE within the stipulated time frame from the day of the occurrence.

<input type="checkbox"/>	Reporting Only
<input type="checkbox"/>	Claim OD
<input type="checkbox"/>	Claim TP
<input checked="" type="checkbox"/>	Claim <del>OD</del> TP at other workshop

DECLARATION

I/WE declare the foregoing particulars are true in every respect.

*[Signature]*  
 Policyholder's signature  
 Date & Time 24/5

\_\_\_\_\_  
 Driver's Signature  
 (If driver not the policyholder)  
 Date & Time

*[Signature]*  
 Reporting Centre Personnel's Signature  
 Name:  
 Nric/Fin No.

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

NO: 7-40 SIMANGIONE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 25/05/2019  
 VEHICLE NO: SLS7722L  
 MODEL: MERCEDES CLA180  
 YEAR:  
 ACCIDENT DATE: 24/05/2019  
 TYPE OF CLAIM: TP  
 CLAIM ADVISOR: LOUIS (91928963)  
 Email: louisongautowheels@yahoo.com

## ESTIMATE

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID X	1	\$ X 1,823.10
BOOTLID CHROME MOULDING X	1	\$ X 345.10
REAR EMBLEM X	1	\$ X 96.50
REAR LOGO - CLA X	1	\$ X 65.20
REAR LOGO - 180 X	1	\$ X 67.20
REAR BUMPER repair	1	\$ X 1,575.30
REAR BUMPER CLIPS	10	\$ X 50.00
REAR BUMPER RETAINER X	2	\$ X 244.60
REAR BUMPER BRACKET X	2	\$ X 166.40
REAR BUMPER DIFFUSER	1	\$ 635.20
REAR BUMPER DIFFUSER CHROME LINING ?	1	\$ 355.70 grazed
REAR REINFORCEMENT ?	1	\$ X 655.30
END PANEL	1	REPAIR
REVERSE SENSOR X	4	\$ X 1,028.80
REVERSE SENSOR HOLDER X	4	\$ X 224.80
REAR EXHAUST PIPE FINISHER X	2	\$ X 634.20
TAILLAMP X	2	\$ X 1,998.40
REAR SMART BOOTLID SENSOR X	1	\$ X 564.20

TOTAL: \$ 10,530.00  
 DISCOUNT 10%: \$ 1,053.00  
\$ 9,477.00

990.9  
 10%  
891.81

S/NET  
 REAR NUMBER PLATE

PRICE  
 X \$ 40.00 X

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 25/05/2019  
 VEHICLE NO: SLS7722L  
 MODEL: MERCEDES CLA180  
 YEAR:  
 ACCIDENT DATE: 24/05/2019  
 TYPE OF CLAIM: TP  
 CLAIM ADVISOR: LOUIS (91928963)  
 Email: louis@autowheels@yahoo.com

## ESTIMATE

### LABOUR

- LABOUR FOR FACILITATE REPAIR - REAR PORTION
- TO RESPRAY AFFECTED AREAS - BOOTLID
- TO RESPRAY AFFECTED AREAS - REAR BUMPER
- TO RESPRAY AFFECTED AREAS - END PANEL
- TO CHECK AND RECONNECT ALL NECESSARY WIRING
- TO REMOVE AND REFIT REAR TRIMMING FOR FACILITATE REPAIR
- TO REMOVE AND REFIT REVERSE SENSOR
- TO RESET AND DIAGNOSE TO ORIGINAL SETTING
- SUNDARIES
- RUST PROOFING

### PRICE

\$	<del>1,000.00</del> 200	
\$	300.00 X	
\$	<del>300.00</del> 200	
\$	300.00 X	
\$	100.00 X	
\$	150.00 X	
\$	<del>150.00</del> X	400
\$	150.00 X	
\$	60.00 X	
\$	80.00 X	

TOTAL: \$ 2,590.00 Total: \$1,291.81

TOTAL: \$ 12,107.00  
 7% GST: \$ 847.49  
 \$ 12,954.49

2 days

I, the undersigned hereby notify the Repairer of the following:

- To estimate the cost of repairing
- To estimate the cost of parts to be replaced
- To estimate the cost of labour
- To estimate the cost of paint
- To estimate the cost of rust proofing
- To estimate the cost of sundaries
- To estimate the cost of transport

Accepted and by Repairer:

RASW

Hp 90010068

2 days

P/P

29/05/19 @ 1030

Resay the new rear bumper diffuser

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 25/05/2019  
 VEHICLE NO: SLS7722L  
 MODEL: MERCEDES CLA180  
 YEAR:  
 ACCIDENT DATE: 24/05/2019  
 TYPE OF CLAIM: TP  
 CLAIM ADVISOR: LOUIS (91928963)  
 Email: louisongautowheels@yahoo.com

## ESTIMATE

DESCRIPTION	QTY	LIST PRICE
<b>PARTS</b>		
BOOTLID X	1	\$ 1,823.10
BOOTLID CHROME MOULDING X	1	\$ 345.10
REAR EMBLEM X	1	\$ 96.50
REAR LOGO - CLA X	1	\$ 65.20
REAR LOGO - 180 X	1	\$ 67.20
REAR BUMPER repair	1	\$ 1,575.30
REAR BUMPER CLIPS AM-XAN	10	\$ 50.00 X
REAR BUMPER RETAINER X } AN	2	\$ 244.60
REAR BUMPER BRACKET X } AN	2	\$ 166.40
REAR BUMPER DIFFUSER SEA-	1	\$ 635.20 ✓
REAR BUMPER DIFFUSER CHROME LINING ? SEA-	1	\$ 355.70 ✓
REAR REINFORCEMENT ? XVC	1	\$ 655.30 X
<b>END PANEL</b>		<b>REPAIR</b>
REVERSE SENSOR X	4	\$ 1,028.80
REVERSE SENSOR HOLDER X	4	\$ 224.80
REAR EXHAUST PIPE FINISHER X	2	\$ 634.20
TAILLAMP X	2	\$ 1,998.40
REAR SMART BOOTLID SENSOR X	1	\$ 564.20

TOTAL: \$ 10,530.00  
 DISCOUNT 10%: \$ 1,053.00  
\$ 9,477.00

S/NET

REAR NUMBER PLATE

PRICE

\$ 40.00 X SEA

# AUTO WHEELS

MOTORWORKS PTE LTD

NO 1 BUKIT BATOK CRESCENT WCEGA PLAZA

#02-40 SINGAPORE 658064

ATTN: CHINA TAIPING INSURANCE

DATE: 25/05/2019  
 VEHICLE NO: SLS7722L  
 MODEL: MERCEDES CLA180  
 YEAR:  
 ACCIDENT DATE: 24/05/2019  
 TYPE OF CLAIM: TP  
 CLAIM ADVISOR: LOUIS (91928963)  
 Email: louisongautowheels@yahoo.com

## ESTIMATE

### LABOUR

LABOUR FOR FACILITATE REPAIR - REAR PORTION  
 TO RESPRAY AFFECTED AREAS - BOOTLID  
 TO RESPRAY AFFECTED AREAS - REAR BUMPER  
 TO RESPRAY AFFECTED AREAS - END PANEL  
 TO CHECK AND RECONNECT ALL NECESSARY WIRING  
 TO REMOVE AND REFIT REAR TRIMMING FOR FACILITATE REPAIR  
 TO REMOVE AND REFIT REVERSE SENSOR  
 TO RESET AND DIAGNOSE TO ORIGINAL SETTING  
 SUNDARIES  
 RUST PROOFING

### PRICE

\$	1,000.00	200
\$	300.00	X 17
\$	300.00	200
\$	300.00	X 7
\$	100.00	X 7
\$	150.00	X 7
\$	150.00	X 17
\$	150.00	X 7
\$	60.00	X 7
\$	80.00	X 7

TOTAL: \$ 2,590.00

TOTAL: \$ 12,107.00

7% GST: \$ 847.49

\$ 12,954.49

*[Handwritten signature]*  
30/5/19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature:

Date:

Rasul

Hp 90010068

2-3 days

P/P

29/05/19 @ 1030

Resey the new rear bumper diffuser

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009253/R1QD3N2  
Date: 18/06/2019

#### REFERENCE

Handling	China Taiping Insurance	Policy No:	DMCVSN19039719000
Insurer:	(Singapore) Pte. Ltd.	Insured	GBJ2061J
Claimant	SLS7722L	Vehicle No :	
Vehicle No :		Nature of	TP
Date of Loss:	24/05/2019	Claim	SNM19D202367C02
		No:	

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS7722L	Engine No:	27091031472673
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (A)	Chassis No:	WDD1179422N593211
Reg. Date:	28/11/2017 (Man. Year: 2017)	Odometer:	11748 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car	N/A		
Price:			
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,577.00	891.81	8,685.19	90.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	400.00	2,130.00	84.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>12,107.00</b>	<b>1,291.81</b>	<b>10,815.19</b>	<b>89.33</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>847.49</b>	<b>90.43</b>	<b>757.06</b>	<b>89.33</b>
<b>Nett Amount (S\$)</b>	<b>12,954.49</b>	<b>1,382.24</b>	<b>11,572.25</b>	<b>89.33</b>

#### INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	29/05/2019 Inspected At:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA Singapore 658064
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2019)
Parts: 143	MERCEDES-BENZ CLA180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLS7722L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,823.10 FL	*- FL
2	1		*BOOTLID CHROME MOULDING	Not Necessary	345.10 FL	*- FL
3	1		*REAR EMBLEM	Not Necessary	96.50 FL	*- FL
4	1		*REAR LOGO-CLA	Not Necessary	65.20 FL	*- FL
5	1		*REAR LOGO-180	Not Necessary	67.20 FL	*- FL
6	1		*REAR BUMPER	Repair	1,575.30 FL	*- FL
7	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
8	2		*REAR BUMPER RETAINER	Not Necessary	244.60 FL	*- FL
9	2		*REAR BUMPER BRACKET	Not Necessary	166.40 FL	*- FL
10	1		*REAR BUMPER DIFFUSER	Scratched	635.20 FL	*635.20 FL
11	1		*REAR BUMPER DIFFUSER CHROME LINING	Scratched	355.70 FL	*355.70 FL
12	1		*REAR REINFORCEMENT	Serviceable	655.30 FL	*- FL
13	1		*END PANEL (NPA)	Repair	0.00 FL	*- FL
14	4		*REVERSE SENSOR	Not Necessary	1,028.80 FL	*- FL
15	4		*REVERSE SENSOR HOLDER	Not Necessary	224.80 FL	*- FL
16	2		*REAR EXHAUST PIPE FINISHER	Not Necessary	634.20 FL	*- FL
17	2		*TAILLAMP	Not Necessary	1,998.40 FL	*- FL
18	1		*REAR SMART BOOTLID SENSOR	Not Necessary	564.20 FL	*- FL
19	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
20	1		*SUNDARIES	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,630.00</b>	<b>990.90</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,053.00	99.09
<b>Total Parts (\$\$)</b>	<b>9,577.00</b>	<b>891.81</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR FACILITATE REPAIR-REAR PORTION	New	1,000.00	200.00
2	TO RESPRAY AFFECTED AREAS-BOOTLID	New	300.00	0.00
3	TO RESPRAY AFFECTED AREAS-REAR BUMPER	New	300.00	200.00
4	TO RESPRAY AFFECTED AREAS-END PANEL	New	300.00	0.00
5	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	100.00	0.00
6	TO REMOVE AND REFIT REAR TRIMING FOR FACILITATE REPAIR	New	150.00	0.00
7	TO REMOVE AND REFIT REVERSE SENSOR	New	150.00	0.00
8	TO RESET AND DIAGNOSE TO ORIGINAL SETTING	New	150.00	0.00
9	RUST PROOFING	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,530.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >