

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Kh

Not Authorized

Resurvey B4 paint

8 days

11 Day @ 9250/r

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 24.05.2019

Accident Date : 22.05.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Citroen C4" Reg. No. SLR7872S Claiming Against Your Insured Reg. No. GBD2830M			
1pc	Rear Door LH <i>1361.00</i>		Ry 1,680.00 ✓
1pc	Rear Door Outer Handle <i>318.00</i>		Red 420.00 ✓
1pc	Rear Door Outer Handle Ganish		Sw 150.00 X
1pc	Rear Door Outer Handle Side Cover		Red 110.00 ✓
1pc	Rear Door Outer Handle Side Cover Ganish		Sw 120.00 X
1pc	Rear Door Inner Lock		Red 380.00 ✓
1pc	Rear Door Weatherstrip		Com 138.00 ✓
1pc	Rear Door Trim Board <i>968.00</i>		MJUM 1,120.00 ✓
10pcs	Rear Door Trim Board Clips	10.00	M 100.00 ✓
1pc	Rear Door Glass Outer Moulding		Red 198.00 ✓
1pc	Rear Door Glass Regulator <i>305</i>		Ry 430.00 ✓
1pc	Rear Door Glass Motor		Sw 410.00 ✓
1pc	Rear Door Sticker		M 160.00 ✓
1pc	Rear Door Outer Handle Base Bracket		CM 185.00 ✓
1pc	Rear Fender <i>1320</i>		Ry 1,780.00 ✓
1pc	Rear Fender Glass Moulding		M 180.00 ✓
1pc	Rear Fender Inner Panel		R 480.00 X
1pc	Rear Fender Shield		Diy 136.00 ✓
6pcs	Rear Fender Shield Clips	10.00	M 60.00 ✓
1pc	Rear Bumper <i>858.00</i>		CM 890.00 ✓
10pcs	Rear Bumper Clips	10.00	M 100.00 ✓
1pc	Rear Wheel Bearing		M 220.00 ✓
1pc	Rear Shock Absorber		Ry 210.00 ✓
1pc	Rear Axle Beam		R 1,550.00 ✓
	Less 10%		11,207.00
			1,120.70
			10,086.30
1pc	Rear Fender Glass Sealant		M 50.00 SN
1pc	Rear Fender Glass Fastener		30SN 50.00 SN
1pc	Rear Wheel Rim LH <i>571.00</i>		Red 980.00 SN ✓
	To Conduct Rear Electrical Check		30.00 201
	To Dismantle / Transfer <i>Door</i> Boot Fittings and Accessories		150.00 601
	To Dismantle / Refit Roof Lining		150.00 1001
	To Dismantle / Refit Rear Fender Glass		90.00 601
			11,586.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

C/F

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

 Accident Date : 22.05.2019

Policy No: Third Party

 Date: 24.05.2019

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
 代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Citroen C4" Reg. No. SLR7872S Claiming Against Your Insured Reg. No. GBD2830M		
		B/F	11,586.30
	To Dismantle / Refit Trunk Compartment Board, Trims etc		100.00 <i>501</i>
	To Apply Rust Proofing / Reseal Tuff Coating		100.00 <i>601</i>
	To Dismantle / Replace Front ^{Rear} Under Carriage to Facilitate Repair		280.00 <i>2001</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>601</i>
	To reseal N/S Rocker Panel Chip Resistant Primer		100.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Front N/S Door, Pillar, Rocker Panel, Floor Panel, Rear Wheel Housing etc. Cnt, Weld Rear Fender and Parts Replacement		1,500.00 <i>9001</i>
	To Respray Affected Areas		<i>10001</i>
		Total :	<u>1,200.00</u> <u>14,946.30</u>