

# 趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

*Not Authorized  
Resurvey B&P paint  
8 days*

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: \_\_\_\_\_ Third Party

Date: 24.05.2019

Accident Date : 22.05.2019

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
<b>Estimate Cost Of Repair To "Citroen C4" Reg. No. SLR7872S Claiming Against Your Insured Reg. No. GBD2830M</b>			
1pc	Rear Door LH		<i>Ry</i> 1,680.00 ✓
1pc	Rear Door Outer Handle		<i>nd</i> 420.00 ✓
1pc	Rear Door Outer Handle Ganish		150.00 ?
1pc	Rear Door Outer Handle Side Cover		<i>nd</i> 110.00 ✓
1pc	Rear Door Outer Handle Side Cover Ganish		120.00 ?
1pc	Rear Door Inner Lock		<i>nd</i> 380.00 ✓
1pc	Rear Door Weatherstrip		<i>nd</i> 138.00 ✓
1pc	Rear Door Trim Board		1,120.00 ?
10pcs	Rear Door Trim Board Clips	10.00	100.00 ?
1pc	Rear Door Glass Outer Moulding		<i>nd</i> 198.00 ✓
1pc	Rear Door Glass Regulator		430.00 ?
1pc	Rear Door Glass Motor		410.00 ?
1pc	Rear Door Sticker		<i>nd</i> 160.00 ✓
1pc	Rear Door Outer Handle Base Bracket		185.00 ?
1pc	Rear Fender		<i>Ry</i> 1,780.00 ✓
1pc	Rear Fender Glass Moulding		<i>nd</i> 180.00 ✓
1pc	Rear Fender Inner Panel		<i>n</i> 480.00 X
1pc	Rear Fender Shield		136.00 ?
6pcs	Rear Fender Shield Clips	10.00	60.00 ?
1pc	Rear Bumper		<i>cm</i> 890.00 ✓
10pcs	Rear Bumper Clips	10.00	<i>nd</i> 100.00 ✓
1pc	Rear Wheel Bearing		220.00 ?
1pc	Rear Shock Absorber		210.00 ?
1pc	Rear Axle Beam		1,550.00 ?
	Less 10%		11,207.00
			1,120.70
			10,086.30
1pc	Rear Fender Glass Sealant		<i>nd</i> 50.00 SN
1pc	Rear Fender Glass Fastener		<i>30sn</i> 50.00 SN
1pc	Rear Wheel Rim LH		<i>nd</i> 980.00 SN ✓
	To Conduct Rear Electrical Check		30.00 <i>20l</i>
	To Dismantle / Transfer <i>Door</i> <del>Boot</del> Fittings and Accessories		150.00 <i>60l</i>
	To Dismantle / Refit Roof Lining		150.00 <i>100l</i>
	To Dismantle / Refit Rear Fender Glass		90.00 <i>60l</i>
			11,586.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_ C/F

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 24.05.2019

Accident Date : 22.05.2019

Specialised in Car Painting, Welding,  
 Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
 代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Citroen C4" Reg. No. SLR7872S Claiming Against Your Insured Reg. No. GBD2830M		
		B/F	11,586.30
	To Dismantle / Refit Trunk Compartment Board, Trims etc		100.00 <i>501</i>
	To Apply Rust Proofing / Reseal Tuff Coating		100.00 <i>601</i>
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		280.00 <i>?</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>601</i>
	To reseal N/S Rocker Panel Chip Resistant Primer		100.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Front N/S Door, Pillar, Rocker Panel, Floor Panel, Rear Wheel Housing etc. Cnt, Weld Rear Fender and Parts Replacement		1,500.00 <i>9001</i>
	To Respray Affected Areas		<i>10001</i>
		Total :	<u>1,200.00</u> <u>14,946.30</u>