

22/03/2012

ASS. REC. BY:

REF: CS/CTI19009258/Rlg d3

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person): Elaine chong

of

CTI

Date/Time: 24.5.2019 18.03 p.m

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 76K

Insured:

PC 51994

at Workshop m/s

charn's Customcraft

Tel:

62717054

of Block 1010 Bukit nriah Lane 3 # 01-105

Policy No: DMBLSN/6164319033

Claim No: SNM190702290102

Sum Insured:

Excess:

Make of Veh:

D.O.A 20.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 24.5.2019 9.50 a.m

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SJJ 76K - CC31AIG 7023265/Klub 392

D.O.A - 03/12/2017

PC 51994 - X

18/7/19 @ 5.11pm Email final fig \$650 (Red \$260, 29.1%)

ASSIGNMENTFrom: _____ Date: 3.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJJ 76Kat Workshop m/s Charm's Customcraft
of Blt 1010 Bukit Merah Lane 3 #01-105

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 12.00 p.m - 2.00 p.m Owner waiting

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJJ 76K Yr Regn: 2017 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MAZDA 6 2.5L C.C. 2488Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 34669 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Jm69L103100102612Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R19R: 1BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 20/05/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 JUL 2019

[Signature]
19/7/2019

Date/Time, File Pass to?

☐ : Preli. Report1) 20/7/2019☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format : MEMOLump Sum / I.B.I: (\$ 650)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 May 2019		24 May 2019 18:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	CHEW TIAN TRANSPORT SERVICES, Co. Reg. No.: 53003736W								
Main Claimant:	JONAH KEN TAN CHOON KHENG, ID: S70111201								
Vehicle Reg. No.:	SJJ76K	Date of Loss:	20/05/2019 13:00 - :59 [24 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202290C02	Policy/Cover Note No.:	DMB1SN16164319033 (Third Party Only)						
Vehicle Reg. No. (Insured):	PC5199Y	Policy No. (Claimant):	MT/00463636/01						
		Excess:	S\$1,000.00						
Repairer:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/06/2019]								
Driver/Custodian (Insured):	GAN LAI HOCK (60 / Male) , NRIC: S12863953 Email:								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Charn's Customcraft <charns@singnet.com.sg>
Sent: Thursday, 18 July 2019 6:10 PM
To: Rasul (LKKAUTO)
Subject: RE: Accd Invlg: SJJ 76 K & PC 5199 Y on 20.05.2019 - China Ref: SNM19D202290/C02/9

Importance: High
Sensitivity: Confidential

Thank you Rasul

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Thursday, 18 July, 2019 5:11 PM
To: Charn's Customcraft
Subject: RE: Accd Invlg: SJJ 76 K & PC 5199 Y on 20.05.2019 - China Ref: SNM19D202290/C02/9
Sensitivity: Confidential

Hi Sharon,

Finalised amount confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Charn's Customcraft [mailto:charns@singnet.com.sg]
Sent: Wednesday, 17 July, 2019 6:26 PM
To: Rasul (LKKAUTO)
Cc: Bryan Ang (LKKAUTO); SUR
Subject: RE: Accd Invlg: SJJ 76 K & PC 5199 Y on 20.05.2019 - China Ref: SNM19D202290/C02/9
Importance: High
Sensitivity: Confidential

Hi Rasul

Noted with thanks.

Please finalize this case.

Labour only \$650 (before GST).

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L
Company Reg No: 25151300M

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, 8 July, 2019 10:22 AM
To: Charn's Customcraft
Cc: Bryan Ang (LKKAUTO); SUR
Subject: RE: Accd Invl: SJJ 76 K & PC 5199 Y on 20.05.2019 - China Ref: SNM19D202290/C02/9
Sensitivity: Confidential

Hi Sharon,

Damages was on the LH side portion rear portion. Rear boot is not due to accident and moreover is inconsistent to accident

The LH rear door is unlikely affected coz the damages is more nearer to the rear bumper side portion


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Charn's Customcraft [<mailto:charns@singnet.com.sg>]
Sent: Thursday, 27 June, 2019 5:07 PM
To: Rasul (LKKAUTO)
Cc: Bryan Ang (LKKAUTO); SUR
Subject: FW: Accd Invl: SJJ 76 K & PC 5199 Y on 20.05.2019 - China Ref: SNM19D202290/C02/9
Sensitivity: Confidential

Hi Rasul

You had surveyed this vehicle on 03.06.2019.

Client claimed that rear LH door and rear boot was related to the accident.

Please let us have your view.

Thanks & Regards,
Sharon Lee
Charn's Customcraft
Tel: 6272 5429 Fax: 6273 6676
Email: charns@singnet.com.sg
GST Reg. No: M90367863L

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	11201
Vehicle Details	
Vehicle No.:	SJJ76K
Vehicle to be Exported:	No
Intended Deregistration Date:	21 May 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 WAGON 2.5L SP.6EAT SR
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	PY20833982
Chassis No.:	JM6GL103100102612
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$28,678.00
Original Registration Date:	26 Apr 2017
First Registration Date:	26 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$32,150.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2027
PARF Rebate Amount:	\$24,112.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,501.00
COE Rebate Amount:	\$42,809.00
Total Rebate Amount:	\$66,921.00

The information contained herein is correct as at 21 May 2019

OK



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

DA/CHINA TAIPING(PC5199Y)

DOA: 20/05/2019@1345

CHINA TAIPING INSURANCE (S) PTE LTD

24/5/2019

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SJJ 76 K - MAZDA 6 WAGON 2.5L SP.6EAT SR

CHASSIS NO: JM6GL103100102612 (04/2017)

Alignment

\$ 60.00 X^{ny}

Repair and respray rear rim LH.

\$ 100.00 X^{ny}

Jacking, panel beating, repair and straighten rear fender and rear bumper.

\$ ~~300.00~~ 250
\$ ~~450.00~~ 400 } 650

Putty and respray rear fender LH and rear bumper.

\$ 910.00
\$ 63.70
\$ 973.70

ADD 7% GST

Note: The above is an estimate only. IF other parts required during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
6/6/19
Rashid
Hp 90610068
3 days
P/P
03/06/19 @ 1230
Resurvey after repair

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009258/R1QD3N2

Date: 22/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN16164319033	
Claimant Vehicle No :	SJJ76K	Insured Vehicle No :	PC5199Y	
Date of Loss:	20/05/2019	Nature of Claim:	TP	Claim No: SNM19D202290C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJJ76K	Engine No:	PY20833982
Make & Model:	MAZDA 6, 2.5 L WAGON SR (A)	Chassis No:	JM6GL103100102612
Reg. Date:	26/04/2017 (Man. Year: 2016)	Odometer:	34669 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R19	Rear Tyre Size:	225/45 R19
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	650.00	260.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	910.00	650.00	260.00	28.57
+ GST 7.00/7.00% (\$\$)	63.70	45.50	18.20	28.57
Nett Amount (\$\$)	973.70	695.50	278.20	28.57

INSPECTION

Date of Assignment:	24/05/2019	
Date Inspected:	03/06/2019	Inspected At:
		Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105 Singapore 159724
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jul 2019)
Parts:	143	MAZDA 6 2.5 L WAGON SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ76K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ALIGNMENT.	New	60.00	0.00
2	REPAIR AND RESPRAY REAR RIM LH.	New	100.00	0.00
3	JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR FENDER AND REAR BUMPER.	New	300.00	250.00
4	PUTTY AND RESPRAY REAR FENDER LH AND REAR BUMPER.	New	450.00	400.00
Gross Labour Cost (S\$)			910.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >