

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0645/2019/DY/TF
Date : 21-May-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian, Rasul

You recommended 8 days,

We took 20 days - jb - 17 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ong Eu-Wen
Address : 27 Adam Road
#02-21
Singapore 289895
Telephone : HP +65 90078967
Type of Claim : Own Damage Claims
Policy No. : 2100478823-02
Vehicle No : **SKA 5575 P**
Model Code : Audi RS 3 SportBack 2.5
Model / Year : Aug-16
Engine No : CZG014118
Chassis No : WAUZZZ8V2GA909706
Mileage : 56158
Date In : 18-May-19
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 18-May-19
Place of Accident : Chai Chee Lane Junction (THK Home-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 5575 P

S/N	Nature of Jobs			Estimated Charges		
1	To tow and recover vehicle from scene of accident.	S/N		AIG		
2	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$	360.00	\$	360.00
3	To remove and transfer aircon condenser, additional radiator, radiator, electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$	1,200.00		
4	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages. <i>(Remove/renew glass slot shield, R/l wing mirror for respray door)</i>	S/N	\$	280.00	\$	280.00
SUB-TOTAL LABOUR CHARGES		:	\$	1,840.00	\$	640.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKA 5575 P

S/N	Nature of Jobs		Estimated Charges		
		<i>c/f</i>		\$	640.00
5	To dismantle and renew front bumper, rhs headlight, rhs front fender, bonnet and rhs front door. To repair rhs A-pillar. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 7,000.00	\$	1,250.00
6	To respray front bumper, bonnet, hinges, rhs upper A-pillar, rhs front fender and rhs front door.		\$ 5,000.00	\$	2,475.00
7	To renew rhs front rim and tyre. To carry out wheel alignment. Inspect rhs front suspension for further damages.	S/N	\$ 280.00	\$	280.00
8	Added labour - see attached		\$ 1,800.00	\$	1,800.00
9	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 16,112.00	\$	6,637.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 5575 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 5,156.00	\$ 4,124.80
2	FRONT BUMPER ADHESIVE TAPE	\$ 161.00	\$ 128.80
3	FRONT BUMPER FOIL	\$ 38.00	\$ 29.84
4	FRONT BUMPER GUIDE SECTION - RH	\$ 74.00	\$ 59.20
5	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 411.00	
6	FRONT BUMPER GRILLE - RH	\$ 169.00	
7	FOAM FILLER PIECE - RH	\$ 111.00	
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
9	FRONT BUMPER SPOILER	\$ 1,444.00	
10	FRONT BUMPER AIR GUIDE - RH	\$ 37.00	
11	FRONT BUMPER LOCKING CLIP	\$ 22.00	\$ 17.28
12	FRONT BUMPER REINFORMENT BAR	\$ 1,058.00	
13	FRONT BUMPER REINFORMENT COVER	\$ 197.00	
14	FRONT BUMPER TOP COVER	\$ 168.00	
15	FRONT FENDER - RH	\$ 2,380.00	\$ 1,904.00
16	FRONT FENDER BRACKET - RH	2 \$ 68.00	\$ 53.84
17	FRONT FENDER RIVET	\$ 24.00	\$ 19.20
18	FRONT FENDER SEAL - RH	\$ 31.00	\$ 24.40
19	FRONT FENDER BRACE - RH	\$ 88.00	\$ 69.84
20	FRONT FENDER CLOSING ELEMENT - RH	\$ 56.00	\$ 44.24
SUB-TOTAL SPARE PARTS		\$ 11,884.00	\$ 6,475.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 5575 P

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		<i>c/f</i>	\$	6,475.44
21	FRONT FENDER TOP BRACE - RH	\$ 21.00	\$	16.32
22	FRONT WHEEL HOUSING LINER - RH	\$ 313.00	\$	250.00
23	FRONT FENDER STONE CHIP GUARD - RH	\$ 42.00	\$	33.36
24	BONNET	\$ 2,501.00		
25	BONNET EDGE PROTECTION	\$ 25.00		
26	BONNET CATCH	\$ 81.00		
27	BONNET HINGE - LH / RH	\$ 112.00		
28	HEADLIGHT - RH	\$ 6,151.00		4920.8
29	HEADLIGHT POWER MODULE - DIPPED BEAM	\$ 508.00		
30	HEADLIGHT POWER MODULE - DAY DRIVE LIGHTS	\$ 520.00		
31	HEADLIGHT POWER MODULE - CORNERING LIGHT	\$ 508.00		
32	HEADLIGHT VENTILATION HOSE - RH	\$ 46.00		
33	HEADLIGHT LIFT CYLINDER - RH	\$ 181.00		
34	LOCK CARRIER	\$ 1,915.00		
35	COOLANT	\$ 84.00		
36	FRONT DOOR - RH	\$ 2,073.00		
37	FRONT DOOR OUTER SEAL - RH	\$ 146.00		
38	BONDING AGENT	\$ 45.00		
39	CLEANING SOLUTION	\$ 65.00		
40	APPLICATOR	\$ 7.00		
SUB-TOTAL SPARE PARTS		:	\$ 15,344.00	\$ 11,695.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKA 5575 P

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
		<i>c/f</i>	<i>\$ 11,695.92</i>
41	FRONT DOOR CATCH - RH	\$ 96.00	
42	ROOF CHROME MOULDING - RH	\$ 651.00	
43	FRONT DOOR WINDOW SLOT SEAL CHROME - RH	\$ 481.00	<i>\$ 384.80</i>
44	TYRE RIM	2 \$ 2,646.00	<i>\$ 2,116.80</i>
45	RUBBER VALVE	\$ 13.00	<i>\$ 9.92</i>
46	DATA PLATE FOR TYRE PRESSURE	\$ 26.00	
47	FRONT FENDER CLOSING ELEMENT - RH	\$ 30.00	
48	PLENUM CHAMBER COVER	\$ 164.00	
49	PLENUM CHAMBER SIDE COVER - RH	\$ 37.00	
50	FRONT TYRE - RH	<i>\$ 380.00</i>	<i>\$ 380.00</i>
52	SUPPLEMENTARY	<i>\$ 4,933.00</i>	<i>\$ 3,945.36</i>
53	SUNDRIES	\$ 1,000.00	<i>\$ 84.56</i>
TOTAL SPARE PARTS		\$ 37,685.00	<i>\$ 18,617.36</i>
TOTAL LABOUR CHARGES		\$ 16,112.00	<i>\$ 6,637.00</i>
GRAND TOTAL		\$ 53,797.00	<i>\$ 25,254.36</i>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0645/2019/DY/TF 11-Jun-19 Glory Tan 1 of 1 SKA 5575 P Audi RS 3 SportBack 2.5	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	Front track control arm RHS		\$ 336.00	\$ 268.80
2	Front guide joint RHS		\$ 132.00	\$ 105.20
3	Front wheel bearing housing RHS		\$ 1,355.00	\$ 1,084.40
4	Front wheel bearing assembly		\$ 1,287.00	\$ 1,029.60
5	Front suspension strut storage		\$ 114.00	\$ 91.20
6	Plain bearing		\$ 51.00	\$ 40.16
7	Gas shock absorber		\$ 1,517.00	\$ 1,213.60
8	Frnt fender, wheel liner		\$ 141.00	\$ 112.40
			\$ 4,933.00	\$ 3,945.36
<u>LABOURS</u>				
1	To remove and renew rhs front suspension.	S/N	\$ 1,800.00	\$ 1,800.00
GRAND TOTAL		:	\$ 6,733.00	\$ 5,745.36

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant