

ASS. REC. BY:

REF

A19

ASSIGNMENT

From: _____ Date: 3-6-2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 9072Kat Workshop m/s Estem Performance
of 385 Sin Ming Drive

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 11-309-M

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1-B.1 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS sup

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLT 9072K Yr Regn: 11 17Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Priu C.C. 1700Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 105602 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JD K B 3FU303575884Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD / A/Rim orTyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 8/12/18D.O.I. 3/6/19Survey held at ✓Des. of Damages: Nil / Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

(PIP \$ 3,512.99 / Red \$ 3,567.73 / 50%)

5 days + 1 PACHA RAYAN = 6 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLT 9072 K

*Not Authorised
Resurvey Repair*

Parts (a) Cost / List Price Items	<i>Finalised</i> \$ 2550.65 5,787.63
Plus/Less 25%	\$ <i>637.66</i> 1,446.91
Total of Cost / List	\$ <i>1912.99</i> 4,340.72
(b) Nett Price Items	
Less	
Total of Nett Item	
(c) Special Nett Items	
Total Parts Cost	\$ <i>1912.99</i> 4,340.72
Labour	\$ <i>1690.00</i> 2,740.00
Total	\$ 2602.99 7,080.72

1,600

3512.99 ✓

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKK

Survey conducted on

3/6/19

at

10.35am

Remarks By Surveyor

(a) The repair of this vehicle is ^{*not*} authorized / is ~~not~~ authorized until further notice.

(b) Recommended Days of Repair : *04* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess

\$

Le

(e) Signature of surveyor

Date:

3/6/19



ESTEEM PERFORMANCE PTE LTD

Bld 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6454 1221 Fax: +65-6484 7829 Website: www.esteemport.com.sg

Spare Parts

Vehicle No : SLT 9072 K
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU303575884

Submit By :
Year Manufacture : 2017
Engine No :
Cost / List

SERENGE

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$1,211.40		X
2	LH rear door hinge top	1	\$78.34		X
3	LH rear door hinge bottom	1	\$78.34		X
4	LH rear door weatherstrip	1	\$198.70		X
5	LH rear fender <i>Repair</i>	1	\$883.60		X
6	LH rear fender undershield	1	\$92.30		X
7	LH rear fender undershield clip	10	\$30.00		X
8	LH rear rim	1	\$1,555.10		X
9	LH rear tyre	1	\$350.00		X
10	Rear bumper	1	\$497.50		X
11	Rear bumper clip	10	\$40.00		X
12	Rear bumper side retainer LH	1	\$112.70		X
13	Rear bumper side retainer RH	1	\$112.70		X
14	Rear bumper lower garnish LH	1	\$149.70		X
15	Rear bumper under cover LH	1	\$187.60		X
16	Rear bumper under cover clip	4	\$14.00		X
17	LH rear hub cap	1	\$195.65		X
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Bld 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

25/10/17



ESTEEM PERFORMANCE PTE LTD

81k 5033 Ang Mo Kio, Ind Park 2 #01-25/1 258, 600538.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No : **SLT 9072 K**
Make & Model : **TOYOTA PRIUS**

Submit By : **SERENCE**
Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
3	To tuff coat. <i>nn</i>	\$150.00	30 X
4	TO Check wiring	\$50.00	20
5	To remove & refit petrol tank to assist work load. <i>nn</i>	\$150.00	60 X
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	100
8	To do wheel alignment.	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1600



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg


Repair Estimates

SLT 9072 K

Not Authorized

Resurvey Repair

Parts	(a) Cost / List Price Items	\$	5,787.63
	Plus/Less 25%	\$	1,446.91
	Total of Cost / List	\$	4,340.72
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	4,340.72
Labour		\$	2,740.00
Total		\$	7,080.72



The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 3/6/18 at 10.35am

Remarks By Surveyor

- (a) The repair of this vehicle is ^{not} authorized / ~~is not authorized~~ until further notice.
- (b) Recommended Days of Repair : 05 day(s)
- (c) Resurvey : Required / ~~Not Required~~
- (d) Excess : \$
- (e) Signature of surveyor : Le Date: 3/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLT 9072 K**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU303575884**

Submit By : **SERENCE**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$1,211.40		X
2	LH rear door hinge top	1	\$78.34		✓
3	LH rear door hinge bottom	1	\$78.34		✓
4	LH rear door weatherstrip	1	\$198.70		✓
5	LH rear fender	1	\$883.60		✓
6	LH rear fender undershield	1	\$92.30		?
7	LH rear fender undershield clip	10	\$30.00		?
8	LH rear rim	1	\$1,555.10		✓
9	LH rear tyre	1	\$350.00		X
10	Rear bumper	1	\$497.50		✓
11	Rear bumper clip	10	\$40.00		✓
12	Rear bumper side retainer LH	1	\$112.70		✓
13	Rear bumper side retainer RH	1	\$112.70		X
14	Rear bumper lower garnish LH	1	\$149.70		✓
15	Rear bumper under cover LH	1	\$187.60		X
16	Rear bumper under cover clip	4	\$14.00		X
17	LH rear hub cap	1	\$195.65		✓
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLT 9072 K** Submit By : **SERENCE**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	7001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	7001
3	To tuff coat.	\$150.00	301
4	TO Check wiring	\$50.00	201
5	To remove & refit petrol tank to assist work load.	\$150.00	601
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	201
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	1001
8	To do wheel alignment.	\$120.00	601

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

* **PRE-REPAIR INSPECTION REQUEST – SLT9072K vs SGT5915D (OI) on D.O.A.: 08/12/2018**

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur
Sent: 5/24/2019 3:45:39 PM
Attachments:  20190524142425324.pdf

Hi,

Please refer to the enclosed request from **Esteem Performance Pte Ltd**.

Claim no : 0948938149SG003

Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thanks & Regards,

Hor Yinnul (Viviane)

AIG

Claim Adjuster II, Singapore FNOL Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

From: serence cte [mailto:serence@esteemperf.com.sg]

Sent: Friday, May 24, 2019 2:25 PM

To: AIG SGP, Claims-Survey

Cc: Carmen Lim; jenny chong

Subject: [EXTERNAL] REQUEST FOR PRI SURVEY SLT9072K

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Grab Rentals PTE LTD who has appointed the under-mentioned workshop to repair his motor vehicle no.SLT 9072 K.

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : 385, Sin Ming Drive (Inside Vicom) S 575718

Tel : 6566 2112 / 8799 0066

Fax : 6259 3326

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

We are prefer LKK Auto Kenneth to survey car.

Thanks

Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6566 2112

E: serence@esteemperf.com.sg

[3033 Ang Mo Kio Industrial Park 2 #01-259 \(Head](#)

*Vel Out
check liability first*

Office)

385 Sin Ming Drive Vicom Inspection Centre
(Showroom)

www.esteemperformance.com



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Khanchna (LKK Auto)

From: Sarah Lee <lee.changzhen@gmail.com>
Sent: Tuesday, 6 August 2019 12:13 AM
To: Khanchna (LKK Auto)
Cc: Admin A
Subject: Re: ACCIDENT INVOLVING SJT5915D & SLT9072K ALONG BRADELL ROAD ON 08/12/2018

Hi Kanchana,

Apologies for the delay as I was overseas for most of the days in July. Unfortunately I was still unable to get in touch with the traffic police officer who was in charge of our case. As such, please proceed with the necessary review on your end to ensure a fair assessment. Do keep me updated with any progress.

Thank you for your patience and understanding.

Best Regards
Sarah

Sent from my iPhone

On 5 Aug 2019, at 08:41, Khanchna (LKK Auto) <khanchna@lkkauto.com> wrote:

Dear Sarah,

The above matter and your e-mail dated 28/6/2019 refers.

Kindly let us know whether you are able to obtain CCTV footage of the accident to enable us to review the matter.

We appreciate your prompt reply by as to avoid litigation costs.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sarah Lee <lee.changzhen@gmail.com>
Sent: Friday, 28 June 2019 5:31 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Subject: Re: ACCIDENT INVOLVING SJT5915D & SLT9072K ALONG BRADELL ROAD ON 08/12/2018

Hi Khanchna,

Draft

Reminded by → 11/7/19

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 25 June 2019 4:37 PM
To: Hsiao Tong (LKKAuto)
Subject: ACCIDENT INVOLVING SJT5915D & SLT9072K ALONG BRADELL ROAD ON 08/12/2018 [DRAFT***]
Attachments: AVF SJT5915D & SLT9072K.mp4

Our Ref: CC4/AIG19009266/KKA3

Dear Sir/Madam,

Ol daughter - (Sara)
wants to know how
the mva happened.

-e-mail done ✓ 26/6
→ to call!

ACCIDENT INVOLVING SJT5915D [AIG] & SLT9072K ALONG BRADELL ROAD ON 08/12/2018

We refer to the above subject matter.

We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLT9072K against your motor insurance policy.

As requested, we attach herewith a copy of the accident video footage from the Third party.

We have reviewed the matter and based on the accident report and accident video, your vehicle was turning right at the cross junction and the Third party was moving straight. As such, based on the information on hand, we are of the opinion that liability is not in our favour as the said Third party has the right of way and any vehicle making a turn should ensure greater caution and ensure that it is safe to complete the turn.

We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 6 August 2019 11:45 AM
To: Carmen Lim
Cc: coleen kwok; jenny chong; Admin A
Subject: RE: LOD SLT9072K (TP-AIG)
Attachments: TP MARKED ESTIMATE.pdf

Tracking:	Recipient	Delivery
	Carmen Lim	
	coleen kwok	
	jenny chong	
	Admin A	
	olivialau@lkkauto.com	Delivered: 6/8/2019 11:45 AM
	Meikwan@lkkauto.com	Delivered: 6/8/2019 11:45 AM
	shupeil@lkkauto.com	Delivered: 6/8/2019 11:45 AM

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Please amend your LOD on COR and Final Tax invoice as based on the calculation, the finalize amount should be \$3,512.99(before GST).

Please e-mail us the soft copy for our further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carmen Lim <carmen@esteemperf.com.sg>
Sent: Tuesday, 9 July 2019 3:28 PM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: coleen kwok <coleen21@esteemperf.com.sg>; jenny chong <jenny@esteemperf.com.sg>; Admin A <admin-

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 15 August 2019 2:20 PM
To: Carmen Lim
Cc: coleen kwok; jenny chong; Admin A
Subject: RE: LOD SLT9072K (TP-AIG)
Attachments: DV AIG.pdf

Tracking:	Recipient	Delivery
	Carmen Lim	
	coleen kwok	
	jenny chong	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 15/8/2019 2:20 PM
	olivialau@lkkauto.com	Delivered: 15/8/2019 2:20 PM
	shupeil@lkkauto.com	Delivered: 15/8/2019 2:20 PM

Our Ref: CC4/AIG19009266/Kka3

Your Ref: SLT9072K

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as follows: -

1. Cost of Repair (w/GST)	\$ 3,758.90
2. Loss of Rental (6 days x \$78.95)	\$ 473.70
3. LTA/GIA Search Fee	\$ 7.45
TOTAL	<u>\$ 4,240.05</u>

We attach herewith a copy of the DV for your further action.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Your Ref : SJT 5915 D
Our Ref : SLT 9072 K

Date : 09-07-19

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building
78 Shenton Way
#07-16
Singapore 079120

RE : ACCIDENT INVOLVING SLT 9072 K & SJT 5915 D
ACCIDENT DATE 08.12.2018
ACCIDENT ALONG BRADDELL RD SLIP ROAD TOWARD CTE/SLE

We are the workshop for the owner of motor vehicle no : SLT 9072 K which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured SJT 5915 D we are submitting these claims for your consideration.

1	Cost of repair	S \$	3,758.90
2	Loss of rental <u>06</u> days @ <u>\$ 78.95</u> / day	S \$	473.70
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.45
		<u>S \$</u>	<u>4,240.05</u>

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim
Claims Executive
Email : carmen@esteemperf.com.sg



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC4/AIG19009266/KKA3

11 JUNE 2019

**LEE SOON HUAT
BLK 532 SERANGOON
NORTH AVENUE 4
#06-255
SINGAPORE 550532**

Dear Sir/Madam,

**ACCIDENT INVOLVING SJT5915D & SLT9072K ALONG BRADELL ROAD ON
08/12/2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLT9072K against your motor insurance policy.

We have reviewed the matter and based on the accident report and accident video, your vehicle was turning right at the cross junction and the Third party was moving straight. As such, based on the information on hand, we are of the opinion that liability is not in our favor as the said Third party has the right of way and any vehicle making a turn should ensure greater caution and ensure that it is safe to complete the turn. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within **10 days** from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA
Case Handler
DID: 6841-2360
FAX: 6741 4108
Email: khanchna@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

LETTER OF AUTHORITY

To Whom It May Concern:

ACCIDENT INVOLVING SLT 9072 K & SJT 5915 D along braddell Road
On 08/12/2018 @ 22:30

I, Grab Rentals Pte Ltd Nric No. 201617200G
of 18 Sin Ming Lane #01-08 Midview City Singapore 573960
Owner of motor vehicle no. SLT 9072 K do hereby appoint M/S
ESTEEM PERFORMANCE PTE LTD as my authorized representation and
_____ as my solicitors to write, to negotiate and settle my claim against
the other party/parties involved in the above mentioned accident. M/S ESTEEM
PERFORMANCE PTE LTD shall have absolute discretion to settle the matter at the best
terms.

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to
M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final
discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge
voucher on my behalf.


Signature of Owner

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, ESTEEM PERFORMANCE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,758.90 (Repair Cost), S\$473.70 (Loss of Use/Rental), S\$7.45 (Disbursement) for vehicle no. SLT9072K that was damaged pursuant to the accident which occurred on 08/12/2018 (date) along CROSS JUNCTION OF BRADDELL ROAD AND LORONG CHUAN (location) involving vehicle no/s SJT5915D. This is pursuant to the inspection conducted on 03/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD (the third party claimant") of vehicle no. SLT9072K make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLT9072K (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 15 (day) of Aug (month) 2019 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



ESTEEM PERFORMANCE PTE LTD

nt:2

Blk 5033 Ang Mo Kio Industrial Park 2, #01-259/01-251, Singapore 569536.

Tel : 6484 1221 Fax : 6484 7829

385 Sin Ming Drive (Inside Vicom) Singapore 575718.

Tel : 6753 2112 Fax : 6451 0394

Co. Reg No.: 200005485N GST Reg No.: 20-0005485-N

M/S : AIG ASIA PACIFIC INSURANCE PTE.LTD
AIG BUILDING
78 SHENTON WAY
#07-16 SINGAPORE 079120

ATTN: Motor Claim Department

Your Ref No: SJT5915D
Claim Type: Third Party
Accident Date: 08/12/2019
TP Veh Reg No: SJT5915D

Claim No: CER1301564
Final No: CIV1302042
Date: 06 Jul 2019
Policy No:
Veh Reg No: SLT9072K
Make/Model: TOYOTA PRIUS
HYBRID 1.8 CVT
Chassis No: JTDKB3FU303575884
Engine No: 2ZRS110672
Reg. Date: 16/11/2017

Tax Invoice to Vehicle No :SLT9072K

Description	Quantity	List Price	Amount
		SS	SS
Others			
1 COST OF REPAIR	1 PCS	3,512.99	
		3,512.99	3,512.99
Total			SS 3,512.99
Add GST @ 7%			245.91
Total Amount Payable			SS 3,758.90

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVEN HUNDRED FIFTY EIGHT AND CENTS NINETY ONLY

The above vehicle was surveyed by KENNETH on 03/06/2019

For Esteem Performance Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE



CONFIDENTIAL
SCHEDULE TO VEHICLE RENTAL AGREEMENT

Date:		11/09/2018		Vehicle Rental Agreement No.		11342	
Renter Details				Additional Driver (if any)			
<input checked="" type="checkbox"/> Name	Yan Lee Ng			<input checked="" type="checkbox"/> Name			
<input checked="" type="checkbox"/> Address	275 Joo Chiat Place #01-02			<input checked="" type="checkbox"/> Address			
<input checked="" type="checkbox"/> Date of Birth	12/22/1958			<input checked="" type="checkbox"/> Date of Birth			
<input checked="" type="checkbox"/> NRIC/Passport No.				<input checked="" type="checkbox"/> NRIC No.			
<input checked="" type="checkbox"/> Driving License No.	S1286100A			<input checked="" type="checkbox"/> Driving License No.			
<input checked="" type="checkbox"/> Telephone No.	8581860309			<input checked="" type="checkbox"/> Telephone No.			
<input checked="" type="checkbox"/> Mobile No.	6581860309			<input checked="" type="checkbox"/> Mobile No.			
Vehicle Description				Additional Driver (if any)			
<input checked="" type="checkbox"/> Vehicle No	ELT9072K			<input checked="" type="checkbox"/> Name			
<input checked="" type="checkbox"/> Make/Model	TOYOTA Plus			<input checked="" type="checkbox"/> Address			
Rental Period				Additional Driver (if any)			
<input checked="" type="checkbox"/> Minimum Rental Period	407			<input checked="" type="checkbox"/> Date of Birth			
<input checked="" type="checkbox"/> Date/ Time Checked Out	11/09/2018			<input checked="" type="checkbox"/> NRIC No.			
<input checked="" type="checkbox"/> No. of Days				<input checked="" type="checkbox"/> Driving License No.			
<input checked="" type="checkbox"/> Expected Date/Time of Return	12/21/2019			<input checked="" type="checkbox"/> Telephone No.			
<input checked="" type="checkbox"/> Actual Date/Time of Return				<input checked="" type="checkbox"/> Mobile No.			
Rental Charges* & Deposit							
<input checked="" type="checkbox"/> () RR Rental Charges/Day	Per day @ S\$85.00 Per week @ S\$595.00			Deposit Received	S \$1,500.00		
<input checked="" type="checkbox"/> (X) ER Promotion Rental Charges/Day	Per day @ S \$78.96 Per week @ S\$552.66			Total Amount Received*	S \$3,553.79		
<input checked="" type="checkbox"/> (X) CDW Charges/Day	Per day @ S\$4.28 Per week @ S\$29.96			* Inclusive GST			
Rental Period	407 days / 58 weeks			Total Rental Charges	S \$0.00		

Insurance Matters (Accident/Theft)				
Liability Assessment / Nature of Incident	Non-Refundable Excess Payable by Renter*			Rental Charge / Replacement Vehicle
	Section 1 (Own Damage)*	Section 2 (3rd Party Damage if applicable)*	Renter or authorised driver(s) is below 26 years of age	
3rd Party Fault	S\$2,140.00	S\$2,140.00	S\$1,605.00	Rental Charges waived or replacement vehicle provided (subject to availability)
Own Fault (inclusive of accidents in Malaysia)	S\$2,140.00	S\$2,140.00	S\$1,605.00	No waiver of Rental Charges & no replacement vehicle provided
Act of God	S\$2,140.00	Not applicable	S\$1,605.00	Rental Charges waived or replacement vehicle provided (subject to availability)
Stolen Vehicle	S\$2,140.00	Not applicable	S\$1,605.00	Rental Charges waived or replacement vehicle provided (subject to availability)
Damage to Windscreen	S\$107.00	Not Applicable	Not Applicable	No waiver of Rental Charges & no replacement vehicle provided
Unreported or late reporting of accidents	Renter is liable for 3rd parties & own vehicle repair costs associated with the accident			No waiver of Rental Charges & no replacement vehicle provided

* excess payable is accumulative & inclusive of GST

Payment Method			
<input checked="" type="checkbox"/> Driver Wallet		<input type="checkbox"/> Cash	S\$
<input type="checkbox"/> Credit Card		<input type="checkbox"/> Debit Account	
Type		Bank Name	
Card No.		Account No.	

CONFIDENTIAL

I, the Renter, agree that the Lessor may collect, use & disclose my personal data, as provided in this Schedule &/or pursuant to the Agreement from time to time, including my vehicle location information (through various channels and methods such as through the use of telematics technology), for the following purposes in accordance with the Personal Data Protection Act 2012 & the Lessor's group Privacy Policy (available at www.grab.com/sq/privacy/):

- (a) administration of the vehicle rental under the Agreement;
- (b) to help maintain the safety, security and integrity of the products and services of the Grab group;
- (c) to improve and enhance the products and services of the Grab group;
- (d) to administer the driver-partner relationship between the Grab group and myself;
- (e) for internal tracking, analysis and administrative purposes;
- (f) to communicate with me; &
- (g) for the Lessor to comply with its obligations under law.

☒ X

Further, I understand that my personal data may be used for marketing purposes by the Lessor, its affiliated companies or their partners; & I hereby consent to receive marketing & promotional materials by telephone, SMS or e-mail.

Additional Notes:

Where the Renter & all authorised drivers (each of which hold a valid PDVL or TDVL) are 26 years of age or older, the Renter shall enjoy the following Discount:

Renter shall only be liable to pay S\$535.00 in insurance excess (for each section) instead of the excess amount indicated in the Insurance Matters table above (Sections 1 & 2 ONLY) PROVIDED THAT the Renter fulfills all of the following:

- fulfilment of Minimum Rental Period
 - timely payment of all Rental Charges at all times
 - timely reporting of all accidents, thefts & other incidents in accordance with the Agreement
 - there are no accidents, thefts or other incidents occurring within the first week of rental
 - the Renter at all times is in full compliance with the Agreement & any other undertakings & arrangements entered into with Lessor or its affiliated entities
- ("Qualifying Incident").

The Lessor may at its sole discretion allow or disallow an incident to count as a Qualifying Incident.

The above Discount may be cancelled at any time at the Lessor's sole discretion. In the case of cancellation, the CDW Charges rate shall no longer apply & instead the ER Promotion Rental Charges rate (only) shall apply (subject to the relevant terms & conditions being continually fulfilled in order for the ER Promotion Rental Charges rate to apply), & the Lessor shall hold to the credit of the Renter the amount comprised in the CDW Charges (where paid) ("Credit Amount"). The Credit Amount may be applied by the Lessor to satisfy any & all costs & payments due to the Lessor under the Agreement.

Subject to Renter's fulfilment of Minimum Rental Period, Renter shall enjoy the following Discounts:
[insert description of promotion(s) &/or refer to relevant section above if already described above]

Agreement

The Renter has read, understood & agrees with all terms & conditions of this Agreement.



Renter's Signature/Stamp
Date:



Authorised Signatory/Stamp
Grab Rentals Pte Ltd



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 23 May 2019 / 11:06:20

Receipt Date/Time : 23 May 2019 / 11:06:20

Tax Invoice/Receipt

Receipt No. : LTACT-MTX-190523-000081

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
1	Perform VRL Enquiry - SJT5915D Enquiry Fee 20190523110500790929	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			-0.04
	Total Amount Payable			7.45
	Paid By			
	Cash			10.00
	Total			10.00
	Cash Change			2.55
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Dec 2018 Edit Reg		24 May 2019 00:00 Edit Adj Rpt	S\$3,512.99 Edit Estimates	S\$3,512.99 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LEE SOON HUAT , ID: S1458769A									
Main Claimant: GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G									
Vehicle Reg. No.: SLT9072K		Date of Loss: 08/12/2018 22:00 - :59 [12 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 0948938149SG		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): SJT5915D		Policy No. (Claimant): A29069766MKF							
		Excess:							
Repairer: Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive, 575718 Sin Ming - Tel:									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com									
Claimant's Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 06/06/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT9072K (0948938149SG)
[SJT5915D]
TP
GRAB RENTALS PTE LTD
Dec 8 2018 10:00PM
[LEE SOON HUAT]
Esteem Performance Pte Ltd - Sin Ming

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 10:52	Video - Accident TP VIDEO	Load MP4	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
2	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
3	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
4	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
5	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
6	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
7	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
8	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
9	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
10	11/06/19 11:01	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
11	11/06/19 11:01	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
12	11/06/19 11:01	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/05/19 14:06	ACKNOWLEDGEMENT EMAIL TO AIG DD 24.05.2019	Load PDF	
2	27/05/19 14:06	EMAIL FROM AIG DD 24.05.2019	Load PDF	
3	27/05/19 14:06	TP ESTIMATE + TP GIA REPORT	Load PDF	
4	04/06/19 16:06	TP ESTIMATE - MARKED	Load PDF	
5	11/06/19 14:09	Letter to Insured	Load PDF	
6	28/08/19 15:59	WORKSHOP INVOICE	Load PDF	
7	28/08/19 15:59	AUTHORISATION TO ACT FORM	Load PDF	
8	28/08/19 15:59	Release Voucher	Load PDF	
9	28/08/19 15:59	RENTAL RECEIPT	Load PDF	
10	28/08/19 15:59	LTA SEARCH	Load PDF	
11	28/08/19 15:59	LOD	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	28/05/19 10:57	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJT5915D (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID
	SLT9072K (TP veh)		CVT (A)
Date of Accident:	08/12/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	7,576.37
Final Repair Cost	:	\$	3,758.90
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	473.70 6 days
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,240.05

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Esteem Performance Pte Ltd	:	\$ 4,240.05
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

28 Aug
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19009266/KKA3Q2

Date: 28/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle
No : SLT9072K

Insured Vehicle No : SJT5915D

Date of Loss: 08/12/2018

Nature of Claim: TP

Claim No: 0948938149SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT9072K

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No: 2ZRS110672

Reg. Date: 16/11/2017 (Man. Year: 2017)

Chassis No: JTDKB3FU303575884

Colour: Metallic Silver

Odometer: 105602 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,340.72	1,912.99	2,427.73	55.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,740.00	1,600.00	1,140.00	41.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,080.72	3,512.99	3,567.73	50.39
+ GST 7.00/7.00% (S\$)	495.65	245.91	249.74	50.39
Nett Amount (S\$)	7,576.37	3,758.90	3,817.47	50.39
+ Car Rental (6.0 x S\$78.95/day) (S\$)		473.70		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,240.05		

INSPECTION

Date of Assignment: 24/05/2019

Date Inspected: 03/06/2019 Inspected At:

Esteem Performance Pte Ltd - Sin Ming
(HQ)
385 Sin Ming Drive
Singapore 575718

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Repair	1,211.40 FL	*- FL
2	1		*LH REAR DOOR HINGE TOP	Repair	78.34 FL	*- FL
3	1		*LH REAR DOOR HINGE BOTTOM	Repair	78.34 FL	*- FL
4	1		*LH REAR DOOR WEATHERSTRIP	Serviceable	198.70 FL	*- FL
5	1		*LH REAR FENDER	Repair	883.60 FL	*- FL
6	1		*LH REAR FENDER UNDERSHIELD	Serviceable	92.30 FL	*- FL
7	10		*LH REAR FENDER UNDERSHIELD CLIP	Not Necessary	30.00 FL	*- FL
8	1		*LH REAR RIM	Dented	1,555.10 FL	*1,555.10 FL
9	1		*LH REAR TYRE	Serviceable	350.00 FL	*- FL
10	1		*REAR BUMPER	Mtg Cracked	497.50 FL	*497.50 FL
11	10		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
12	1		*REAR BUMPER SIDE RETAINER LH	Distorted	112.70 FL	*112.70 FL
13	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	112.70 FL	*- FL
14	1		*REAR BUMPER LOWER GARNISH LH	Mtg Cracked	149.70 FL	*149.70 FL
15	1		*REAR BUMPER UNDER COVER LH	Serviceable	187.60 FL	*- FL
16	4		*REAR BUMPER UNDER COVER CLIP	Not Necessary	14.00 FL	*- FL
17	1		*LH REAR HUB CAB	Missing	195.65 FL	*195.65 FL

F=Franchise part, L=ListItemDisc.

Sub Total (S\$)	5,787.63	2,550.65
- List Item Discount on L Items 25.00/25.00% (S\$)	1,446.91	637.66

Total Parts (S\$)	4,340.72	1,912.99
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA ,(LHF DOOR ,LHR FENDER, REAR BUMPER END PANEL)	New	1,000.00	700.00
2	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (LHR DOOR ,LHR FENDER,REAR BUMPER END PANEL)	New	1,000.00	700.00
3	TO TUFF COAT	New	150.00	0.00
4	TO CHECK WIRING	New	50.00	20.00
5	TO REMOVE & REFIT PETROL TANK TO ASSIST WORK LOAD	New	150.00	0.00
6	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING	New	120.00	20.00
7	TO REMOVE & REFIT INNER SEAT & UPHOLSTERY TO ASSIST WORK LOAD	New	150.00	100.00
8	TO DO WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			2,740.00	1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >