



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Repair Estimates

SLT 9072 K

Parts	(a) Cost / List Price Items	\$	5,787.63
	Plus/Less 25%	\$	1,446.91
	<b>Total of Cost / List</b>	<b>\$</b>	<b>4,340.72</b>
	(b) Nett Price Items		
	Less		
	<b>Total of Nett Item</b>		
	(c) Special Nett Items		
<b>Total Parts Cost</b>		<b>\$</b>	<b>4,340.72</b>
<b>Labour</b>		<b>\$</b>	<b>2,740.00</b>
<b>Total</b>		<b>\$</b>	<b>7,080.72</b>

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 3/6/18 at 10.35am

### Remarks By Surveyor

(a) The repair of this vehicle is <sup>not</sup> authorized / is ~~not~~ authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$                     

(e) Signature of surveyor : De Date: 3/6/18



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Spare Parts

Vehicle No. : **SLT 9072 K**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU303575884**

Submit By : **SERENCE**  
Year Manufacture : **2017**  
Engine No. :  
**Cost / List**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door <i>RC</i>	1	\$1,211.40		X
2	LH rear door hinge top <i>RC</i>	1	\$78.34		X
3	LH rear door hinge bottom <i>RC</i>	1	\$78.34		X
4	LH rear door weatherstrip <i>SW</i>	1	\$198.70		X
5	LH rear fender <i>RC</i>	1	\$883.60		✓
6	LH rear fender undershield	1	\$92.30		?
7	LH rear fender undershield clip	10	\$30.00		?
8	LH rear rim <i>RC</i>	1	\$1,555.10		✓
9	LH rear tyre <i>SW</i>	1	\$350.00		X
10	Rear bumper <i>RC</i>	1	\$497.50		✓
11	Rear bumper clip <i>RC</i>	10	\$40.00		✓
12	Rear bumper side retainer LH <i>DIS</i>	1	\$112.70		✓
13	Rear bumper side retainer RH <i>SW</i>	1	\$112.70		X
14	Rear bumper lower garnish LH <i>RC</i>	1	\$149.70		✓
15	Rear bumper under cover LH <i>SW</i>	1	\$187.60		X
16	Rear bumper under cover clip <i>RC</i>	4	\$14.00		X
17	LH rear hub cap <i>RC</i>	1	\$195.65		✓
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.  
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

### Labour

Vehicle No. : **SLT 9072 K** Submit By : **SERENCE**  
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
3	To tuff coat.	\$150.00	30
4	TO Check wiring	\$50.00	20
5	To remove & refit petrol tank to assist work load.	\$150.00	60
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	100
8	To do wheel alignment.	\$120.00	60

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.