



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLT 9072 K

Parts (a) Cost / List Price Items

Finalised
\$ ~~2550.65~~ 5,787.63

Plus/Less 25%

\$ 637.66 1,446.91

Total of Cost / List

\$ 1912.99 4,340.72

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

\$ 1912.99 4,340.72

Labour

\$ 1690.00 2,740.00

Total

\$ ~~2602.99~~ 7,080.72

3512.99

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

CKK

Survey conducted on

3/8/19

at

10.35am

Remarks By Surveyor

(a) The repair of this vehicle is ^{not} authorized / is ~~not~~ authorized until further notice.

(b) Recommended Days of Repair

04

day(s)

(c) Resurvey

Required / ~~Not Required~~

(d) Excess

:\$

(e) Signature of surveyor

ck

Date:

3/8/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6464 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLT 9072 K
Make & Model : TOYOTA PRIUS
Chassis No. : JTDKB3FU303575884

Submit By : SERENCE
Year Manufacture : 2017
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH rear door	1	\$1,211.40		X
2	LH rear door hinge top	1	\$78.34		X
3	LH rear door hinge bottom	1	\$78.34		X
4	LH rear door weatherstrip	1	\$198.70		X
5	LH rear fender <i>Repair</i>	1	\$883.60		X
6	LH rear fender undershield	1	\$92.30		X
7	LH rear fender undershield clip	10	\$30.00		X
8	LH rear rim	1	\$1,555.10		X
9	LH rear tyre	1	\$350.00		X
10	Rear bumper	1	\$497.50		X
11	Rear bumper clip	10	\$40.00		X
12	Rear bumper side retainer LH	1	\$112.70		X
13	Rear bumper side retainer RH	1	\$112.70		X
14	Rear bumper lower garnish LH	1	\$149.70		X
15	Rear bumper under cover LH	1	\$187.60		X
16	Rear bumper under cover clip	4	\$14.00		X
17	LH rear hub cab	1	\$195.65		X
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2017-05



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLT 9072 K**

Submit By : **SERENCE**

Make & Model : **TOYOTA PRIUS**

Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHR DOOR, LHR FENDER, REAR BUMPER) END PANEL)	\$1,000.00	700
3	To tuff coat. <i>nn</i>	\$150.00	300 X
4	TO Check wiring	\$50.00	200
5	To remove & refit petrol tank to assist work load. <i>nn</i>	\$150.00	600 X
6	To conduct water leakage tests to ensure proper air and sealing	\$120.00	200
7	To remove & refit inner seat & upholstery to assist work load.	\$150.00	1000
8	To do wheel alignment.	\$120.00	600

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

1690