

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

LKS Auto Consultants hereby notify the Repairer of the following:

- To resurvey (resurvey/spray painting)
- To despatch damaged parts during resurvey
- These prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct roadworthy is allowed
- Supplementary repairs must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Estimate : 21009

Date : 02.04.2019

Vehicle Num : SLM 2676B

Make/Model : BMW 116D

Chassis/Engine no :

Accident Date : 29.03.2019

Claim No : 0419-21009

Reference :

Policy No :

*not allowed here
1/5 @ 5000
3.7.*

Qty	Particular	Amount S\$
-----	------------	------------

List Item :

1 pc	Front bonnet	\$ 11	1,483.50	X
2 pc	Front bonnet hinge @ 126.50	\$ 11	253.00	X
1 pc	Front logo	\$ 22	74.80	—
1 pc	Front bonnet insulator	\$ 11	175.00	X
2 pc	Front bonnet absorber @ 125.00	\$ 11	250.00	X
1 pc	Front bonnet lock	\$ 11	295.00	X
2 pc	Front bonnet side lock @ 85.00	\$ 11	170.00	X
1 pc	Front top panel	\$ R	235.00	X
2 pc	Headlamp @ 2850.00	\$ 285	5,700.00	1pc
2 pc	Headlamp hid sensor @ 862.00	\$ 11	1,724.00	X
2 pc	Headlamp led control module @ 945.00	\$ 11	1,890.00	X
1 pc	Front number plate base	\$ 48	48.00	—
2 pc	Front headlamp panel @ 175.00	\$ 11	350.00	X
2 pc	Front headlamp bracket @ 85.00	\$ 11	170.00	X
1 pc	Front bumper	\$ 1550	1,550.00	—
1 pc	Front bumper reinforcement	\$ 685	685.00	—
2 pc	Front bumper reinforcement bracket @ 45.00	\$ 11	90.00	X
1 pc	Front bumper sponge	\$ 245	245.00	—
2 pc	Front bumper fog lamp cover @ 120.00	\$ 240	240.00	1pc
1 pc	Front bumper PDC sensor 1pc	\$ 220	220.00	—
1 pc	Front bumper tow cover	\$ 11	65.00	X
1 pc	Front bumper lower grille	\$ 11	165.00	X
1 pc	Front grille 1pc	\$ 190	190.00	—
2 pc	Front grille moulding @ 75.00	\$ 11	150.00	X
2 pc	Horn @ 90.00	\$ 11	180.00	X
1 pc	Radiator	\$ 11	955.00	X
1 pc	Radiator air duct	\$ 11	155.00	X
1 pc	Aircon condensor	\$ 11	1,350.90	X
1 pc	Aircon fan motor assy	\$ 11	758.00	X
1 pc	Air cleaner box assy	\$ 11	565.00	X
1 pc	Air duct	\$ 11	155.00	X
1 pc	Oil cooler	\$ 11	751.00	X
1 pc	Air cleaner box hose	\$ 11	76.00	X
1 pc	Radiator top hose	\$ 11	155.00	X
1 pc	Radiator top by pass hose	\$ 11	175.00	X
1 pc	Front mudguard LH	\$ 11	1,600.00	X
1 pc	Front mudguard inner shield LH	\$ 11	200.00	X
		\$	23,809.20	

n/s

n/s

*5648.65
53
5366.21*

KIM CHWEE AUTO PTE LTD

PAGE 2 OF 2

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 199802379-R

Estimate : 21009

Date : 02.04.2019

Vehicle Num : SLM 2676B

Make/Model : BMW 116D

Chassis/Engine no :

Accident Date : 29.03.2019

Claim No : 0419-21009

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front shock absorber LH	\$ 11 380.00 X
1 pc	Front knuckle arm LH	\$ 11 950.00 X
1 pc	Front wheel bearing LH	\$ 11 225.00 X
1 pc	Front wheel bearing hub LH	\$ 11 292.00 X
1 pc	Front lower arm LH	\$ 11 750.00 X
1 pc	Front control arm LH	\$ 11 552.00 X
2 pc	Engine mouting @ 780.00	\$ 11 1,560.00 X
2 pc	Gearbox mounting @ 620.00	\$ 11 1,240.00 X
Nett Item Total:		\$ 29,758.20
Discount 5%		\$ 1,487.91
		\$ 28,270.29

Nett Item :

8 pcs	Front bonnet insulator clips @ 8.00	\$ 11 64.00 X
6 pcs	Front support panel top garnish clips @ 8.00	\$ 11 48.00 X
1 pc	Front number plate	\$ Sent 60.00 40
1 pc	Front sport rim LH	\$ 11 1,800.00 X
1 pc	Front tyre LH	\$ 11 850.00 X
Special Nett Total :		\$ 2,822.00

Labour charge :

To check wiring & diagnostic headlamp sensor	\$ 380.00 50
Tuff kote	\$ 11 150.00 X
Remove and replace aircon condenser & refill gas	\$ 11 250.00 X
Remove and replace radiator	\$ 11 160.00 X
Remove and refix engine & gear mounting	\$ 11 350.00 X
Remove and refix front under carriage, suspension etc	\$ 11 450.00 X
Recheck wheel alignment	\$ 11 120.00 X
To remove and replace spare part and panel beating	\$ 1,500.00 400
To spray paint affected portion	\$ 1,500.00 400
Labour charge total :	\$ 4,860.00

6286.21

E & O . E

Total Amount : \$ 35,952.29