

	Date	No.
Rear Boot Lid Reps	1100.00	X
- " Hinge 2x 850 H/M	100.00	X
- " Lock H/M	180.00	X
- " ABS-T-Date 2x 2180 H/M	360.00	X
- " Rubber H/M	135.00	X
- " Number Plate Lamp Garnish	220.00	X
- " Elbow (H) H/M	25.00	X
- " " Vezel New	56.00	✓
- " Inner Garnish Cover H/M	240.00	X
Rear End Panel Reps	538.00	X
- " " Top Cover - Cracked	92.30	✓
Rear Bumper Behind	863.50	✓
- " " Sensor - Dented	350.00 220 (1N)	
Rear Panel Top Cover - H/M	300.00	X
Rear Fender outer side Bumper 2x 195	390.00	X
Rear Fender Lamp 2x 460 H/M	920.00	X
Rear Boot Lid Lamp 2x 240 H/M	480.00	X
Rear Exhaust H/M	850.00	X
Rear Bumper Clips. New 30	7199.80	
Rear Bumper Side Holders @ 48.60 97.20	1439.86	
To remove upholstery 60	5759.84	
To spray painting affected areas	1000.00	600
To knock, oil tighten all necessary parts, including changing & repairing off all damaged parts	1200	400
To remove reverse sensor 140	7959.84	
List: 1139		
km 20% 911.20		
S.N: 280		
Labour: 1110		
Total: 2241.20		
H/S: 18K 03 Days		
Jump Sum: \$ 6367.00		

18K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To remove damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

A'ZONE