

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5283G**AAD1905-204***Not Authored*
1/1/2014

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5283G

VF1ABL15AUC276738

RENAULT

LATITUDE

22.5.19

AIG

7/3/2014

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Dir</i> 151.41 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mgm</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>CM</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	TOW COVER FRT	\$	<i>Sn</i> 28.61
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>na</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61
1	BONNET HINGE LH	\$	<i>R</i> 348.31
1	BONNET HINGE RH	\$	<i>R</i> 348.31
1	BONNET LOCK	\$	<i>R</i> 305.48
1	BONNET CABLE	\$	<i>Sn</i> 119.19

X

Trans-cab Auto Services Pte Ltd

AAD1905-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5283G

1	BONNET CABLE COVER	\$	SL	161.03	X
1	BONNET SEAL OUTER	\$	SL	92.36	X
1	BONNET SEAL INNER	\$	SL	157.28	X
1	DOOR PANEL FRT RH	\$	Bil/warp	2,844.66	
1	DOOR HINGE UPPER RH	\$	N	261.28	X
1	DOOR HINGE LOWER RH	\$	N	300.55	
1	DOOR CHECK FRT RH	\$	SL	194.77	
1	DOOR LOCK FRT RH	\$	N	908.75	
1	DOOR CATCH FRT RH	\$	SL	131.23	
1	DOOR HANDLE OUTER FRT RH	\$	SL	477.76	
1	DOOR HANDLE COVER FRT RH	\$	SL	13.22	
1	DOOR HANDLE MODULE FRT RH	\$	SL	133.60	
1	DOOR REGULATOR FRT RH	\$	SL	505.19	
1	DOOR REGULATOR MOTOR FRT RH	\$	SL	796.46	X
1	DOOR REGULATOR GUIDE FRT RH	\$	SL	120.97	
1	DOOR MIRROR ASSY RH	\$	CM	1,483.40	
1	DOOR MIRROR GLASS RH	\$	na	148.20	X
1	DOOR MIRROR BACK COVER RH	\$	na	218.46	X
1	LOWER ARM RH L70Y	\$		685.76	?
1	KNUCKLE ARM RH L70Y	\$		846.98	?
1	ABSORBER FRT RH L70Y	\$		360.54	?
1	DRIVESHAFT RH	\$	N	1,747.45	X
1	STABILIZER BAR FRT	\$	SL	604.65	X
1	WIPER RESERVOIR MOTOR	\$	SL	270.06	
1	WIPER RESERVOIR	\$	SL	348.25	
1	WIPER RESERVOIR NECK	\$	SL	136.11	
1	ROCKER PANEL INNER GARNISH RH	\$	SL	466.51	
1	ROCKER PANEL INNER RH	\$	N	1,024.79	X
1	ROCKER PANEL CENTER RH	\$	N	990.25	
1	ROCKER PANEL OUTER RH	\$	N	1,184.99	
1	DOOR HARNESS WIRE RH	\$	SL	2,670.00	
1	WHEEL HOUSING PANEL FRNT RH	\$	N	4,682.09	
TOTAL		\$		39,329.82	
10%		\$		3,932.98	
		\$		35,396.84	

Special Nett

1 FRONT DOOR STICKER 'Trans-cab'

\$

na 80.00 605N

Trans-cab Auto Services Pte Ltd

AAD1905-204

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5283G

1	FRONT DOOR STICKER 'Classic'	\$	na	80.00	155
1	BUMPER CLIP FRT	\$	na	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	na	12.00	} X
1	BUMPER SUPPORT CLIP FRT RH	\$	na	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	} X
1	WHEELARCH CLIP FRT RH	\$	na	30.50	
1	FRONT RIGHT TYRE	\$	na	300.00	
1	FRONT RIGHT TYRE RIM	\$	na	380.00	
1SET	Front licence plate with holder	\$	na	80.00	} X
1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1	WINDSCREEN SEALANT	\$	na	253.80	
1	FRONT WINDSCREEN MOULDING	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30	
2	BONNET STRUT L70Y	\$	na	88.61	
2	BONNET CABLE CLIP L70Y	\$	na	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	
1	DOOR CATCH SCREW L70Y	\$	na	10.06	
TOTAL		\$		1,984.51	

TOTAL PARTS	\$	37,381.34
--------------------	-----------	------------------

LABOUR

To transfer of front windscreen fittings and conduct
water seepage test.

\$	na	170.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd**AAD1905-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5283G

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5001 7,500.00
To rust-proofing of the affected areas.	\$	170.00 601
Putty and spray painting of the affected portion.	\$	7,500.00 7001
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	220.00 601
To transfer of tire, rim and on wheel balancing.	\$	170.00 201
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 601
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00 ?
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X

Trans-cab Auto Services Pte Ltd**AAD1905-204**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5283GLabour charge to mount and dismount vehicle on
jig bench, to facilitate repair.

\$

nn 380.00 *X*To remove and refit air bag system and reset vehicle
warning indicators.

\$

nn 480.00 *X*

To Check Electrical Lighting Concerned.

\$

170.00 *2d*To check ABS brake efficiency, final checking and
testing.

\$

nn 380.00 *X***TOTAL**

\$

20,180.00**Over All Total**

\$

57,561.34**LUMP SUM (REPAIR DAY)****~~25~~ DAYS***4 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: