

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notified
11 May @?
Resurvey After Paint
4 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 25.05.2019

Accident Date : 20.05.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Honda Civic" Reg. No. SLQ1713M Claiming Against Your Insured Reg. No. SKT252D			
1pc	Rear Bumper	3.80	730.50 ✓
10pcs	Rear Bumper Clips		38.00 ✓
1pc	Rear Bumper Top Retainer LH	18.90	18.00 ✓
2pcs	Rear Bumper Corner Holders		37.80 X
1pc	Boot		561.60 ✓
1pc	Boot Emblem		28.00 ✓
1pc	Boot Badge Civic		38.30 ✓
1pc	Boot Badge 1.8		32.00 ✓
1pc	Boot Badge I VETEC		32.00 ✓
1pc	Boot Lamp LH		255.00 ✓
1pc	Boot Lamp Gasket		110.90 ✓
1pc	Boot Lamp Lock		81.80 X
1pc	Boot Wheatherstrip		1,963.90
	Less 20%		392.78
			1,571.12
1pc	Rear Bumper Reverse Sensor		280.00 SN
	To Conduct Electrical Check, Replace Reverse Sensor, Module etc		120.00 601
	To Dismantle / Transfer Boot Fittings and Accessories		100.00 501
	To Apply Rust Proofing / Reseal Tuff Coating		80.00 301
	Labour Charge - Panel Beating, Repairing Of End Panel, and Parts Replacement		600.00 4001
	To Respray Affected Areas		750.00 4001
		Total :	3,501.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: