



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLU 7377 P

*Not Authorized
Resurvey Repair*

Parts (a) Cost / List Price Items	\$	<u>1,461.60</u>
Plus/Less 25%	\$	<u>365.40</u>
Total of Cost / List	\$	<u>1,096.20</u>
(b) Nett Price Items		_____
Less		_____
Total of Nett Item		_____
(c) Special Nett Items		_____
Total Parts Cost	\$	<u>1,096.20</u>
Labour	\$	<u>370.00</u>
Total	\$	<u>1,466.20</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 27/5/19 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : lc Date: 27/5/19

