

ASS. REC. BY:

REF: G/CT1900290/T15 d3ek Special Instruction:

Surveyor: Taufiq

## ASSIGNMENT (Office)

From (Person): Elaine Chong

of CT1

Date/Time: 27.5.2019 15:04pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJH 79455

Insured: XD 7085D

at Workshop m/s Teamwork Garage

Tel: 6844 2475

of 53 ubi Ave 1 #01-24

Policy No: DM CVS 18061819011

Claim No: SNM19D202350C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23.5.2019

(Client's Record)

28.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27.5.19 3:08pm

Person Contacted: Susan

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJH 79455 - NA/11/190009201/24	D.O.A - 23/05/2019
	XD 7085D - NA/11/190009201/24	D.O.A - 23/05/2019

Surveyor: Tamplin

REF: CT1

**ASSIGNMENT**

CoE 2028 Aug

From: \_\_\_\_\_ Date: 28.5.2019

Estimated Cost: \_\_\_\_\_

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SJH 79455

at Workshop m/s Teamwork Garage

of 53 Wls Ave 1 #01-24

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$44K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS rup's

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: Darren

Veh No: SJH 79455

Yr Regn: 2008

Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

Altis

c.c 1598

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 185828

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WIKOS32FE-106114947

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 28/5/19

Survey held at Teamwork Garage

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit \$12k  
4/546300, 10 days.  
C \$ 9,729.69 red - 61%

RECEIVED 04 SEP 2019

4/9/2019

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 10

1) Typist

☒ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee: 270

2)

Add Fee: ☐ : Site Insp (\$)

Transportation: \_\_\_\_\_

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ 6,300/- 45)

270

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019		27 May 2019 15:04 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD</b> , Co. Reg. No.: 199904117E								
Main Claimant:	<b>SONG JIANHAO</b> , ID: S9111882C								
Vehicle Reg. No.:	<b>SJH7945S</b>	Date of Loss:	23/05/2019 23:00 - :59 [128 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202350C02</b>	Policy/Cover Note No.:	DMCVSN18061819011						
Vehicle Reg. No. (Insured):	<b>XD7085D</b>	Policy No. (Claimant):	5108035404						
		Excess:	S\$0.00						
Repairster:	<b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 06/06/2019]</b>								
Driver/Custodian (Insured):	<b>THANGARASU CHITRARASU</b> (36 / Male) , NRIC: G7454273K Email:								
<b>ASSOCIATED MAIL RECEIVED</b>		<b>View All</b> <b>Compose Case Mail</b>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<b>View All</b> <b>Search Tasks</b> <b>Create New Task</b> <b>Complete</b>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1882C
Vehicle Details	
Vehicle No.:	SJH7945S
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4786003
Chassis No.:	MR053ZEE106114947
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	25 Aug 2008
First Registration Date:	25 Aug 2008
Transfer Count:	3
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$34,197.00
COE Rebate Amount:	\$31,595.00
Total Rebate Amount:	\$31,595.00

The information contained herein is correct as at 28 May 2019

OK



## **Shirley Hiew (LKK Auto)**

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 30 May 2019 5:06 PM  
**To:** 'TEAMWORK'  
**Cc:** SUR  
**Subject:** SJH 7945S (TP) XD 7085D (OI) DOA - 23/05/2019 CTI

Hi Darren,

Repair limit is \$ 12K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/05/2019 16:36
Date Of Accident	23/05/2019 23:15
Exact Location Of Accident	TAMPINES AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH7945S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SONG JIANHAO
NRIC No	S9111882C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90225793
Alternative Phone No	OFFICE-90225793

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108035404
Cover Note Number	

### Driver

Name of Driver	MICHAEL MEGA
NRIC No	S8429072F
Date Of Birth	02/10/1984
Occupation	INDOOR
Date Of Driving Pass	26/11/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81023977
Fax Number	
Contact Number	OFFICE-81023977
Email Address	NOEMAIL

Address	BLK 214 UPPER EAST COAST ROAD #05-04
Postcode	466402
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 65470000 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190524/7001.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD7085D
Vehicle Make/Model/Colour	VOLVO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name MICHAEL MEGA

Approximate Age

Injuries Sustain NECK & BACK

Injured person in which vehicle? SJH7945S

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

## Accident Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
  - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) Investigations the accident and/or my claims;
  - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
  - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or
  - (ii) For complying with requirements under my regulations, laws or court orders.


  
Policy holder's signature  
Date / time:

  
Driver's signature  
(if driver is not policy holder)  
Date / time:

  
reporting centre personnel's Signature  
Date / time:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature  
Date & time:

Driver's signature  
(If driver is not policy holder)  
Date & time:

reporting centre personnel's Signature  
Name:  
NRIC/FIN No.:

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190524/7001

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20190524/7001

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 24/05/2019 02:06	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars			
Name of Informant: MICHAEL MEGA		Address: APT BLK 214 UPPER EAST COAST ROAD #05-04 SINGAPORE 466402	
ID Type / ID No.: NRIC NO / S8429072F		Contact No.: Home/Office: Mobile: 81023977	
Nationality: SINGAPORE CITIZEN		Email: mmichael.consult@gmail.com	
Sex: Male	Age: 34	Date of Birth: 02/10/1984	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: PART TIME DRIVER		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/05/2019 23:15	Type of Location: Straight Road
Location:  TAMPINES AVENUE 1				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Parked Vehicle			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJH7945S	Car					0
XD7085D	Lorry				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20190524/7001

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190524/7001

### CONTINUATION OF REPORT

Driver			
Name	MICHAEL MEGA	ID No.	S8429072F
Related Vehicle	SJH7945S (Car)	Contact No.	81023977
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Serious

#### Brief Details.

I was stationary along Tampines Avenue 1 bus stop waiting for my passenger to come when suddenly I felt a collision on the rear of my vehicle.

I have sustained injuries from the above mentioned accident and was issued 5 days of medical certificate.

Police Report



**SINGAPORE  
POLICE FORCE**



T/20190524/7001

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20190524/7001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
SHARIFAH NOR FARIZAN BINTE SYED MOHD  
SAID  
Contact No.: 65476172

Authentication Stamp

NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
24/05/2019 02:06

Classification Of Case:



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

China Taiping Insurance (Singapore) Pte Ltd

105 Cecil Street #19-00

The Octagon

Singapore 069534

Vehicle number	SJH7945S
Make / Model	TOYOTA/ALTIS
Chassis number	MR053ZEE106114947
Accident date	23 May 2019
Reference	1905-80

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	BOOTLID	635 735.30 bt ✓
1	BOOTLID EMBLEM - LOGO	61.63 ne ✓
1	BOOTLID EMBLEM - COROLLA	61.40 ne ✓
1	BOOTLID EMBLEM - ALTIS	63.70 ne ✓
1	BOOTLID EMBLEM - 1.6	59.10 ne ✓
2	BOOTLID LAMP	448.50 LH-X, RH-X, RH-nt ✓ 224.25
1	BOOTLID LOCK	159.93 ? X nn ✓
1	BOOTLID LOCK STRIKER	45.15 Ry ✓
1	BOOTLID RUBBER	210.54 ? cm ✓
2	BOOTLID HINGE	171.10 Ry ✓
1	BOOTLID OUTER CHROME GARNISH	210.40 X nn ✓
1	END PANEL	685.71 bt ✓
1	END PANEL TOP GARNISH	251.20 X cm ✓
1	REAR BUMPER	595.53 de ✓
2	REAR BUMPER SIDE RETAINER	120.30 LH-X, RH-X, RH-ne ✓ 60.15
2	REAR BUMPER SIDE BRACKET	128.30 LH-X, RH-X, RH-ne ✓ 64.15
2	REAR BUMPER REFLECTOR	103.50 LH-X, RH-X, RH-nt ✓ 51.75
1	REAR BUMPER SPONGE	130.21 ? cm ✓
2	REAR BUMPER DAMPER	207.00 ? X nn ✓
1	SPARE TYRE PANEL	870.55 Ry ✓
1	SPARE TYRE TOP BOARD	312.80 X nn nn ✓
2	TAILLAMP	954.50 LH-X, RH-X, RH-cm ✓ 477.25
2	TAILLAMP PANEL	416.30 LH-X, RH-X, RH-bt ✓ 208.15
2	TAILLAMP INNER SEAL	42.00 LH-X, RH-X, RH-ne ✓ 21
1	REAR RH FENDER	1187.70 bu ✓
2	REAR FENDER INNER TRIM	1163.20 LH-X, RH-X, RH-de ✓ 581.60
1	REAR FENDER INNER SHIELD RH	171.20 de ✓
1	REAR WINDSCREEN MOULDING	171.30 ne ✓
1	REAR RH CHASSIS FRAME	710.34 Ry ✓
1	REAR EXHAUST SILENCER	1055.17 Ry ✓
1	REAR EXHAUST MOUNTING	51.10 X nn ✓
1	REAR EXHAUST HEAT SHIELD	178.25 X nn ✓
		11732.91
		2933.22
		8799.69
Subtotal		8799.69
Balance C/F		8799.69

5972.52

4479.39

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8799.69
1 SET <sup>Ren</sup> FRONT BUMPER CLIP		40.00 30.00
1 SET FRONT FENDER INNER TRIM CLIP		30.00 20.00
1 SET FRONT FENDER INNER SHIELD CLIP		20.00 10.00
1 SET REAR REVERSE SENSOR		400.00 200.00 ? started ✓
1 FLOOR INSULATOR		150.00 x 11.00
1 JOINT SEALANT		150.00 60.00
1 WINDSCREEN SEALANT		150.00 60.00 } net
1 REAR NUMBER PLATE		80.00 x 11.00
	Subtotal	1020.00
	Balance C/F	9819.69
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	9819.69
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	60.00 30.00
2	REMOVE, REFIT REAR LINING, TRIM AND GANRISH	200.00 60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 30.00
4	REMOVE AND RENEW REAR EXHAUST SILENCER	150.00 80.00 photo ✓
5	REMOVE AND RENEW REAR FLOOR INSULATOR	150.00 x 11.00
6	REMOVE AND REFIT REAR WINDSCREEN	150.00 120.00
7	REMOVE AND REFIT FULE TANK	150.00 x 11.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60.00
9	MOUNT VEHICLE ON BENCH FOR REAR CHASSIS REPLACEMNT	500.00 200.00 x 11.00
10	PANEL BEATING ON AFFECTED AREAS	2500.00 1300.00
11	SPRAY PAINTING ON AFFECTED AREAS	1800.00 1300.00
12	APPLY ANTI RUST ON AFFECTED AREAS	200.00 60.00
	Subtotal	6210.00
	Grand total	16029.69

390.

3040.

*[Signature]*  
31/5/19

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Taufik 97495749  
wp'  
28/5/19 @ 440pm  
10 days  
taufik@lkhauto.com

7909.39  
4/5/19 (300.  
10 days



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019		27 May 2019 15:04 <a href="#">Edit Adj Rpt</a>	<b>S\$6,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>KOK TONG TRANSPORT &amp; ENGINEERING WORKS PTE LTD</b> , Co. Reg. No.: 199904117E									
Main Claimant: <b>SONG JIANHAO</b> , ID: S9111882C									
Vehicle Reg. No.: <b>SJH7945S</b>		Date of Loss: 23/05/2019 23:00 - :59 [128 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D202350C02</b>		Policy/Cover Note No.: <b>DMCVSN18061819011</b>							
Vehicle Reg. No. (Insured): <b>XD7085D</b>		Policy No. (Claimant): <b>5108035404</b>							
		Excess: <b>S\$0.00</b>							
Repairer: <b>Teamwork Garage Pte Ltd (HQ)</b> 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 06/06/2019]									
Driver/Custodian (Insured): <b>THANGARASU CHITRARASU (36 / Male)</b> , NRIC: G7454273K Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJH7945S (SNM19D202350C02)**  
**[XD7085D]**
























































TP

SONG JIANHAO

May 23 2019 11:00PM



















**[KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD]**  
**Teamwork Garage Pte Ltd**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>		<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>
<b>Assessment Reports</b>		1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)
1	24/05/19 17:15	<b>Accident Statement</b>
		1 Load HTM <input type="checkbox"/>
<b>Photos/Images</b>		3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	04/09/19 09:54	<b>General View</b>
2	04/09/19 09:54	<b>General View</b>
3	04/09/19 09:54	<b>General View</b>
4	04/09/19 09:54	<b>General View</b>
5	04/09/19 09:54	<b>General View</b>
6	04/09/19 09:54	<b>General View</b>
7	04/09/19 09:54	<b>General View</b>
8	04/09/19 09:54	<b>General View</b>
9	04/09/19 09:54	<b>General View</b>
10	04/09/19 09:54	<b>General View</b>
11	04/09/19 09:54	<b>General View</b>
12	04/09/19 09:54	<b>General View</b>
13	04/09/19 09:54	<b>General View</b>
14	04/09/19 09:54	<b>General View</b>
15	04/09/19 09:54	<b>General View</b>
16	04/09/19 09:54	<b>General View</b>
17	04/09/19 09:54	<b>General View</b>
18	04/09/19 09:54	<b>General View</b>
19	04/09/19 09:54	<b>General View</b>
20	04/09/19 09:54	<b>General View</b>
21	04/09/19 09:54	<b>General View</b>
22	04/09/19 09:54	<b>General View</b>
23	04/09/19 09:54	<b>General View</b>
24	04/09/19 09:54	<b>General View</b>
25	04/09/19 09:54	<b>General View</b>
26	04/09/19 09:54	<b>General View</b>
27	04/09/19 09:54	<b>General View</b>
28	04/09/19 09:54	<b>General View</b>
29	04/09/19 09:54	<b>General View</b>
30	04/09/19 09:54	<b>General View</b>
31	04/09/19 09:54	<b>General View</b>
32	04/09/19 09:54	<b>General View</b>
33	04/09/19 09:54	<b>General View</b>
34	04/09/19 09:54	<b>General View</b>
35	04/09/19 09:54	<b>General View</b>
36	04/09/19 09:54	<b>General View</b>
37	04/09/19 09:54	<b>General View</b>
38	04/09/19 09:54	<b>General View</b>
39	04/09/19 09:54	<b>General View</b>
40	04/09/19 09:54	<b>General View</b>
		1 Load JPG <input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/09/19 09:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
96	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	04/09/19 09:55	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/05/19 15:02	INSD XD7085D GIA REPORT	 Load PDF	

## Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	24/05/19 17:15	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	24/05/19 17:12	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	24/05/19 17:12	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	24/05/19 17:12	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	24/05/19 17:12	Police Report	 Load JPG	<input checked="" type="checkbox"/>
4	24/05/19 17:12	Police Report	 Load JPG	<input checked="" type="checkbox"/>
5	24/05/19 17:12	Police Report	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009292/T1SD3E2

Date: 27/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18061819011
Claimant Vehicle No :	SJH7945S	Insured Vehicle No :	XD7085D
Date of Loss:	23/05/2019	Nature of Claim: TP	Claim No: SNM19D202350C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJH7945S</b>		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4786003
Reg. Date:	25/08/2008 (Man. Year: 2008)	Chassis No:	MR053ZEE106114947
Colour:	Silver	Odometer:	185828 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,819.68	4,869.39	4,950.29	50.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,210.00	3,040.00	3,170.00	51.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,029.68</b>	<b>7,909.39</b>	<b>8,120.29</b>	<b>50.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,300.00</b>		
<b>(S\$)</b>	16,029.68	6,300.00	9,729.68	60.70
<b>+ GST 7.00/7.00% (S\$)</b>	1,122.08	441.00	681.08	60.70
<b>Nett Amount (S\$)</b>	<b>17,151.76</b>	<b>6,741.00</b>	<b>10,410.76</b>	<b>60.70</b>

## INSPECTION

Date of Assignment:	27/05/2019	
Date Inspected:	28/05/2019 Inspected At:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	10.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJH7945S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	735.30 FL	*635.00 FL
2	1		*BOOTLID EMBLEM - LOGO	Necessary	61.63 FL	*61.63 FL
3	1		*BOOTLID EMBLEM - COROLLA	Necessary	61.40 FL	*61.40 FL
4	1		*BOOTLID EMBLEM - ALTIS	Necessary	63.70 FL	*63.70 FL
5	1		*BOOTLID EMBLEM - 1.6	Necessary	59.10 FL	*59.10 FL
6	1		*BOOTLID LAMP	N/S Not Necessary/O/S Cut	448.50 FL	*224.25 FL
7	1		*BOOTLID LOCK	Not Necessary	159.93 FL	*- FL
8	1		*BOOTLID LOCK STRIKER	Repair	45.15 FL	*- FL
9	1		*BOOTLID RUBBER	Cracked	210.54 FL	*210.54 FL
10	2		*BOOTLID HINGE	Repair	171.10 FL	*- FL
11	1		*BOOTLID OUTER CHROME GARNISH	Not Necessary	210.40 FL	*- FL
12	1		*END PANEL	Bent	685.71 FL	*685.71 FL
13	1		*END PANEL TOP GARNISH	Cracked	251.20 FL	*251.20 FL
14	1		*REAR BUMPER	Deformed	595.53 FL	*595.53 FL
15	1		*REAR BUMPER SIDE RETAINER	N/S NotNecessary/O/S Necessary	120.30 FL	*60.15 FL
16	1		*REAR BUMPER SIDE BRACKET	N/S NotNecessary/O/S Necessary	128.30 FL	*64.15 FL
17	1		*REAR BUMPER REFLECTOR	N/S NotNecessary / O/S Cut	103.50 FL	*51.75 FL
18	1		*REAR BUMPER SPONGE	Cracked	130.21 FL	*130.21 FL
19	2		*REAR BUMPER DAMPER	Not Necessary	207.00 FL	*- FL
20	1		*SPARE TYRE PANEL	Repair	870.55 FL	*- FL
21	1		*SPARE TYRE TOP BOARD	Not Necessary	312.80 FL	*- FL
22	1		*TAILLAMP	N/S NotNecessary / O/S Cracked	954.50 FL	*477.25 FL
23	1		*TAILLAMP PANEL	N/S NotNecessary / O/S Bent	416.30 FL	*208.15 FL
24	1		*TAILLAMP INNER SEAL	N/S NotNecessary/O/S Necessary	42.00 FL	*21.00 FL
25	1		*REAR RH FENDER	Buckled	1,187.70 FL	*1,187.70 FL
26	1		*REAR FENDER INNER TRIM	N/S NotNecessary/ O/S Deformed	1,163.20 FL	*581.60 FL
27	1		*REAR FENDER INNER SHIELD RH	Deformed	171.20 FL	*171.20 FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	171.30 FL	*171.30 FL
29	1		*REAR RH CHASSIS FRAME	Repair	710.34 FL	*- FL
30	1		*REAR EXHAUST SILENCER	Repair	1,055.17 FL	*- FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	51.10 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	178.25 FL	*- FL
33	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
34	1		*SET FRONT FENDER INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
35	1		*SET FRONT FENDER INNER SHIELD CLIP	Necessary	20.00 FS	*10.00 FS
36	1		*SET REAR REVERSE SENSOR	Shorted	400.00 FS	*200.00 FS
37	1		*FLOOR INSULATOR	Not Necessary	150.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		<b>*JOINT SEALANT</b>	Necessary	150.00 FS	*60.00 FS
39	1		<b>*WINDSCREEN SEALANT</b>	Necessary	150.00 FS	*60.00 FS
40	1		<b>*REAR NUMBER PLATE</b>	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,752.91</b>	<b>6,362.52</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>2,933.23</b>	<b>1,493.13</b>
<b>Total Parts (\$\$)</b>	<b>9,819.68</b>	<b>4,869.39</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	New	200.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	30.00
4	REMOVE AND RENEW REAR EXHAUST SILENCER	New	150.00	80.00
5	REMOVE AND RENEW REAR FLOOR INSULATOR	New	150.00	0.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
7	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
8	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	60.00
9	MOUNT VEHICLE ON BENCH FOR REAR CHASSIS REPLACEMENT	New	500.00	0.00
10	PANEL BEATING ON AFFECTED AREAS	New	2,500.00	1,300.00
11	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	1,300.00
12	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>6,210.00</b>	<b>3,040.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >