

21/03/2019

ASS. REC. BY:

REF:

CS/AGI/KCO 9307 At d3n2 Special Instruction:

Survey: Adrian

ASSIGNMENT (Office)

From (Person): Ivy

of AGI

Date/Time: 27/5/2019

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 2821D

Insured: SLG 1260E

at Workshop m/s Premium

Tel: 67689911

of 55 Ubi Rd 1

Policy No:

Claim No: C1000 3173/JW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/5/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27/5

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Intmpt	✓
	SME 2821D-X		
	SLG 1260E-X		
Confirm part by part \$27,335.50 (red: 11626.50, 29%)			

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 Hrs days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME2821D Yr Regn: 2008 SeptType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 SB cc 1395Colour White A/C: Insured / Std / NI / NASp. Reading 10419 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU228V3JA145088Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SRM / STD A/Rim orTyre Size: F: 205/55 R16R: 205/55 R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/05/19Survey held at PremisesDes. of Damages FR / REAR / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

RECEIVED 11 JUL 2019

mv:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report

Final Report

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

450

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 27 May 2019 12:54 PM
To: Admin-D (LKKAuto)
Cc: SUR; Justin Wong
Subject: Claim ref:C10003173/JW || OI- SLG1260E (Grey) TP- SME2821D || Est:0.00 || Premium Automobiles
Attachments: SME 2821 D - 27052019 GIA.pdf

Hi Team,

We would like to arrange TP Survey for SME2821D. Please see below email for reference.

Kindly confirm.

Ivy
Admin Executive, Claims

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may

be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Claims <claims@premiumauto.com.sg>

Sent: Monday, 27 May 2019 10:33 AM

To: Claims <claims@budgetdirect.com.sg>

Cc: Claims <claims@premiumauto.com.sg>

Subject: ACCIDENT INVOLVING SME 2821 D AND YOUR INSURED SMK5620R DATED ON 25/05/2019 VEH IN

Dear All,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

Do take note video is attached in Merimen, Kindly arrange the survey as vehicle is in our compound.

Best Regards,

Diyana

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902211W)

55 Lhi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email and any attachments are confidential and may be subject to legal privilege.

If you are not the intended recipient, please do not print, copy, retransmit, or otherwise use the information contained herein.

If you are not the intended recipient, please do not print, copy, retransmit, or otherwise use the information contained herein.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/05/2019 10:13
Date Of Accident	25/05/2019 14:50
Exact Location Of Accident	PIE (CHANGI) SAFRA TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME2821D
Insured/Policyholder	
Name Of Registered Owner	LEE MAY CHING JUNE
NRIC No	S8120279F
Email Address	JUNEJUNE186@YAHOO.COM
Mobile Phone No	(LOCAL) +65-94877637
Alternative Phone No	OTHERS-94877637

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SPORTSBACK 1.4 TF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800113561
Cover Note Number	

Driver

Name of Driver	MOK LI KUANG
NRIC No	S8226988F
Date Of Birth	14/09/1982
Occupation	INDOOR
Date Of Driving Pass	21/04/2003
Driving Experience	16 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-85226852
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	18D CIRCUIT ROAD #19-230
Postcode	374018
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : MOK CHUCK WHYE GENDER: : MALE
Passenger 2	NAME: : LEE MAY CHING JUNE GENDER: : FEMALE
Passenger 3	NAME: : PUDIQUET LOLITA GENDER: : FEMALE
Passenger 4	NAME: : MOK ZI EN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO DRIVER'S ACCIDENT STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG1260E
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	PRIVATE CAR
Name of Driver	YAN TIAN ZHU
NRIC/Passport Number	S8086367E
Contact Number	
Address	
Postcode	
Insurance Company Name	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKU8805B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMK5620R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: Wahid Khan Shah
NRIC/FIN No.: G 29 84451

Sketch Plan #2

SKETCH PLAN

	- YIN HIN SKU 8805B
	- SMK #10 SMK 5620R
	- SME 2821D
	- SIG 061E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

please refer to the Driver's accident statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: Wally Kwok GENE KONG
NRIC/PIN NO: 0729871432

ACCIDENT STATEMENT

I MOK LI KUANG, NRIC S8226988F WAS
DRIVING VEHICLE SME2821D ALONG PIE WHEN
I WAS REAR ENDED BY VEHICLE SLG1260E
DRIVEN BY TAN TIAN ZHU, LICENSE NUMBER
S8086367E

THIS HAPPENED ABEAM SAFRA TORA PAYOH IN THE
DIRECTION TOWARDS CHANGI AIRPORT AT 1445HRS,
25th MAY 2019.

UPON IMPACT, MY CAR SURGED FORWARD AND
COLLIDED WITH VEHICLE NUMBER SMK5620R
DRIVEN BY CHUA WEI LIANG AARON, LICENSE
NUMBER S9425586D.



25/05/19.



June Lee
27/5/19

ACCIDENT STATEMENT

I MOK LI KUANG, NRIC 58226988F

AUTHORISE LEE MAY CHING JUNE,

NRIC 58120279F TO REPORT THE

CAR ACCIDENT ON 25th MAY 2019

AS I WILL BE LEAVING THE COUNTRY

FROM 26th MAY ONWARDS.

Li Kuang

June Lee
27/5/19

Accident Photo





Name of Policyholder : LEE MAY CHING JUNE (LI MEIQING JUNE)
 Period of Insurance : 25 Sep 2018 To 24 Dec 2019
 Engine No. : CZE824180
 Chassis No. : WAUZZZ8V3JA145088

Vehicle No. : SME2821D
Policy No. : 1800113561
Endorsement No. : 000000000258069
Issued Date : 13 Feb 2019

Make/Model : AUDI A3 Sportback 1.4 TFSI

Engine Capacity/Tonnage : 1,395.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Driver Restriction NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Lots of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 129) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0, Own Damage - \$500, Theft - \$0, Flood Cover - \$0

Section 2

Property Damage - \$0

Winterscreen = \$100

Named Driver and Excess (where applicable)

LEE MAY CHING JUNE (LI MEIQING JUNE) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS⁷(FOR CLAIMS RELATED REPAIRS)

1. Aus Customer Service Center, Add: 55 Ubi Road 1 Singapore 408800 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0504125200

PREMIUM LEASING - AP

781 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159038

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Abstract

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e.: refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0678/2019/DY/TF
Date	:	27-May-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SLG 1260 E**

Budget Direct Insurance

190 Clemenceau Avenue

#03-01

Singapore Shopping Centre

Singapore 239924

Attn: Motor Claims Dept

Tel: 6221 2111

Owner's Name : Ms. Lee May Ching June

Address : Blk 18D Circuit Road
#19-230
Singapore 374018

Telephone : (HP)+65

Type of Claim : Third party Claims

Policy No. : 1800113561

Vehicle No : **SME 2821 D**

Model Code : Audi A3 SB 1.4

Model / Year : Sep-18

Engine No : CZE 824180

Chassis No : WAUZZZ8V3JA145088

Mileage : 10419

Date In : 27-May-19

Liability : -

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 25-May-19

Place of Accident : PIE (Changi) Safra Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2821 D - FRONT

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To remove front fittings, dismantle and renew front bumper, radiator grille, and bonnet assy. Re-organise frontal crash management components. Reinstall all parts removed.	\$ 2,100.00 1250 1400 ✓
3	To respray front bumper and bonnet assy.	\$ 1,500.00 1400 1400 ✓
FRONT -TOTAL LABOUR CHARGES		: <u>\$ 3,960.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2821 D - REAR

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ? ✓
4	To dismantle rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel, rhs tail lamp panel and reinforcement. Repair lhs rear fender. Re-align rear lock carrier and renew damaged panels. Re-organise rear crash management components. Reinstall all parts removed.	1750 without end panel \$ 4,800.00 with end panel. 3500. Panel. ✓
5	To respray rear bumper, rear lid, end panelling, spare tyre housing, lhs rear fender, carry out joint sealer work and cavity waxing.	\$4,400.00 2100 ✓ 2800
6	To remove and renew rear windscreen	S/N \$400.00 ✓✓
7	To carry out diagnostic check.	S/N \$192.00 ✓✓
REAR - TOTAL LABOUR CHARGES		: \$ 10,832.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BONNET <i>Bent</i>	\$ 2,501.00	✓ ✓ 281 2501
2	FRONT BONNET ATTACHMENT PARTS <i>Not New</i>	\$ 149.00	? +
3	FRONT BONNET EDGE PROTECTION <i>new</i>	\$ 25.00	✓ ✓ 24.90
4	FRONT BONNET CATCH <i>new</i>	\$ 81.00	+
5	FRONT BUMPER <i>replaced</i>	\$ 1,698.00	✓ 1698
6	FRONT BUMPER LOWER GRILLE - CENTRE <i>crushed</i>	\$ 146.00	✓ 145.50
7	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 70.00	+
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>replaced</i>	\$ 270.00	✓ 270
9	FOAM FILLER PIECE <i>replaced</i>	\$ 172.00	? ✓ 172
10	RADIATOR GRILLE <i>crushed</i>	\$ 1,301.00	✓ ✓ 1301
11	FRONT REINFORCEMENT BAR <i>Not New</i>	\$ 660.00	? +
12	FRONT REINFORCEMENT COVER <i>replaced</i>	\$ 111.00	? ✓ 111
13	RADIATOR GRILLE BACK PLATE <i>crushed</i>	\$ 174.00	✓ 173.50
14	FRONT NO. PLATE <i>Bent</i>	S/N \$ 40.00	✓ 40
15	SUNDRIES <i>Not New</i>	\$ 300.00	? +
FRONT-TOTAL SPARE PARTS		\$ 7,698.00	
FRONT-TOTAL LABOUR CHARGES		\$ 3,960.00	
FRONT-TOTAL		\$ 11,658.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - REAR

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$	1,708.00	✓ 1708
2	REAR BUMPER STICKY PAD <i>not new</i>	\$	11.00	✓ X
3	REAR BUMPER FIXING PARTS <i>Not New</i>	\$	175.00	? X
4	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	\$	24.00	+ X
5	REAR BUMPER ADAPTER - LH / RH <i>Not New</i>	\$	68.00	? X
6	REAR BUMPER SPOILER <i>Distorted</i>	\$	216.00	✓ 216
7	REAR BUMPER REFLECTOR - LH / RH <i>Lit curled</i>	\$	54.00	26 90
8	REAR BUMPER REINFORCEMENT <i>Bent</i>	\$	522.00	✓ 522
9	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$	120.00	+ X
10	REAR BUMPER BRACKET - LH / RH <i>Not New</i>	\$	51.00	? X
11	REAR BUMPER WIRING SET <i>new</i>	\$	472.00	+ X
12	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4 \$	924.00	462. ✓
13	REAR LID <i>Dented</i>	\$	1,864.00	✓ ✓
14	REAR LID ATTACHMENT PARTS <i>Not New</i>	\$	267.00	? X
15	REAR LID HINGE <i>new</i>	2 \$	275.00	+ X
16	REAR LID STOPPER <i>new</i>	\$	34.00	+ X
17	REAR LID ABSORBER <i>Not New</i>	\$	93.00	+ X
18	REAR LID BALL STUD <i>new</i>	2 \$	37.00	? 36.40
19	REAR LID GASKET <i>new</i>	\$	185.00	✓ 184.50
20	REAR LID LOCK <i>Jammed</i>	\$	164.00	✓ 163.50
SUB REAR - TOTAL SPARE PARTS		:	\$ 7,264.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SME 2821 D - REAR

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
21	REAR LID LOCK COVER	Not nec	\$ 7.00	? X
22	REAR LID PUSH BOTTOM	nec	\$ 167.00	+ X
23	REAR LID ADHESIVE	nec	\$ 18.00	✓ 17.40
24	REAR LID LOCK STRIKER	Not nec	\$ 78.00	? X
25	AUDI EMBLEM	2 } Nec	\$ 113.00	✓ 112.50
26	A3 EMBLEM		\$ 87.00	✓ 86.60
27	TFSI EMBLEM		\$ 87.00	✓ 86.60
28	REAR LID TAIL LIGHT - LH / RH	Not nec Not nec	\$ 1,500.00	800. X
29	REAR LID NO. PLATE LIGHT	nec	2 \$ 191.00	+ X
30	REAR WINDSCREEN	nec	\$ 742.00	✓ 741.50
31	PRIMER	nec	\$ 19.00	✓ 18.60
32	REAR LID SPOILER FORM STRIPS	nec	\$ 127.00	? X
33	REAR LID SPOILER ATTACHMENT PARTS	Not nec	\$ 152.00	? X
34	REAR WINDSCREEN ADHESIVE	nec	\$ 25.00	✓ 24.20
35	REAR CROSS PANEL	Dented	\$ 224.00	? 223.50
36	REAR CROSS PANEL REINFORMCENT	Dented	\$ 669.00	? 669
37	REAR NO. PLATE WITH HOLDER	Dented	S/N \$ 50.00	✓ 50
38	REAR WINDSCREEN SEALANT	nec	S/N \$ 200.00	✓ 200
39	ACRYLIC SEALANT	Nec	S/N \$ 180.00	? ✓ 180
40	CAVITY WAX	Nec	S/N \$ 140.00	? ✓ 140
41	STONE CHIP TREATMENT	Nec	S/N \$ 180.00	? ✓ 180
42	SUNDRIES	nec	\$ 400.00	? ✓ 149.50
REAR-TOTAL SPARE PARTS		:	\$ 12,320.00	
REAR-TOTAL LABOUR CHARGES		:	\$ 10,832.00	
GRAND TOTAL (FRONT + REAR)		:	\$ 34,810.00	36953.90

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian, hiny
Surveyed Date : 29/05/19. ✓
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised,

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(Without end Panel)

Front : 4 Days.

Rear (End Panel) : 8 Days

Without End Panel : 5 Days

9 Days
12 Days
(End Panel)

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Budget Direct Insurance
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
Singapore 239924
Attn: Motor Claims Dept
Tel: 6221 1111

Estimate No. PA/TP/0678/2019/DY/TF
Date 10-Jun-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SME 2821 D
Model No Audi A3 SB 1.4

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	Taillight inner RHS	\$ 800.00	✓
---	---------------------	-----------	---

over
[Signature] 11/6/19

\$ 800.00

LABORS

TOTAL \$ 800.00

For Premium Automobiles Pte Ltd

[Signature]

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Budget Direct Insurance
190 Clemenceau Avenue
#03-01 Singapore Shopping Centre
Singapore 239924
Attn: Motor Claims Dept
Tel: 6221 1111

Estimate No. PA/TP/0678/2019/DY/TF
Date 3-Jun-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SME 2821 D
Model No Audi A3 SB 1.4

Quantity	Description	Unit Price	Amount
Parts			
1	Bonnet catch hook / BT	\$ 58.00	57.20
2	Radiator air guide LHS / BR	\$ 22.00	21.40
3	End panel connecting plate RHS / RT	\$ 37.00	36.40
4	Trim for end panelling / BR	\$ 141.00	140.50
5	Reverse camera / BR	\$ 1,230.00	688
			\$ 1,488.00

LABORS

TOTAL \$ 1,488.00

For Premium Automobiles Pte Ltd


Authorized Signature

Steve
3/6/19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - FRONT

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	FRONT BONNET <i>dent</i>	\$	2,501.00	✓
2	FRONT BONNET ATTACHMENT PARTS ?	\$	149.00	?
3	FRONT BONNET EDGE PROTECTION <i>new</i>	\$	25.00	✓
4	FRONT BONNET CATCH <i>new</i>	\$	81.00	x
5	FRONT BUMPER <i>dent</i>	\$	1,698.00	✓
6	FRONT BUMPER LOWER GRILLE - CENTRE <i>crack</i>	\$	146.00	✓
7	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$	70.00	x
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>dent</i>	\$	270.00	✓
9	FOAM FILLER PIECE ?	\$	172.00	?
10	RADIATOR GRILLE <i>crack</i>	\$	1,301.00	✓
11	FRONT REINFORCEMENT BAR ?	\$	660.00	?
12	FRONT REINFORCEMENT COVER ?	\$	111.00	?
13	RADIATOR GRILLE BACK PLATE <i>crack</i>	\$	174.00	✓
14	FRONT NO. PLATE <i>Bent</i>	S/N \$	40.00	✓
15	SUNDRIES ?	\$	300.00	?
FRONT-TOTAL SPARE PARTS		:	\$ 7,698.00	
FRONT-TOTAL LABOUR CHARGES		:	\$ 3,960.00	
FRONT-TOTAL		:	\$ 11,658.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$ 1,708.00	✓
2	REAR BUMPER STICKY PAD <i>new</i>	\$ 11.00	✓
3	REAR BUMPER FIXING PARTS ?	\$ 175.00	?
4	REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i>	\$ 24.00	+
5	REAR BUMPER ADAPTER - LH / RH ?	\$ 68.00	?
6	REAR BUMPER SPOILER <i>Distorted</i>	\$ 216.00	✓
7	REAR BUMPER REFLECTOR - LH / RH	\$ 54.00	
8	REAR BUMPER REINFORCEMENT <i>Bent</i>	\$ 522.00	✓
9	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	\$ 120.00	+
10	REAR BUMPER BRACKET - LH / RH ?	\$ 51.00	?
11	REAR BUMPER WIRING SET <i>new</i>	\$ 472.00	+
12	REAR BUMPER SENSOR <i>2 pieces damaged</i>	4 \$ 924.00	462
13	REAR LID <i>Dented</i>	\$ 1,864.00	✓
14	REAR LID ATTACHMENT PARTS ?	\$ 267.00	?
15	REAR LID HINGE <i>new</i>	2 \$ 275.00	+
16	REAR LID STOPPER <i>new</i>	\$ 34.00	+
17	REAR LID ABSORBER <i>Not new</i>	\$ 93.00	+
18	REAR LID BALL STUD ?	2 \$ 37.00	?
19	REAR LID GASKET <i>new</i>	\$ 185.00	✓
20	REAR LID LOCK <i>Jammed</i>	\$ 164.00	✓

SUB REAR - TOTAL SPARE PARTS

: \$ 7,264.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID LOCK COVER ?	\$ 7.00	✓
22	REAR LID PUSH BOTTOM New	\$ 167.00	✓
23	REAR LID ADHESIVE New	\$ 18.00	✓
24	REAR LID LOCK STRIKER ?	\$ 78.00	?
25	AUDI EMBLEM	\$ 113.00	✓
26	A3 EMBLEM	\$ 87.00	✓
27	TFSI EMBLEM	\$ 87.00	✓
28	REAR LID TAIL LIGHT - LH / RH new RH could	\$ 1,600.00	800
29	REAR LID NO. PLATE LIGHT New	2 \$ 191.00	✓
30	REAR WINDSCREEN New	\$ 742.00	✓
31	PRIMER New	\$ 19.00	✓
32	REAR LID SPOILER FORM STRIPS ?	\$ 127.00	?
33	REAR LID SPOILER ATTACHMENT PARTS ?	\$ 152.00	?
34	REAR WINDSCREEN ADHESIVE New	\$ 25.00	✓
35	REAR CROSS PANEL ?	\$ 224.00	?
36	REAR CROSS PANEL REINFORMCENT ?	\$ 669.00	?
37	REAR NO. PLATE WITH HOLDER Detach	S/N \$ 50.00	✓
38	REAR WINDSCREEN SEALANT New	S/N \$ 200.00	✓
39	ACRYLIC SEALANT ?	S/N \$ 180.00	?
40	GRAVITY WAX ?	S/N \$ 140.00	?
41	STONE CHIP TREATMENT ?	S/N \$ 180.00	?
42	SUNDRIES	\$ 400.00	?
REAR-TOTAL SPARE PARTS		\$ 12,320.00	
REAR-TOTAL LABOUR CHARGES		\$ 10,832.00	
GRAND TOTAL (FRONT + REAR)		\$ 34,810.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0678/2019/DY/TF
Date : 27-May-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no. : **SLG 1260 E**

Budget Direct Insurance

190 Clemenceau Avenue

#03-01

Singapore Shopping Centre

Singapore 239924

Hi Adrian

12 days exclude 2 Sundays 1 PH

jb 24 Jun 19

Attn: Motor Claims Dept

Tel: 6221 2111

Owner's Name : Ms. Lee May Ching June

Address : Blk 18D Circuit Road

#19-230

Singapore 374018

Telephone : (HP)+65

Type of Claim : Third party Claims

Policy No. : 1800113561

Vehicle No : **SME 2821 D**

Model Code : Audi A3 SB 1.4

Model / Year : Sep-18

Engine No : CZE 824180

Chassis No : WAUZZZ8V3JA145088

Mileage : 10419

Date In : 27-May-19

Liability : -

Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 25-May-19

Place of Accident : PIE (Changi) Safra Toa Payoh

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2821 D - FRONT

S/n	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To remove front fittings, dismantle and renew front bumper, radiator grille, and bonnet assy. Re-organise frontal crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,400.00
3	To respray front bumper and bonnet assy.	\$ 1,500.00	\$ 1,400.00
FRONT -TOTAL LABOUR CHARGES		: \$ 3,960.00	\$ 3,160.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2821 D - REAR

S/n	Nature of Jobs	Estimated Charges	
	<i>front labour c/f</i>	\$	3,160.00
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	\$ 480.00
4	To dismantle rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel, rhs tail lamp panel and reinforcement. Repair lhs rear fender. Re-align rear lock carrier and renew damaged panels. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,800.00	\$ 3,500.00
5	To respray rear bumper, rear lid, end panelling, spare tyre housing, lhs rear fender, carry out joint sealer work and cavity waxing. (Added LHS rear fender \$700.00)	\$4,400.00	\$ 2,800.00
6	To remove and renew rear windscreen	S/N \$400.00	\$ 400.00
7	To carry out diagnostic check.	S/N \$384.00	\$ 192.00
REAR - TOTAL LABOUR CHARGES		\$ 14,984.00	\$ 11,092.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - FRONT

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BONNET	\$ 2,501.00	\$ 2,501.00
2	FRONT BONNET ATTACHMENT PARTS	\$ 149.00	
3	FRONT BONNET EDGE PROTECTION	\$ 25.00	\$ 24.90
4	FRONT BONNET CATCH	\$ 81.00	
5	FRONT BUMPER	\$ 1,698.00	\$ 1,698.00
6	FRONT BUMPER LOWER GRILLE - CENTRE	\$ 146.00	\$ 145.50
7	FRONT BUMPER GUIDE SECTION - LH / RH	\$ 70.00	
8	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 270.00	\$ 270.00
9	FOAM FILLER PIECE	\$ 172.00	\$ 172.00
10	RADIATOR GRILLE	\$ 1,301.00	\$ 1,301.00
11	FRONT REINFORCEMENT BAR	\$ 660.00	
12	FRONT REINFORCEMENT COVER	\$ 111.00	\$ 111.00
13	RADIATOR GRILLE BACK PLATE	\$ 174.00	\$ 173.50
14	FRONT NO. PLATE	S/N \$ 40.00	\$ 40.00
15	SUNDRIES	\$ 300.00	
FRONT-TOTAL SPARE PARTS		\$ 7,698.00	\$ 6,436.90
FRONT-TOTAL LABOUR CHARGES		\$ 3,960.00	\$ 3,160.00
FRONT-TOTAL		\$ 11,658.00	\$ 9,596.90

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2821 D - REAR

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
	Front materials c/f	\$	6,436.90
1	REAR BUMPER	\$ 1,708.00	\$ 1,708.00
2	REAR BUMPER STICKY PAD	\$ 11.00	
3	REAR BUMPER FIXING PARTS	\$ 175.00	
4	REAR BUMPER LOCKING MECHANISM - LH / RH	\$ 24.00	
5	REAR BUMPER ADAPTER - LH / RH	\$ 68.00	
6	REAR BUMPER SPOILER	\$ 216.00	\$ 216.00
7	REAR BUMPER REFLECTOR - LH / RH	\$ 54.00	\$ 26.90
8	REAR BUMPER REINFORCEMENT	\$ 522.00	\$ 522.00
9	REAR BUMPER GUIDE SECTION - LH / RH	\$ 120.00	
10	REAR BUMPER BRACKET - LH / RH	\$ 51.00	
11	REAR BUMPER WIRING SET	\$ 472.00	
12	REAR BUMPER SENSOR	4 \$ 924.00	\$ 462.00
13	REAR LID	\$ 1,864.00	\$ 1,864.00
14	REAR LID ATTACHMENT PARTS	\$ 267.00	
15	REAR LID HINGE	2 \$ 275.00	
16	REAR LID STOPPER	\$ 34.00	
17	REAR LID ABSORBER	\$ 93.00	
18	REAR LID BALL STUD	2 \$ 37.00	\$ 36.40
19	REAR LID GASKET	\$ 185.00	\$ 184.50
20	REAR LID LOCK	\$ 164.00	\$ 163.50
SUB REAR - TOTAL SPARE PARTS		\$ 7,264.00	\$ 11,620.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SME 2821 D - REAR

S/N	Parts Description	Damaged Parts & Prices		
		S/Nett	Remark	
			\$	11,620.20
		c/l		
21	REAR LID LOCK COVER	\$ 7.00		
22	REAR LID PUSH BOTTOM	\$ 167.00		
23	REAR LID ADHESIVE	\$ 18.00	\$ 17.40	
24	REAR LID LOCK STRIKER	\$ 78.00		
25	AUDI EMBLEM	\$ 113.00	\$ 112.50	
26	A3 EMBLEM	\$ 87.00	\$ 86.60	
27	TFSI EMBLEM	\$ 87.00	\$ 86.60	
28	REAR LID TAIL LIGHT - LH / RH	\$ 1,600.00		
29	REAR LID NO. PLATE LIGHT	2 \$ 191.00		
30	REAR WINDSCREEN	\$ 742.00	\$ 741.50	
31	PRIMER	\$ 19.00	\$ 18.60	
32	REAR LID SPOILER FORM STRIPS	\$ 127.00		
33	REAR LID SPOILER ATTACHMENT PARTS	\$ 152.00		
34	REAR WINDSCREEN ADHESIVE	\$ 25.00	\$ 24.20	
35	REAR CROSS PANEL	\$ 224.00	\$ 223.50	
36	REAR CROSS PANEL REINFORMCENT	\$ 669.00	\$ 669.00	
37	REAR NO. PLATE WITH HOLDER	S/N \$ 50.00	\$ 50.00	
38	REAR WINDSCREEN SEALANT	S/N \$ 200.00	\$ 200.00	
39	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00	
40	CRAVITY WAX	S/N \$ 140.00	\$ 140.00	
41	STONE CHIP TREATMENT	S/N \$ 180.00	\$ 180.00	
42	Added parts - see attached	\$ 1,488.00	\$ 943.90	
43	Added parts - see attached	\$ 800.00	\$ 800.00	
45	SUNDRIES	\$ 400.00	\$ 149.50	
	REAR-TOTAL SPARE PARTS	\$ 12,320.00	\$ 16,243.50	
	REAR-TOTAL LABOUR CHARGES	\$ 14,984.00	\$ 11,092.00	
	GRAND TOTAL (FRONT + REAR)	\$ 38,962.00	\$ 27,335.50	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Budget Direct Insurance 190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924 Attn: Motor Claims Dept Tel: 6221 1111		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0678/2019/DY/TF 3-Jun-19 Glory Tan 1 of 1 SME 2821 D Audi A3 SB 1.4
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Bonnet catch hook	\$ 58.00	\$ 57.20
2	Radiator air guide LHS	\$ 22.00	\$ 21.40
3	End panel connecting plate RHS	\$ 37.00	\$ 36.80
4	Trim for end panelling	\$ 141.00	\$ 140.50
5	Reverse camera	\$ 1,230.00	\$ 688.00
		\$ 1,488.00	\$ 943.90
<u>LABORS</u>			
	TOTAL	\$ 1,488.00	\$ 943.90

BT
BR
BT
BR
BR

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Budget Direct Insurance 190 Clemenceau Avenue #03-01 Singapore Shopping Centre Singapore 239924 Attn: Motor Claims Dept Tel: 6221 1111		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0678/2019/DY/TF 10-Jun-19 Glory Tan 1 of 1 SME 2821 D Audi A3 SB 1.4
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Taillight inner RHS	\$ 800.00	\$ 800.00
		\$ 800.00	\$ 800.00
<u>LABORS</u>			
	TOTAL	\$ 800.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19009307/Atd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 16-07-2019 Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLG 1260E	Veh. Inspected	SME 2821D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003173/JW	Excess (\$)	0.00	
Assign From	IVY	Assign Date	27/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A3 SB	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WAUZZZ8V3JA145088	Colour	WHITE	
Odometer	10419	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Front Tyre	205/55 R16	GOODYEAR	6 mm	
R/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
L/H Rear Tyre	205/55 R16	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2019	Inspection Date	29/05/2019	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 2821D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET (SN)	DENTED	2,501.00	2,501.00
1	FRONT BONNET ATTACHMENT PARTS (SN)	NOT NECESSARY	149.00	-
1	FRONT BONNET EDGE PROTECTION (SN)	NECESSARY	25.00	24.90
1	FRONT BONNET CATCH (SN)	NOT NECESSARY	81.00	-
1	FRONT BUMPER (SN)	DEFORMED	1,698.00	1,698.00
1	FRONT BUMPER LOWER GRILLE-CENTRE (SN)	CRACKED	146.00	145.50
2	FRONT BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	70.00	-
1	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE (SN)	DEFORMED	270.00	270.00
1	FOAM FILLER PIECE (SN)	DEFORMED	172.00	172.00
1	RADIATOR GRILLE (SN)	CRACKED	1,301.00	1,301.00
1	FRONT REINFORCEMENT BAR (SN)	NOT NECESSARY	660.00	-
1	FRONT REINFORCEMENT COVER (SN)	DEFORMED	111.00	111.00
1	RADIATOR GRILLE BACK PLATE (SN)	CRACKED	174.00	173.50
1	FRONT NO PLATE (SN)	BENT	40.00	40.00
1	SUNDRIES (SN)	NOT NECESSARY	300.00	-
1	REAR BUMPER (SN)	DISTORTED	1,708.00	1,708.00
1	REAR BUMPER STICKY PAD (SN)	NOT NECESSARY	11.00	-
1	REAR BUMPER FIXING PARTS (SN)	NOT NECESSARY	175.00	-
2	REAR BUMPER LOCKING MECHANISM-LH/RH (SN)	NOT NECESSARY	24.00	-
2	REAR BUMPER ADAPTER-LH/RH (SN)	NOT NECESSARY	68.00	-
1	REAR BUMPER SPOILER (SN)	DISTORTED	216.00	216.00
2	REAR BUMPER REFLECTOR-LH/RH (SN)	N/S CRACKED	54.00	26.90
1	REAR BUMPER REINFORCEMENT (SN)	BENT	522.00	522.00
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	120.00	-
2	REAR BUMPER BRACKET-LH/RH (SN)	NOT NECESSARY	51.00	-
1	SET REAR BUMPER WIRING (SN)	NOT NECESSARY	472.00	-
4	REAR BUMPER SENSOR (SN)	DAMAGED (2 PCS ONLY)	924.00	462.00
1	REAR LID (SN)	DENTED	1,864.00	1,864.00
1	REAR LID ATTACHMENT PARTS (SN)	NOT NECESSARY	267.00	-
2	REAR LID HINGE (SN)	NOT NECESSARY	275.00	-
1	REAR LID STOPPER (SN)	NOT NECESSARY	34.00	-
1	REAR LID ABSORBER (SN)	NOT NECESSARY	93.00	-

Report Ref No. CS/AGI19009307/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR LID BALL STUD (SN)	NECESSARY	37.00	36.40
1	REAR LID GASKET (SN)	NECESSARY	185.00	184.50
1	REAR LID LOCK (SN)	JAMMED	164.00	163.50
1	REAR LID LOCK COVER (SN)	NOT NECESSARY	7.00	-
1	REAR LID PUSH BOTTOM (SN)	NOT NECESSARY	167.00	-
1	REAR LID ADHESIVE (SN)	NECESSARY	18.00	17.40
1	REAR LID LOCK STRIKER (SN)	NOT NECESSARY	78.00	-
1	AUDI EMBLEM (SN)	NECESSARY	113.00	112.50
1	A3 EMBLEM (SN)	NECESSARY	87.00	86.60
1	TFSI EMBLEM (SN)	NECESSARY	87.00	86.60
2	REAR LID TAIL LIGHT-LH/RH (SN)	NOT NECESSARY	1,600.00	-
2	REAR LID NO PLATE LIGHT (SN)	NOT NECESSARY	191.00	-
1	REAR WINDSCREEN (SN)	NECESSARY	742.00	741.50
1	PRIMER (SN)	NECESSARY	19.00	18.60
1	REAR LID SPOILER FORM STRIPS (SN)	NOT NECESSARY	127.00	-
1	REAR LID SPOILER ATTACHMENT PARTS (SN)	NOT NECESSARY	152.00	-
1	REAR WINDSCREEN ADHESIVE (SN)	NECESSARY	25.00	24.20
1	REAR CROSS PANEL (SN)	DENTED	224.00	223.50
1	REAR CROSS PANEL REINFORCEMENT (SN)	DENTED	669.00	669.00
1	REAR NO PLATE WITH HOLDER (SN)	DENTED	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	200.00	200.00
1	ACRYLIC SEALANT (SN)	NECESSARY	180.00	180.00
1	CAVITY WAX (SN)	NECESSARY	140.00	140.00
1	STONE CHIP TREATMENT (SN)	NECESSARY	180.00	180.00
1	SUNDRIES (SN)	NECESSARY	400.00	149.50
1	BONNET CATCH HOOK (ADDITIONAL)(SN)	BENT	57.20	57.20
1	RADIATOR AIR GUIDE LHS (ADDITIONAL)(SN)	BROKEN	21.40	21.40
1	END PANEL CONNECTING PLATE RHS (ADDITIONAL)(SN)	BENT	36.80	36.80
1	TRIM FOR END PANELLING (ADDITIONAL)(SN)	BROKEN	140.50	140.50
1	REVERSE CAMERA (ADDITIONAL)(SN)	BROKEN	688.00	688.00
1	TAILLIGHT INNER RHS (ADDITIONAL)(SN)	CRACKED	800.00	800.00
			22,161.90	16,243.50
	LABOUR			
	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.		360.00	360.00

Report Ref No. CS/AGI19009307/Atd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE FRONT FITTINGS,DISMANTLE AND RENEW FRONT BUMPER,RADIATOR GRILLE,AND BONNET ASSY.RE-ORGANISE FRONTAL CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		2,100.00	1,400.00
	TO RESPRAY FRONT BUMPER AND BONNET ASSY.		1,500.00	1,400.00
	TO REMOVE AND TRANSFER REAR PARKING AID,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.		280.00	280.00
	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.		280.00	280.00
	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS.		480.00	480.00
	TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND REWELD REAR OUTER,INNER AND LOWER REAR CROSS PANEL,RHS TAIL LAMP PANEL AND REINFORCEMENT.REPAIR LHS REAR FENDER.RE-ALIGN REAR LOCK CARRIER AND RENEW DAMAGED PANELS.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.		4,800.00	3,500.00
	TO RESPRAY REAR BUMPER,REAR LID,END PANELLING,SPARE TYRE HOUSING,LHS REAR FENDER,CARRY OUT JOINT SEALER WORK AND CAVITY WAXING.		4,400.00	2,800.00
	TO REMOVE AND RENEW REAR WINDSCREEN.		400.00	400.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			14,792.00	11,092.00
GRAND TOTAL			36,953.90	27,335.50
RECOMMENDED COST OF REPAIRS				27,335.50

Report Ref No. CS/AGI19009307/Atd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.