

22/03/2012

ASS. REC. BY:

REF:

CS/CTI19009308/Jtd302

Special Instruction:

Surveyor: HWL JirASSIGNMENT (Office)From (Person): Chong Boon Sen of CTI Date/Time: 27/5/2019

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLM 8107M Insured: GBC 8232Eat Workshop m/s CTS Automobile Tel: 62192098of 38 Doodlands Ind Park El #07-17Policy No: _____ Claim No: SNM190202369

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/05/19
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 27/5 Person Contacted: Me Tee Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate ()
	<u>SLM 8107M-X</u>	
	<u>GBC 8232E-X</u>	

Huse Jie

REF: CT1

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s 38 woodland lnd E1

of #07-17

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SLM 8107M Yr Regn: 12 Apr 2017

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 42374 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRHFC5650GT0014143

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 26/5/19 D.O.I. 28/5/19

Survey held at CYS Auto

Des. of Damages: (Fr) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Confirmed P/P #6065-721 5 days of repair. (Red: 2232-92; 26%)

RECEIVED: 13 JUN 2019

Date/Time. File Pass to?

☐ : Preli. Report

1) 12/6 Typist

☒ : Final Report

Date/Time. File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + PS. SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$) 6065.72

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

TOTAL

220

Nivitha (LKK Auto)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 27 May 2019 3:21 PM
To: 'Chong Boon Sen'
Cc: SUR; assignments
Subject: RE: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY / OUR REF: SNM19D202369

Dear Boon Sen,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]
Sent: Monday, 27 May 2019 2:28 PM
To: CYSAUTO <cysauto@singnet.com.sg>
Cc: sur@lkkauto.com; assignments@lkkauto.com
Subject: RE: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY / OUR REF: SNM19D202369

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: CYSAUTO [mailto:cysauto@singnet.com.sg]

Sent: Monday, 27 May, 2019 2:27 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: sur@lkkauto.com

Subject: RE: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY /
OUR REF: SNM19D202369

Dear Mr Chong Boon Sen,

WITHOUT PREJUDICE

We would like request Mr. Chua Wei Jie survey this car. Thanks

Dear admin,

Kindly arrange TP survey at 38 Woodlands Industrial Park E1 #07-17 S(757700). Thanks

Warm regards,

Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

From: Chong

Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, May 27, 2019 2:21 PM

To: cysauto@singnet.com.sg

Subject: RE: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY /
OUR REF: SNM19D202369

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG

SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 27 May, 2019 2:13 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; cysauto@singnet.com.sg

Cc: Angie Foo <angie.foo@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Subject: FW: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY

Dear Boon Sen,

Please conduct PRS on behalf of Elaine – TP: SLM8107M (SNM19D202369) soonest possible.

File with Boon Sen – 63896171

OIC – Elaine – 63896530

From: CYSAUTO [<mailto:cysauto@singnet.com.sg>]

Sent: Monday, 27 May 2019 1:25 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SLM8107M YOUR INSURED: GBC8232E - KINDLY ARRANGE TP SURVEY & CHECK LIABILITY

Our Ref: SLM8107M

Your Insured: GBC8232E

WITHOUT PREJUDICE

Dear Sirs,

ACCIDENT INVOLVING SLM8107M AND GBC8232E AT BLK. 627 HOUGANG AVE 8 OPEN AIR CARPARK ON 26 MAY 2019

Attached herewith estimate and GIA report for your attention. Kindly arrange TP survey at 38 Woodlands Industrial Park E1 #07-17 S(757700) and let us have your list of 10 motor surveyors. Thanks

Dear officer,

Kindly check liability for this claim. Thanks and look forward for your reply.

Warm regards,
Ms Tee Wee Sin



CYS AUTOMOBILE SERVICES PTE LTD

38 Woodlands Industrial Park E1 #07-17 S(757700)

Tel: 62192098 Fax: 62192096

Email: cysauto@singnet.com.sg

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

7351D

Vehicle Details

Vehicle No.:

SLM8107M

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 May 2019

Vehicle Make:

HONDA

Vehicle Model:

CIVIC 1.6 VTI CVT

Primary Colour:

Grey

Manufacturing Year:

2017

Engine No.:

R16B21601723

Chassis No.:

MRHFC5650GT001413

Maximum Power Output:

92.0 kW (123 bhp)

Open Market Value:

\$20,480.00

Original Registration Date:

12 Apr 2017

First Registration Date:

12 Apr 2017

Transfer Count:

1

Actual ARF Paid:

\$20,672.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Apr 2027

PARF Rebate Amount:

\$15,504.00

Intended COE Rebate Details

COE Expiry Date:

11 Apr 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$51,765.00

COE Rebate Amount:

\$40,707.00

Total Rebate Amount:

\$56,211.00

The information contained herein is correct as at 27 May 2019

OK



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO: 20-0105041-E

MR WOON LU FONG
11 ST. HELIER'S AVE
SINGAPORE 550808

POLICY NO :
YOUR REF :
OUR REF :
VEHICLE NO :
MAKE/MODEL :
DATE OF ACCIDENT :
THIRD PARTY CLAIM
GBC 8232 E (CHINA)
TP 6031
SLM 8107 M
HONDA CIVIC 1.6
26.05.19

DATE : 27.05.19

SURVEY BY

1 PC BONNET	BUC /	42.00	\$S	681.50
2 PCS BONNET HINGES	BT /			84.00
1 PC FRONT GRILLE	CRA /			155.50
1 PC FRONT GRILLE EMBLEM	rec /			27.40
1 PC FRONT GRILLE CHROME	CRA /			151.80
2 PCS HEADLAMP ASSY	CRA /	1,155.00		2,310.00
1 PCS HEADLAMP TOP CHROME	SCR /	150.50 X		301.00 X
2 PCS HEADLAMP LOWER RETAINERS	CRA /	28.90		57.80
1 PC FRONT BUMPER	DEF /			659.50
1 PC FRONT BUMPER REINFORCEMENT	nnx			385.80 X
2 PCS FRONT BUMPER SIDE RETAINERS	DEF /	21.00		42.00
1 PC FRONT BUMPER TOP RUBBER				29.80
1 PC FRONT BUMPER BEAM	BUC /			335.80
1 PC FRONT SUPPORT PANEL	Repair X			560.50 X
1 PC FRONT SUPPORT PANEL TOP GARNISH	nnx			37.80 X
1 PC FRONT SUPPORT PANEL SIDE RUBBER RH	nnx			19.00 X
1 PC AIR-CON CONDENSER	BT /			754.40
1 PC AIR-CON DISCHARGE HOSE	BT /			151.40
1 PC RADIATOR ASSY	nnx			1,100.80 X

LESS 20%

\$S 7,845.80
1,569.16
\$S 6,276.64

1 PC FRONT NO. PLATE	SCR /	\$S	45.00	S/NETT
1 SET FRONT BUMPER CLIPS	rec /		28.00	"
1 SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	rec /		20 39.00	"
		\$S	112.00	

TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS

\$S 120.00 50

TO CHECK WIRING FUNCTION

30.00 /

TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL

60.00 40

LABOUR CHARGES

800.00 700

TO PUTTY AND SPRAY PAINTING CHARGES

900.00 800

Total - \$6065.72/-

\$S 8,298.64

SIN DOLLARS: EIGHT THOUSAND TWO HUNDRED NINETY-EIGHT AND CENTS SIXTY-FOUR ONLY

YOUR FAITHFULLY,

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

CYS AUTOMOBILE SERVICES PTE LTD Tel: 6219 2096 Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

Hwee Jia-LK
28/5/19
P/P 5 days.

進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

MR WOON LU FONG
11 ST. HELIER'S AVE
SINGAPORE 550808

POLICY NO	:	THIRD PARTY CLAIM
YOUR REF	:	GBC 8232 E (CHINA)
OUR REF	:	TP 6031
VEHICLE NO	:	SLM 8107 M
MAKE/MODEL	:	HONDA CIVIC 1.6
DATE OF ACCIDENT	:	26.05.19

SURVEY BY

DATE : 27.05.19

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE
1	PC BONNET		\$81.50
2	PCS BONNET HINGES	42.00	84.00
1	PC FRONT GRILLE		155.50
1	PC FRONT GRILLE EMBLEM		27.40
1	PC FRONT GRILLE CHROME		151.80
2	PCS HEADLAMP ASSY	1,155.00	2,310.00
1	PCS HEADLAMP TOP CHROME	150.50	150.50
2	PCS HEADLAMP LOWER RETAINERS	28.90	57.80
1	PC FRONT BUMPER		659.50
1	PC FRONT BUMPER REINFORCEMENT		385.80
2	PCS FRONT BUMPER SIDE RETAINERS	21.00	42.00
1	PC FRONT BUMPER TOP RUBBER		29.80
1	PC FRONT BUMPER BEAM		335.80
1	PC FRONT SUPPORT PANEL		37.80
1	PC FRONT SUPPORT PANEL TOP GARNISH		19.00
1	PC FRONT SUPPORT PANEL SIDE RUBBER RH		754.40
1	PC AIR-CON CONDENSER		151.40
1	PC AIR-CON DISCHARGE HOSE		1,100.80
1	PC RADIATOR ASSY		\$7,845.80
	LESS 20%		1,569.16
			\$6,276.64

1	PC FRONT NO. PLATE	SCR/	93.00	SS	45.00	S/NETT
1	SET FRONT BUMPER CLIPS	nee/			28.00	"
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	nee/			20.00	"
				SS	112.00	

TO REMOVE AIR-CON CONDENSER, PIPE, DRIER AND TOP-UP AIR-CON GAS S\$ 120.00 50

TO CHECK WIRING FUNCTION	30.00	✓
--------------------------	-------	---

TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL 60.00 40

LABOUR CHARGES	1620.00	800.00	700
----------------	---------	--------	-----

TO PUTTY AND SPRAY PAINTING CHARGES	900.00	807
-------------------------------------	--------	-----

P/P - 86186.12

SS	8,298.64
----	----------

SIN DOLLARS: EIGHT THOUSAND TWO HUNDRED NINETY-EIGHT AND CENTS SIXTY-FOUR ONLY

YOUR FAITHFULLY

Huee Jia - Uk
28/5/19
P/P Solays.

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19009308/JTD3N2

Date: 18/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30740018000
Claimant Vehicle No :	SLM8107M	Insured Vehicle No :	GBC8232E
Date of Loss:	26/05/2019	Nature of Claim:	TP
		Claim No:	SNM19D202369C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM8107M	Engine No:	R16B21601723
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC5650GT001413
Reg. Date:	12/04/2017 (Man. Year: 2017)	Odometer:	42374 km
Colour:	Grey		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,388.64	4,445.72	1,942.92	30.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	1,620.00	290.00	15.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,298.64	6,065.72	2,232.92	26.91
+ GST 7.00/7.00% (S\$)	580.90	424.60	156.30	26.91
Nett Amount (S\$)	8,879.54	6,490.32	2,389.22	26.91

INSPECTION

Date of Assignment: 12/06/2019

Date Inspected: 28/05/2019 Inspected At:

CYS Automobile Services Pte Ltd
(Woodlands)
38 Woodlands Industrial Park East 1,
#07-17, Admiralty Industrial Park
Singapore 757700

Estimated Period of Repair: 5.0 days

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2019)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM8107M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET	Buckled	681.50 FL	*681.50 FL
2	2	*BONNET HINGES	Bent	84.00 FL	*84.00 FL
3	1	*FRONT GRILLE	Cracked	155.50 FL	*155.50 FL
4	1	*FRONT GRILLE EMBLEM	Necessary	27.40 FL	*27.40 FL
5	1	*FRONT GRILLE CHROME	Cracked	151.80 FL	*151.80 FL
6	2	*HEADLAMP ASSY	Cracked	2,310.00 FL	*2,310.00 FL
7	2	*HEADLAMP TOP CHROME	Not Necessary	301.00 FL	*- FL
8	2	*HEADLAMP LOWER RETAINERS	Cracked	57.80 FL	*57.80 FL
9	1	*FRONT BUMPER	Deformed	659.50 FL	*659.50 FL
10	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	385.80 FL	*- FL
11	2	*FRONT BUMPER SIDE RETAINERS	Necessary	42.00 FL	*42.00 FL
12	1	*FRONT BUMPER TOP RUBBER	Deformed	29.80 FL	*29.80 FL
13	1	*FRONT BUMPER BEAM	Buckled	335.80 FL	*335.80 FL
14	1	*FRONT SUPPORT PANEL	Repair	560.50 FL	*- FL
15	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	37.80 FL	*- FL
16	1	*FRONT SUPPORT PANEL SIDE RUBBER RH	Not Necessary	19.00 FL	*- FL
17	1	*AIR-CON CONDENSER	Bent	754.40 FL	*754.40 FL
18	1	*AIR-CON DISCHARGE HOSE	Bent	151.40 FL	*151.40 FL
19	1	*RADIATOR ASSY	Not Necessary	1,100.80 FL	*- FL
20	1	*FRONT NO PLATE	Scratched	45.00 FS	*45.00 FS
21	1	*SET FRONT BUMPER CLIPS	Necessary	28.00 FS	*28.00 FS
22	1	*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	39.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,957.80	5,533.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,569.16	1,088.18
Total Parts (\$\$)	6,388.64	4,445.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AIR-CON CONDENSER,PIPE,DRIER AND TOP-UP AIR-CON GAS	New	120.00	50.00
2	TO CHECK WIRING FUNCTION	New	30.00	30.00
3	TO APPLY RUSTING AND PROOFING ON REPLACED AND REPAIR PANEL	New	60.00	40.00
4	LABOUR CHARGES	New	800.00	700.00
5	TO PUTTY AND SPRAY PAINTING CHARGES	New	900.00	800.00
Gross Labour Cost (\$\$)			1,910.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >