

ASS. REC. BY:

REF: CS/FC1 19009341 / E/sd322

Special Instruction:

Survivor: Hwa Jie

ASSIGNMENT (Office)

From (Person): Joanne

of FC1

Date/Time: 28.5.19 9.30a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLG 9485X

Insured: SHD 4397M

at Workshop m/s World Auto

Tel: 63 621776

of NO 1 Kranji Loop

Policy No:

Claim No: D19003447MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.5.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"NP"

H.O.D. Endorsement:

Date/Time: 28.5.19 9.30a.m

Person Contacted: Daniel

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLG 9485X - CC4/EQ1 17020820/SLG 352 D.O.A. - 28/10/2019
	SHD 4397M - CS/FC1 17004587/UGH3N2 D.O.A. - 04/03/2017
30/05/19 @ 16:03 pm	revised PA to Joanne via email.

(08/11/13)

ASS. REC. BY: Three JREF FLI**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG9485X Yr Regn: 19 Oct 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda vezel c.c. 1496Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 177758 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RV31213029Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roadstar

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/5/19 D.O.I. 28/5/19Survey held at World AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
19/7/19	Final amount \$7130.32, 6 ppn days (\$ 5,455.44 Red - 43%)

RECEIVED 25 JUL 2019

Date/Time, File Pass to?

25/07/191) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 6Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

2x15=30

170+30

50

50

45

345

Report Format:

Lump Sum / I.B.I. (\$) 7,130.32 p/p

MOTOR SURVEY ASSIGNMENT

Date	27-05-2019	Our Ref No. D19003447MFSH
Accident Date	24-05-2019	Claim Type. Third Party
Insured Vehicle	SHD4397M	Third Party Vehicle. SLG9485X
Survey Location	NO.1, KRANJI LOOP	
Contact Person.	GAN PING	
Contact No.	63621776/ 0	Fax No. 63631250
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WORLD AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLG9485X
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	LEB5913019
Chassis No.:	RU31213009
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$29,125.00
Original Registration Date:	19 Oct 2016
First Registration Date:	19 Oct 2016
Transfer Count:	1
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Oct 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$36,299.00
Total Rebate Amount:	\$40,049.00

The information contained herein is correct as at 29 May 2019

OK

Shirley Hiew (LKK Auto)

From: Gan Ping <ganping@worldauto.com.sg>
Sent: Wednesday, 24 July 2019 2:33 PM
To: 'Shirley Hiew (LKK Auto)'
Cc: 'SUR'; daniel@worldauto.com.sg
Subject: RE: SLG 9485X TP DOA - 24/05/2019

Dear Shirley

Confirmed finalized COR P/P \$7,130.32 (before GST) and 6 repair days.

Gan ping
Thks & Rgds,
World Auto Pte Ltd
Tel: 63621776

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, July 24, 2019 1:44 PM
To: ganping@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLG 9485X TP DOA - 24/05/2019

Dear Gan Ping,

Please re-confirm P/P \$ 7,130.32/6 days before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Tuesday, 23 July 2019 10:47 AM
To: ganping@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: SLG 9485X TP DOA - 24/05/2019

Dear Gan Ping,

Please confirm P/P \$ 7,017.32/6 days before GST.

Thank you.

Best Regards,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 May 2019 4:03 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003447MFSH/1
Attachments: SLG 9485X- Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle SLG 9485X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 28 May 2019 9:44 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19003447MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 28 May, 2019 9:30 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003447MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003447MFSH

Date: 30 May 2019

Our Ref: CS/FCI19009341/Jsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 9485X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 28/05/2019 at the premises of M/s World Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 12,437.76</u> .
Revised Estimate Amount	: <u>S\$ 7,878.16</u> .
"Check" Items Amount	: <u>S\$ 4,444.40</u> .
Market Value	: <u>S\$</u> .
LTA Reimbursement Value	: <u>S\$</u> .
Nett Value	: <u>S\$</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 5 Days

Yours faithfully,

Ong Hwee Jie

Automotive Assessor

First Capital.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/05/2019 14:41
Date Of Accident	24/05/2019 12:00
Exact Location Of Accident	AYE TWDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9485X
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 HYBRID (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	

Driver

Name of Driver	TAY TECK SENG
NRIC No	S6818364B
Date Of Birth	18/05/1968
Occupation	OUTDOOR
Date Of Driving Pass	20/04/1989
Driving Experience	30 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90027025
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NOADDRESS
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4397M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/05/19 around 12:00pm, I was driving along AYE towards City, Suddley a car cut into the front of my car, I jam brake immediately and I felt an impact from behind, this car SHD 4397M hit onto the Rear of my car.

DECLARATION

I/We declare the foregoing particulars are true to my best knowledge.






Driver's Signature
Date & Time

Signature

Driver's Signature
If driver is not the police officer
Date & Time

Suggesting Police Officer's Name
Name
NRIC/ID No

Sketch Plan #3



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON RD #16-01 CITY HOUSE
 068877

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES190096

Date : 24/05/2019
 Vehicle Num. : SLG 9485X (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 24/05/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR TAILGATE <i>Buc /</i>		1,100.00
2.	1	REAR TAILGATE INNER LOCK <i>Inc / ? X</i>		211.90
3.	1	REAR TAILGATE INNER HANDGRIP COVER <i>?</i>		55.00
4.	1	REAR TAILGATE INNER TRIM BOARD <i>?</i>		278.00
5.	2	REAR TAILGATE REFLECTOR LAMP <i>X</i>	580.00	1,160.00
6.	1	REAR TAILGATE VEZEL EMBLEM <i>nec /</i>		84.60
7.	1	REAR TAILGATE HYBRID EMBLEM <i>nec /</i>		88.60
8.	1	REAR BUMPER <i>Buc /</i>		865.00
9.	<i>2</i> 1	REAR SIDE BUMPER <i>DEF - LH -</i>	135.00	270.00
10.	2	REAR BUMPER SIDE RETAINER <i>nec -</i>	78.00	156.00
11.	1	REAR BUMPER UNDERDUST COVER <i>DEF -</i>		155.00
12.	1	REAR END PANEL <i>Buc -</i>		630.00
13.	1	REAR END PANEL TOP GARNISH <i>DEF -</i>		138.50
14.	1	REAR BOOT COMPARTMENT BOX <i>?</i>		320.00
15.	1	REAR BOOT FLOOR PANEL <i>?</i>		790.00
16.	1	REAR BOOT FLOOR PANEL STIFFENER <i>?</i>		130.00
17.	2	REAR TAIL LAMP <i>X</i>	680.00	1,360.00
18.	1	REAR NUMBER PLATE LAMP GARNISH <i>nec X</i>		144.00
19.	1SET	REAR WINDSCREEN GLASS MOULDING <i>nec</i>		195.00
20.	1	SMART BUZZER SENSOR <i>TR</i>		155.00
21.	1	REAR BOOT FLOOR BOARD <i>?</i>		345.00
22.	<i>2</i> 1	REAR BUMPER REFLECTOR LENS <i>CRA - LH /</i>	132.80	265.60
List Total S\$:				8,697.20
20.00% Discount S\$:				1,739.44
				6,957.76

SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>?</i>		30.00

Parts — \$5565.40
 Supplementary — \$185

\$5750.40

20% = \$4600.32

S/P = \$340

below = \$2300

7240.32

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON RD #16-01 CITY HOUSE
 068877

Attention : Motor Claim Department
 Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES190096

Date : 24/05/2019
 Vehicle Num. : SLG 9485X (LCR)
 Make/Model : HONDA VEZEL HYBRID
 Chassis/Eng# :
 Accident Date : 24/05/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	REAR BUMPER CLIP <i>nec</i>		30.00
3.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>nec</i>		20.00
4.	1	WINDSCREEN SEALANT <i>nec</i>		60.00
5.	1SET	REVERSE SENSOR <i>shorted</i>		20.00
Special Nett Total S\$:				440.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				120 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				50 180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				30 180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				800 1,800.00
DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)				250 ? 450.00
PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)				250 ? 450.00
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS				800 1,800.00
Labour Total S\$:				5,040.00
E. & O.E.			Total S\$:	12,437.76

for WORLD AUTO PTE LTD

Hua Jie-Lik
 28/5/19
 P/P Selaya


WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON RD #16-01 CITY HOUSE
068877

Attention : Motor Claim Department
Contact : 6222 2311 Fax No. : 6222 3547

Supplementary Estimate : SE190096

Date : 11/06/2019
Vehicle Num. : SLG 9485X (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 11/06/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LIST ITEMS :		
1.	1	REAR FRAME END FLANGE LH		30.00
2.	1	REAR BOOT WEATHER STRIP		155.00
List TotalS\$:				185.00
20.00% Discount S\$:				37.00
				148.00

E. & O.E.

Total S\$: 148.00

=====

for WORLD AUTO PTE LTD

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON RD #16-01 CITY HOUSE

068877

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES190096

Date : 24/05/2019

Vehicle Num. : SLG 9485X (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/05/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE <i>BVC /</i>		1,100.00 /
2.	1	REAR TAILGATE INNER LOCK <i>Imm /</i>		211.90 /
3.	1	REAR TAILGATE INNER HANDGRIP COVER <i>? X MM</i>		55.00 X
4.	1	REAR TAILGATE INNER TRIM BOARD <i>? CRU</i>		278.00 /
5.	2	REAR TAILGATE REFLECTOR LAMP <i>? X MM</i>	580.00	1,160.00 X
6.	1	REAR TAILGATE VEZEL EMBLEM <i>nec /</i>		84.60 /
7.	1	REAR TAILGATE HYBRID EMBLEM <i>nec /</i>		88.60 /
8.	1	REAR BUMPER <i>BVC /</i>		865.00 /
9.	2	REAR SIDE BUMPER <i>DEF - LH /</i>	135.00 /	270.00
10.	2	REAR BUMPER SIDE RETAINER <i>nec /</i>	78.00	156.00 /
11.	1	REAR BUMPER UNDERDUST COVER <i>DEF /</i>		155.00 /
12.	1	REAR END PANEL <i>BVC /</i>		630.00 /
13.	1	REAR END PANEL TOP GARNISH <i>DEF / CRU</i>		138.50 /
14.	1	REAR BOOT COMPARTMENT BOX <i>? /</i>		320.00 /
15.	1	REAR BOOT FLOOR PANEL <i>? /</i>		790.00 /
16.	1	REAR BOOT FLOOR PANEL STIFFENER <i>? /</i>		130.00 /
17.	2	REAR TAIL LAMP <i>? X MM</i>	580.00	1,160.00 X
18.	1	REAR NUMBER PLATE LAMP GARNISH <i>nn x</i>		144.00 X
19.	1SET	REAR WINDSCREEN GLASS MOULDING <i>nec /</i>		195.00 /
20.	1	SMART BUZZER SENSOR <i>? /</i>		155.00 /
21.	1	REAR BOOT FLOOR BOARD <i>? X MM</i>		345.00 X
22.	2	REAR BUMPER REFLECTOR LENS <i>CRA - LH /</i>	132.80 /	265.60
List TotalS\$:			556540	8,697.20
20.00% Discount S\$:			-2%	1,739.44
			4452.32	6,957.76

SPECIAL NETT ITEMS :				
1.	1SET	REAR TAILGATE INNER TRIM BOARD CLIPS <i>?</i>	<i>nec 20 /</i>	30.00

*Supp - 7/30.32**P- 4452.32**AI- 330**L- 2200**6982.32**6 repair days*

CONTINUE / ...

Request before spray photo

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON RD #16-01 CITY HOUSE

068877

Attention : Motor Claim Department

Contact : 6222 2311 Fax No. : 6222 3547

Estimate : ES190096

Date : 24/05/2019

Vehicle Num. : SLG 9485X (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 24/05/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	REAR BUMPER CLIP <i>rec</i>		30.00
3.	1SET	REAR END PANEL TOP GARNISH CLIPS <i>rec</i>		20.00
4.	1	WINDSCREEN SEALANT <i>rec</i>		60 80.00
5.	1SET	REVERSE SENSOR <i>shorted</i>		20 280.00
Special Nett Total S\$:				<i>330</i> 440.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				<i>120</i> 180.00
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				<i>50</i> 180.00
WIRINGS CHECK AND RECTIFY WHERE NECESSARY				<i>30</i> 180.00
REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS				<i>800</i> 1,800.00
DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)				<i>200</i> ? 450.00
PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)				<i>200</i> ? 450.00
PUTTY AND SPRAY PAINT ALL AFFECTED AREAS				<i>800</i> 1,800.00
Labour Total S\$:				<i>2200</i> 5,040.00

12,585.76

for WORLD AUTO PTE LTD

E. & O. E. consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$ *12,437.76*

31/1/19
Three Jie-Lik
28/5/19
P/P Eclay

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
Halcyon 2, S'pore 577200
Tel No. : 6451 3933 Fax No. : 6455 7576
E-Mail : worldaut@singnet.com.sg
Website : www.worldauto.com.sg
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON RD #16-01 CITY HOUSE
068877

Attention : Motor Claim Department
Contact : 6222 2311 Fax No. : 6222 3547

Supplementary Estimate : SE190096

Date : 11/06/2019
Vehicle Num. : SLG 9485X (LCR)
Make/Model : HONDA VEZEL HYBRID
Chassis/Eng# :
Accident Date : 11/06/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR FRAME END FLANGE LH		30.00
		REAR BOOT WEATHER STRIP		155.00
		List TotalS\$:		185.00
		20.00% Discount S\$:		37.00
				148.00

Handwritten notes: DA, A, ER4

E. & O.E.

Total S\$: 148.00

for WORLD AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19009341/Esd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-08-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4397M	Veh. Inspected	SLG 9485X
Policy No.		Coverage (\$)	0.00
Claim No.	D19003447MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	28/05/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31213009	Colour	SILVER
Odometer	177758	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	ROADSTONE	6 mm
L/H Front Tyre	215/60 R16	ROADSTONE	6 mm
R/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
L/H Rear Tyre	215/60 R16	ROADSTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/05/2019	Inspection Date	28/05/2019
Survey held at	NO. 1 KRANJI LOOP		
Repairer	WORLD AUTO PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9485X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BUCKLED	1,100.00	1,100.00
1	REAR TAILGATE INNER LOCK	JAMMED	211.90	211.90
1	REAR TAILGATE INNER HANDGRIP COVER	NOT NECESSARY	55.00	-
1	REAR TAILGATE INNER TRIM BOARD	CRUSHED	278.00	278.00
2	REAR TAILGATE REFLECTOR LAMP @\$580.00	NOT NECESSARY	1,160.00	-
1	REAR TAILGATE VEZEL EMBLEM	NECESSARY	84.60	84.60
1	REAR TAILGATE HYBRID EMBLEM	NECESSARY	88.60	88.60
1	REAR BUMPER	BUCKLED	865.00	865.00
2	REAR SIDE BUMPER @\$135.00	N/S DEFORMED	270.00	135.00
2	REAR BUMPER SIDE RETAINER @\$78.00	NECESSARY	156.00	156.00
1	REAR BUMPER UNDERDUST COVER	DEFORMED	155.00	155.00
1	REAR END PANEL	BUCKLED	630.00	630.00
1	REAR END PANEL TOP GARNISH	DEFORMED	138.50	138.50
1	REAR BOOT COMPARTMENT BOX	CRUSHED	320.00	320.00
1	REAR BOOT FLOOR PANEL	DENTED	790.00	790.00
1	REAR BOOT FLOOR PANEL STIFFENER	DENTED	130.00	130.00
2	REAR TAIL LAMP @\$580.00	NOT NECESSARY	1,160.00	-
1	REAR NUMBER PLATE LAMP GARNISH	NOT NECESSARY	144.00	-
1	SET REAR WINDSCREEN GLASS MOULDING	NECESSARY	195.00	195.00
1	SMART BUZZER SENSOR	BROKEN	155.00	155.00
1	REAR BOOT FLOOR BOARD	NOT NECESSARY	345.00	-
2	REAR BUMPER REFLECTOR LENS @\$132.80	N/S CRACKED	265.60	132.80
1	REAR FRAME END FLANGE LH (ADDITIONAL)	DENTED	30.00	30.00
1	REAR BOOT WEATHER STRUP (ADDITIONAL)	CRUSHED	155.00	155.00
	LESS 20% DISCOUNT		-1,776.44	-1,150.08
			7,105.76	4,600.32
SPECIAL NETT ITEMS				
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	20.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	20.00	20.00

Report Ref No. CS/FCI19009341/Esd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			440.00	330.00
	LABOUR			
	REMOVE & REFIT REAR WINDSCREEN GLASS.		180.00	120.00
	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES.		180.00	50.00
	WIRINGS CHECK AND RECTIFY WHERE NECESSARY.		180.00	30.00
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		1,800.00	800.00
	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	200.00
	PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISE HV HYBRID SYSTEM (HV HYBRID SYSTEM SAFETY PROCEDURES)		450.00	200.00
	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS.		1,800.00	800.00
			5,040.00	2,200.00
GRAND TOTAL			12,585.76	7,130.32
RECOMMENDED COST OF REPAIRS				7,130.32

Report Ref No. CS/FCI19009341/Esd3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.