(C3/ TM) 10	90093431 NSd302
REF:	M)
SILIFALL: WILL	IGNMENT
<u>A331</u>	
From: . Dale:	Veh No: 314 A 3413 Y Yr Regn: 19 Jul 200
Eslimaled Cosl:	Type: M.Car / M.Cycle / BuS / Van / Lorry / (Lax) / Prime Mover /
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Make: TOVOTA PRIMS c.o. 1,798
To Inspect Vehicle No:	Make: 10 OTA PRIMS c.c. 178 A/C: (Insur.d) Sid/ NI/NA
at Workshop m/s	COIONI BENE
ol	Sp.Reading 273 817 T/Radio; (nsured)Std / NI / NA
Innured:	Eng/No:
Policy No.	CNO: JtD483FU203561524
Claims No.	Gon, Cond: Good (Ealr) Poor / Burnt
Sum Insured: Excess:	Sleering: Inorder I Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder/ Jammed / Leaked / Burnt or
Make of Veh:	Modl: NII / S/RIm / STD A/RIm or
	Modl: NII / S/R/m / STD A/R/m or Tyre Sizo: F: 195/65 R 15
(Policy Condition)	R: ()
Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF DURATURN (F), WESTLAKIE(R)
XXX	Dect
Bal, or Market Value:	Front R/Bal. C mm R/Bal. S mm
Contraction of the second of t	UBal. 6 mm UBal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	D.O.A. 23/5/19 U.O.I. 24/5/19
Est. Repairs: days Res.: Yes or No	
Luin Sum: % 3 Val.; Yes or No	
CA / REV / REP. / 24 HRS	Das, of Damages: Frt / Rear DOIS / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	The U/C / Chasals frame / Body Structure affected due to collisto
Date / Time Action / Instruction	7MI P.P.
23/7/19 FINALIZED PART BY PART REPA	AIR \$5,916.72 / 4 REPAIR DAY)
(\$ 1,954.61 Red - 25	//)
	marryo
	ED 2 5 JUL 2019
	1 50475914
	4
Oute/Time, File Pass 10? : Pretti Report	Days Of Repair: 4 Survey Fee: 250
1) Typica : Final Report	Resurvey No. of Trip: Survey Fee: Transportation:
Osterfine, File Roturn 107 Add Fe	
?)	: Interview (\$) Photos
Report Format	: Tech, Inva (\$), oners
Lump Sum (1.87: (\$ \$5,9/672 P/P)	:Weakend (\$)
T 2 ! !! ! !!	TOTAL . 161

OMFORTDELORO

COMFORTDELLIRO

Date/Time: 24.05.2019 08:49

Page : 1

Team:

ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3924802

JC NO.: 305297832

STOMER

COMFORT TRANSPORTATION PTE LTD

REGN NO.: SHA3413Y

MILEAGE

/MS STOMER NO.

7010045

TOYOTA

MAKE:

....1/2.

FUEL

DRESS

383 SIN MING DRIVE Singapore SINGAPORE 575717

PRIUS HYBRID(G4)23.05.2019 15:45 MODEL

65508755

YR OF MANUE. 07.2017

TARGET DATE

(R)

CHASSIS CODE JTDKB3FU203561524 COMPLETION DATE/TIME

COUNT CARD NO

JOB DESCRIPTION


Accident Date: 23.05.2019

NATURE: 3P 23.05.2019

S/NO

LABOR CODE

DESCRIPTION



TOKIO - Rear

IECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

owledgement Slip

Exit Pass

ile No.:

SHA3413Y

Vehicle No.:

SHA3413Y

e of Service Advisor

Larry Ng

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard

Shirley Hiew (LKK Auto)

From:

Naz (LKKAuto) < Naz@lkkauto.com>

Sent:

Tuesday, 23 July 2019 5:02 PM

To:

Ng Nyuk Phin

Cc:

Shirley Hiew (LKK Auto)

Subject:

Re: SHA 3413Y FINALIZATION

Attachments:

FINALIZED.pdf

Dear Mr Ng,

Finalized Part by Part Repair \$5916.72 / 4 Repair Days subject to insurance approval.

Thank you.

Best Regards,

Naz | Technical Investigator

LKK Auto Consultants

Phone: 6841-2157 | Email: Naz@lkkauto.com | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Nyuk Phin <ngnp@cdge.com.sg> Sent: Monday, 22 July 2019 5:20 PM To: Naz (LKKAuto) <Naz@lkkauto.com>

Subject: Fw: SHA3413Y FINALISATION * Pending, Revised *

Dear Naz,

As spoken, please see attached Revised Finalisation with the Merimen fee at \$11.

Regards, Larry Ng CDGE Loyang Taxi Crash Repairs 6124 8316

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for

네 가장 많아 보다 하다 하는데 얼마나 내가 모든데 보고 있다면 하는데 하는데 하는데 되었다면 하는데 하는데 하는데 되었다.	 be made available upon application by interested parties. bu hereby consent to the archiving of this report at the centre and to copies of the report being made available
establish to the Marshall Registration of	ACCIDENT STATEMENT
Date Of Report	24/05/2019 08:17
Date Of Accident	23/05/2019 09:35
Exact Location Of Accident	TPE TWDS CHANGI AIRPORT (B/4 KPE EXIT)
Country/State of Loss	SINGAPORE
and the contract of the second	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SHA3413Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	

Manufacturer TOYOTA

Model PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category TAXI

Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD Name of Insurance Company

THIRD PARTY FIRE AND/OR THEFT Type Of Coverage

Fleet Policy YES

Policy Number MCOM0015

Cover Note Number

Driver

Name of Driver TAN SIONG MOH

NRIC No S0026868B Date Of Birth 18/01/1952 Occupation OUTDOOR Date Of Driving Pass 04/06/1972

46 YEARS AND 11 MONTHS Driving Experience

Gender MALE

Mobile Number (LOCAL) +65-96628614

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 46 CIRCUIT ROAD

#09-647

Postcode

370046

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

NO

involved in the accident

4

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

2

Passenger 1

NAME:

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police? If Yes, Please state which Police Station

YES

Police Station Name

TAMPINES NORTH NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 461 TAMPINES STREET 44 #01-56, POSTCODE: 520461,

COUNTRY: SINGAPORE

TEL NO: 1800-7818999 - FAX NO: 67838603

Police Station Contact Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20190523/2093

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

GBB9591S

Details Of Properties

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLL3664J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address Postcode

Insurance Company Name

Nature Of Damage

FRONT AND REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

YP1815D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

UNKNOWN

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN SIONG MOH

Approximate Age

Injuries Sustain

LOWER BACK AND NECK

Injured person in which vehicle?

SHA3413Y

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and <u>accurate</u> as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy</u> liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mall packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

and the same of th

Driver's Signature

(If driver's not the policyholder)

Date & Time:

Jeckson Heng

C3O

Reporting Centre Personnel's Signature Name:

NRIC/FIN No .:

ETCH PLAN		
	attais	Men I I I I I I I I I I I I I I I I I I I
	eelthell	
ESCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
010 010	t alla d	1
Kefer Police	e report ablach	leh
PIO	000002 2002	
7/2	0190523/2093	
	110	
e declare the foregoing particula		23/5/19
CLARATION Ve declare the foregoing particula MFORT TRANSPORTATION CO. REG. NO. 19930382	PTE LTD IN	23/5/19 Jackson House FACRA





1 of 3

Report No. T/20190523/2093

Police Station Of Origin: Tampines North NPP 461 Tampines Street 44 #01-56 SINGAPORE 520461

Tel No: 1800-7818999

REPORT O	F A TRAFFIC	ACCIDENT				
Date/Time Report Made: 23/05/2019 15:16			Vide Report No.:	Station Diary No.: 23		
Informa	nt's Particu	ulars				
Market State of State	Informant: NG MOH		Address: APT BLK 46 CIRCUIT ROAD #09-647 SINGAPORE 370046			
ID Type / ID No.: NRIC NO / S0026868B			Contact No.: Home/Office:	Mobile: 96628614		
Nationality: SINGAPORE CITIZEN			Email:			
Sex: Age: Date of Birth: Male 67 18/01/1952			Type of Informant: Driver			
Race: Chinese			Language:	Institution / School Name:		
Occupation: Taxi driver			Driving Licence Information: Class: 3	Date of Expiry:		

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 23/05/2019 09:35	Type of Location Straight Road	
Location: Along Road 1 TAMPINES EXPRESSWAY Along TPE toward Changi Airport direct Weather: Clear		direction and before KP Road Surface: Dry	E exit	Road Speed Limit:	
Traffic Flow: Tra		Traffic Control: Not Controlled		Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To R		To Rear		Anyone conveyed by ambulance:	

Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
GBB9591S	Lorry				Slightly Damaged	0
SHA3413Y	Car				Slightly Damaged	1
SLL3664J	Car -				Slightly Damaged	0
YP1815D	Car				Slightly Damaged	0





2 of 3

Report No. T/20190523/2093

Police Station Of Origin: Tampines North NPP

461 Tampines Street 44 #01-56 SINGAPORE

520461

CONTINUATION OF REPORT

Tel No: 1800-7818999

Any Pedestrian Ir	nvolved: No						
No. of Pedestrians Injured: NIL			Use of Pe	destriar	Cross	ing: NA	
Driver			With Miles				
Name	TAN SIONG MOH			ID No	•1	S0026868B	
Related Vehicle	SHA3413Y (Car)			Contact No.		96628614	
Hospital/Clinic	SUNSHINE CLINIC FAMILY PRACTIC SURGERY			Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL	
Date Treatment	23/05/2019 Date D			harge	23/05	5/2019	
No. of Days granted Medical Leave 05			Degree of	finjury	Slight		

Brief Details.

On the above mentioned date, time and said location, I was driving my Comfort Taxi, SHA3413Y, blue in colour TPE toward Changi Airport direction before the KPE exit with one female passenger seated behind. I was travelling along the extreme left lane and follow the flow of the traffic to slow down and stopped my taxi. In around 3 second, suddenly I felt an impact from my rear. I then make a check on my passenger which she did not reply me. I then alighted my taxi and saw this chain collision involving 4 vehicle including mine. The sequence as follow: 1st veh: SHA3413Y, 2nd veh: GBB9591S, 3rd veh: SLL3664J, last veh: YP1815D. I wish to state I did not check whether anyone was injured however after the accident I felt a pain on my back and back neck area and went to consult a doctor, I was then given 5 days MC. All of the involving party did not exchange particular and just left after taking the plate number. Due to the accident my taxi damages is the rear portion and I have in car camera and it is in working condition.





Police Station Of Origin:
Tampines North NPP
461 Tampines Street 44 #01-56 SINGAPORE
520461 CONTINUATION OF REPORT

3 of 3 Report No. T/20190523/2093


Tel No: 1800-7818999


Sketch F	Plan
----------	------

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.

Signature Of Officer Recording The Report: G / Staff Sgt TAN YI KUN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 23/05/2019 15:16
Officer In Charge Of Case: TP / AEIT / Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED MOHDISAID	Classification Of Case:
Contact No a 65476 470RE Authentication Stamp Force	














ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

BEAN CITY FOODSTUFF PTE LTD

Singapore

Claimant Insurer:

India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Policy No:

MC014589

Vehicle Reg. No.:

SHA3413Y

Party At Fault:

UNKNOWN

Driver (TP):

TAN SIONG MOH

Make/Model:

TOYOTA PRIUS, 1.8 HYBRID CVT

Vehicle Reg. Date:

19/07/2017

23/05/2019

YES

Vehicle Colour:

(A) BLUE

Gen Condition:

GOOD

Engine No: Odometer: 2ZRS056497 273817 KM

rsul Ma

Chassis No:

Ref. No:

Date of Loss:

Driveable?

JTDKB3FU203561524

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

Description of

Accident/Loss

REFER POLICE REPORT NO: T/20190523/2093

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS

Parts

Miscellaneous Items

Labour

Paintwork Labour

Towing

Gross Total (S\$)

7871.

6,668.37

+ GST 7.00% (S\$)

466.79

Amount

4.778.37

1,880.00

10.00

0.00

Nett Amount (S\$)

7,135.16

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 24 May 2019)

Parts:

144

Repairer's

TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

(Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA3413Y/24/05/2019 09:55

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	25.00	0.00	
2	1		*REAR BUMPER BEAM	25.00	0.00	=*318.80 FL
3	1		*REAR BUMPER SPONGE	25.00	0.00	*143.40 FL
4	10		*REAR BUMPER CLIPS	25.00	0.00	-*22.00 FL€
5	1		*REAR BUMPER UNDERCOVER	25.00	0.00	
3	1		*REAR END PANEL	25.00	0.00	
7	1		*REAR BUMPER SIDE RETAINER - RH	25.00	0.00	*112.70 FL ?
3	1		*REAR BUMPER SIDE SEAL - RH	25.00	0.00	*148.40 FL ?
9	1		*REAR BUMPER TOW COVER	25.00	0.00	/*82.70 FL /
0	1		*REAR TRUNK LID COVER	25.00	0.00	> *1,126.60 FLX
1	1		*REAR TRUNK LID PRIUS LOGO	25.00	0.00	// *52.90 FL/
2	1		*REAR TRUNK LID HYBRID LOGO	25.00	0.00	≠52.90 FL
3	1		*REAR TRUNK LID TOYOTA LOGO	25.00	0.00	→47.00 FL /
4	1		*REAR WIDNSCREEN GLASS WITH MOLDING	25.00 -	NG(0.00	=*1,778.30 FL €
5	1		*TAIL LAMP - UPPER - RH	25.00	0.00	/*557.90 FL/
6	1		*REVERSE SENSOR	0	0.00	*135.70 FS x
7	1		*REAR TRUNK LID APP STICKER	0	0.00	=*40.00 FS
8	1		*REAR TRUNK LID COMFORT STICKER	0	0.00	
9	1		*REAR TRUNK LID TEL STICKER	0	0.00	
=Fra	nchise	part. S=SpcNet	tt. L=ListItemDisc.			
			Sub Total (S\$)			6,292.60
			- List Item Discount on L Items (S\$)			1,514.23
			Total Parts (S\$)			4,778.37

ComfortDelGro Engineering Pte Ltd/SHA3413Y/24/05/2019 09:55. Not valid without Reference section. Generated using Merimen e-Claims IEAS

4591:7 6194.3 3443.77 4645.4

Larry NO

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

OD/TP Case (Insurer) 1

10.00

Sub Total (S\$)

10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Lab	our Items		
1	PANEL BEATING	New	Z50.00 45
2	SPRAY PAINTING	New	750:00 60
3	TUFF KOTE	New	80.00 50
4	WIRING CHARGE	New	80.00 30
5	REMOVE / REFIX REVERSE SENSOR	New	100.00 30
6	REMOVE / REFIX REAR WINDSCREEN	New	120.00 KN
		Gross Labour Cost (S\$)	1,880.00

ComfortDelGro Engineering Pte Ltd/SHA3413Y/24/05/2019 09:55. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

4 DAYS

CHECK ITEMS (HOTO)

BEFOLE (AWT (HOTO)

LKK Auto Consultanta hence notify

the Repairer of the following:

- . To resurvey beforelatter apray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal medification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

VEHICLE NO.:	SHA3413Y	TYPE OF CLAIM	:	3P / TOKIO
MODEL :	PRIUS	SURVEYED BY	:	LKK / NAZ
JOB NO :	305297832	DATE	:	27.06.2019

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

	SUPPLEMENTAR			
S/No	DESCRIPTION	QTY	ESTIMATE	REMARKS
1	Garnish, Tail gate	1	\$881.70	TORK A
		TOTAL:		

COMFORTDELGRO ENGINEERING

JOB NO : 305297832

VEHICLE NO	D.:	SHA3413Y	TYPE OF CLAIM	:	3P / TOKIO	
MODEL	-	PRIUS	SURVEYED BY	:	LKK / NAZ	
JOB NO		305297832	DATE	:	13.06.2019	

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

DESCRIPTION Glass, Back Window	1		
	1	\$720.90	NEC A
4			
		TOTAL	TOTAL:

COMFORTDELGRO

						ENGINEERING	
Our J	lob Re	f No . 3052	297832			LINGINEERING	
Date		: 22. J	ul. 2019		59 Loy	rtDelGro Engineering Pte Ltd ang Drive. Singapore 508969 546 8156	
FINA	LIZAT	ION FORM			7 34, 64	710 0100	
То	: _		LKK		Fax:		
Attn	:		NAZ				
Vehic	cle Reg	No. : SHA3	413Y	Date	of Accident:	23. May. 2019	
The	NO/ON	and estimates of t	he repairs of the ab	ove mentiones	Lushiola ara as	follows	
1110 3	survey	and estimates or t			verlicie are as		
1.	The	repair job shall bill	to:	гокіо		GBB9591S	
2.	The	finalized amount si	hall be:				
	(a)	Spare Parts afte	r List discount			\$4,745.69	44745.
	(b)	Labour Charges				\$1,171.00	
		Total for Part-B	y-Part Repair Cos	t		\$5,916.69	\$5,916.
	(c.)	Lumpsum Repai Total for Lumpsu Final Lumpsum	um repair cost after	Less:			
3. 4.	Wes	shall treat the abo	od for repairs:			s no reply from you	
	with	in 7 working days	3				
5.	Thar	nk you for your ass	istance.		e confirm the es alized amount	stimates and	
	Sign	ature :	C. K	Si	gnature:	4	
	Nam	e :	Larry Ng	Na	me : N	92 LKK	
	Tel	: 6214 831	6	Da	ite :	2317119	
	Fax	: 6546 8156	6	_			
For (Officia	I Use Only					
				Document			
		Item	Amount	Attached Yes or No	Confirm By (Signature)	Remarks	
1. R	tental F	Rate P/Day		YES			
2. L	oss of	Income Paid					
3. S	urvey	Fees					
		arch Fee Fees (on behalf	\$7.49				
0	f driver	r, if applicable)					
6 C	verrur))					

Remarks:

REPAIR ESTIMATE

Date: 22.07.2019 Time: 17:10:45

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: SHA3413Y : 0000000000

: 305297832

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(G4)

DATE OF REGN DATE/TIME IN

: 19.07.2017 : 23.05.2019 15:45

ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2267-G	PRIVC BUMPER PIECE 10 22.	00 25.00 16.50
0002 04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C 1	552.60 25.00 414.45
0003 04-01-0302-2286-G	PRIG4 COVER REAR BUMPER-T	82.70 25.00 62.02
0004 04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM 1	52.90 25.00 39.67
0005 04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B 1	47.00 25.00 35.25
0006 04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM 1	52.90 25.00 39.67
0007 28-01-0302-2013-A	PRIVC REAR BONNET APP TAX 1	40.00 . 40.00
0008 28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	30.00 30.00
0009 28-01-0302-0006-A	PRIVC REAR BOOT 65521111 1	30.00 30.00
0010 04-01-0302-0585-G	PRIG4 LENS & BODY RR COMB 1	557.90 25.00 418.42
0011 04-01-0302-2256-G	PRIG4 PANEL SUB-ASSY BACK	1,126.60 25.00 844.95
0012 04-01-0302-2257-G	PRIG4 GLASS BACK WINDOW F	720.90 25.00 540.67
0013 04-01-0302-2258-G	PRIG4 GLASS BACK DOOR 1 1,7	778.30 25.00 1,333.72

Date: 22.07.2019 Time: 17:10:45

REPAIR ESTIMATE

Page: 2

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO

: 305297832 : SHA3413Y

MILEAGE

: 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(C

DATE OF REGN

19.07.2017

DATE/TIME IN

23.05.2019 15:45

ACCIDENT DATE

: 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0302-2346-G PRIG4 GARNISH SUB ASSY BA 1 881.70 25.00 661.27

0015 04-01-0302-2288-G PRIG4 REINFORCEMENT SUB-A 1 318.80 25.00 239.10

SUB-TOTAL : 4,745.69 4,745.72

JOB NATURE

0000 L MERIMEN FEE

11.00

0001 PB

PANEL BEATING

450.00

0002 23-502

SPRAYPAINT ON AFFECTED AREA

600.00

0003 20-00

TUFF COAT ON AFFECTED PARTS.

50.00

30.00

0004 17-01

WIRING CHARGE

30.00

0005 L

REMOVE/REFIX REVERSE SENSOR

SUB-TOTAL : 1,171.00

Date: 22.07.2019 Time: 17:10:45

REPAIR ESTIMATE

Page: 3

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO : 305297832 : SHA3413Y : 0000000000

MILEAGE MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(C

DATE OF REGN DATE/TIME IN

19.07.2017

: 23.05.2019 15:45

ACCIDENT DATE

: 23.05.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL

: 5,916.69 5,916.72

SURVEYOR NAME & SIGNATURE

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

DATE:

DATE:

Date: 13.06.2019 Time: 16:19:59

Page: 1

REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE : 305297832 : SHA3413Y : 0000000000

MAKE

: TOYOTA

MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 19.07.2017
DATE/TIME IN : 23.05.2019 15:45

ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2267-G PRIVC BUMPER PIECE 10 22.00 25.00 16.50
0002 04-01-0302-2287-G PRIG4 GUARD-REAR BUMPER C 1 552.60 25.00 414.45
0003 04-01-0302-2286-G PRIG4 COVER REAR BUMPER-T 1 82.70 25.00 62.02
0004 04-01-0302-2270-G PRIG4 PLATE-BACK DOOR NAM 1 52.90 25.00 39.67
0005 04-01-0302-2269-G PRIG4 ORNAMENT SUB-ASSY B 1 47.00 25.00 35.25
0006 04-01-0302-2271-G PRIG4 PLATE-BACK DOOR NAM 1 52.90 25.00 39.67
0007 28-01-0302-2013-A PRIVC REAR BONNET APP TAX 1 40.00 40.00
0008 28-01-0302-2015-A PRIVC REAR BONNET COMFORT 1 30.00 30.00
0009 28-01-0302-0006-A PRIVC REAR BOOT 65521111 1 30.00 30.00
0010 04-01-0302-0585-G PRIG4 LENS & BODY RR COMB 1 557.90 25.00 418.42
0011 04-01-0302-2256-G PRIG4 PANEL SUB-ASSY BACK 1 1,126.60 25.00 844.95
0012 04-01-0302-2257-G PRIG4 GLASS BACK WINDOW F 1 720.90 25.00 540.67
0013 04-01-0302-2258-G PRIG4 GLASS BACK DOOR 1 1,778.30 25.00 1,333.72

Date: 13.06.2019 Time: 16:19:59

Page: 2 REPAIR ESTIMATE

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO : 305297832 : SHA3413Y

MILEAGE MAKE

: 0000000000 : TOYOTA

MODEL

: PRIUS HYBRID(C

DATE OF REGN : 19.07.2017 DATE/TIME IN : 23.05.2019 15:45 ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0302-2346-G PRIG4 GARNISH SUB ASSY BA 1 881.70 25.00 661.27

0015 04-01-0302-2288-G PRIG4 REINFORCEMENT SUB-A 1 318.80 25.00 239.10

SUB-TOTAL : 4,745.69

JOB NATURE

MERIMEN FEE	19:00 11:00	
PANEL BEATING	450.00	
SPRAYPAINT ON AFFECTED AREA		600.00
TUFF COAT ON AFFECTED PARTS.		50.00
WIRING CHARGE	30.00	
REMOVE/REFIX REVERSE SENSOR		30.00
	PANEL BEATING SPRAYPAINT ON AFFECTED AREA TUFF COAT ON AFFECTED PARTS. WIRING CHARGE	PANEL BEATING 450.00 SPRAYPAINT ON AFFECTED AREA TUFF COAT ON AFFECTED PARTS. WIRING CHARGE 30.00

SUB-TOTAL : 1,170.00

SURVEYOR NAME & SIGNATURE

Date: 13.06.2019 Time: 16:19:59

REPAIR ESTIMATE

Page: 3

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

. 7

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO : 305297832 : SHA3413Y

MILEAGE

: 0000000000

MAKE

: TOYOTA

MODEL

: PRIUS HYBRID(C

DATE OF REGN

: 19.07.2017

DATE/TIME IN : 23.05.2019 15:45

ACCIDENT DATE : 23.05.2019

JOB / PARTS DESCRIPTION

OTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,915.69

AUTHORISED: YES / NO

MVA NAME & SIGNATURE

DATE:

DATE:

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBI	FOLDER TRACKI	ING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	24 May 2019 09:24 Sendback Est	24 May 2019 09:55 \$\$6,668.37	24 May 2019 11:36 Edit Adj Rpt	S\$5,916.72 Edit Estimates	S\$5,916.72 View Rpt		Pending for Survey Report Cancel Case	
	Main	Refere	ence	Claim Details		Documents	Show All	
CLAIM SU	BFOLDER DETA	ILS						
Insured:	BEAN CITY F	OODSTUFF PTE L	TD, Co. Reg. No.:	199903097R				
Main Claimant:	COMFORT TR	ANSPORTATION	PTE LTD, Co. Re	eg. No.: 199303821R				
Vehicle Reg No.:	SHA3413Y			Date of Loss:	23/05/2019 09 [22 Months ar		Reg Date (Man Yr)]	
Claim Type	TP / M1903	755		Policy/Cover Note No.:	MC014589 (Third Party Only) Coverage: 23/11/2018 - 22/11/2019			
Vehicle Reg No. (Insured):	GBB9591S			Policy No. (Claimant):	MCOM0015			
				Excess:	S\$0.00			
Repairer:	ComfortDelG	ro Engineering P	te Ltd (Loyang) 5	9 Loyang Drive, 5089	69 Loyang - Tel:	6214 8300		
Handling Insurer:	Tokio Marine	Insurance Singa	pore Ltd (HQ) - 1	Tel: 6221 6111 [Ha	ndled by Ho Ter	ng Boon Eliza]		
Claimant's Insurer:	India Interna	ational Insurance	Pte Ltd (HQ) - T	el: 63476100				
Adjuster:	04/06/2019		(HQ) - Tel: 6256-	3561 [Handled by I	Muhammad Na	zril Bin Abdullah]	[Final Rpt due	
ASSOCIAT	ED MAIL RECEI	IVED				View All	Compose Case Mail	
There are n	o mail for this cas	e.					-	
ALL ASSO	CIATED TASKS	=			View All Sear	rch Tasks Create	New Task Complete	
Due Date	e Priority	Гуре Task Gro	up Subject	-			Created On Done	

Claim Documents

SHA3413Y (M1903755)

[GBB9591S]

TP

COMFORT TRANSPORTATION PTE LTD

May 23 2019 9:00AM

[BEAN CITY FOODSTUFF PTE LTD]

ComfortDelGro Engineering Pte Ltd

Ass	essment Reports		1 per p	age 🔻	~
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	24/05/19 08:28	Accident Statement	0	Load HTM	
2	24/05/19 09:55	Repairer Estimates	0	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	24/05/19 09:54	Accident Statement From:SC - Reg. No: GBB95915, Claimant: BEAN CITY FOODSTUFF PTE LTD	0	Load HTM	
Pho	tos/Images		3 per p	age 🔻	V
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	24/05/19 08:27	Accident Photo [Linked Accident Report Documents]	Ð	Load JPG	✓
2	24/05/19 08:27	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
3	24/05/19 08:27	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
4	24/05/19 08:28	Accident Photo [Linked Accident Report Documents]	0	Load JPG	✓
5	24/05/19 08:28	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/19 17:09	General View	0	Load JPG	✓
2	23/07/19 17:09	General View	0	Load JPG	✓
3	23/07/19 17:09	General View	0	Load JPG	V
4	23/07/19 17:09	General View	0	Load JPG	~
5	23/07/19 17:09	General View	0	Load JPG	V
6	23/07/19 17:09	General View	0	Load JPG	✓
7	23/07/19 17:09	General View	0	Load JPG	~
8	23/07/19 17:09	General View	0	Load JPG	~
9	23/07/19 17:09	General View	0	Load JPG	~
10	23/07/19 17:09	General View	0	Load JPG	4
11	23/07/19 17:09	General View	0	Load JPG	~
12	23/07/19 17:09	General View	Ð	Load JPG	V
13	23/07/19 17:09	General View	0	Load JPG	~
14	23/07/19 17:09	General View	0	Load JPG	~
15	23/07/19 17:09	General View	0	Load JPG	V
16	23/07/19 17:09	General View	0	Load JPG	~
17	23/07/19 17:09	General View	0	Load JPG	V
18	23/07/19 17:09	General View	0	Load JPG	V
19	23/07/19 17:09	General View	0	Load JPG	~
20	23/07/19 17:09	General View	0	Load JPG	V
21	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
22	23/07/19 17:09	Dismantled Parts	0	Load JPG	∀
23	23/07/19 17:09	Dismantled Parts	0	Load JPG	V

Ass	essment Reports		1 per p	page 🗸	\checkmark
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
24	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
25	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
26	23/07/19 17:09	Dismantled Parts	Ð	Load JPG	V
27	23/07/19 17:09	Dismantled Parts	Ð	Load JPG	✓
28	23/07/19 17:09	Dismantled Parts	Ð	Load JPG	✓
29	23/07/19 17:09	Dismantled Parts	0	Load JPG	✓
30	23/07/19 17:09	Dismantled Parts	Ð	Load JPG	V
31	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
32	23/07/19 17:09	Dismantled Parts	Ð	Load JPG	V
33	23/07/19 17:09	Dismantled Parts	0	Load JPG	▼
34	23/07/19 17:09	Dismantled Parts	0	Load JPG	✓
35	23/07/19 17:09	Dismantled Parts	0	Load JPG	✓
36	23/07/19 17:09	Dismantled Parts	0	Load JPG	✓
37	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
38	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
39	23/07/19 17:09	Dismantled Parts	0	Load JPG	✓
40	23/07/19 17:09	Dismantled Parts	0	Load JPG	V
41	23/07/19 17:10	Dismantled Parts	0	Load JPG	~
42	23/07/19 17:10	Dismantled Parts	0	Load JPG	✓
43	23/07/19 17:10	Dismantled Parts	0	Load JPG	☑
Doc	umentation		1 per	page 🔻	V
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	-
1	24/05/19 09:54	TP - SLL3664J GIA REPORT (3/4) From:SC - Reg. No: GBB9591S, Claimant: BEAN CITY FOODSTUFF PTE LTD	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/07/19 14:10	Supplementary	0	Load PDF	

Linked Accident Report Documents

			View View in Browser
Ass	essment Reports		1 per page
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail Print
1	24/05/19 08:28	Accident Statement	1 Load HTM
Pho	otos/Images		3 per page ✓ ✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail Print
1	24/05/19 08:27	Accident Photo	■ Load JPG
2	24/05/19 08:27	Accident Photo	1 Load JPG
3	24/05/19 08:27	Accident Photo	■ Load JPG
4	24/05/19 08:28	Accident Photo	■ Load JPG
5	24/05/19 08:28	Accident Photo	1 Load JPG ✓
Doc	cumentation		1 per page 🗸
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail Print
1	24/05/19 08:27	Sketch Plan	Load TIF

Documents Checklist

Reset	Save	Print
	Reser	Neset Save

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI19009348/NSD3E2

Date:

25/07/2019

REFERENCE

Date of Loss:

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No:

MC014589

Claimant Vehicle SHA3413Y

Insured Vehicle No:

GBB9591S

No:

23/05/2019

Nature of Claim:

Claim No: M1903755

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SHA3413Y

Make & Model:

TOYOTA PRIUS, 1.8 HYBRID CVT (A)

Engine No:

2ZRS056497

Reg. Date:

19/07/2017 (Man. Year: 2017)

Chassis No: Odometer:

JTDKB3FU203561524 273817 km

Colour:

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Good

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

Good

CONDITION OF TYRES

Front Tyre Size:

195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Front Right Side: **DURATURN 6 mm DURATURN 6 mm** Rear Left Side: Rear Right Side: West Lake 5 mm West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,778.37	4,745.72	32.65	0.68
Miscellaneous Items		10.00	11.00	-1.00	-10.00
Labour		1,880.00	1,160.00	720.00	38.30
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	6,668.37	5,916.72	751.65	11.27
	+ GST 7.00/7.00% (S\$)	466.79	414.17	52.62	11.27
	Nett Amount (S\$)	7,135.16	6,330.89	804.27	11.27

INSPECTION

Date of Assignment:

24/05/2019 Present Location:

ComfortDelGro Engineering Pte Ltd

(Loyang)

Date Inspected:

24/05/2019 Inspected At:

ComfortDelGro Engineering Pte Ltd

(Loyang)

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

4.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jul 2019)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA3413Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	458.60 FL	*-FL
2	1		*REAR BUMPER BEAM	Deformed	318.80 FL	*318.80 FL
3	1		*REAR BUMPER SPONGE	Serviceable	143.40 FL	*-FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*REAR BUMPER UNDERCOVER	Cracked	552.60 FL	*552.60 FL
6	1		*REAR END PANEL	Serviceable	602.10 FL	*-FL
7	1		*REAR BUMPER SIDE RETAINER - RH	Serviceable	112.70 FL	*-FL
8	1		*REAR BUMPER SIDE SEAL - RH	Serviceable	148.40 FL	*-FL
9	1		*REAR BUMPER TOW COVER	Missing	82.70 FL	*82.70 FL
10	1		*REAR TRUNK LID COVER	Deformed	1,126.60 FL	*1,126.60 FL
11	1		*REAR TRUNK LID PRIUS LOGO	Necessary	52.90 FL	*52.90 FL
12	1		*REAR TRUNK LID HYBRID LOGO	Necessary	52.90 FL	*52.90 FL
13	1		*REAR TRUNK LID TOYOTA LOGO	Necessary	47.00 FL	*47.00 FL
14	1		*REAR WIDNSCREEN GLASS WITH MOLDING	Necessary	1,778.30 FL	*1,778.30 FL
15	1		*TAIL LAMP - UPPER - RH	Scratched	557.90 FL	*557.90 FL
16	1		*REVERSE SENSOR	Serviceable	135.70 FS	*-FS
17	1		*REAR TRUNK LID APP STICKER	Necessary	40.00 FS	*40.00 FS
18	1		*REAR TRUNK LID COMFORT STICKER	Necessary	30.00 FS	*30.00 FS
19	1		*REAR TRUNK LID TEL STICKER	Necessary	30.00 FS	*30.00 FS
20	1		*GARNISH, TAIL GATE	Cracked	-	*881.70 FL
21	1		*GLASS, BACK WINDOW	Necessary	-	*720.90 FL
F=Fra	anchise	part. S=SpcI	Nett. L=ListItemDisc.			120222
				Sub Total (S\$)	6,292.60	6,294.30
			- List Item Discount on L Items	25.00/25.00% (S\$)	1,514.23	1,548.58
				Total Parts (S\$)	4,778.37	4,745.72

Report was unsubmitted during this print-out.

30.00

30.00 0.00

1,160.00

4

6

WIRING CHARGE

REMOVE / REFIX REVERSE SENSOR

REMOVE / REFIX REAR WINDSCREEN

Recommende	d Miscellaneous	Items
1 CCCOIIIIICIICE		ILCIIIS

No	Qty Particulars		Repairer's	Amount
Mis	cellaneous Items			
1	1 OD/TP Case (Insurer)		10.00	11.00
		Sub Total (S\$)	10.00	11.00
D-				
ĸe	commended Labour			
Re No	ecommended Labour Particulars	Lab.Type	Repairer's	Amount
No		Lab.Type	Repairer's	Amount
No	Particulars	Lab.Type New	Repairer's	
No	Particulars oour Items	·	•	450.00 600.00

New

New

New

Gross Labour Cost (S\$)

80.00

100.00

120.00

1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >