

28/8/19


Accident

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: \_\_\_\_\_  
at Workshop m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SDQ388U Yr Regn: 2002 / Jan.  
Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Mercedes Benz E200 cc 1998  
Colour: Gold A/C: Insured / Std / NI / NA  
Sp. Reading 188287 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: WDB21004828458238

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16  
R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>19/06/19</u>	

Survey held at Modern

Des. of Damages: Frd / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPA lg.
	COE Expiry: 30/11/21
	LS - \$2750 (Red \$4620.50 / 63%)
	MV: 2010 (Depreciation of \$8K).
	PV: 16.6K
	Nett: 3.4K.

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check		Survey Fee:	Date:
1)	2)	IN	OUT	Basic & Add.	
3)	4)			S + RS, SI	
5)	6)			Photos	
Prel. Report				Others	
Final Report				TOTAL	

Attn: Adrian

**MODERN AUTOMOTIVE PTE LTD**

**BLK 3023A UBI ROAD 1 #01-61**

**SINGAPORE 408717**

**Tel : 67484422 / 67454422 Fax : 6747-6720 REG NO 200501102H**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

Charts Building

78 Shenton Way #07-16

Singapore 079120

Tel : 6419 - 3000

Fax : 6835 - 7416

**Quotation**

DATE : 07.06.2019

VEH NO : SDQ388U

MODEL : Merc E200

D O A : 25.05.2019

YR REF : SFJ4783Z

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SDQ388U (MERCEDES E200)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Number Plate Garnish <i>Deband</i>	1	121.00 ✓
2	Front Bumper <i>Deband</i>	1	1,210.00 ✓
3	Front Bumper Clips <i>new</i>	1 set	50.00 ✓
4	Front Bumper Side Holder - LH & RH <i>new</i>	2	130.00 ✓
5	Front Bumper Chrome Moulding - LH & RH <i>new</i>	2	90.00 ✓
6	Front Bumper Lower Grille <i>new</i>	1	98.00 x
7	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	630.00 x
8	Front Bumper Inner Moulding <i>Deband</i>	1	98.00 x
9	Front Bumper Reinforcement <i>new</i>	1	552.00 x
10	Front Bumper Inner Sponge - LH & RH	2	96.00 x
11	Bonnet <i>new</i>	1	1,350.00 x
12	Bonnet Logo <i>new</i>	1	125.00 x
13	Bonnet Grille <i>cracked</i>	1	535.00 ✓
14	Head Lamp - LH & RH <i>RT cracked</i>	2	1,710.00 <del>855</del>

8,845.00

Less 10%

(884.50)

\$ 6,160.50

**S/NETT ITEMS**

1	Front Number Plate <i>Best</i>	1	30.00 ✓
2	Front Number Plate Holder <i>cracked</i>	1	30.00 ✓

**Total Parts**

\$ 6,220.50

**LABOUR CHARGE**

1	To knocking & pull out front portion & renew above parts	\$ 600.00 <del>400</del>
---	--	--------------------------

RE : ESTIMATE FOR ACCIDENT REPAIR SDQ388U (MERCEDES E200)

2	To putty & spray up paint work	680	\$	<del>500.00</del> 250
3	To check wiring		\$	<del>50.00</del> 30
Total Labour			\$	1,150.00
Grand Total			\$	7,370.50

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN  
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY  
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE  
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 3431.90

L/S: 2750

03 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner/Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4057F
Vehicle Details	
Vehicle No.:	SDQ388U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200ML AUTO
Primary Colour:	Beige
Manufacturing Year:	2001
Engine No.:	11195732331678
Chassis No.:	WDB2100482B458238
Maximum Power Output:	-
Open Market Value:	\$48,906.00
Original Registration Date:	21 Jan 2002
First Registration Date:	21 Jan 2002
Transfer Count:	0
Actual ARF Paid:	\$68,469.00
Intended PARF/COE Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Details	
COE Expiry Date:	30 Nov 2021
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$67,299.00
COE Rebate Amount:	\$16,637.00
Total Rebate Amount:	\$16,637.00

The information contained herein is correct as at 10 Jun 2019

OK





**FOR SALE BY OWNER**  
  
**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

---

 [Post an Ad](#)  [Advertiser Login](#)  [Ways of Selling](#)

**New 5 Years COE Renewal Toyota Wish 1.8A.**

 3.18% P.A. \$0 Admin Fees @ Gv  
Finance. 7 Years Warranty.  
Monthly from \$638.  
Or Cash \$16,100. StarAd



 **AutoInn**  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

 Print

Sort by Date Posted ▾ 20 results/page ▾

Advanced Search Search View All

Make Model Price Depreciation Ring Date Eng Cap Mileage Veh Type Status

Search Selection	E-Class E200HL	Any	Any	> 10 year(s)	Any	Any	Any	Available
------------------	----------------	-----	-----	--------------	-----	-----	-----	-----------



<input type="checkbox"/> Mercedes-Benz E-Class E200ML (New 10-yr COE)	\$53,888	\$5,380 /yr	19-Oct-2000	1,998 cc	-	Luxury	Available
---	----------	-------------	-------------	----------	---	--------	-----------

E200M, Kompressor Model, Tip Top Condition, All Wear And Tear Parts Replaced, New Carpet, Roof Lining, New Leather Upholstery Steering Rewrapped, New Engine Mountings, New Undercarriage Bushings New A.

Minister Motors (Pty) Ltd



<input type="checkbox"/> Mercedes-Benz E-Class E200ML (COE till 03/2029)	\$48,500	\$4,940 /yr	13-Nov-2000	1,998 cc	-	Luxury	Available
---	----------	-------------	-------------	----------	---	--------	-----------

Go Along With Nice Registration Number, Gearbox Just Overhaul And Engine Leakage Required

<sup>a</sup>Fig.: 2000 Mercedes-Benz E200W, 2000 Mercedes-Benz C200K, Mercedes-Benz E200W, Mercedes-Benz C200K, Mercedes-Benz E200W, 2000 Mercedes-Benz C200K, 2000 Mercedes-Benz C200K.



<input type="checkbox"/> Mercedes-Benz E-Class E200ML (COE till 03/2029)	\$50,800	\$5,180 /yr	12-Dec-2000	1,998 cc	-	Luxury	Available
---	----------	-------------	-------------	----------	---	--------	-----------

Well Kept, Good Condition. \$50,800 With New 10 Years COE. Loan And Insurance Can Be Arrange

† From: 2000 Mercedes-Benz E280T, 7000-mile; 2004 Mercedes-Benz E280T, 69,000-mile; 2004 Mercedes-Benz E280T, 120,000-mile; 2004 Mercedes-Benz E280T, 120,000-mile.



<input type="checkbox"/> Mercedes-Benz E-Class E200ML (COE till 02/2026)	\$49,800	\$7,430 /yr	21-Feb-2006	1,796 cc	-	Luxury	Available
---	----------	-------------	-------------	----------	---	--------	-----------

*New Arrival Black Elegant Model With Light Grey, Clean And Neat Interior, No Oil Leak View To Believe By Appointment Only*

Tipos: 2006 Mercedes-Benz E200PL, 2006 Mercedes-Benz e300GL, Mercedes-Benz E200PL, Mercedes-Benz e300GL, Mercedes-Benz E200PL, Mercedes-Benz e300GL, Mercedes-Benz E200PL, Mercedes-Benz e300GL

Save this search criteria, to get email alerts whenever a match is found

**Save Space**

Make ▼ Model ▼ Price ▼ Depreciation ▼ Reg Date ▼ Eng Cap ▼ Mileage ▼ Veh Type ▼ Status ▼

For old advertisements, view [Expired ads](#).

20 • results / page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

Follow [sgCarMart.com](http://sgCarMart.com)



**Keywords:** child sexual abuse; disclosure; social support

Continued on page 100

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

## MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6744-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

Your Ref : SFJ4783Z

Our Ref : SDQ388U

Date : 02.07.2019

The Claims Manager

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78, Shenton Way #07-16

Singapore 079120

Tel : 6-419-300 Fax : 6-415-3727

Attn : The Motor Claim Dept

RE : ACCIDENT INVOLVING SDQ388U & SFJ4783Z ON 25.05.2019  
AT TRAFFIC JUNCTION BETWEEN MIDDLE ROAD & NORTH BRIDGE ROAD

---

We refer to the above matter.

We have been authorized by our client Mr Lim Lak Ching to make claim against your insured vehicle No.SFJ4783Z in respect of the above accident for the following:

Repair Cost	\$ 2,942.50	(Incl GST)
Loss of use (\$100 x 3 days)	\$ 300.00	
Search fee	\$ 2.00	
Total :	\$ 3,244.50	

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

## Jia Le (LKK Auto)

---

**From:** Chin <chin@modernautomotive.com.sg>  
**Sent:** Friday, 26 July 2019 3:05 PM  
**To:** Jia Le (LKK Auto)  
**Subject:** RE: TP Settlement SDQ388U (AIG)  
**Attachments:** 20190726151538.pdf

Dear Jia Le

Attached please find the duly signed DV for process of payment.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

---

**From:** Jia Le (LKK Auto) [mailto:JiaLe@lkkauto.com]  
**Sent:** Friday, July 26, 2019 11:14 AM  
**To:** Chin <chin@modernautomotive.com.sg>  
**Subject:** RE: TP Settlement SDQ388U (AIG)

Without Prejudice

Dear Grace,

DV attached.

Thank you.

Best Regards,  
**Carlor Chan** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chin [mailto:chin@modernautomotive.com.sg]  
**Sent:** Thursday, 25 July 2019 3:58 PM  
**To:** Jia Le (LKK Auto)  
**Subject:** RE: TP Settlement SDQ388U (AIG)

Dear Jia Le

We accept your offer of amount \$3184.50 in settlement of the above claims and please forward us your DV.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

---

**From:** Jia Le (LKK Auto) [mailto:[JiaLe@lkkauto.com](mailto:JiaLe@lkkauto.com)]  
**Sent:** Thursday, July 25, 2019 3:35 PM  
**To:** Chin <[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)>  
**Subject:** RE: TP Settlement SDQ388U (AIG)

Without Prejudice

Dear Sir/Mdm,

We refer to the above matter.

We propose settlement as follows:-

1. Cost of Repair (w/GST)	\$ 2,942.50
2. Loss of Use (3days x \$80.00)	\$ 240.00
3. LTA/GIA Search Fee	\$ 2.00
<b>TOTAL</b>	<b>\$ 3,184.50</b>

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,  
**Carlor Chan** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Chin [mailto:[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)]  
**Sent:** Tuesday, 2 July 2019 5:45 PM  
**To:** Asher Sng (LKKAuto)  
**Cc:** Jia Le (LKK Auto)  
**Subject:** Re: TP Settlement SDQ388U (AIG)

Dear Asher

We refer to the above matter.

Kindly confirm settlement below:

Repair Cost: \$2,942.50 (Incl GST)  
Loss of Use (\$100 x 3 days) : \$300.00  
Search fee: \$2.00  
Total: \$3,244.50

We enclosed herewith our LOD for your perusal and please revert.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

## Hsiao Tong (LKKAUTO)

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Monday, 29 July 2019 12:57 PM  
**To:** 'Joel Goh'  
**Cc:** Admin A  
**Subject:** <SEEK MANDATE> Direct Settlement - Accident Involving YM9731A (OI : EQI - DM19HO00957-JG) AND GX4798X (TP : LKK REF - CC6/EQI19006028/Upa3) on 13/02/2019  
**Attachments:** LKK SURVEY REPORT & PHOTOS.pdf; TP LOD & DOCS.pdf

EQ ref : **DM19HO00957-JG**  
LKK ref : CC6/EQI19006028/Upa3s2

Dear Sirs/Madam,

### ACCIDENT INVOLVING YM9731AJ(EQ-OI) / GX4798X(TP) / OTHERS ON 13/02/2019

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.  
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer Third Party repairer "**Jin Auto Services Pte Ltd**" at **\$11,625.00(all-in)**.

The summary is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$15,513.78	\$ 8,025.00
2. Loss of Use (60days x \$70.00)**	\$ 4,200.00	\$ 3,600.00 (60days x \$60.00)
Total	\$19,713.78	<b><u>\$11,625.00</u></b>

\*\* Third party vehicle was compounded at Traffic Police compound till 03/04/2019.  
Surveyor recommended 10days for repair.

Date:	Remark:	Days:
13/02/2019 (Wednesday)	Date of Accident	49days
03/04/2019 (Wednesday)	Notice for vehicle collection from traffic police	
04/04/2019 (Thursday)	Date of Inspection	1 day
		10 repair days
		<b><u>60 days</u></b>

Enclosed here with all the relevant documents for your perusal.

**Kindly let us have your approval/instruction.**



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19009349/Ada3

18 JUNE 2019

**TAN POH KOK**  
130T SOPHIA ROAD  
SINGAPORE 228185

Dear Sir/Madam,

**ACCIDENT INVOLVING SFJ 4783Z & SDQ 388U ALONG/AT MIDDLE ROAD QUEEN STREET ON 25/05/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SDQ 388U against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as your vehicle was making a right turn at the junction when accident happened. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE  
Case Handler  
DID: 6749 5792  
FAX: 6741 4108  
Email: [JiaLe@lkkauto.com](mailto:JiaLe@lkkauto.com)

c.c. *AIG Asia Pacific Insurance Pte Ltd*  
*(Motor Claims Dept)*

## LETTER OF AUTHORIZATION

Date: 27/5/19

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SDQ 388 U / SFJ 4783 Z

ON 25/5/19 ALONG Traffic Junction Between


Middle Road & North Bridge Road.

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

**MODERN AUTOMOTIVE PTE LTD** is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully



Signature of Owner

LIM LAK CHING

Name / NRIC S0574057F

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, MODERN AUTOMOTIVE PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$2,942.50 (Repair Cost), S\$240.00 (Loss of Use/Rental), S\$2.00 (Disbursement) for vehicle no. SDQ 388U that was damaged pursuant to the accident which occurred on 25/05/2019 (date) along TRAFFIC JUNCTION BETWEEN MIDDLE ROAD & NORTH BRIDGE ROAD (location) involving vehicle no/s SFJ 4783Z. This is pursuant to the inspection conducted on 10/06/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LIM LAK CHING ("the third party claimant") of vehicle no. SDQ 388U make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SDQ 388U (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 (day) of July (month) 20 19 (year)

  
LWP

Signed by appointed surveyor



Signed by "the workshop" (with chop)

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01-58 / 61 SINGAPORE 408717  
TEL : 67474422, 67454422 FAX : 67476720  
GST REG NO : 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY #07-16  
SINGAPORE 079120

Attention : Motor Claim Department  
Contact : 6415-3727 6419-3000

## Tax Invoice : TP001386

Date : 02/07/2019  
Vehicle Num : SDQ 388U  
Make/Model : MERCEDES / 210-2002  
Chassis/Eng# :  
Accident Date : 25/05/2019  
Claim No :  
Reference :  
Policy No : 5010919306-13

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		2,750.00
		Labour Total S\$ :		2,750.00

Total S\$ : 2,750.00  
GST @ 7% S\$ : 192.50  
Amount Due S\$ : 2,942.50  
=====

  
MODERN AUTOMOTIVE PTE LTD

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-19-082982

Date of Request: 27/05/2019

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 27/05/2019  
Enquiry By Chin Soi Shong  
TP Vehicle No. SFJ4783Z  
Accident Date 25/05/2019

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFJ4783Z	AIG Asia Pacific Insurance Pte. Ltd.	26/05/2018-25/05/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-19-082982

Date of Request: 27/05/2019

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 27/05/2019  
Enquiry By Chin Soi Shong  
TP Vehicle No. SFJ4783Z  
Accident Date 25/05/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane





































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019 <a href="#">Edit Reg</a>		10 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$42,750.00</b> <a href="#">Edit Estimates</a>	<b>\$42,750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>TAN POH KOK</b> , ID: S1163895C								
Main Claimant:	<b>LIM LAK CHING</b> , ID: S0574057F								
Vehicle Reg. No.:	<b>SDQ388U</b>	Date of Loss:	25/05/2019 17:00 - :59 [208 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 2752074634SG</b>	Policy/Cover Note No.:	(TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	<b>SFJ4783Z</b>	Policy No. (Claimant):	5010919306-13						
		Excess:							
Repairer:	<b>Modern Automotive Pte Ltd (HQ)</b> Blk 3023A Ubi Road 1, #01-61 & #01-58, 408717 Ubi - Tel: 6748 4422 / 6747 4422								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... [Final Rpt due 07/06/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SDQ388U (2752074634SG)  
[SFJ4783Z]  
TP  
LIM LAK CHING  
May 25 2019 5:00PM  
[TAN POH KOK]  
Modern Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1	Edit				
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
2	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
3	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
4	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
5	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
6	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
7	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
8	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
9	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
10	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
11	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
12	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
13	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
14	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
15	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
16	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
17	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
18	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
19	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
20	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
21	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
22	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
23	18/06/19 10:05		General View												1	Load JPG		<input checked="" type="checkbox"/>		
24	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
25	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
26	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
27	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
28	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
29	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
30	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
31	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
32	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
33	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		
34	18/06/19 10:06		General View												1	Load JPG		<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	18/06/19 10:06	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	18/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 12:07	TP GIA REPORT	 Load PDF	
2	18/06/19 13:50	TP ESTIMATE	 Load PDF	
3	13/08/19 08:53	WORKSHOP INVOICE	 Load PDF	
4	13/08/19 08:53	AUTHORISATION TO ACT FORM	 Load PDF	
5	13/08/19 08:53	Release Voucher	 Load PDF	
6	13/08/19 08:53	GIA SEARCH	 Load PDF	
7	13/08/19 08:53	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	29/05/19 11:22	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

Vehicle No:	SFJ4783Z (Insd veh)	Model:	MERCEDES-BENZ E200ML
	SDQ388U (TP veh)		2.0 (A)
Date of Accident:	25/05/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	7,886.44
Final Repair Cost	:	\$	2,942.50
Loss of Use	:	\$	240.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,184.50

3.00 days at \$80.00 per day  
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Modern Automotive Pte Ltd	:	\$ 3,184.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Aug  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19009349/ADA3Q2

Date: 13/08/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SDQ388U

**Insured Vehicle No :** SFJ4783Z

Date of Loss: 25/05/2019

Nature of Claim: TP

Claim No: 2752074634SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDQ388U**

Make & Model: MERCEDES-BENZ E200ML, 2.0 (A)

Engine No: 11195732331678

Reg. Date: 21/01/2002 (Man. Year: 2001)

Chassis No: WDB2100482B458238

Colour: Gold

Odometer: 188287 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,220.50	2,796.90	3,423.60	55.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	680.00	470.00	40.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,370.50</b>	<b>3,476.90</b>	<b>3,893.60</b>	<b>52.83</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,750.00</b>		
(S\$)	7,370.50	2,750.00	4,620.50	62.69
<b>+ GST 7.00/7.00% (S\$)</b>	515.94	192.50	323.44	62.69
<b>Nett Amount (S\$)</b>	<b>7,886.44</b>	<b>2,942.50</b>	<b>4,943.94</b>	<b>62.69</b>
<b>+ Loss of Use (3.0 x S\$80.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,184.50</b>		

### INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Modern Automotive Pte Ltd (HQ)  
Blk 3023A Ubi Road 1, #01-61 & #01-58  
Singapore 408717

Estimated Period of Repair: 3.0 days

---

**Adjuster:** ADRIAN LING

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE GARNISH	Deformed	121.00 FL	*121.00 FL
2	1		*FRONT BUMPER	Deformed	1,210.00 FL	*1,210.00 FL
3	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
4	2		*FRONT BUMPER SIDE HOLDER -LH & RH	Necessary	130.00 FL	*130.00 FL
5	2		*FRONT BUMPER CHROME MOULDING -LH& RH	Necessary	90.00 FL	*90.00 FL
6	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	98.00 FL	*- FL
7	2		*FRONT BUMPER FOG LAMP -LH & RH	Not Necessary	630.00 FL	*- FL
8	1		*FRONT BUMPER INNER MOULDING	Not Necessary	98.00 FL	*- FL
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	552.00 FL	*- FL
10	2		*FRONT BUMPER INNER SPONGE -LH & RH	Not Necessary	96.00 FL	*- FL
11	1		*BONNET	Repair	1,350.00 FL	*- FL
12	1		*BONNET LOGO	Not Necessary	125.00 FL	*- FL
13	1		*BONNET GRILLE	Cracked	585.00 FL	*585.00 FL
14	1		*HEAD LAMP -LH & RH	O/S Cracked	1,710.00 FL	*855.00 FL
15	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
16	1		*FRONT NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,905.00	3,101.00
- List Item Discount on L Items 10.00/10.00% (S\$)	684.50	304.10
Total Parts (S\$)	6,220.50	2,796.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS	New	600.00	400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	500.00	250.00
3	TO CHECK WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			1,150.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >