

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747-6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax : 6835 - 7416

Quotation

DATE : 07.06.2019
VEH NO : SDQ388U
MODEL : Merc E200
D O A : 25.05.2019
YR REF : SFJ4783Z

Jiale.

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SDQ388U (MERCEDES E200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Number Plate Garnish <i>Deband</i>	1	121.00 ✓
2	Front Bumper <i>Deband</i>	1	1,210.00 ✓
3	Front Bumper Clips <i>new</i>	1 set	50.00 ✓
4	Front Bumper Side Holder - LH & RH <i>new</i>	2	130.00 ✓
5	Front Bumper Chrome Moulding - LH & RH <i>new</i>	2	90.00 ✓
6	Front Bumper Lower Grille <i>new</i>	1	98.00 x
7	Front Bumper Fog Lamp - LH & RH <i>new</i>	2	630.00 x
8	Front Bumper Inner Moulding <i>Deband</i>	1	98.00 x
9	Front Bumper Reinforcement <i>new</i>	1	552.00 x
10	Front Bumper Inner Sponge - LH & RH	2	96.00 x
11	Bonnet <i>new</i>	1	1,350.00 x
12	Bonnet Logo <i>new</i>	1	125.00 x
13	Bonnet Grille <i>cracked</i>	1	585.00 ✓
14	Head Lamp - LH & RH <i>RT cracked</i>	2	1,710.00 855
			6,845.00
Less 10%			(684.50)
			\$ 6,160.50
S/NETT ITEMS			
1	Front Number Plate <i>Best</i>	1	30.00 ✓
2	Front Number Plate Holder <i>cracked</i>	1	30.00 ✓
Total Parts			\$ 6,220.50

LABOUR CHARGE

1 To knocking & pull out front portion & renew above parts \$ 600.00 ~~400~~

RE: ESTIMATE FOR ACCIDENT REPAIR SDQ388U (MERCEDES E200)

2 To putty & spray up paint works

\$ ~~500.00~~ 250

3 To check wiring

\$ ~~50.00~~ 30

Total Labour

\$ 1,150.00

Grand Total

\$ 7,370.50

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN
THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY
WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE
FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 3431.90

1/2: 2750

03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: