

Surveyor *Tayfun*

REF: A14 CC3/11619009354/T1td302

Meimen

ASSIGNMENT

From: Date: *27.5.2019*

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SGW 7667B*

at Workshop m/s *Premium Automobile*

of *24 Beni Sector*

Insured:

Policy No: *180000362*

Claims No: *7739034963*


Sum Insured: Excess: *162 \$600*

(Client's Record)

Make of Veh: *9.00 a.m - 11.00 a.m*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: *\$16510*

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *9* days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: *Chery* Vehicle: IN / OUT

Veh No: *SGW 7667B* Yr Regn: *2018, Jan*

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Audi A5 SB* cc *1984*

Colour: *Silver* A/C: Insured / Std / NI / NA

Sp. Reading: *13133* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: *W44222K51 JMO 49480*

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *245/40 R18*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *6* mm R/Bal. *6* mm

L/Bal. *6* mm L/Bal. *6* mm

D.O.A. D.O.I. *27/5/19 Q12pm*

Survey held at *Premium Beni*

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>28/5/19 @ 3:39pm</i>	<i>SGW 7667B - X</i>
<i>29/5/19 @ 10:21pm</i>	<i>authorise repair by Victor Koh</i>
<i>29/5/19 @ 11:33am</i>	<i>email to claims premium authorise repair excess \$600</i>

RECEIVED 21 JAN 2020

Part by Part \$17,183.52 (Red: 9339.43; 3670)

Date/Time, File Pass to? ☐ : Preli. Report

11/2/11 Typist ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *9*

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format : *OD*

Lump Sum / I.B.I: (\$ *17,183.52*)

700

11

211

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 29 May 2019 11:33 AM
To: 'Chang Chee Sing'
Subject: RE: SGW 7667B / OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGW 7667B (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 29 May 2019 9:20 AM
To: 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: SGW7667B / OD

Dear Sir,

Please note the excess at \$600

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199807198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nadaraja, Deeban

Date: 28 May 2019

Preliminary Advice

Vehicle No	: SGW7667B	Accident Date	: 10/05/2019
Make	: AUDI A5	Policy No.	: 1800003668
Assignment Date	: 28/05/2019	Excess	: S\$0.00
Date of Inspection	: 27/05/2019	Est. Duration of Repair	: 9.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	52,283.00
Revised Amount	:S\$	14,031.00
Check Items (Estimated)	:S\$	8,657.00
Total	:S\$	22,688.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	165,000.00
COE / PARF Rebate	:S\$	72,889.00
Salvage Value	:S\$	
Margin for Repair	:S\$	92,111.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7104B
Vehicle Details	
Vehicle No.:	SGW7667B
Vehicle to be Exported:	No
Intended Deregistration Date:	28 May 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	CVK050751
Chassis No.:	WAUZZZF51JA049480
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$37,949.00
Original Registration Date:	12 Jan 2018
First Registration Date:	12 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$45,129.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2028
PARF Rebate Amount:	\$33,846.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,289.00
COE Rebate Amount:	\$39,043.00
Total Rebate Amount:	\$72,889.00

The information contained herein is correct as at 28 May 2019

OK

View Received Message

This mail is associated with :

***SGW7667B (7739084963SG)**

OD

May 10 2019 10:00AM

[TAN CHENG HONG]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 29/05/2019 10:21 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14031.00) - SGW7667B - Claim Handler: Chan, Yoke Shi

Approved:14031.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

- OD claim # SGW7667B # 10/05/2019

From: Chan, Yoke Shi
To: claims@premiumauto.com.sg
Cc: Parthiban, Theerthan, Mohd Rizal, Nur Mariah Huibrechts, Lim, Sheng Yang, 'SUR'
Sent: 5/28/2019 3:40:20 PM

Dear Sir/Madam,

Kindly be informed that excess is S600.

Thank you

Regards,

Yoke Shi
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

yokeshi.chan@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/05/2019 14:38
Date Of Accident	10/05/2019 10:20
Exact Location Of Accident	ECP TOWARDS AYE (LAMP POST 188)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW7667B
Insured/Policyholder	
Name Of Registered Owner	TAN CHENG HONG
NRIC No	S1477104B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98159670
Alternative Phone No	OTHERS-98159670
Vehicle Particulars	
Manufacturer	AUDI
Model	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	TAN SHOU JIE, DARREN
NRIC No	S9118003J
Date Of Birth	08/05/1991
Occupation	INDOOR
Date Of Driving Pass	30/07/2010
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90721616
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 107 TECK WHYE LANE #12-538
Postcode	680107
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : CHIA MAN YUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKW7254L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



 Policyholder's Signature
 Date & Time: 10/5/19 15:10 hrs


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 10/5/19 3pm


 Reporting Centre Person's Signature
 Name: _____
 NRIC/FIN No.: _____

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE: SGW7667B	ACCIDENT DATE & TIME: 10/5/2019 10:20am
CONTACT NUMBER: 90721616	E-MAIL ADDRESS: dor91@live.com.sg
LOCATION: ICP towards ATE / lamp post number 188	
On 10 May 2019, around 10.20 am I was on the highway driving towards ATE highway, Traffic was slightly heavy and as I was slowing down coming to a stop, suddenly a car from behind bump into my rear and my car roll forward and bump into the front rear bumper. Subsequently I come down to assess the damage.	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
☐ Claim Own Policy	☒ Claim Third Party
☐ Claim OD/TP at other workshop	☐ Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time 10/5/19 15:10 hrs

Driver's Signature: Dave
(If driver is not the policyholder)
Date & Time: 10/5/19
3pm

Reporting Centre Personnel's Signature:
Name: _____
NIR/C/SH No. _____

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MM01A060801-01 Vehicle Registration No: SGW7667B
Name (as shown in NRIC) : Tan Cheng Hong NRIC/FIN/Passport No : 98159670
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore()
Contact (Tel) : _____ Mobile No. : 9815 9670
Email Address : _____
Date of Accident : _____ Time of Accident : _____
Place of Accident : _____
Insurance Company : AIG Insurance

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:


I would like to claim under own policy and then proceed with Recovery
against third party.



Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:



Name of Policyholder : TAN CHENG HONG
Period of Insurance : 12 Jan 2019 To 11 Jan 2020
Engine No. : CVK050751
Chassis No. : WAUZZZF51JA049480

Vehicle No. : SGW7667B
Policy No. : 1800003668-01
Endorsement No. :
Issued Date : 19 Dec 2018

Make/Model	AUDI A5 Sportback 2.0TFSI S Tronic (Design)		
Engine Capacity/Tonnage	1,984.00 CC	Sum Insured	Market Value
First Year of Registration	2018		
Driver Restriction	NA	Off Peak Car	No
Insuring with COE/PARF	Yes		
Person or Classes of Persons Entitled to Drive*			

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,900 as "Young and/or Inexperienced Driver Excess" ("YIDM") if you are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

¹ Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia). Not to be included under these headings.

Section 1
Fire - \$0; Own Damage - \$1800; Theft - \$0; Flood Cover - \$0

Section I
Property Damage - \$0

Wissenschaftsjahre 1990

Named Driver and Excess (where applicable)

TAN CHENG HONG - \$1600 (Own Damage)



1. And Customer Service Center Add: 38 Ubi Road 1 Singapore 408699 63962223

For safer, approved reporting centres/authorised repairers, please contact our 24-hour accident emergency hotline at +65 6338 8200. Alternatively, you may refer to AIG website www.aig.com.sg

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).)

0504125708

PREMIUM LEASING - SLOH

201 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Abstract

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0625/2019/CCS
Date : 25-May-19

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Cheng Hong
Address : Blk 107 Teck Whye Lane
#12-S38
Singapore 680107
Telephone : HP +65 98159670
Type of Claim : Third Party Claim
Policy No. : 1800003668-01
Vehicle No : **SGW 7667 B**
Model Code : Audi A5 SPORTBACK 2.0 TFSI
Model / Year : Jan-18
Engine No : CVK 050751
Chassis No : WAUZZZF51JA049480
Mileage : -
Date In : 13-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-May-19
Place of Accident : ECP TOWARDS AYE (LAMP POST 188)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGW 7667 B

S/N	Nature of Jobs	Estimated Charges	Surveyor Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓	✓
2	To dismantle and renew front bumper, both headlights and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 3,200.00 ✓ 500	✓
3	To respray front bumper and bonnet. ✕	\$ 2,200.00 ✓ 550	✓
TOTAL LABOUR CHARGES - FRONT		: \$ 5,880.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,073.00	de ✓ 1659.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	x
3	FRONT BUMPER SECURING STRIP	2 \$ 64.00	x
4	FRONT BUMPER GRILLE - LOWER CENTER	\$ 178.00	x
5	FRONT BUMPER CLOSING ELEMENT - LWR CTR	\$ 207.00	x
6	FRONT BUMPER SPOILER	\$ 489.00	x
7	FRONT BUMPER AIR GUIDE - LH/RH	2 \$ 112.00	x
8	RADIATOR GRILLE	\$ 2,131.00	de ✓ 1704.80
9	FRONT SENSOR SUPPORT - LH/RH	2 \$ 96.00	de ✓ 75.52
10	RADIATOR GRILLE COVER - UPPER	\$ 174.00	de ✓ ? x un
11	FRONT BUMPER AIR GRILLE - LH/RH	2 \$ 862.00	x un
12	FRONT REINFORCMENT BEAM	\$ 733.00	? x un
13	FRONT BUMPER FOAM - INNER	\$ 113.00	de ✓ 90.40
14	FRONT BUMPER TOP COVER	\$ 116.00	de ✓ 92.40
15	SIGN 'CAUTION' STICKER	\$ 13.00	de ✓ 9.76
16	STICKER FOR AIR CONDITIONER	\$ 7.00	de ✓ 5.12
17	FRONT LOCK CARRIER BRACKET	\$ 125.00	? x
18	FRONT BUMPER SUPPORT - LH/RH	2 \$ 52.00	? x
19	FRONT PARKING AID SENSOR - INNER	2 \$ 462.00	x
20	FRONT PARKING AID SENSOR SEAL	\$ 12.00	de ✓ x un
SUB SPARE PARTS CHARGES - FRONT		\$ 8,387.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BONNET	\$ 2,602.00	X
22	BONNET ATTACHMENT PARTS	\$ 111.00	✓
23	BONNET IMPACT PROTECTION - CENTER	\$ 25.00	X
24	BONNET IMPACT PROTECTION - LH/RH	2 \$ 50.00	✓
25	BONNET LOCK BOWDEN CABLE	\$ 53.00	X
26	BONNET LOCK RELEASE LEVER	\$ 12.00	✓
27	LED HEADLIGHT - LH/RH	2 \$ 14,408.00	X
28	FRONT NO. PLATE	S/N \$ 40.00	67 ✓
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 25,688.00
TOTAL LABOUR CHARGES - FRONT			\$ 5,880.00
TOTAL - FRONT			\$ 31,568.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGW 7667 B

S/N	Nature of Jobs	Estimated Charges	Surveyor Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓✓	
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ✓? ✓	
3	To dismantle and renew rear bumper. Cut out and weld rear end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,000.00 500. (2000) with end panel.	
4	To respray rear bumper and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 2,300.00 550 (1100) with end panel.	
5	To remove and renew center and both rear exhaust silencer. To align to position.	S/N \$ 480.00 P. plus to.	
6	To carry out diagnostic check.	S/N \$ 384.00 ✓✓	
TOTAL LABOUR CHARGES - (REAR)		: \$ 8,004.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,311.00	de ✓ 1842.80
2	REAR BUMPER FIXING PARTS	\$ 150.00	X nh
3	REAR BUMPER SECURING STRIP	\$ 203.00	acc ✓ 162.40
4	REAR BUMPER CHROME TRIM	\$ 928.00	mis ✓ 742.40
5	REAR BUMPER LIGHT REFLECTOR - LH/RH	\$ 76.00	29.63 1/2 LH-CR ✓ RH-X nh
6	REAR REINFORCEMENT BEAM	\$ 819.00	? H ✓ 655.20
7	SEAL REINFORCEMENT BEAM	2 \$ 25.00	X }
8	REAR BUMPER GUIDE - LOWER LH/RH	2 \$ 80.00	X }
9	REAR BUMPER GUIDE - UPPER LH/RH	2 \$ 40.00	X }
10	REAR BUMPER GUIDE LOCK PIN	2 \$ 5.00	X }
11	REAR PARKING AID SENSOR	4 1/4 \$ 924.00	1 - ✓ 739.20
12	REAR PARKING AID SENSOR O-RING	\$ 12.00	acc ✓ 8.96
13	REAR BUMPER WIRING HARNESS	\$ 618.00	X nh
14	REAR LID OPENING CONTROL UNIT	\$ 381.00	? dis ✓ 304.40
15	REAR LID OPENING SENSOR LINE	\$ 190.00	? X }
16	REAR LID OPENING CONTROL UNIT BRACKET	\$ 7.00	? X }
17	AERIAL FOR KEYLESS	\$ 102.00	? X }
18	REAR CROSS PANEL - OUTER	\$ 329.00	? H ✓ 262.80
19	REAR CROSS PANEL - INNER	\$ 577.00	X nh
20	REAR CROSS PANEL TRIM - UPPER	\$ 329.00	X nh
SUB PARTS REAR		\$ 8,106.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	REAR EXHAUST SILENCER - LH/RH	650 1/2 \$	RH X nh. 1,626.00 ? photo LH-b/v
22	REAR SILENCER DUAL CLIP	70-88 2/S	180.00 rel ✓ LH-b/v, RH-X nh
23	CENTRE SILENCER	\$	825.00 X b/v ✓ 659.60
24	CENTRE SILENCER DUAL CLIP	\$	45.00 X nh - X
25	REAR SILENCER BRACKET - LH/RH	2 \$	76.00 ? b/v ✓ 30.32
26	REAR SILENCER CHROME PIPE	\$	153.00 cut ✓ 122.40
27	ACRYLIC SEALER	S/N \$	180.00 ? nh - 180
28	CAVITY WAX	S/N \$	140.00 ? nh - 140
29	STONE CHIP	S/N \$	180.00 ? nh - 180
40	SUNDRIES	\$	1,200.00 4.48 nh ✓ 4.49
TOTAL SPARE PARTS CHARGES - REAR		:	\$ 12,711.00
TOTAL LABOUR CHARGES - REAR			\$ 8,004.00
TOTAL - REAR			\$ 20,715.00
GRAND TOTAL - FRONT & REAR			\$ 52,283.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

52664.60

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Tan Jiah 97495744
Ex: to be advise

Not Authorise

27/5/19 R 1230

6-9 days

Resurvey before paint

sure maintenance


28/5/19

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0625/2019/CCS
Date : 25-May-19

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian, Taufikh

9 days exclude 1 Sunday

and 1 PH - jb - 26 Aug 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Cheng Hong
Address : Blk 107 Teck Whye Lane
#12-538
Singapore 680107
Telephone : HP +65 98159670
Type of Claim : Third Party Claim
Policy No. : 1800003668-01
Vehicle No : **SGW 7667 B**
Model Code : Audi A5 SPORTBACK 2.0 TFSI
Model / Year : Jan-18
Engine No : CVK 050751
Chassis No : WAUZZZF51JA049480
Mileage : -
Date In : 13-May-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-May-19
Place of Accident : ECP TOWARDS AYE (LAMP POST 188)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGW 7667 B

S/N	Nature of Jobs	Estimated Charges	Surveyor Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, both headlights and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 3,200.00	\$ 500.00
3	To respray front bumper and bonnet.	\$ 2,200.00	\$ 550.00
TOTAL LABOUR CHARGES - FRONT		: \$ 5,880.00	\$ 1,530.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER SECURING STRIP	2 \$ 64.00	
4	FRONT BUMPER GRILLE - LOWER CENTER	\$ 178.00	
5	FRONT BUMPER CLOSING ELEMENT - LWR CTR	\$ 207.00	
6	FRONT BUMPER SPOILER	\$ 489.00	
7	FRONT BUMPER AIR GUIDE - LH/RH	2 \$ 112.00	
8	RADIATOR GRILLE	\$ 2,131.00	\$ 1,704.80
9	FRONT SENSOR SUPPORT - LH/RH	2 \$ 96.00	\$ 75.52
10	RADIATOR GRILLE COVER - UPPER	\$ 174.00	
11	FRONT BUMPER AIR GRILLE - LH/RH	2 \$ 862.00	
12	FRONT REINFORCMENT BEAM	\$ 733.00	
13	FRONT BUMPER FOAM - INNER	\$ 113.00	\$ 90.40
14	FRONT BUMPER TOP COVER	\$ 116.00	\$ 92.40
15	SIGN 'CAUTION' STICKER	\$ 13.00	\$ 9.76
16	STICKER FOR AIR CONDITIONER	\$ 7.00	\$ 5.12
17	FRONT LOCK CARRIER BRACKET	\$ 125.00	
18	FRONT BUMPER SUPPORT - LH/RH	2 \$ 52.00	
19	FRONT PARKING AID SENSOR - INNER	2 \$ 462.00	
20	FRONT PARKING AID SENSOR SEAL	\$ 12.00	
SUB SPARE PARTS CHARGES - FRONT		\$ 8,387.00	\$ 3,636.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 3,636.40
21	BONNET		\$ 2,602.00	
22	BONNET ATTACHMENT PARTS		\$ 111.00	
23	BONNET IMPACT PROTECTION - CENTER		\$ 25.00	
24	BONNET IMPACT PROTECTION - LH/RH	2	\$ 50.00	
25	BONNET LOCK BOWDEN CABLE		\$ 53.00	
26	BONNET LOCK RELEASE LEVER		\$ 12.00	
27	LED HEADLIGHT - LH/RH	2	\$ 14,408.00	
28	FRONT NO. PLATE	S/N	\$ 40.00	\$ 40.00
TOTAL SPARE PARTS CHARGES - FRONT			\$ 25,688.00	\$ 3,676.40
TOTAL LABOUR CHARGES - FRONT			\$ 5,880.00	\$ 1,530.00
TOTAL - FRONT			\$ 31,568.00	\$ 5,206.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGW 7667 B

S/N	Nature of Jobs		Estimated Charges	Surveyor Recommendation
		<i>Frt labour c/f</i>	\$ 5,880.00	\$ 1,530.00
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N	\$ 360.00	\$ 360.00
2	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N	\$ 480.00	\$ 480.00
3	To dismantle and renew rear bumper. Cut out and weld rear end panelling. Re-organise rear crash management components. Reinstall all parts removed.		\$ 4,000.00	\$ 2,000.00
4	To respray rear bumper and end panelling. To carry out joint sealer works and stone chip treatment.		\$ 2,300.00	\$ 1,100.00
5	To remove and renew center and both rear exhaust silencer. To align to position.	S/N	\$ 480.00	\$ 480.00
6	To carry out diagnostic check.	S/N	\$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES - (REAR)		:	\$ 13,884.00	\$ 6,334.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	<i>Front materials c/f</i>		\$ 3,676.40
1	REAR BUMPER	\$ 2,311.00	\$ 1,848.80
2	REAR BUMPER FIXING PARTS	\$ 150.00	
3	REAR BUMPER SECURING STRIP	\$ 203.00	\$ 162.40
4	REAR BUMPER CHROME TRIM	\$ 928.00	\$ 742.40
5	REAR BUMPER LIGHT REFLECTOR - LH/RH	2 \$ 76.00	\$ 29.68
6	REAR REINFORCEMENT BEAM	\$ 819.00	\$ 655.20
7	SEAL REINFORCEMENT BEAM	2 \$ 25.00	
8	REAR BUMPER GUIDE - LOWER LH/RH	2 \$ 80.00	
9	REAR BUMPER GUIDE - UPPER LH/RH	2 \$ 40.00	
10	REAR BUMPER GUIDE LOCK PIN	2 \$ 5.00	
11	REAR PARKING AID SENSOR	4 \$ 924.00	\$ 739.20
12	REAR PARKING AID SENSOR O-RING	\$ 12.00	\$ 8.96
13	REAR BUMPER WIRING HARNESS	\$ 618.00	
14	REAR LID OPENING CONTROL UNIT	\$ 381.00	\$ 304.40
15	REAR LID OPENING SENSOR LINE	\$ 190.00	
16	REAR LID OPENING CONTROL UNIT BRACKET	\$ 7.00	
17	AERIAL FOR KEYLESS	\$ 102.00	
18	REAR CROSS PANEL - OUTER	\$ 329.00	\$ 262.80
19	REAR CROSS PANEL - INNER	\$ 577.00	
20	REAR CROSS PANEL TRIM - UPPER	\$ 329.00	
SUB PARTS REAR		\$ 8,106.00	\$ 8,430.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGW 7667 B.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 8,430.24
21	REAR EXHAUST SILENCER - LH/RH (lhs)	2	\$ 1,626.00	\$ 650.00
22	REAR SILENCER DUAL CLIP	2	\$ 180.00	\$ 70.88
23	CENTRE SILENCER		\$ 825.00	\$ 659.60
24	CENTRE SILENCER DUAL CLIP		\$ 45.00	
25	REAR SILENCER BRACKET - LH/RH	2	\$ 76.00	\$ 30.32
26	REAR SILENCER CHROME PIPE		\$ 153.00	\$ 122.40
27	ACRYLIC SEALER	S/N	\$ 180.00	\$ 180.00
28	CAVITY WAX	S/N	\$ 140.00	\$ 140.00
29	STONE CHIP	S/N	\$ 180.00	\$ 180.00
30	Added parts - see attached		\$ 478.00	\$ 381.60
31	SUNDRIES		\$ 1,200.00	\$ 4.48
	Materials front/rear	:	\$ 13,189.00	\$ 10,849.52
	Labour charges front/rear		\$ 13,884.00	\$ 6,334.00
	Total		\$ 27,073.00	\$ 17,183.52

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0625/2019/CCS 30-May-19 Glory Tan 1 of 1 SGW 7667 B Audi A5 SPORTBACK 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	Loudspeaker housing with loudspeaker.	\$ 339.00	\$ 270.80	dis
2	Heat shield for rear silencer.	\$ 139.00	\$ 110.80	h
		\$ 478.00	\$ 381.60	
<u>LABORS</u>				
	TOTAL	\$ 478.00	\$ 381.60	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGW 7667 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0625/2019/NH

20TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SGW 7667 B, Audi A5 Sportback 2.0 TFSI.

With reference to the above-mentioned vehicle, no. **SGW 7667 B**, claimant, **Mr. Tan Cheng Hong**, please find the related document per attached.

1. A copy of the Original invoice no. 85014751 – S\$ 17,744.37.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SGW 7667 B

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014751 Date : 16/01/2020 Order : SGW7667B Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SGW7667B (V 36301)	Regn Date: 12/01/2018	Mileage: 13133	WIP No.: 53417
Model: A3 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF51JA049480	Engine: CVR 050751	Dept: U
You have been assisted by :- UB-Tony Poong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	550.00	1.00	550.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALER, CAVITY WAX AND STONE CHIP	500.00	1.00	500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	360.00	1.00	360.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD REAR END PANELLING. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	2000.00	1.00	2,000.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER AND END PANELLING.	1100.00	1.00	1,100.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
251 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
251 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9826 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 15:18

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014751 Date: 16/01/2020 Order: SGW7667B Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SGW7667B (V 36301) Regn Date: 12/01/2018 Mileage: 13133 WIP No.: 53417

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF51JA049480 Engine: CVK 050751 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT M:	480.00	1.00	480.00
S	BODYWORK	TO REMOVE AND RENEW CENTER AND LHS REAR EXHAUST SILENCER.TO ALIGN TO POSITION M:	384.00	1.00	384.00
X	ABW6807065D GRU	TO CARRY OUT DIAGNOSTIC CHECK COVER (LAST) Less 020%	1.00	2073.00	1,656.40
X	ABW6853651A RN4	GRILLE (LAST) Less 020%	1.00	2131.00	1,704.80
X	ABW6919267D RN4	007254/ (V) (GER) MOUNT Less 020%	1.00	47.20	37.76
X	ABW6919268D RN4	MOUNTING (LAST) Less 020%	1.00	47.20	37.76
X	ABW6807550J	FOAM INSER (LAST) Less 020%	1.00	113.00	90.40
X	ABW6807081B	COVER Less 020%	1.00	115.50	92.40
X	ABK0010520A	PLATE Less 020%	1.00	12.20	9.76
X	ABW0010515A	STICKER Less 020%	1.00	6.40	5.12
X	ABW6807067N GRU	COVER Less 020%	1.00	2311.00	1,848.80
X	ABW6807900	STRIP (LAST) Less 020%	1.00	203.00	162.40
X	ABW6853551A 222	MOLDING Less 020%	1.00	928.00	742.40
X	ABW6945105A	REFLECTOR Less 020%	1.00	37.10	29.68
X	A5Q0919275B GRU	(SK) SENSOR Less 020%	4.00	231.00	739.20
X	ABW7253609F	(V) (GER) SILENCER 29/ Less 020%	1.00	812.50	650.00
X	ABW0253141C	CLAMP Less 020%	1.00	44.30	35.44
X	ABW0253141C	CLAMP (LAST) Less 020%	1.00	44.30	35.44
X	ABW9253409	007269/ (V) (GER) MUFFL Less 020%	1.00	824.50	659.60
X	A4M0253144E	(SK) BRACKET Less 020%	1.00	37.90	30.32
X	ABW0071762	SPORT TAILPIPE TRIM Less 020%	1.00	153.00	122.40
X	A5Q0919133 704	WASHER Less 020%	4.00	2.80	8.96
X	A5Q0919133 704	WASHER Less 020%	2.00	2.80	4.48
X	ABW6813307A	REAR APRON Less 020%	1.00	328.50	262.80
X	ABW0807309	BRACKET Less 020%	1.00	819.00	655.20
X	A3AA962243H	CONTR.UNIT Less 020%	1.00	380.50	304.40
X	ABW9035382B	007259/ (V) (GER) LOUDS Less 020%	1.00	338.50	270.80
X	ABW0804172	007259/ (V) (SK) PLATE Less 020%	1.00	138.50	110.80

Parts 10,309.52
Labour 0.00
Sublet 6,874.00
Menus 0.00
Lubricant 0.00

Sub-Total 16,583.52

7% GST 1,160.85

Grand Total 17,744.37



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGW 7667 B

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0625/2019/TG
7 June 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SPORTBACK 2.0 TFSI
Vehicle Chassis No. : WAUZZZF51JA049480
Vehicle Regn No. : SGW 7667 B
Vehicle Mileage : 13133KM
Vehicle Owner : Mr. Tan Cheng Hong
Certificate No : 1800003668-01
Own Damage Excess : \$642.00 (Inclusive 7%GST)
Accident Date : 10/05/2019
Place : ECP towards AYE (Lamp Post 188)
Repair Cost : \$ 17,744.37
WIP No. : 53417
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 08/06/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 May 2019		28 May 2019 12:36 Edit Adj Rpt	\$417,183.52 Edit Estimates	\$417,183.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: TAN CHENG HONG , ID: S1477104B, Tel: +6598159670									
Vehicle Reg. No.: SGW7667B		Date of Loss: 10/05/2019 10:00 - :59 [15 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 7739084963SG		Policy/Cover Note No.: 1800003668 (Comprehensive)							
		Excess: \$600.00							
Repairer: Premium Automobiles Pte Ltd (Benol) 24 Benol Sector, 629857 Pioneer - Tel: 67689911 / 63882323									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Chan, Yoke Shi] yokeshi.chan@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 07/06/2019]									
Driver/Custodian: TAN SHOU JIE, DARREN (28 / Male) , NRIC: S91180031, Tel: +6590721616 Email: NOEMAIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/12/2019): Alert - Adj Mandate Approved (\$417183.52) - SGW7667B - Claim Handler: Chan, Yoke... - AIG_SG (26/11/2019): Alert - Adj Mandate Maintained - SGW7667B - Claim Handler: Chan, Yoke Shi - AIG_SG (29/05/2019): Alert - Adj Mandate Approved (\$14031.00) - SGW7667B - Claim Handler: Chan, Yoke...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGW7667B (7739084963SG)

OD

May 10 2019 10:00AM

[TAN CHENG HONG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser v		
Assessment Reports														1 per page v		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	28/05/19 15:38	Adjuster Immediate Advice												Load HTM			
														3 per page v		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail	Print		
1	28/05/19 13:52	Odometer Reading												Load JPG	☒		
2	28/05/19 13:52	Chassis Number												Load JPG	☒		
3	28/05/19 13:52	General View												Load JPG	☒		
4	28/05/19 13:52	General View												Load JPG	☒		
5	28/05/19 13:52	General View												Load JPG	☒		
6	28/05/19 13:52	General View												Load JPG	☒		
7	28/05/19 13:52	General View												Load JPG	☒		
8	28/05/19 13:52	General View												Load JPG	☒		
9	28/05/19 13:52	General View												Load JPG	☒		
10	28/05/19 13:52	General View												Load JPG	☒		
11	28/05/19 13:52	General View												Load JPG	☒		
12	28/05/19 13:52	General View												Load JPG	☒		
13	28/05/19 13:52	General View												Load JPG	☒		
14	28/05/19 13:52	General View												Load JPG	☒		
15	28/05/19 13:52	General View												Load JPG	☒		
16	28/05/19 13:52	General View												Load JPG	☒		
17	28/05/19 13:52	General View												Load JPG	☒		
18	28/05/19 13:52	General View												Load JPG	☒		
19	28/05/19 13:52	General View												Load JPG	☒		
20	28/05/19 13:52	General View												Load JPG	☒		
21	28/05/19 13:52	General View												Load JPG	☒		
22	28/05/19 13:52	General View												Load JPG	☒		
23	28/05/19 13:52	General View												Load JPG	☒		
24	28/05/19 13:52	General View												Load JPG	☒		
25	28/05/19 13:52	General View												Load JPG	☒		
26	28/05/19 13:52	General View												Load JPG	☒		
27	28/05/19 13:52	General View												Load JPG	☒		
28	28/05/19 13:52	General View												Load JPG	☒		
29	28/05/19 13:52	General View												Load JPG	☒		
30	28/05/19 13:52	General View												Load JPG	☒		
31	28/05/19 13:52	General View												Load JPG	☒		
32	28/05/19 13:52	General View												Load JPG	☒		
33	28/05/19 13:52	General View												Load JPG	☒		
34	28/05/19 13:52	General View												Load JPG	☒		
35	28/05/19 13:52	General View												Load JPG	☒		
36	28/05/19 13:52	General View												Load JPG	☒		
37	28/05/19 13:52	General View												Load JPG	☒		
38	28/05/19 13:52	General View												Load JPG	☒		
39	28/05/19 13:52	General View												Load JPG	☒		
40	28/05/19 13:52	General View												Load JPG	☒		
41	28/05/19 13:52	General View												Load JPG	☒		

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
42	28/05/19 13:52	General View		☒
43	28/05/19 13:52	General View		☒
44	28/05/19 13:52	General View		☒
45	28/05/19 13:52	General View		☒
46	28/05/19 13:52	General View		☒
47	28/05/19 13:52	General View		☒
48	28/05/19 13:52	General View		☒
49	28/05/19 13:52	General View		☒
50	28/05/19 13:52	General View		☒
51	28/05/19 13:52	General View		☒
52	28/05/19 13:52	General View		☒
53	28/05/19 13:52	General View		☒
54	28/05/19 13:52	General View		☒
55	26/11/19 17:31	Reinspection Photo		☒
56	26/11/19 17:31	Reinspection Photo		☒
57	26/11/19 17:31	Reinspection Photo		☒
58	26/11/19 17:31	Reinspection Photo		☒
59	26/11/19 17:31	Reinspection Photo		☒
60	26/11/19 17:31	Reinspection Photo		☒
61	26/11/19 17:31	Reinspection Photo		☒
62	26/11/19 17:31	Reinspection Photo		☒
63	26/11/19 17:31	Reinspection Photo		☒
64	26/11/19 17:31	Reinspection Photo		☒
65	26/11/19 17:31	Reinspection Photo		☒
66	26/11/19 17:31	Reinspection Photo		☒
67	26/11/19 17:31	Reinspection Photo		☒
68	26/11/19 17:31	Reinspection Photo		☒
69	26/11/19 17:31	Reinspection Photo		☒
70	26/11/19 17:31	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/05/19 13:53	Singapore Accident Statement		☐
2	28/05/19 13:53	Certificate of Insurance		☐
3	28/05/19 13:53	Driver's Driving License		☐
4	28/05/19 13:53	ESTIMATE		☐
5	01/11/19 11:45	supplementary		☐
6	07/11/19 09:33	ESTIMATE		☐
7	26/11/19 17:21	ESTIMATE MARKING		☐
8	21/01/20 15:28	Workshop Invoice		☐
9	21/01/20 15:28	Discharge Voucher		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	10/05/19 16:09	Addendum Sheet		☐
2	25/05/19 11:35	Addendum Sheet		☐
3	04/09/19 00:41	Accident Statement		☐
4	04/09/19 00:44	Accident Statement		☐
5	04/09/19 01:08	Accident Statement		☐
6	17/09/19 09:12	Addendum Sheet		☐
7	06/12/19 18:32	Accident Statement		☐
8	06/12/19 18:32	Accident Statement		☐
9	06/12/19 18:32	Accident Statement		☐
10	06/12/19 18:33	Accident Statement		☐
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print

Assessment Reports				1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/05/19 16:01	Accident Photo		Load JPG	☒
2	10/05/19 16:01	Accident Photo		Load JPG	☒
3	10/05/19 16:01	Accident Photo		Load JPG	☒
4	10/05/19 16:01	Accident Photo		Load JPG	☒
5	10/05/19 16:01	Accident Photo		Load JPG	☒
6	10/05/19 16:01	Accident Photo		Load JPG	☒
7	10/05/19 16:01	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)		Thumbnail	Print
1	10/05/19 15:51	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19009354/T1TD3E2

Date: 21/01/2020

REFERENCE

Insured/Claimant: TAN CHENG HONG Policy No: 1800003668
Date of Loss: 10/05/2019 Nature of Claim: OD Claim No: 7739084963SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW7667B**
Make & Model: AUDI A5, 2.0 TFSI QUATTRO (A) Engine No: CVK050751
Reg. Date: 12/01/2018 (Man. Year: 2017) Chassis No: WAUZZZF51JA049480
Colour: Silver Odometer: 13133 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$165,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	38,780.60	10,849.52	27,931.08	72.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,884.00	6,334.00	7,550.00	54.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,664.60	17,183.52	35,481.08	67.37
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	52,064.60	16,583.52	35,481.08	68.15
+ GST 7.00/7.00% (S\$)	3,644.52	1,160.85	2,483.67	68.15
Nett Amount (S\$)	55,709.12	17,744.37	37,964.75	68.15

INSPECTION

Date of Assignment: 28/05/2019
Date Inspected: 27/05/2019 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,073.00 FS	*1,658.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	368.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	64.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LOWER CENTER	Not Necessary	178.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LWR CTR	Not Necessary	207.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Not Necessary	489.00 FS	*- FS
7	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	112.00 FS	*- FS
8	1		*RADIATOR GRILLE	Cracked	2,131.00 FS	*1,704.80 FS
9	2		*FRONT SENSOR SUPPORT - LH / RH	Necessary	96.00 FS	*75.52 FS
10	1		*RADIATOR GRILLE COVER - UPPER	Not Necessary	174.00 FS	*- FS
11	2		*FRONT BUMPER AIR GRILLE - LH / RH	Not Necessary	862.00 FS	*- FS
12	1		*FRONT REINFORCEMENT BEAM	Not Necessary	733.00 FS	*- FS
13	1		*FRONT BUMPER FOAM - INNER	Deformed	113.00 FS	*90.40 FS
14	1		*FRONT BUMPER TOP COVER	Deformed	116.00 FS	*92.40 FS
15	1		*SIGN CAUTION STICKER	Necessary	13.00 FS	*9.76 FS
16	1		*STICKER FOR AIR CONDITIONER	Necessary	7.00 FS	*5.12 FS
17	1		*FRONT LOCK CARRIER BRACKET	Not Necessary	125.00 FS	*- FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	52.00 FS	*- FS
19	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	462.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR SEAL	Not Necessary	12.00 FS	*- FS
21	1		*BONNET	Not Necessary	2,602.00 FS	*- FS
22	1		*BONNET ATTACHMENT PARTS	Not Necessary	111.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - CENTER	Not Necessary	25.00 FS	*- FS
24	2		*BONNET IMPACT PROTECTION - LH / RH	Not Necessary	50.00 FS	*- FS
25	1		*BONNET LOCK BOWDEN CABLE	Not Necessary	53.00 FS	*- FS
26	1		*BONNET LOCK RELEASE LEVER	Not Necessary	12.00 FS	*- FS
27	2		*LED HEADLIGHT - LH / RH	Not Necessary	14,408.00 FS	*- FS
28	1		*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
29	1		*REAR BUMPER	Deformed	2,311.00 FS	*1,848.80 FS
30	1		*REAR BUMPER FIXING PARTS	Not Necessary	150.00 FS	*- FS
31	1		*REAR BUMPER SECURING STRIP	Necessary	203.00 FS	*162.40 FS
32	1		*REAR BUMPER CHROME TRIM	Missing	928.00 FS	*742.40 FS
33	1		*REAR BUMPER LIGHT REFLECTOR - LH / RH	N/S Cracked / O/S Not Necessary	76.00 FS	*29.68 FS
34	1		*REAR REINFORCEMENT BEAM	Bent	819.00 FS	*655.20 FS
35	2		*SEAL REINFORCEMENT BEAM	Not Necessary	25.00 FS	*- FS
36	2		*REAR BUMPER GUIDE - LOWER LH / RH	Not Necessary	80.00 FS	*- FS
37	2		*REAR BUMPER GUIDE - UPPER LH / RH	Not Necessary	40.00 FS	*- FS
38	2		*REAR BUMPER GUIDE LOCK PIN	Not Necessary	5.00 FS	*- FS
39	4		*REAR PARKING AID SENSOR	Not Working	924.00 FS	*739.20 FS
40	1		*REAR PARKING AID SENSOR O-RING	Necessary	12.00 FS	*8.96 FS
41	1		*REAR BUMPER WIRING HARNESS	Not Necessary	618.00 FS	*- FS
42	1		*REAR LID OPENING CONTROL UNIT	Distorted	381.00 FS	*304.40 FS
43	1		*REAR LID OPENING SENSOR LINE	Not Necessary	190.00 FS	*- FS
44	1		*REAR LID OPENING CONTROL UNIT BRACKET	Not Necessary	7.00 FS	*- FS
45	1		*AERIAL FOR KEYLESS	Not Necessary	102.00 FS	*- FS
46	1		*REAR CROSS PANEL - OUTER	Bent	329.00 FS	*262.80 FS
47	1		*REAR CROSS PANEL - INNER	Not Necessary	577.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*REAR CROSS PANEL TRIM - UPPER	Not Necessary	329.00 FS	*- FS
49	1		*REAR EXHAUST SILENCER - LH / RH	N/S Bent / O/S Not Necessary	1,626.00 FS	*650.00 FS
50	1		*REAR SILENCER DUAL CLIP	N/S Bent / O/S Not Necessary	180.00 FS	*70.88 FS
51	1		*CENTRE SILENCER	Bent	825.00 FS	*659.60 FS
52	1		*CENTRE SILENCER DUAL CLIP	Not Necessary	45.00 FS	*- FS
53	2		*REAR SILENCER BRACKET - LH / RH	Bent	76.00 FS	*30.32 FS
54	1		*REAR SILENCER CHROME PIPE	Cut	153.00 FS	*122.40 FS
55	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
56	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
57	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
58	1		*SUNDRIES	Necessary	1,200.00 FS	*4.48 FS
59	1		*LOUDSPEAKER HOUSING WITH LOUDSPEAKER	Distorted	270.80 FS	*270.80 FS
60	1		*HEAT SHIELD FOR REAR SILENCER	Bent	110.80 FS	*110.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	38,780.60	10,849.52
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,200.00	500.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,200.00	550.00
4	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS	New	480.00	480.00
6	TO DISMANTLE AND RENEW REAR BUMPER. CUT OUT AND WELD REAR END PANELLING. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,000.00	2,000.00
7	TO RESPRAY REAR BUMPER AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	2,300.00	1,100.00
8	TO REMOVE AND RENEW CENTER AND BOTH REAR EXHAUST SILENCER. TO ALIGN TO POSITION	New	480.00	480.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			13,884.00	6,334.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >