

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9872K**AAD1905-205**

3rd floor
Not Notarized
C/Sing \$ 1850

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB 9872K

VF1ABL15AUC273331

RENAULT

LATITUDE

22.5.19

CHINA TAIPING

30/8/2013

		PART	LIST	
1	1	BUMPER COVER REAR	\$ Rd/Bn 1,108.46	✓
2	1	BUMPER LOWER REAR	\$ Sn 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$ Sn 113.47	}
4	1	BUMPER BRACKET SIDE RH REAR	\$ Sn 135.97	
5	1	BUMPER RETAINER RH REAR	\$ Sn 44.99	
6	1	BUMPER REFLECTOR RH	\$ Sn 43.61	
7	1	BUMPER BRACKET SIDE LH REAR	\$ Sn 135.97	
8	1	BUMPER RETAINER LH REAR	\$ Sn 44.99	
9	1	BUMPER REFLECTOR LH	\$ Sn 43.61	
10	1	BUMPER BEAM REAR	\$ N 777.52	
11	1	BUMPER BEAM BRACKET LH REAR	\$ N 225.95	
12	1	BUMPER BEAM BRACKET RH REAR	\$ N 225.95	
13	1	OUTER PANEL REAR (End Panel)	\$ N 1,471.77	} X
14	1	OUTER PANEL REAR (End Panel)TRIM	\$ Sn 404.56	
15	1	TAILLAMP RH	\$ Sn 552.55	
16	1	TAILLAMP PANEL RH	\$ N 986.70	
17	1	TAILLAMP LH	\$ Sn 552.55	
18	1	TAILLAMP PANEL LH	\$ N 986.70	
19	1	BOOT REAR	\$ N 2,872.68	
20	1	BOOT FINISHER	\$ Sn 470.06	
21	1	BOOT WHEATERSTRIP	\$ Sn 323.05	
22	1	BOOT REFLECTOR LAMP LH	\$ Sn 493.35	
23	1	BOOT REFLECTOR LAMP RH	\$ Sn 493.35	
24	1	BOOT BADGE 'RENAULT'	\$ N 225.36	
25	1	BOOT BADGE	\$ N 225.36	
26	1	BOOT STRUT LH	\$ Sn 276.08	
27	1	BOOT STRUT RH	\$ Sn 276.08	
28	1	BOOT HINGE LH	\$ N 367.84	
29	1	BOOT HINGE RH	\$ N 367.84	

Trans-cab Auto Services Pte Ltd

AAD1905-205

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9872K

30	1	BOOT INNER TRIM	\$	586.45	X
31	1	BOOT SWITCH	\$	168.13	X
32	1	BOOT LOCK	\$	202.67	X
33	1	BOOT LOCK CATCH	\$	74.40	X
TOTAL			\$	16,046.87	
10%			\$	1,604.69	
			\$	14,442.19	

Special Nett

1	1SET	PARKING AID	\$	700.00	X
2	1SET	REAR BUMPER CLIP	\$	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	30.00	} X
11	1	BOOT STICKER "6555-3333"	\$	30.00	
12	1	EXHAUST MOUNTING REAR	\$	17.82	
13	2	REAR WINDSCREEN SEALANT	\$	80.00	
14	1	WINDSCREEN MOULDING	\$	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
16	1	BOOT INNER TRIM CLIP	\$	45.00	
17	1SET	BOOT FINISHER CLIP	\$	24.20	
18	1	TAILLAMP CLIP LH	\$	5.00	
19	1	TAILLAMP CLIP RH	\$	5.00	
TOTAL			\$	1,384.02	
TOTAL PARTS			\$	15,826.21	

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1905-205**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9872K

To reinstall rear bumper parking sensor.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	un X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	un X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To repair and realign rear exhaust pipe.	\$	170.00	un X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	un X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	un X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	un X
To check steering geometry and computer wheel alignment	\$	220.00	un X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	un X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	un X

TOTAL \$ 8,890.00**Over All Total \$ 24,716.21****LUMP SUM (REPAIR DAY) 10 DAYS**

2 days

the Repairer to notify the following:

- To repair the vehicle spray painting
- To deliver the vehicle during resurvey
- Parts to be replaced to confirmation
- Third party claims on a "Without Prejudice" basis
- No ill will (actions) is allowed
- Supplier (parts) must be resurveyed and is subject to approval from Insurer

Acknowledge Repairer