

22/03/2019

ASS. REC. BY:

REF: CS/CTI/9009390/USC13n2 Special Instruction:

Surveyor: Marius**ASSIGNMENT (Office)**From (Person): Chong Boon Sen of CTI Date/Time: 28/5/19 @ 9:19am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐ CSTo Inspect Vehicle No: SLZ 1223M Insured: GBH 5206Aat Workshop m/s Zoom Autowerks Tel: 9450 7920of 15 Kaki Bukit Rd 1 #01-53Policy No: \_\_\_\_\_ Claim No: SNM19D202376

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 26/5/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10:22am @ 28/5/19 Person Contacted: Clin Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction	
	<u>SLZ 1223M - NA/INC 19009321/24</u>	<u>D.O.A. - 26/05/2019</u>
	<u>GBH 5206A - NA/INC 19009321/24</u>	<u>D.O.A. 26/05/2019</u>

(08/11/19) waf

ASS. REC. BY: Marcus

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLZ1223M  
 at Workshop m/s Zoom  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 10 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS LTA37926  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SLZ1223M Yr Regn: 4, 18  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: Honda C.C. 1317  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 38315 T/Radio: Insured / Std / NI / NA  
 Eng/No: GK31316501  
 C/No: \_\_\_\_\_  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 175/70R14  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front 7 mm Rear 7 mm  
 R/Bal. 7 mm L/Bal. 7 mm  
 D.O.A. 26/5/19 D.O.I. 28/5/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction  
12/6/19 1/5 @ 8600 confirmed with Elin

(18,250.92 Red - 49%)

RECEIVED 4 JUN 2019

Date/Time, File Pass to?

14/06/19

1)

Typ: 4

Date/Time, File Return to?

2)

☐  
☒

Preli. Report

Final Report

Days Of Repair: 10Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$ 8,600/- HS)

TOTAL

120

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		28 May 2019 16:17 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

Insured:

Main Claimant: **PASUNI B MAULAN**, ID: S11079208

Vehicle Reg. No.: **SLZ1223M**      Date of Loss: 26/05/2019 23:00 - :59

Claim Type: **TP / SNM19D202376C02**      Policy/Cover Note No.: DMCVSN18204118000

Vehicle Reg. No. (Insured): **GBH5206A**      Policy No. (Claimant): 5109078467

Excess: S\$0.00

Repairer: **Zoom Auto Werks - Kaki Bukit (HQ)** BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE, 417808 Kaki Bukit - Tel: 94507920

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Chong Boon Sen**]

Claimant's Insurer: **NTUC Income Insurance Co-operative Ltd (HQ)** - Tel:

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Final Rpt due 07/06/2019]

**ASSOCIATED MAIL RECEIVED**

[View All](#)      [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#)      [Search Tasks](#)      [Create New Task](#)      [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Tuesday, 28 May 2019 9:19 AM  
**To:** Zoom Autowerks  
**Cc:** assignments  
**Subject:** RE: Pre-Repair Inspection for SLZ 1223 M // Accident on 26/05/2019 @ 23:00HR at along Junction of Clementi Road & Commonwealth Avenue West involving Vehicle Number SLZ 1223 M & GBH 5206 A / our ref: snm19d202376

**WITHOUT PREJUDICE**

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Zoom Autowerks [mailto:zoomautowerks@gmail.com]  
**Sent:** Tuesday, 28 May, 2019 8:54 AM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** Re: Pre-Repair Inspection for SLZ 1223 M // Accident on 26/05/2019 @ 23:00HR at along Junction of Clementi Road & Commonwealth Avenue West involving Vehicle Number SLZ 1223 M & GBH 5206 A / our ref: snm19d202376

Dear All,

Kindly arrange Marcus Chua for the survey.

On Tue, May 28, 2019, 08:51 Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)> wrote:

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

## Chong Boon Sen

Claims Executive

Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID (65) 63896171 | M. (65) XXXX XXXX | F. (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平狮城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID (65) 63896171 | M. (65) XXXX XXXX | F. (65) 6222 1033

From: Claims Dept of CTI

Sent: Tuesday, 28 May, 2019 8:50 AM

To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; [zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

Cc: Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>; Alfred Toh <[alfred.toh@sg.cntaiping.com](mailto:alfred.toh@sg.cntaiping.com)>; Chee So Chow <[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>

Subject: FW: Pre-Repair Inspection for SLZ 1223 M // Accident on 26/05/2019 @ 23:00HR at along Junction of Clementi Road & Commonwealth Avenue West involving Vehicle Number SLZ 1223 M & GBH 5206 A

Dear Boon Sen,

Please conduct PRS – TP: SLZ1223M (SNM19D202376) soonest possible.

File with OIC – Boon Sen - 63896171

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: Monday, 27 May 2019 5:39 PM

To: Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

Cc: Elaine Cheong <[elaine.cheong@eqinsurance.com.sg](mailto:elaine.cheong@eqinsurance.com.sg)>

Subject: Pre-Repair Inspection for SLZ 1223 M // Accident on 26/05/2019 @ 23:00HR at along Junction of Clementi Road & Commonwealth Avenue West involving Vehicle Number SLZ 1223 M & GBH 5206 A

Dear Sir/Madam,

We are instructed by Pasuni Bin Maulan to notify you of a road traffic accident on 26/05/2019 at about 23:00HR at along Junction of Clementi Road & Commonwealth Avenue West involving our client's vehicle registration number SLZ 1223 M and vehicle registration number GBH 5206 A driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

Warmest Regards,

Elin Cai

**Zoom Autowerks Pte Ltd**

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉[zoomautowerks@gmail.com](mailto:zoomautowerks@gmail.com)

**- Please note our change in mailing/registered address with effect from 1st July 2018 -**

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	7920B
<b>Vehicle Details</b>	
Vehicle No.:	SLZ1223M
Vehicle to be Exported:	No
Intended Deregistration Date:	29 May 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3GF CVT
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	L13B1419198
Chassis No.:	GK31316501
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$14,807.00
Original Registration Date:	24 Apr 2018
First Registration Date:	24 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2028
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Apr 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,389.00
COE Rebate Amount:	\$34,176.00
<b>Total Rebate Amount:</b>	<b>\$37,926.00</b>

The information contained herein is correct as at 29 May 2019

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/05/2019 19:56
Date Of Accident	26/05/2019 23:00
Exact Location Of Accident	JUNC CLEMENTI RD & COMMONWEALTH AVE WEST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1223M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PASUNI B MAULAN
NRIC No	S1107920B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90047819
Alternative Phone No	OFFICE-90047819

### Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3GF CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109078467
Cover Note Number	

### Driver

Name of Driver	PASUNI BIN MAULAN
NRIC No	S1107920B
Date Of Birth	17/10/1945
Occupation	INDOOR
Date Of Driving Pass	01/01/2009
Driving Experience	10 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90047819
Fax Number	
Contact Number	OFFICE-90047819
Email Address	NOEMAIL

Address	BLK 45 WOODLANDS STREET 32 #03-206
Postcode	730345
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SITI ZALIHA BTE MAT AMIN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20190527/7013.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH5206A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

# Accident Sketch Plan

SKETCH PLAN

Vehicle A: SLZ 1223M

Vehicle B: GBH 5206A



A

B


Wentworth Road


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- Refer to Police Report -

## DECLARATION

(/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NIC/FIN No.:

Scanned by CamScanner

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190527/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408855  
Tel No: 65470000

1 of 3

Report No. T/20190527/7013

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/05/2019 13:04	Vide Report No.: D/20190526/0142	Station Diary No.:
--	-------------------------------------	--------------------

### Informant's Particulars

Name of Informant: PASUNI BIN MAULAN	Address: APT BLK 345 WOODLANDS STREET 32 #03-206 SINGAPORE 730345		
ID Type / ID No.: NRIC NO / S1107920B	Contact No.:	Mobile: 90047819	
Nationality: SINGAPORE CITIZEN	Email: p_maulan@yahoo.com		
Sex: Male	Age: 73	Date of Birth: 17/10/1945	Type of Informant: Driver
Race: Javanese	Language: English	Institution / School Name:	
Occupation: Retiree	Driving Licence Information: Class:		Date of Expiry:

### General Information of the Accident

Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/05/2019 23:00	Type of Location: X-Junction
Location:  CLEMENTI ROAD			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way	Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH5206A	Lorry				Slightly Damaged	0
SLZ1223M	Car	HONDA	FIT 1.3GF CVT	Grey	Seriously Damaged	1

### Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLZ1223M	NTUC Income Insurance Co-Operative Limited	5109078467	24/04/2019	23/04/2020

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20190527/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20190527/7013

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	PASUNI BIN MAULAN	ID No.	S1107920B
Related Vehicle	SLZ1223M (Car)	Contact No.	90047819
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details

ON 26/05/2019, AT ABOUT 23:00HR, I WAS DRIVING MY VEHICLE - SLZ1223M, ALONG CLEMENTI ROAD ALONG WITH MY WIFE - SITI ZALIHA BTE MAT AMIN, NRIC: S2003516H. I WAS STATIONARY AT THE TRAFFIC LIGHT FOR A WHILE WHEN VEHICLE NUMBER - GBH5206A, HIT ONTO MY STATIONARY VEHICLE'S REAR PORTION.

Police Report



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20190527/7013

3 of 3

Report No. T/20190527/7013

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPB /  
YEO CHUN JIAN  
Contact No: 65476213

Authentication Stamp  
NP168

Signature Of Informant:

The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
27/05/2019 13:04

Classification Of Case:



# ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road  
#08-1339 Singapore 470130  
Tel: 9450 7920

\* zoomautowerks@gmail.com

Not Authorized

28 May 2019

2/2/19

28/5/19

4/5 #8600

10 day

Take place After repair

REG NO.: SLZ 1223 M  
MAKE/MODEL: HONDA FIT

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen glass	\$ shattered 1,285.60 ✓
2	Rear windscreen inner side garnishes	\$ 11 190.00 X
1	Rear windscreen moulding	\$ 11 150.80 ✓
1	Rear tailgate	\$ Body 1,014.60 ✓
2	Rear tailgate dampers	\$ 11 261.00 X
2	Rear tailgate hinges	\$ 11 150.00 X
1	Rear tailgate inner trim board	\$ Re/cne 300.30 ✓
2	Rear tailgate lamps	\$ cne 970.00 ✓
1	Rear tailgate lock	\$ 10/shut 157.20 ✓
1	Rear tailgate rubber	\$ 11 121.30 ✓
1	Rear tailgate "FIT" emblem	\$ 11 58.60 ✓
2	Rear number plate lamps	\$ 11 99.20 X
1	Rear tailgate outer garnish	\$ 370 285.00 ✓
1	Rear wiper arm	\$ 11 128.60 ✓
1	Rear wiper motor	\$ 11 435.20 ✓
2	Rear taillamps	\$ 11 1,171.00 ✓
2	Rear taillamp panels	\$ 11 811.00 1/2 ✓
2	Rear taillamp lower brackets	\$ 11 96.40 X
1	Rear end panel	\$ 11 686.80 ✓
1	Rear end panel inner garnish	\$ 11 185.50 ✓
1	Rear keyless sensor	\$ 11 195.80 X
1	Rear bumper	\$ 11 688.80 ✓
2	Rear bumper brackets	\$ 11 141.20 1/2 ✓
1	Rear bumper centre moulding	\$ 11 155.00 ✓
2	Rear bumper side mouldings	\$ 11 300.00 1/2 ✓
2	Rear bumper side grilles	\$ 11 214.60 X
2	Rear bumper side retainers	\$ 11 91.60 1/2 ✓
1	Rear floor board	\$ 11 280.50 ✓
1	Rear floor panel	\$ 11 1,600.80 X
1	Rear floor sponge tray board	\$ 11 307.50 X
1	Rear fender -L/H	\$ 11 877.30 ✓
2	Rear fender inner trim boards	\$ 11 671.20 ✓
		\$ 14,082.40
	Less 20%	\$ 2,816.48
		\$ 11,265.92

8655.20  
20%  
6924.16



**SPECIAL NETT ITEMS**

1	Rear windscreen sealant
1	Rear wiper blade
1	Rear bumper clip (1 set)
1	Rear reverse sensor (1 set)
1	Rear reverse camera
1	Rear number plate with holder
1	Rear fender quarter glass sealant

\$	rec	80.00	40
\$	11	45.00	X
\$	rec	50.00	30
\$	shuf	350.00	200
\$	shuf	480.00	350
\$	11	50.00	X
\$	rec	100.00	40
\$		<u>1,155.00</u>	

**S/N****LABOUR CHARGES**

1	To remove, replaced damaged lamps and check up rear wiring.
2	To remove and refit inner garnishes.
3	To remove and refit rear reverse sensor.
4	To transfer rear tailgate mechanism and wiring assembly.
5	To remove and refit fuel tank assembly with all attachments.
6	To remove and refit rear windscreen glass.
7	To apply undercoating.
8	Panel beating.
9	To re-spray painting on the affected areas.

\$	80.00	30
\$	150.00	80
\$	150.00	50
\$	120.00	60
\$	150.00	60
\$	180.00	120
\$	200.00	100
\$	1,800.00	1500
\$	1,600.00	1200
\$	<u>4,430.00</u>	

**GRAND TOTAL :****\$ 16,850.92**

I/We, the undersigned, hereby notify  
 the Insurer of the following:  
 • That the vehicle has been spray painted  
 • That the vehicle has been repaired (parts) during resurvey  
 • That the vehicle has been subject to confirmation  
 • That the vehicle has been on a "Without Prejudice" basis  
 • That the vehicle has been allowed  
 • That the vehicle must be resurveyed and  
 as such, with the approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date:

P - 6924.16  
 S.N - 660.00  
 (a/c) - 3200.00  
10784.16  
 201  
8627.32

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119009390/USD3N2  
Date: 17/06/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18204118000	
Claimant Vehicle No :	SLZ1223M	Insured Vehicle No :	GBH5206A	
Date of Loss:	26/05/2019	Nature of Claim:	TP	Claim No: SNM19D202376C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLZ1223M	Engine No:	L13B1419198
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK31316501
Reg. Date:	24/04/2018 (Man. Year: 2018)	Odometer:	38315 km
Colour:	Grey		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,420.92	7,584.16	4,836.76	38.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	3,200.00	1,230.00	27.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,850.92</b>	<b>10,784.16</b>	<b>6,066.76</b>	<b>36.00</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>8,600.00</b>		
<b>Nett Amount (\$\$)</b>	<b>16,850.92</b>	<b>8,600.00</b>	<b>8,250.92</b>	<b>48.96</b>

## INSPECTION

Date of Assignment:	28/05/2019	
Date Inspected:	28/05/2019	Inspected At: Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE Singapore 417808

Estimated Period of Repair: 10.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jun 2019)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ1223M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN GLASS	Shattered	1,285.60 FL	*1,285.60 FL
2	2	*REAR WINDSCREEN INNER SIDE GARNISHES	Not Necessary	190.00 FL	*- FL
3	1	*REAR WINDSCREEN MOULDING	Necessary	150.80 FL	*86.50 FL
4	1	*REAR TAILGATE	Badly Dented	1,014.60 FL	*859.30 FL
5	2	*REAR TAILGATE DAMPERS	Not Necessary	261.00 FL	*- FL
6	2	*REAR TAILGATE HINGES	Not Necessary	150.00 FL	*- FL
7	1	*REAR TAILGATE INNER TRIM BOARD	Deformed/Cracked	300.30 FL	*300.30 FL
8	2	*REAR TAILGATE LAMPS	Cracked	970.00 FL	*571.00 FL
9	1	*REAR TAILGATE LOCK	Dented/Shorted	157.20 FL	*157.20 FL
10	1	*REAR TAILGATE RUBBER	Twisted	121.30 FL	*121.30 FL
11	1	*REAR TAILGATE FIT EMBLEM	Necessary	58.60 FL	*58.60 FL
12	2	*REAR NUMBER PLATE LAMPS	Not Necessary	99.20 FL	*- FL
13	1	*REAR TAILGATE OUTER GARNISH	Broken	285.00 FL	*285.00 FL
14	1	*REAR WIPER ARM	Bent	128.60 FL	*128.60 FL
15	1	*REAR WIPER MOTOR	Bent/Jammed	435.20 FL	*435.20 FL
16	2	*REAR TAILLAMPS	Cracked	1,171.00 FL	*701.00 FL
17	1	*REAR TAILLAMP PANELS	N/s Dented	811.00 FL	*295.50 FL
18	2	*REAR TAILLAMP LOWER BRACKETS	Not Necessary	96.40 FL	*- FL
19	1	*REAR END PANEL	Badly Dented	686.80 FL	*366.50 FL
20	1	*REAR END PANEL INNER GARNISH	Twisted	185.50 FL	*185.50 FL
21	1	*REAR KEYLESS SENSOR	Not Necessary	195.80 FL	*- FL
22	1	*REAR BUMPER	Distorted	688.80 FL	*588.60 FL
23	1	*REAR BUMPER BRACKETS	N/s Cracked	141.20 FL	*65.00 FL
24	1	*REAR BUMPER CENTRE MOULDING	Cut	155.00 FL	*155.00 FL
25	1	*REAR BUMPER SIDE MOULDINGS	N/s Cut	300.00 FL	*150.00 FL
26	2	*REAR BUMPER SIDE GRILLE	Not Necessary	214.60 FL	*- FL
27	1	*REAR BUMPER SIDE RETAINERS	N/s Cracked	91.60 FL	*30.50 FL
28	1	*REAR FLOOR BOARD	Warped	280.50 FL	*280.50 FL
29	1	*REAR FLOOR PANEL	Repair	1,600.80 FL	*- FL
30	1	*REAR FLOOR SPONGE TRAY BOARD	Not Necessary	307.50 FL	*- FL
31	1	*REAR FENDER-L/H	Dented/Buckled	877.30 FL	*877.30 FL
32	2	*REAR FENDER INNER TRIM BOARDS	Deformed/Cracked	671.20 FL	*671.20 FL
33	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1	*REAR WIPER BLADE	Not Necessary	45.00 FS	*- FS
35	1	*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
36	1	*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
37	1	*REAR REVERSE CAMERA	Shorted	480.00 FS	*350.00 FS
38	1	*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
39	1	*REAR FENDER QUARTER GLASS SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,237.40 9,315.20  
 - List Item Discount on L Items 20.00/20.00% (\$\$) 2,816.48 1,731.04

Total Parts (\$\$) 12,420.92 7,584.16

Report was unsubmitted during this print-out.

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT FUEL TANK ASSEMBLY WITH ALL ATTACHMENTS	New	150.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO APPLY UNDERCOATING	New	200.00	100.00
8	PANEL BEATING	New	1,800.00	1,500.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,200.00
Gross Labour Cost (S\$)			<b>4,430.00</b>	<b>3,200.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;