

22/03/2019

ASS. REC. BY:

REF: CS/FCI19009346/Asd3

Special Instruction:

Sponsor: Adrian

ASSIGNMENT (Office)

From (Person): Karen Tan

of

FCI

Date/Time: 12:54pm 28/5/19

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDF 1103B

Insured:

SHD 4396R

at Workshop m/s

Woodlands Transport Service (WTS)

Tel:

6844 9449 / 6844 9457

of

17 Kaki Bukit Rd 4 # 01-58

Policy No:

Claim No:

D19003467MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 25/05/2019

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

2:32pm 28/5/19

Person Contacted:

Idrum

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ✓

SDF 1103B-X

SHD 4396R-CC3/11G1702 0461/K/hb392

D.O.A. 22/10/17

30/05/19

@ 16:12 pm revert pending estimate from reparker to Karen via email.

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Police Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SDF1103B

Yr Regn: 2010 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C180 c.c. 1796

Colour: Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 110606 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD20404924378040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 29/05/19

Survey held at WTS

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

18/06/19 Confirmed HS \$ 11,000/- @ 10 days with Adrian

(\$ 12,348.85 Red - 53%)

MV : 37K

PV : 25.9K

Nett: 11.1K

MV - \$ 37K

LTA - \$ 25,942.00

Nett - \$ 11,058.00

RECEIVED 18 JUN 2019

Resurvey No. of TP - 2

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date: 12x15=180

1) 18/06/19

2)

IN

OUT

3) TPAST

4)

Basic & Add.

S + RS + SI

Photos

Others

TOTAL

170+180

50

50+50

128

628

Preli. Report:

Final Report \$ 11,000/- 2/5

19/6/19

MOTOR SURVEY ASSIGNMENT

Date	27-05-2019	Our Ref No. D19003469MFSH
Accident Date	25-05-2019	Claim Type. Third Party
Insured Vehicle	SHD4396R	Third Party Vehicle. SDF1103B
Survey Location	17 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTRE #01-58	
Contact Person.	MUHAMMAD IDRAM	
Contact No.	68449449/ 0	Fax No. 68449463
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WOODLANDS TRANSPORT SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 30 May 2019 4:12 PM
To: 'Karen Tan'; 'CWS Motor Claims'
Cc: assignments; SUR
Subject: RE: SURVEY ASSESSMENT - D19003469MFSH/1

Dear Karen,

Please be informed that we have inspected the vehicle SDF 1103B on 29/05/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 28 May 2019 3:51 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Karen Tan' <karentan@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19003469MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Tuesday, 28 May 2019 12:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003469MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System


Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

CHEAPEST CAR INSURANCE RENEWAL


Choice of
\$0 excess

Option of any
workshop

GET A CHEAPER QUOTE NOW!

SEARCH

c180

Price Range

Depreciation

2010

Vehicle Type

Search

View All

Advanced Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Mercedes-Benz C-Class C180 CGI

Mercedes-Benz C-Class C180 CGI
Avantgarde

Mercedes-Benz C-Class C180 CGI

Mercedes-Benz C-Class C180 CGI



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Add to Shortlist

CAR DETAILS

Price	\$36,888	\$37,800	\$37,300	\$39,800
Instalment	\$1,909	\$1,830	\$1,806	\$1,927
Registration Date	02-Aug-2010	15-Sep-2010	17-Sep-2010	22-Sep-2010
Manufactured	2010	2010	2010	2010
Mileage	133,000 km	-	102,000 km	148,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,796 cc	1,796 cc	1,796 cc	1,796 cc
Road Tax	\$974 /yr	\$974 /yr	\$974 /yr	\$974 /yr
Power	115.0 kW (154 bhp)	115.0 kW (154 bhp)	115.0 kW (154 bhp)	115.0 kW (154 bhp)
Curb Weight	1,495 kg	1,495 kg	1,495 kg	1,495 kg
Features	1.8L CGI Inline 4 Cylinder Turbocharged Engine, 154BHP, 250NM, 5 Speed Auto, 6 x SRS Airbags, 4 x ABS Disc Brakes, Cruise Control. 0 To 100Km/H: 8.5s	1.6L 4 Cylinders Inline Supercharged Engine, 5 Speed Automatic Transmission, Cruise Control, SRS Airbags, ABS, Auto Headlights And Rain Sensors.	Smooth And Reliable 1.8L Turbocharged Engine Deliver 154BHP. Automatic Transmission. Multi Function Steering. New Mounting Set Just Changed.	1.8L CGI Inline 4 C Engine, 156BHP, 2 6 x SRS Airbags, 4 Cruise Control. 0 To 100Km/H: 8.5s
Accessories	17" Original Alloy Wheels, Brown Leather Upholstery Retractable Side Mirrors, Reverse Camera And Sensors, Rear Knockdown Seats.	Leather Seats, Sports Rims, Integrated Bluetooth Telephony, LCD Monitor, Reverse Camera And Sensors, CD Changer, Fog Lamps.	Reverse Camera And Sensors. Front Electric Seats. Passenger Aircon. Original Mercedes Rims. Integrated Bluetooth Telephony.	17" Original Alloy V Upholstery Retractable Side Mirrors, Reverse Camera And Sensors, Rear Knockdown Seats.
Description	Powerful And Responsive Luxury Small Sedan. Excellent Fuel Efficiency Compare To Its Predecessor Kompressor. Ideally For New Business Owner On Budget To Have A MercZ. Great For Young Management Office Holder, Ideally For GoJekker And Grabber For PHV. Immaculate Condition. See To Believe. Trade In Available, Major Bank Loan, High In House Loan, Balloon/Leasing Scheme Available. Contact Us Now.	100% Loan Available. High Trade In. Reliable Luxury Sedan. Low Mileage. No Repair Needed, Powerful And Economical Drive With Well Balance Handling. Accident Free, Well Kept Interior, Running On The Current Gen 1.8L Turbocharged Engine, Powerful Yet Fuel Efficient Paired With The Proven And Smooth Transmission. Best Buy For Short Term Drive. Call Us To View The Car Before It's Gone.	In Immaculate Condition C180 CGI Looking For New Owner. Superbly Maintained. Original Paintwork. Stock Condition. Ideal For Daily Driven Transportation. Powerful Yet Fuel Efficiently. No Gimmick. Call Us For Viewing.Trade In Welcome. Easy Financing.	Lady Owner! Well Maintained. That Just Change 1 More With Receipts Well Maintained C1 Hurry, Call For App
COE	\$42,889	\$42,810	\$41,010	\$42,889
OMV	\$38,917	\$38,917	\$38,917	\$38,917
ARF	\$38,917	\$38,917	\$38,917	\$38,917
Depreciation	\$14,790 /yr	\$14,120 /yr	\$13,680 /yr	\$15,440 /yr
No. of Owners	2	2	2	3
Type of Vehicle	Luxury	Luxury	Luxury	Luxury
Category	PARF Car	PARF Car	PARF Car	PARF Car, Consign
Availability	Available	Available	Available	Available

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Singapore NRIC
Owner ID:	8150J
Vehicle Details	
Vehicle No.:	SDF1103B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 May 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 CGI
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	27182030045478
Chassis No.:	WDD2040492A378040
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$38,917.00
Original Registration Date:	20 Jul 2010
First Registration Date:	20 Jul 2010
Transfer Count:	0
Actual ARF Paid:	\$38,917.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jul 2020
PARF Rebate Amount:	\$21,404.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$39,911.00
COE Rebate Amount:	\$4,538.00
Total Rebate Amount:	\$25,942.00

The information contained herein is correct as at 29 May 2019

OK

Spare Parts (Appendix A)

Vehicle No. : SDF1103B Submit By : IDRAM
Make & Model : MERCEDES C180 CGI Year Manufacture : 2010
Chassis No. : MR053HY9305002665 Engine No. : 27182030045478

S/No.	Part Description	Qty	Cost Price	Disposition by Surveyor
1	FRONT BONNET <i>Painted</i>	1	\$1,450.00	✓
2	FRONT BONNET SEAL <i>cut</i>	1	\$35.00	✓
3	FRONT BONNET SPRING LH <i>? Missing</i>	1	\$45.00	✓
4	FRONT BONNET SPRING RH <i>new</i>	1	\$45.00	✓
5	FRONT BONNET LOGO <i>new</i>	1	\$80.00	✓
6	FRONT RHS TOP PANEL <i>Beckled</i>	1	\$180.00	✓
7	FRONT RHS TOP PANEL COVER <i>Beckled</i>	1	\$55.00	✓
8	RHS HEADLAMP <i>cut</i>	1	\$880.00	✓
9	RHS HEADLAMP MOULDING <i>cut</i>	1	\$50.00	✓
10	FRONT TOP SUPPORT PANEL <i>Bent</i>	1	\$150.00	✓
11	FRONT TOP SUPPORT PANEL COVER <i>Beckled</i>	1	\$200.00	✓
12	FRONT TOP GRILLE BRACKET <i>Beckled</i>	1	\$25.00	✓
13	RADIATOR GRILLE WITH LOGO <i>cut</i>	1	\$740.00	✓
14	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$440.00	✓
15	FRONT BUMPER REINFORCEMENT COVER <i>Not New</i>	1	\$110.00	✓
16	FRONT BUMPER SPONGE <i>Beckled</i>	1	\$120.00	✓
17	FRONT BUMPER SIDE CHROME LH <i>new</i>	1	\$88.00	✓
18	FRONT BUMPER SIDE CHROME RH <i>new</i>	1	\$88.00	✓
19	REAR BUMPER <i>Beckled</i>	1	\$1,300.00	✓
20	REAR BUMPER CHROME <i>Distorted</i>	1	\$140.00	✓
21	REAR BUMPER TOWING COVER <i>Beckled</i>	1	\$65.00	✓
22	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$230.00	✓
23	REAR BUMPER RETAINERS LH <i>new</i>	1	\$45.00	✓
24	RADIATOR <i>Bent</i>	1	\$880.00	✓
25	CONDENSER <i>Bent</i>	1	\$1,120.00	✓
26	RADIATOR SUPPORT PANEL <i>Bent</i>	1	\$440.00	✓
27	RADIATOR TOP HOSE LH <i>new</i>	1	\$75.00	✓
28	RADIATOR BOTTOM HOSE RH <i>new</i>	1	\$75.00	✓
29	FRONT PASSENGER HEAD REST <i>Repair</i>	1	\$770.00	✓
30	EXHAUST MUFFLER <i>Bent</i>	1	\$1,500.00	✓
31	EXHAUST CHROME PIPE <i>Bent</i>	1	\$180.00	✓
Sub total			\$11,601.00	
Cost + 15%			\$1,740.15	
Total on parts			\$13,341.15	
Special Nett Items				
1	REVERSE SENSOR <i>Beckled</i>	1	\$280.00	200
2	FRONT NUMBER PLATE CASING HOLDER <i>? new</i>	1	\$80.00	30
3	FRONT NUMBER PLATE WITH CASING	1	\$80.00	30
Total on special nett			\$440.00	
LABOUR CHARGE				
1	TO REMOVE & REFIT ALL DAMAGED PARTS	1	\$1,800.00	1600
2	TO PUTTY & SPRAY FRONT HOOD, FRONT BUMPER, REAR BUMPER	1	\$1,200.00	1000
Total on Labour			\$3,000.00	
Total on labour			\$3,000.00	
Total on parts			\$13,341.15	
Total on SN			\$440.00	16781.15
Sub-Total			\$17,781.15	23,378.85
GST			\$1,205.48	
Grand total			\$18,426.63	22938.85

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

TP 1st Cap
Shirley

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10571
9513.90

2600

2600

Adrian L
H/S 29/03/19
10 days

Supplementary: 3480.30
Total: 15854.20
H/S: 11K

Spare Parts

Vehicle No. : SDF1103B

Submit By : IDRAM

Make & Model : MERCEDES C180 CGI

Year Manufacture : 2010

Chassis No. : MR053HY9305002665

Engine No. : 27182030045478.00

Supplementary

Cost / List

S/No.	Part Description	Qty	Cost Price	List Price	Disposition by Surveyor
S1	FRONT BUMPER <i>replaced</i>	1	\$ 1,099.00	✓	
S2	RH SIDE FRONT FENDER <i>replaced</i>	1	\$ 720.00	+	
S3	LHS HEADLAMP <i>replaced</i>	1	\$ 880.00	✓	
S4	LHS HEADLAMP MOULDING <i>new</i>	1	\$ 50.00	✓	
S5	BONNET LOCK <i>new</i>	1	\$ 65.00	+	
S6	REAR BUMPER RETAINERS CENTRE <i>replaced</i>	1	\$ 65.00	✓	
S7	REAR BUMPER RETAINERS RH <i>new</i>	1	\$ 45.00	✓	
S8	REAR TYRE MUDGUARD <i>new</i>	1	\$ 166.00	+	
S9	EXHAUST SCREEN <i>replaced</i>	1	\$ 140.00	✓	
S10	SPARE TYRE WHEEL WELL <i>for</i>	1	\$ 288.00	✓	
S11	PIRELLI P7 CINTURATO 225/45R17 <i>new</i>	1	\$ 280.00	+	
	SUB TOTAL		\$ 3,798.00		
	COST +15%		\$ 569.70		
	TOTAL PARTS		\$ 4,367.70		
	SPECIAL NETT				
S1	REVERSE SENSOR MODULE <i>replaced</i>	1	\$ 250.00	✓	
S2	AIRCON GAS AND VACUUM <i>new</i>	1	\$ 80.00	✓	
S3	POWER STEERING OIL <i>new</i>	1	\$ 60.00	40	
	TOTAL SPECIAL NETT		\$ 390.00		
	SUPPLEMENTARY LABOUR				
S1	TO REPAIR REAR PANEL	1	\$ 750.00	400	
S2	TO PUTTY AND SPRAY RHS FRONT FENDER, REAR PANEL	1	\$ 500.00	400	
S3	COMPUTER WHEEL ALIGNMENT	1	\$ 150.00	+	
	TOTAL LABOUR		\$ 1,400.00		
	TOTAL ON LABOUR		\$ 1,400.00		
	TOTAL PARTS		\$ 4,367.70		
	TOTAL SPECIAL NETT		\$ 390.00		
	SUB TOTAL		\$ 6,157.70		
	GST		\$ 431.04		
	GRAND TOTAL		\$ 6,588.74		

2567
2310.30

370

800

Adrian
29/05/19

Supplementary
3480.30

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19009396/Asd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 26-06-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4396R	Veh. Inspected	SDF 1103B	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19003469MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	28/05/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C180	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2040492A378040	Colour	GREY	
Odometer	110606	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	PIRELLI	6 mm	
L/H Front Tyre	225/45 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/05/2019	Inspection Date	29/05/2019	
Survey held at	WTS AUTOMOTIVE SERVICES PTE LTD (PITSTOP @ BARTLEY) 17 KAKI BUKIT ROAD 4 #01-58/59/60/61/62 BARTLEY BIZCENTRE S(417809)			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 1103B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET (WCP)	DENTED	1,450.00	1,450.00
1	FRONT BONNET SEAL (WCP)	CUT	35.00	35.00
1	FRONT BONNET SPRING LH (WCP)	MISSING	45.00	45.00
1	FRONT BONNET SPRING RH (WCP)	MISSING	45.00	45.00
1	FRONT BONNET LOGO (WCP)	NECESSARY	80.00	80.00
1	FRONT RHS TOP PANEL (WCP)	BUCKLED	180.00	180.00
1	FRONT RHS TOP PANEL COVER (WCP)	DEFORMED	55.00	55.00
1	RHS HEADLAMP (WCP)	CRACKED	880.00	880.00
1	RHS HEADLAMP MOULDING (WCP)	CUT	50.00	50.00
1	FRONT TOP SUPPORT PANEL (WCP)	BENT	150.00	150.00
1	FRONT TOP SUPPORT PANEL COVER (WCP)	DEFORMED	200.00	200.00
1	FRONT TOP GRILLE BRACKET (WCP)	DAMAGED	25.00	25.00
1	RADIATOR GRILLE WITH LOGO (WCP)	CRACKED	740.00	740.00
1	FRONT BUMPER REINFORCEMENT (WCP)	BENT	440.00	440.00
1	FRONT BUMPER REINFORCEMENT COVER (WCP)	NOT NECESSARY	110.00	-
1	FRONT BUMPER SPONGE (WCP)	DEFORMED	120.00	120.00
1	FRONT BUMPER SIDE CHROME LH (WCP)	NECESSARY	88.00	88.00
1	FRONT BUMPER SIDE CHROME RH (WCP)	NECESSARY	88.00	88.00
1	REAR BUMPER (WCP)	DEFORMED	1,300.00	1,300.00
1	REAR BUMPER CHROME (WCP)	DISTORTED	140.00	140.00
1	REAR BUMPER TOWING COVER (WCP)	DEFORMED	65.00	65.00
1	REAR BUMPER REINFORCEMENT (WCP)	BENT	230.00	230.00
1	REAR BUMPER RETAINERS LH (WCP)	NECESSARY	45.00	45.00
1	RADIATOR (WCP)	BENT	880.00	880.00
1	CONDENSER (WCP)	BENT	1,120.00	1,120.00
1	RADIATOR SUPPORT PANEL (WCP)	BENT	440.00	440.00
1	RADIATOR TOP HOSE LH (WCP)	NOT NECESSARY	75.00	-
1	RADIATOR BOTTOM HOSE RH (WCP)	NOT NECESSARY	75.00	-
1	FRONT PASSENGER HEAD REST (WCP)	TO REPAIR SEE LABOUR	770.00	-
1	EXHAUST MUFFLER (WCP)	BENT	1,500.00	1,500.00

Report Ref No. CS/FCI19009396/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST CHROME PIPE (WCP)	BENT	180.00	180.00
1	FRONT BUMPER (ADDITIONAL) (WCP)	DISTORTED	1,099.00	1,099.00
1	RH SIDE FRONT FENDER (ADDITIONAL) (WCP)	TO REPAIR SEE LABOUR	720.00	-
1	LHS HEADLAMP (ADDITIONAL) (WCP)	CRACKED	880.00	880.00
1	LHS HEADLAMP MOULDING (ADDITIONAL) (WCP)	NECESSARY	50.00	50.00
1	BONNET LOCK (ADDITIONAL) (WCP)	NOT NECESSARY	65.00	-
1	REAR BUMPER RETAINERS CENTRE (ADDITIONAL) (WCP)	DAMAGED	65.00	65.00
1	REAR BUMPER RETAINERS RH (ADDITIONAL) (WCP)	NECESSARY	45.00	45.00
1	REAR TYRE MUDGUARD (ADDITIONAL) (WCP)	NOT NECESSARY	166.00	-
1	EXHAUST SCREEN (ADDITIONAL) (WCP)	CRUMPLED	140.00	140.00
1	SPARE TYRE WHEEL WELL (ADDITIONAL) (WCP)	TORN	288.00	288.00
1	PIRELLI P7 CINTURATO 225/45 R17 (ADDITIONAL) (WCP)	NOT NECESSARY	280.00	-
	LESS 10% DISCOUNT		-	-1,313.80
	COST PLUS 15%		2,309.85	-
			17,708.85	11,824.20
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	FRONT NUMBER PLATE CASING HOLDER (SN)	DAMAGED	80.00	30.00
1	FRONT NUMBER PLATE WITH CASING (SN)	DAMAGED	80.00	30.00
1	REVERSE SENSOR MODULE (ADDITIONAL) (SN)	DAMAGED	250.00	250.00
1	AIRCON GAS AND VACUUM (ADDITIONAL) (SN)	NECESSARY	80.00	80.00
1	POWER STEERING OIL (ADDITIONAL) (SN)	NECESSARY	60.00	40.00
			830.00	630.00
	LABOUR			
	TO REMOVE & REFIT ALL DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF FRONT PASSENGER HEAD REST AND RH SIDE FRONT FENDER.		1,800.00	1,600.00
	TO PUTTY N SPRAY FRONT HOOD,FRONT BUMPER,REAR BUMPER.		1,200.00	1,000.00
	TO REPAIR REAR PANEL (ADDITIONAL).		750.00	400.00
	TO PUTTY AND SPRAY RHS FRONT FENDER,REAR PANEL (ADDITIONAL).		500.00	400.00

Report Ref No. CS/FCI19009396/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COMPUTER WHEEL ALIGNMENT (ADDITIONAL).	NOT NECESSARY	150.00	-
			4,400.00	3,400.00
GRAND TOTAL			22,938.85	15,854.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CS/FCI19009396/Asd3n2

MARKET VALUE: \$37,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$25,942.00=NETT VALUE: \$11,058.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.