ASS. REC. BY:	REF:(S/MSG	19009399/TH	d202 Sp	ecial Instruction:	
Surveyor Taufikh		NMENT (Office)			
From (Person): Jasmine Lot	Klung kwaiof	MSIG		Date/Time: 29.5.19 /	6. p.m
Estimated Cost:		Bill to:			
OD TP WS / TP RES / OD To Inspect Vehicle No:	RESIEVAINVIN	IV / CS	Insured	SCZ 55+4A	*
of 25 Leng kee Road	mage Storpsi S	?	Tel:	9489 9 000	6
Policy No: 29/20555 AV W		Claim No:	59440	0	
Sum Insured:		Excess:			
Make of Veh: (Client's Record) CA / REV / REP. / REV: Date/Time: 25.14.4		cted: Dennie		D.O.A. 14.5. 2019 29.5. 2019 H.O.D. Endorsement: /ehicle_IN_OUT	olwa i+
Date/Time Action/Instruction SLC 8861 x SCZ 5524		nate.			
Part b	y Part \$	1781-68; (fld: 2	2513 321 S8%	6)

Mirmin

(08/1/13) ASS. REC. BY:

ASSIGNMENT

From: Date: 29.5.249	Veh No: SLC 886/X Yr Regn: 2016 1 May
Estimated Cost:	Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No: 5 LC 88 61×	Make: Suham Forester c.c 1998
at Workshop m/s Moto / Image	Colour BULL A/C: Insured / Std / NI / NA
of 25 Long ka Road	Sp.Reading 28742 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CNO: 5 = 1 S J G K 8 5 G G 07 2/02
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh: 2-00 P-m owner watting	Modi: Nil /S/Rim / STD A/Rim or/
-	Tyre Size: F: 235/55/68-
(Policy Condition)	R: ~
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIÇ / OHTSU / PIR / SUMI /
repair at the time of inspection.	тоуо/уоко ог
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 - mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.I. 29/8/19
Lum Sum: % 3 Val.: Yes or No	Survey held at Mator I mage lengthere
CA / REV / REP. / 24 HRS *(AP 1)	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	•
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	2019
RECEIVED 1 7 JU	
,	
	15/1/2019
0_ =	
	_
Date/Time, File Pass to? : Preli. Report D	ays Of Repair: 3
1717 Tune	esurvey No. of Trip: Survey Fee: 160
Date/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$)s+Rs,si
To .	: Interview (\$) Photos
Report Format:	- 1 (6
	: Tech. Invs (\$) Others
Lump Sum / [.B.I: (\$ 1781.68)	: Tech. Invs (\$) Others : Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM S Insured:	UBFOLDER DET	V 00-1501-1501-1501-1501-	IAY KHENG, ID:	-111-1-1	Tel: +6596161360	[Crea	ated by insurer]
	Main	Ref	erence	Claim	Details	Documer	nts Show A
Main	27 May 2019		28 May 2019 16:39 Assign				New Assignment Cancel Case
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAIL	.S		[Create	d by insurer]
Insured:	TAN CHAY KHENG, ID:	S1117195H, Tel: +6596161360)	AND ADDRESS OF A SECOND STREET, STREET
Main Claimant:	LI ZHENG, ID: S738916	56C		
Vehicle Reg. No.:	SLC8861X	Date of Loss:	[35 Mon	019 00:00 - :59 ths and 16 Days From Date (Man Yr)]
Claim Type:	TP / 594400	Policy/Cover Note No.:		5AVW (Comprehensive) e: 28/03/2019 - 020
Vehicle Reg. No. (Insured):	SCZ5524A	Policy No. (Claimant):		
		Excess:		
Repairer:	Motor Image Enterprise	s Pte Ltd (Leng Kee) 25 Leng K	ee Road, 159097 Leng	Kee - Tel:
Handling Insurer:	MSIG Insurance (Singap Kwei - 6594 2550]	pore) Pte. Ltd. (HQ) - Tel: +65	6827 7888 [Handle	d by Jasmine Lok Khe
Handling Insurer: Adjuster:	Kwei - 6594 2550]	te Ltd (HQ) - Tel: +65		
100	Kwei - 6594 2550] LKK Auto Consultants Pt Survey appt 29/05/2019 at	2 100110011001000	[Imm.Advice due	29/05/2019]
Adjuster:	Kwei - 6594 2550] LKK Auto Consultants Pt Survey appt 29/05/2019 at assignment. Liab: dispute (te Ltd (HQ) - Tel: 6256-3561 t 2PM, owner waiting, on WP. Plea	[Imm.Advice due	29/05/2019]
Adjuster: Adj Asg. Remarks:	Kwei - 6594 2550] LKK Auto Consultants Pt Survey appt 29/05/2019 at assignment. Liab: dispute (te Ltd (HQ) - Tel: 6256-3561 t 2PM, owner waiting, on WP. Plea	[Imm.Advice due ase contact us ASAP if 9000/ 6703 8161	29/05/2019] you cannot attend this
Adjuster: Adj Asg. Remarks: ASSOCIATED MAIL RECEIV There are no mail for this case.	Kwei - 6594 2550] LKK Auto Consultants Pt Survey appt 29/05/2019 at assignment. Liab: dispute (te Ltd (HQ) - Tel: 6256-3561 t 2PM, owner waiting. on WP. Ple. (OI NR) Contact: Dennie @ 9489	[Imm.Advice due ase contact us ASAP if 9000/ 6703 8161 View All	29/05/2019] you cannot attend this Compose Case Mail
Adjuster: Adj Asg. Remarks: ASSOCIATED MAIL RECEIV There are no mail for this case.	Kwei - 6594 2550] LKK Auto Consultants Pt Survey appt 29/05/2019 at assignment. Liab: dispute (te Ltd (HQ) - Tel: 6256-3561 t 2PM, owner waiting. on WP. Ple. (OI NR) Contact: Dennie @ 9489	[Imm.Advice due ase contact us ASAP if 9000/ 6703 8161 View All	29/05/2019] you cannot attend this

Denise Tay (LKKAuto)

From:

Denise Tay (LKKAuto)

Sent:

Wednesday, 17 July 2019 10:51 AM

To:

'Dennis Leong'; SUR; Admin A LKINSTEAM; Asher Sng (LKKAuto)

Cc: Subject:

RE: SLC8861X CLAIMS AGAINST SCZ5524A (MSIG) 14/05/2019

Dear Dennis,

Confirm part by part \$1,781.68, 3Days.

Please submit all relevant documents to MSIG.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Dennis Leong <dennisleong@motorimage.net>

Sent: Thursday, 11 July 2019 2:42 PM

To: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: LKINSTEAM <LKINSTEAM@tanchong.org>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Subject: RE: SLC8861X CLAIMS AGAINST SCZ5524A (MSIG) 14/05/2019

Dear Claim Team,

Kindly assist above matter.

Thank you Best Regards,

Dennis Leong

Service Advisor

Motor Image Enterprises Pte Ltd

25 Leng Kee Road

Singapore 159097

HP:(65)9489 9000

DID:(65)6703 8161

FAX:(65)6479 1137

Email:dennisleong@motorimage.net

Save the Earth. Print only when necessary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

By the lodgement of this report to the insurers, you hereby consaforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	15/05/2019 13:02
Date Of Accident	14/05/2019 16:55
Exact Location Of Accident	SLIP ROAD TURNING LEFT TO EAST COAST RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLC8861X
Insured/Policyholder	
Name Of Registered Owner	LIZHENG
NRIC No	S7389166C
Email Address	LI.ZHENG@HOTMAIL.CO.UK
Mobile Phone No	(LOCAL) +65-98271705
Alternative Phone No	OFFICE-98271705
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER 2.0XT CVT AWD SR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy	NO

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Vehicle Category

Insurance Company

Name of Insurance Company

FWD SINGAPORE PTE, LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

Name of Driver

PNPV2018-00006352

Cover Note Number

Driver

LI ZHENG

NRIC No S7389166C Date Of Birth 31/10/1973 Occupation INDOOR

Date Of Driving Pass Driving Experience

4 YEARS AND 8 MONTHS

Gender

MALE

20/08/2014

Mobile Number

(LOCAL) +65-98271705

Fax Number

Contact Number

OFFICE-98271705

EMail Address

LI.ZHENG@HOTMAIL.CO.UK

Address

NIL

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

OWNER

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

? NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

I (SLC8861X) was stationary at the slip road turning left to East Coast road from Siglap road, giving way to traffic from my right when suddenly a car (SCZ5524A) hit me from the back. No injuries involved.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SCZ5524A

Vehicle Make/Model/Colour

VOLKSWAGEN GOLF 1.4 TSI CL BLACK

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

TAN CHAY KHENG

NRIC/Passport Number

S1117195H

Contact Number

96161360


Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)	
I (SLC8861X) was stationary at the stroad, giving way to traffic from my right the back. No injuries involved.	lip road turning left to East Coast road from Siglap ht when suddenly a car (SCZ5524A) hit me from
Taxi Voucher No.:	
DECLARATION I/We declare that the above particulars & information pr	rouided above are true in every agreet
VERIFIED BY AJAX MARS REPORTING OFFICER - MOHAMMAD SULHANDI BIN MOH AFFANDI	Ovided above are title in every aspect
MARS Officer	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time:
15 May 2010 at 11:00 AM	15 May 2010 at 11:00 AM

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD SINGAPORE 159097

ESTIMATE

: ACCIDENT/BODY REPAIRS

√ORKSHOP CONTACT NO : LENG KEE

REFERENCE

: INS/IC/JHI/025/2019

DATE

: 26-MAY-2019

FWD SINGAPORE PTE LTD

5 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

5(038986)

TEL: 68208888

-AX :

DWNER'S NAME

: LI ZHENG

ADDRESS

: 30 JALAN DAUD #04-08

S(419572)

TELEPHONE NO : 98271705

TYPE OF CLAIM : THIRD PARTY CLAIM

OLICY NO : PNPV2018-00006352

VEHICLE NO

: SLC8861X : SJGDKK8

40DEL CODE MODEL/YEAR

: FORESTER 2.0XT AWD CVT

ENGINE NO

: FA20A930562

CHASSIS NO MILEAGE

: JF1SJGK85GG072102

DATE IN

: 1 KM : 26/05/2019

LIABILITY

0.00

EXCESS CLAUSE :

ESTIMATE BY

0.00 : DENNIS LEONG JIA HUI

ACCIDENT DATE : 26/05/2019

Print Date

: 26/05/2019

Print Time

: 18:33:22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD 5INGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC8861X

S/N0	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER ,BUMPER BEAM AND BRKT RH/LH	1740.00	560
2	ZZ/002	RESPRAY REAR BUMPER , BUMPER BEAM AND TAILGATE 440	1440.00	440.
3	ZZ/003	REMOVE AND REINSTALL REVERSE SENSOR	80.00	1
4	ZZ/004	SUNDRIES	100.00	20 V
		TOTAL LABOUR CHARGES	3360.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC8861X

The same and the same are all the same and the same are

				DAMAGE	D PARTS & PR	ICES		
S/NO	PARTS DESCRIPTION		PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
1	BUMPER FACE R	(SUPP)	57704SG012	540.00	de/	V		
2	BRKT SD R RH		57707SG080		? / nn			
3	BRKT SD R LH		57707SG090	14.40	? X ng			
4	BEAM COMPL R EU		57711SG0219P	288.00	3 × mJ			
5	COVER HOOK R		57731SG010NN	12.60	mis v			
6	CLIP BMPR		909140007	12.00	re/			
7	CARGO STEP PANEL (RESIN)		E775ESG000			230.00	ner J	
	SUB TOTAL			881.40	0.00	230.00	0.00	
	LESS DISCOUNT (NETT-20 %)			176.28	0.00	0.00	0.00	
	GRAND TOTAL			705.12	0.00	230.00	0.00	
	OVERALL TOTAL			935.12				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLC8861X

......

TOTAL LABOUR CHARGES TOTAL SPARE PARTS CHARGES 935.12

3360.00

GRAND TOTAL

4295.12 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY : 0.00 0.00

REMARKS

³LS NOTE: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS

WORKSHOP

: LENG KEE

CONTACT NO :

REFERENCE

: INS/IC/JHI/025/2019

: 26-MAY-2019

FWD SINGAPORE PTE LTD

6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)

TEL: 68208888

FAX:

OWNER'S NAME : LI ZHENG

ADDRESS

: 30 JALAN DAUD #04-08

S(419572)

TELEPHONE NO

: 98271705

TYPE OF CLAIM : THIRD PARTY CLAIM

VEHICLE NO : SLC8861X

POLICY NO : PNPV2018-00006352

MODEL CODE : SJGDKKB

.

MODEL/YEAR : FORESTER 2.0XT AWD CVT

ENGINE NO : FA20A930562

MILEAGE

CHASSIS NO : JF1SJGK85GG072102

DATE IN

1 KM : 26/05/2019

LIABILITY

: 0.00

EXCESS CLAUSE :

0.00

ESTIMATE BY

: DENNIS LEONG JIA HUI ACCIDENT DATE : 26/05/2019

Print Date

: 24/06/2019

Print Time

: 20:23:50

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG-KEE ROAD \$INGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC8861X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER ,BUMPER BEAM AND BRKT RH/LH	1740.00	560.00
2	ZZ/002	RESPRAY REAR BUMPER , BUMPER BEAM AND TAILGATE	1440.00	440.00
3	ZZ/003	REMOVE AND REINSTALL REVERSE SENSOR	80.00	80.00
4	ZZ/004	SUNDRIES	100.00	20.00
		TOTAL LABOUR CHARGES	3360.00	1100.00

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG KEE ROAD 6INGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC8861X

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION		PARTS NUMBER	NETT	LIST	S/NETT	S/LIST	REMARKS
1	BUMPER FACE R (SUPP)	57704SG012	540.00				OK
2	BRKT SD R RH		57707SG080	14.40				X
3	BRKT SD R LH		57707SG090	14.40				X
4	BEAM COMPL R EU		57711SG0219P	288.00				X
5	COVER HOOK R		57731SG010NN	12.60				OK
6	CLIP BMPR		909140007	12.00				OK
7	CARGO STEP PANEL (RESIN)		E775ESG000			230.00		OK
	SUB TOTAL			564.60	0.00	230.00	0.00	
	LESS DISCOUNT (NETT-20 %)			112.92	0.00	0.00	0.00	
	GRAND TOTAL			451.68	0.00	230.00	0.00	
	OVERALL TOTAL			681.68				

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD. 25 LENG~KEE ROAD SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLC8861X

NETT ITEM LESS 20 %	564.60	
LESS 20 %		
	-112.92	
NETT AMOUNT	451.68	
LIST ITEM	0.00	
LESS 50 %	0.00	
LIST AMOUNT	0.00	
SPECIAL NETT AMOUNT	230.00	
S/LIST ITEM	0.00	
LESS 30 %	0.00	
S/LIST AMOUNT	0.00	
TOTAL LABOUR CHARGES	1100.00	
TOTAL SPARE PARTS CHARGES	681.68	
TOTAL CHARGES	1781.68	
ADD 7 % GST	124.72	
GRAND TOTAL	1906.40	
	NETT AMOUNT LIST ITEM LESS 50 % LIST AMOUNT SPECIAL NETT AMOUNT S/LIST ITEM LESS 30 % S/LIST AMOUNT TOTAL LABOUR CHARGES TOTAL SPARE PARTS CHARGES TOTAL CHARGES ADD 7 % GST	NETT AMOUNT

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUBF	OLDER TRA	CKING							
Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth'ed	Status	
Main	27 May 2019		28 May 2019 16:39 Edit Adj Rpt	S\$1,781.68 Edit Estimates	1	1,781.68 lew Rpt		Pending for Survey Report Cancel Case	
M	tain	R	eference	Claim D	etails		Documents	\Box	Show All
CLAIM SUE	FOLDER DE	TAILS	THE RESERVE OF THE PARTY.			[Created b	oy insurer]		
Insured:	TAN CHAY	KHENG, ID: S	1117195H, Tel: +	5596161360					
Main Claimant:	LI ZHENG	LI ZHENG, ID: S7389166C							
Vehicle Reg. No.:	SLC8861X			Date	of Loss:	14/05/2019 00:00 - :59 [35 Months and 16 Days From LTA Reg Date (Man Yr)]			
Claim Type:	TP / 594	TP / 594400				29120555AVW (Comprehensive) Coverage: 28/03/2019 - 27/03/2020			
Vehicle Reg. No. (Insured):	SCZ5524A			Policy (Clain	No. nant):				
				Exces					
Repairer:	Motor Im	age Enterprises	Pte Ltd (Leng Kee) 25 Leng Kee Ro	d, 1590	97 Leng Kee	- Tel:		
Handling Insurer:						*	Jasmine Lok Khen		
Adjuster:	29/05/20		Ltd (HQ) - Tel: 62	56-3561 [Hand	led by M	MOHD TAUFI	KH BIN HAMID]	[Imm.Ad	vice due
Adj Asg. Remarks:			2PM, owner waiting. 9489 9000/ 6703 81		ntact us	ASAP if you	cannot attend this as	ssignment. Li	ab: dispute
ASSOCIATI	ED MAIL RE	CEIVED					View A	II Compo	se Case Ma
There are no	mail for this	case.							
ALL ASSO	CIATED TAS	ks⊟			,	View All S	earch Tasks Crea	ite New Task	Complet
Due Date	Priority	Type Task	Group Subjec	t Handler	Assign	ned By	Completed On	Created O	n Done

Claim Documents

*SLC8861X (594400)

[SCZ5524A]

TP

LI ZHENG

May 14 2019 12:00AM

[TAN CHAY KHENG]

Motor Image Enterprises Pte Ltd

				promite .	1
Ass	essment Reports		1 per p		V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	04/06/19 14:25	Accident Statement From:SC - Reg. No: SC25524A, Claimant: TAN CHAY KHENG	0	Load HTM	
Pho	tos/Images		3 per p	age 🔻	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/19 10:53	General View	0	Load JPG	▼
2	17/07/19 10:53	General View	0	Load JPG	V
3	17/07/19 10:53	General View	0	Load JPG	V
4	17/07/19 10:53	General View	0	Load JPG	V
5	17/07/19 10:53	General View	0	Load JPG	V
6	17/07/19 10:53	General View	0	Load JPG	V
7	17/07/19 10:53	General View	0	Load JPG	V
8	17/07/19 10:53	General View	0	Load JPG	V
9	17/07/19 10:53	General View	0	Load JPG	V
10	17/07/19 10:53	General View	0	Load JPG	~
11	17/07/19 10:53	General View	0	Load JPG	V
12	17/07/19 10:53	General View	0	Load JPG	V
13	17/07/19 10:53	General View	0	Load JPG	✓
14	17/07/19 10:53	General View	0	Load JPG	✓
15	17/07/19 10:54	Reinspection Photo	0	Load JPG	~
16	17/07/19 10:54	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per p	age 🔻	V
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	27/05/19 14:06	TP ACCDT REPORT	0	Load PDF	
2	27/05/19 14:07	TP EST BILL	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.	•		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Pava Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19009399/T1TD3E2

Date:

26/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

29120555AVW

Claimant Vehicle Date of Loss:

SLC8861X

Insured Vehicle No:

SCZ5524A

No:

14/05/2019

Nature of Claim:

TP

Claim No: 594400

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLC8861X

Make & Model:

SUBARU FORESTER, 2.0 XT CVT AWD SR (A)

Engine No:

FA20A930562

Reg. Date: Colour:

Chassis No: Odometer:

JF1SJGK85GG072102 28742 km

Engine Capacity:

1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

28/05/2016 (Man. Year: 2016)

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side:

Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side:

Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,035.12	701.68	333.44	32.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,080.00	2,180.00	66.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,295.12	1,781.68	2,513.44	58.52
+ GST 7.00/7.00% (S\$)	300.66	124.72	175.94	58.52
Nett Amount (S\$)	4,595.78	1,906.40	2,689.38	58.52

INSPECTION

Date of Assignment:

28/05/2019

Date Inspected:

29/05/2019 Inspected At:

Motor Image Enterprises Pte Ltd (Leng

Kee)

25 Leng Kee Road Singapore 159097

Estimated Period of Repair:

3.0 days

MOHD TAUFIKH BIN HAMID Adjuster:

Manager: DENISE TAY KWEE CHENG

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_... 26/7/2019

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 26 Jul 2019)

Parts:

M1-SUV

SUBARU FORESTER 2.0 XT CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC8861X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*BUMPER FACE R	Deformed	540.00 FN	*540.00 FN
1		*BRKT SD R RH	Not Necessary	14.40 FN	*- FN
1		*BRKT SD R LH	Not Necessary	14.40 FN	*- FN
1		*BEAM COMPL R EU	Not Necessary	288.00 FN	*- FN
1		*COVER HOOK R	Missing	12.60 FN	*12.60 FN
1		*CLIP BMPR	Necessary	12.00 FN	*12.00 FN
1		*CARGO STEP PANEL (RESIN)	Necessary	230.00 FS	*230.00 FS
1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
anchise	part. S=SpcN	ett. N=NettItemDisc.	_		
			Sub Total (S\$)	1,211.40	814.60
		- Nett Item Discount on I	N Items 20.00/20.00% (S\$)_	176.28	112.92
			Total Parts (S\$)	1,035.12	701.68
	1 1 1 1 1 1 1	Qty Part No. 1 1 1 1 1 1 1 1 1 nnchise part. S=SpcN	1 *BUMPER FACE R 1 *BRKT SD R RH 1 *BRKT SD R LH 1 *BEAM COMPL R EU 1 *COVER HOOK R 1 *CLIP BMPR 1 *CARGO STEP PANEL (RESIN) 1 *SUNDRIES anchise part. S=SpcNett. N=NettItemDisc.	1 *BUMPER FACE R Deformed 1 *BRKT SD R RH Not Necessary 1 *BRKT SD R LH Not Necessary 1 *BEAM COMPL R EU Not Necessary 1 *COVER HOOK R Missing 1 *CLIP BMPR Necessary 1 *CARGO STEP PANEL (RESIN) Necessary 1 *SUNDRIES Nece	1 *BUMPER FACE R Deformed 540.00 FN 1 *BRKT SD R RH Not Necessary 14.40 FN 1 *BRKT SD R LH Not Necessary 14.40 FN 1 *BEAM COMPL R EU Not Necessary 288.00 FN 1 *COVER HOOK R Missing 12.60 FN 1 *CLIP BMPR Necessary 12.00 FN 1 *CARGO STEP PANEL (RESIN) Necessary 230.00 FS 1 *SUNDRIES Necessary 100.00 FS Inchise part. S=SpcNett. N=NettItemDisc. Sub Total (S\$) 1,211.40 - Nett Item Discount on N Items 20.00/20.00% (S\$) 176.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPLACE REAR BUMPER, BUMPER BEAM AND BRKT RH/LH.	New	1,740.00	560.00
2	RESPRAY REAR BUMPER, BUMPER BEAM AND TAILGATE.	New	1,440.00	440.00
3	REMOVE AND REINSTALL REVERSE SENSOR.	New	80.00	80.00
	Gross Labour	Cost (S\$)	3,260.00	1,080.00
	Report was unsubmitted during t			

< END OF ESTIMATES >