

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Lorraine Wong Lee Sin of SMO Date/Time: 28.5.19 17:14 P.M

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9778A Insured: SJN 74U

at Workshop m/s TRIAS-CAB Auto Services Tel: 62130498
of 2 Ang MOKIO Street 63

Policy No: D14MTPV 01004888 Claim No: CM1019 02558

Sum Insured: Excess:

Make of Veh: D.O.A. 26.5.2019
(Client's Record) 29.5.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 28.5.19 5:22 PM Person Contacted: The Wei Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 9778A - CS/FCI/2000167 / kv d3 n2 D.O.A. - 01/01/2018
	SJN 74U - X
30/5/19	Send preli revised via merimen
31/5/19	// Imp & 8500 summt (Red 42,582.07, 836)

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 29.5.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNB 9778 A

at Workshop m/s Trans-cab Auto Services
of 2 Amk Street 63

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS "rep"

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNB 9778 A Yr Regn: 07, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Perant Lotitude c.c. 1995

Colour: M. White / R / A/C: Insured / Std / NI / NA

Sp. Reading: 714809 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: V171 ABL 15 AUG 273116

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 28/5/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 31 MAY 2019

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 31/5 - typist

Report Format: meimen

Lump Sum / I.B.I. (\$) 8500p

Days Of Repair: 10

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation: 450

S + RS, SI 10

Photos

Others

TOTAL 460

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: WONG, LEE SIN LORRIANCE

Date: 30 May 2019

Preliminary Advice

Insured Vehicle No	: SJN74U	Accident Date	: 26/05/2019
TP Vehicle No	: SHB9778A	Assignment Date	: 28/05/2019
Make	: RENAULT LATITUDE	Est. Duration of Repair	: 10
Date of Inspection	: 29/5/2019		
Inspection At	: TRANS-CAB AUTO SERVICES PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	51,087.07
Revised Amount	:S\$	15,474.66
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,474.66

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☒ Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 May 2019		28 May 2019 17:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LEE JUI MENG, ID: S7810232B, Tel: +6590219761, Email: juimeng05@hotmail.com								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHB9778A	Date of Loss:	26/05/2019 14:00 - :59						
Claim Type:	TP / CMTD1902558	Policy/Cover Note No.:	D19MTPV01004888 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJN74U	Policy No. (Claimant):							
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by WONG, LEE SIN LORRIANCE - 6329 5175]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/06/2019]								
Driver/Custodian (Insured):	LEE JUI MENG (41 / Male), NRIC: S7810232B, Tel: +6590219761 Email: juimeng05@hotmail.com								
Adj Asg. Remarks:	WS: ZHEWEI 62130998								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 31 May 2019 8:57 AM
To: Ng Wai Yin; 'calvin.er@transcab.com.sg'
Cc: jasminetan@transcab.com.sg; SUR
Subject: SHB 9778A-DOA: 26/5/2019
Attachments: MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Lump Sum \$8500 (Max) before GST @ 10 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Thursday, 30 May 2019 5:45 PM
To: Veron Chen (LKKAUTO)
Subject: FW: Book value SHB9778A
Attachments: image001.emz; image007.wmz

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: weichunkong <weichunkong@transcab.com.sg>
Sent: Thursday, 30 May 2019 5:31 PM
To: 'Candy Kong' <candy.kong@transcab.com.sg>
Cc: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Subject: RE: Book value SHB9778A

Hi all,

SHB9778A Net book value is \$31,428.71

Thanks
Best regards

CK



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Candy Kong [<mailto:candy.kong@transcab.com.sg>]
Sent: Wednesday, 29 May, 2019 2:51 PM
To: 'weichunkong' <weichunkong@transcab.com.sg>
Cc: 'Kenneth Kong (LKKAUTO)' <KennethKong@lkkauto.com>
Subject: Book value SHB9778A

Hi CK,

Kindly provide me the Book value

Thks & Rdgs
Candy Kong
Claims Service Assistant



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHB9778A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 May 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000239
Chassis No.:	VF1ABL15AUC273116
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Jul 2013
First Registration Date:	31 Jul 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2021
PARF Rebate Amount:	\$8,748.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$51,810.00
COE Rebate Amount:	\$14,084.00
Total Rebate Amount:	\$22,832.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 27 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/05/2019 10:28
Date Of Accident	26/05/2019 14:30
Exact Location Of Accident	ECP TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB9778A
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303678K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	
Driver	
Name of Driver	LIM YONG KHOON
NRIC No	S1554664F
Date Of Birth	01/05/1962
Occupation	OUTDOOR
Date Of Driving Pass	06/09/1982
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90620892
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 660 WOODLANDS RING RD #03-140
Postcode	730660
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 26/05/2019 AT ABOUT 1430HRS, I WAS TRAVELLING STRAIGHT ALONG THE SECOND LANE OF ECP TOWARDS CHANGI AIRPORT. THE VEHICLE IN FRONT OF ME STOPPED AND I FOLLOWED SUIT. SUDDENLY I FELT AN IMPACT FROM THE REAR. VEHICLE B(SJN74U) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJN74U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
[If driver is not the policyholder]
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

ECP towards Chang Airport.

A: SHB 9778A
B: SJN 74U

A diagram illustrating a runway layout. A vertical line on the left is labeled "ECP towards Chang Airport." To the right of this line are four vertical dashed lines. Between the second and third dashed lines, there are two stacked rectangular boxes labeled "A" and "B". Below the dashed lines, there are four upward-pointing arrows, one under each dashed line.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

Refer to GIA Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature: _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9778A**AAD1905-232***Not Authorised
L1 Eng & 850dp. Max*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date Of Registration:

SHB 9778A

VF1ABL15AUC273116

RENAULT

LATITUDE

26.5.19

SOMPO

31/7/2013

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	BOOT REAR
14	1	BOOT FINISHER
15	1	BOOT WHEATERSTRIP
16	1	BOOT REFLECTOR LAMP LH
17	1	BOOT REFLECTOR LAMP RH
18	1	BOOT BADGE 'RENAULT'
19	1	BOOT BADGE
20	1	BOOT STRUT LH
21	1	BOOT STRUT RH
22	1	BOOT HINGE LH
23	1	BOOT HINGE RH
24	1	BOOT INNER TRIM
25	1	BOOT SWITCH
26	1	BOOT LOCK
27	1	BOOT LOCK CATCH
28	2	LICENCE PLATE LAMP
29	2	BOOT RUBBER PLUG
30	1	FENDER PANEL INNER TRIM REAR RH

LIST

\$	<i>By</i>	1,108.46	✓
\$	<i>Dis/As</i>	768.84	✓
\$	<i>CM</i>	113.47	✓
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>CM</i>	43.61	✓
\$	<i>SL</i>	135.97	X
\$	<i>SL</i>	44.99	X
\$	<i>SL</i>	43.61	X
\$	<i>By</i>	777.52	✓
\$	<i>By</i>	225.95	—
\$	<i>By</i>	225.95	—
\$	<i>By</i>	2,872.68	✓
\$	<i>SL</i>	470.06	X
\$	<i>Dis/As</i>	323.05	<i>50 pin 161.53</i>
\$	<i>CM</i>	493.35	✓
\$	<i>CM</i>	493.35	—
\$	<i>SL</i>	225.36	—
\$	<i>SL</i>	225.36	—
\$	<i>SL</i>	276.08	} X
\$	<i>SL</i>	276.08	
\$	<i>SL</i>	367.84	
\$	<i>SL</i>	367.84	
\$	<i>SL</i>	586.45	
\$	<i>SL</i>	168.13	
\$	<i>SL</i>	202.67	
\$	<i>SL</i>	74.40	
\$	<i>SL</i>	50.52	}
\$	<i>SL</i>	221.81	
\$	<i>SL</i>	671.45	

Trans-cab Auto Services Pte Ltd

AAD1905-232

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9778A

31	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
32	1	WHEELARCH REAR RH	\$	Sn	543.47	X
33	1	FENDER PANEL REAR LH	\$	R	3,299.13	X
34	1	FENDER PANEL INNER TRIM REAR LH	\$	Sn	671.45	X
35	1	WHEELARCH REAR LH	\$	R	543.47	X
36	1	TAILLAMP RH	\$	mgcm	552.55	✓
37	1	TAILLAMP PANEL RH	\$	R	986.70	X
38	1	TAILLAMP LH	\$	mgcm	552.55	✓
39	1	TAILLAMP PANEL LH	\$	R	986.70	X
40	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	✓
41	1	OUTER PANEL REAR (End Panel)TRIM	\$	DIT	404.56	✓
42	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bylan	2,189.88	✓
43	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
44	1	EXHAUST REAR	\$	R	7,489.05	X
45	1	EXHAUST CAP REAR	\$	nd	230.49	✓
TOTAL			\$		35,868.94	92
10%			\$		3,586.89	
			\$		32,282.05	

Special Nett

1	1SET	PARKING AID	\$	Red/Shar	700.00	400.00
2	1SET	REAR BUMPER CLIP	\$	Re	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	Re	33.00	✓
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	Re	66.00	✓
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	Re	30.00	✓
13	1	BOOT STICKER "6555-3333"	\$	Re	30.00	✓
14	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
17	1	SPARE TYRE	\$	Sn	330.00	X
18	1	FENDER INNER TRIM CLIP RH	\$	na	28.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-232

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9778A

19	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	✓
20	2	REAR WINDSCREEN SEALANT	\$	<i>nn</i>	80.00	X
21	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	X
22	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	X
23	1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	✓
24	1	FENDER INNER TRIM CLIP LH	\$	<i>nn</i>	28.00	X
25	1SET	FENDER WHEELARCH REAR LH CLIP	\$	<i>nn</i>	35.00	X
TOTAL			\$		2,225.02	

TOTAL PARTS	\$	34,507.07
--------------------	-----------	------------------

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	<i>1100</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>1200</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>60</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>60</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	<i>} 80</i>
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	<i>90</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD1905-232

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9778A

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	380.00	
To transfer of tire, rim and on wheel balancing.	\$	170.00	170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00	380.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	380.00	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	170.00	250
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	380.00	250
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00	380.00	X
TOTAL	\$	16,580.00		
Over All Total	\$	51,087.07		

(LUMP SUM) Repair Days

20 DAYS

10 days

Lump Sum Consultants hence notify the Repairer of the following:

- To deliver vehicle after repair
- To display damaged parts during survey
- Parts costs are subject to quotation
- Third party liability is not a "Virtual Protection" item
- No stage modification is allowed
- Supplementary charges must be payable and to be subject to approval from Insurance Company

Authorised by Manager
Signature
Date

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19009407/KVD3N2

Date: 04/06/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01004888
Claimant Vehicle No :	SHB9778A	Insured Vehicle No :	SJN74U
Date of Loss:	26/05/2019	Nature of Claim:	TP
		Claim No:	CMTD1902558

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9778A	Engine No:	M9R8839C000239
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC273116
Reg. Date:	31/07/2013 (Man. Year: 2013)	Odometer:	714809 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 7 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 7 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	34,507.05	12,474.66	22,032.39	63.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,580.00	3,000.00	13,580.00	81.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	51,087.05	15,474.66	35,612.39	69.71
Approved Total (Overridden) (\$\$)		8,500.00		
(S\$)	51,087.05	8,500.00	42,587.05	83.36
+ GST 7.00/7.00% (S\$)	3,576.09	595.00	2,981.09	83.36
Nett Amount (S\$)	54,663.14	9,095.00	45,568.14	83.36

INSPECTION

Date of Assignment:	28/05/2019	
Date Inspected:	29/05/2019	Inspected At:
		Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version:	1.0 (Last Synchronised: 04 Jun 2019)
Parts:	143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SHB9778A)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Distorted/Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	43.61 FL	*43.61 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	225.95 FL	*225.95 FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT REFLECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
16	1		*BOOT REFLECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
18	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
20	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
21	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
22	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
23	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
24	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
25	1		*BOOT LOCK	Repair	202.67 FL	*- FL
26	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
27	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
28	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
29	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
30	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
31	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
32	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
33	1		*FENDER PANEL INNER TRIM REAR LH	Serviceable	671.45 FL	*- FL
34	1		*WHEELARCH REAR LH	Repair	543.47 FL	*- FL
35	1		*TAILLAMP RH	Mtg Cracked	552.55 FL	*552.55 FL
36	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
37	1		*TAILLAMP LH	Mtg Cracked	552.55 FL	*552.55 FL
38	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
39	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
40	1		*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	*404.56 FL
41	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Bent/Buckled	2,189.88 FL	*2,189.88 FL
42	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*EXHXUST REAR	Repair	7,489.05 FL	*- FL
44	1		*EXHAUST CAP REAR	Dented	230.49 FL	*230.49 FL
45	1		*SET PARKING AID	Dented/Shorted	700.00 FS	*400.00 FS
46	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
47	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
48	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
49	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
50	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
51	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
52	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
53	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
54	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
55	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
56	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
57	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
58	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
59	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
60	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
61	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
62	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
63	1		*TAILLAMP CLIP RH	Necessary	5.00 FS	*5.00 FS
64	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
65	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
66	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
67	1		*TAILLAMP CLIP LH	Necessary	5.00 FS	*5.00 FS
68	1		*REAR FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
69	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
70	1		*BOOT WEATHERSTRIP (50%)	Distorted/ Dented	290.75 FS	*161.53 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	38,061.64	13,772.23
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,554.59	1,297.57
Total Parts (\$\$)	34,507.05	12,474.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	1,100.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	1,200.00
3	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	60.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST)	New	170.00	80.00
7	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST)	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
10	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
11	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	80.00
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
14	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
15	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
17	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
18	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT	New	380.00	0.00
19	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	250.00
20	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
Gross Labour Cost (\$\$)			16,580.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >