

ASS. REC. BY:

REF: CS1CS19009413/ Ald302

Special Instruction:

Survey: AthorASSIGNMENT (Office)From (Person): Janice Goh

of

Fes

Date/Time:

28/5/19 @ 11:23am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGY500J

Insured:

at Workshop m/s

First Autoworks

Tel:

68441985

of

23 Kaki Bukit Ave 4 #04-01

Policy No:

Claim No:

DMPC1900135 H/JG

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

28/5/2019CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:55am @ 28/5/19

Person Contacted:

SuheimiVehicle: IN/OUT

Date/Time	Action/Instruction	Estimate
	SGY 500J - X	✓
	pls seek 2nd opinion from our authorised wlp.	
29/5-	seek mandate	authorise repair
31/5-15:	20-	mandate approve by Janice Goh
3/6-10:	11am	inform workshop authorise repair \$15,500/-

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TF / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGY500J Yr Regn: 2017, August

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Opel Astra c.c 999

Colour: Red A/C: Insured / Std / Nil / NA

Sp. Reading 29072 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WOLBE6EA8H6172390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.L. <u>28/05/19.</u>	
Survey held at <u>Auto Germany</u>			
Des. of Damages: <u>Frt</u> / Rear / O/S / N/S / U/C / Rooftop or			

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>07 ECILS.</u>
	<u>repair sum \$15,500- (Red. 12,574.80 : 44%) 6 days</u>
	<u>mv : 68K.</u>
	<u>PV : 39K</u>
	<u>Nett: 29K.</u>

RECEIVED 11 JUL 2019

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) <u>11/7 Tyast</u>	2) _____	IN _____ OUT _____	Basic & Add. _____	<u>11/7</u>
3) _____	4) _____		S + RS. _____ SI	
5) _____	6) _____		Photos _____	
Prefl. Report _____			Others _____	<u>11</u>
Final Report _____			TOTAL _____	<u>11/7</u>

Nivitha (LKK Auto)

From: Janice Goh Siew Geok (ECICS, Claims) <Janice_Goh@ecics.com.sg>
Sent: Tuesday, 28 May 2019 11:23 AM
To: vincent.sim@alpinemotors.sg; assignments
Cc: Kelvin Chew; suhaimi@alpinemotors.sg; motorsurvey
Subject: RE: SGY500J - OPEL ASTRA -H/B 1.0 - OWN DAMAGED CLAIM - ECICS- DOA 26-5-2019 ; Our claim no DMPC1900135H/JG.
Attachments: SGY500J - OWN DAMAGED.PDF; SGY500J ESTIMATE _0003.jpg; SGY500J ESTIMATE _0001.jpg; SGY500J ESTIMATE _0002.jpg

Hi Vincent

Thank you for your email.
We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange for the OD survey.
Excess: \$500.00.
Our claim no DMPC1900135H/JG.

Thank you.

Best regards

Janice Goh

Senior Associate | Claims



DID (65) 6303 0182

Tel (65) 6337 4779

Email janice_goh@ecics.com.sg Web www.ecics.com.sg

Address 10 Eunos Road 8, Singapore Post Centre, #09-04A, Singapore 408600

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]

Sent: Tuesday, 28 May 2019 11:17 AM

To: motorsurvey

Cc: Janice Goh Siew Geok (ECICS, Claims); Crystabelle Tan Gek Peng (ECICS, Claims); Kelvin Chew; suhaimi@alpinemotors.sg

Subject: SGY500J - OPEL ASTRA -H/B 1.0 - OWN DAMAGED CLAIM - ECICS- DOA 26-5-2019

Dear Sir/Madam,

Kindly dispatch surveyor to inspect the above vehicle ,take not this is a Opel vehicle (Auto Germany Pte Ltd)

Vehicle location is at :

Person in charge :-

Suhaimi , Kelvin – 82925595 H/P.

68441985 – office phone

E-mail :

suhaimi@alpinemotors.sg

Kelvin.chew@alpinemotors.sg

Add:
First Autoworks Pte Ltd
23, Kaki Bukit Ave 4
#04-01 (South Wing)
singapore 415933
(Vicom Building)
tel: 6844-1985

Regards,
Vincent Sim- Claims Dept

Alpine Motors Pte Ltd / Auto Germany Pte Ltd

vincent.sim@alpinemotors.sg

65113022 ext 343

H/P 9247-8842

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Thursday, 11 July 2019 2:48 PM
To: Kelvin.chew@alpinemotors.sg; SUR
Cc: suhaimi@firstautoworks.com.sg
Subject: RE: SGY 500 J OPEL ASTRA ECICS OD DOA 26.05.2019 FINALISE

Dear Kelvin,

As spoken to you yesterday, confirm all in \$15,500 & 6days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Wednesday, 10 July 2019 4:42 PM
To: SUR <sur@lkkauto.com>
Cc: suhaimi@firstautoworks.com.sg
Subject: SGY 500 J OPEL ASTRA ECICS OD DOA 26.05.2019 FINALISE

Hi Lkk,

attach is finalise report.
part by part \$17,934.20 before excess \$500.00 & 6 working days.
kindly please check & confirm with me.
survey by Mr. Adrian on 28.05.2019.
thanks.

from,
kelvin chew
8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 3 June 2019 10:21 AM
To: Kelvin.chew@alpinemotors.sg
Cc: suhaimi@firstautoworks.com.sg; SUR
Subject: SGY 500J / OD / ECICS / DOA: 28/5/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGY 500J (Excess \$500/-). ALL IN LUMP SUM \$15,500/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SGY500J (DMPC1900135H/JG)**

OD

May 26 2019 2:00PM

[YUEN HING LOONG]

First Autoworks Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From ECICS Limited (HQ) (ECICS), sent on 31/05/2019 15:20 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15500.00) - SGY500J - Claim Handler: Janice Goh

Approved:15500.00.

DOCUMENTS SUMMARY

There are no documents.

CHEAPEST CAR INSURANCE RENEWAL



Compare
10+ Insurers

GET A CHEAPER QUOTE NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Model Does Up 2.0D W/V Wheel & Turbo Parts Reconditioned



License Plate: 2017-2018
Insurance: 2017-2018
Warranty: 2017-2018
Direct Owner

Lake View Credit Pte Ltd

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Browse by Category

Sort by Date Posted

20 results/page

vehicles

opel astra

Search Selection

opel astra

Any

Any

2017

Any

Any

Any

Available



Opel Astra Sports Tourer 1.0A

\$70,500

\$8,150 /yr

28-Sep-2017

999 cc

36,500 km

Stationwagon

Available

Loan Interest At 2.28%. Extremely Well Maintained And Fully Agent Maintained. Comes With First 5 Years Warranty And First 5 Years Free Servicing. This Beast Does Not Just Look Beautiful, It's 100% Acc...

Posted: 27-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



Opel Astra Sports Tourer 1.0A

\$79,800

\$8,860 /yr

27-Dec-2017

999 cc

6,000 km

Stationwagon

Available

Android Auto/Carplay Integrated 6-speaker Opel Infotainment. Opel Boot Kit - Nets, Bags And Partitions. Best Value For Money Family Car With Adv Safety Features (6 Airbags), Classy Luxurious Interiors...

Posted: 27-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



Opel Astra Sports Tourer 1.0A

\$65,800

\$8,260 /yr

24-Jan-2017

999 cc

90,000 km

Stationwagon

Available

Consignment Unit. Competitive Insurance Premiums Available. Please Contact Me To Arrange For More Information/Viewing!

Posted: 25-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



Opel Astra Sports Tourer 1.0A

\$69,999

\$8,460 /yr

18-May-2017

999 cc

20,000 km

Stationwagon

Available

Just Arrived. Hot Deal! One Owner! Fully Agent Unit With Agent Warranty, Really Very Beautiful, Low Mileage, Low Depre, Certified Premium Preowned 110 Points Check. Flexible Financing And Special 2.48%...

Premium Automobiles

Posted: 28-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel

Car Buying

Car Selling

Car Ownership

Shopping is your personal choice. Best

Car Aftermarket

On The Move

Lifestyle

Makeup of its Condition?

STA Car Evaluation



Opel Astra 1.0A Turbo (OPC)

\$53,000

\$6,160 /yr

04-Aug-2017

999 cc

23,000 km

Hatchback

Available

Single Owner. Fully Maintained By Auto Germany. Non Abused. Used For Daily Driving Only. Selling Due To Upgrading. Fun Pack Car With Low Fuel Consumption Boosting This 1.1 Engine To Be A Very Economical...

Cars 88 Pte Ltd

Posted: 23-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



Opel Astra 1.0A

\$73,888

\$8,740 /yr

28-Jul-2017

999 cc

20,000 km

Hatchback

Available

Extremely Well Maintained By Meticulous Owner. Genuine Low Mileage Unit. Comes With 5 Years Agent Warranty, 100% Accident Free. We Welcome STA/VICOM Inspection. Attractive Loan Packages Available. Tra...

Posted: 09-May-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel



Opel Astra 1.0A Turbo

\$67,000

\$7,920 /yr

18-Jul-2017

999 cc

19,000 km

Hatchback

Available

Near Perfect 9.5:10 Ratio Condition! Warranty And Fully Maintained By Agent From Day 1! Still Smells Like New In Cabin Due To Under Utilize! Low Mileage Done At 19,000KM! Comes With Free Servicing By ...

Posted: 20-Apr-2019 Tags: 2017 Opel Astra, 2017 opel astra, Opel Astra, opel astra, Opel, Astra, astra, Used Opel

Op

\$80,900

\$9,090 /yr

08-Jun-2017

1,399 cc

43,000 km

Hatchback

Available

Compare

Look N

ge With 1 Owner! Best Value For Your Money. Direct Owner's Beautiful White, Jun/2017 Opel Astra HB 1.4 AT(LED)

Denise Tay (LKKAuto)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>
Sent: Tuesday, 4 June 2019 12:18 PM
To: Denise Tay (LKKAuto)
Cc: suhaimi@firstautoworks.com.sg; SUR
Subject: re: SGY 500J / OD / ECICS / DOA: 28/5/2019

Hi Denise,

SGY 500J (Excess \$500/-). ALL IN LUMP SUM \$15,500/-

agree with thanks.

from,
kelvin chew
8292 5595

From: "Denise Tay (LKKAuto)" <denisetay@lkkauto.com>
Sent: 03 June 2019 10:23
To: "Kelvin.chew@alpinemotors.sg" <Kelvin.chew@alpinemotors.sg>
Cc: "suhaimi@firstautoworks.com.sg" <suhaimi@firstautoworks.com.sg>, "SUR" <sur@lkkauto.com>
Subject: SGY 500J / OD / ECICS / DOA: 28/5/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SGY 500J (Excess \$500/-). ALL IN LUMP SUM \$15,500/-**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 29 May 2019

Preliminary Advice

Vehicle No	: SGY500J	Accident Date	: 26/05/2019
Make	: OPEL ASTRA	Policy No.	: MPC18A00210701
Assignment Date	: 28/05/2019	Excess	: S\$0.00
Date of Inspection	: 28/05/2019	Est. Duration of Repair	: 6.00
Inspection At	: FIRST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,823.80
Revised Amount	:S\$	8,830.20
Check Items (Estimated)	:S\$	10,506.40
Total	:S\$	19,336.60
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	38,951.00
Salvage Value	:S\$	
Margin for Repair	:S\$	29,049.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending 2nd opinion from workshop.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 3266A

Vehicle Details

Vehicle No.: SGY500J
Vehicle to be Exported: Yes
Intended Deregistration Date: 27 May 2019
Vehicle Make: OPEL
Vehicle Model: **ASTRA HB 1.0 AT**
Primary Colour: Red
Manufacturing Year: 2017
Engine No.: B1171497HRXX0502
Chassis No.: W0LBE6EA8HG172390
Maximum Power Output: 77.0 kW (103 bhp)
Open Market Value: \$19,155.00
Original Registration Date: **15 Aug 2017**
First Registration Date: 15 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Aug 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 14 Aug 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$44,002.00
COE Rebate Amount: \$35,201.00
Total Rebate Amount: \$38,951.00

The information contained herein is correct as at 27 May 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	27/05/2019 09:32
Date Of Accident	26/05/2019 14:00
Exact Location Of Accident	LOYANG
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGY500J
Insured/Policyholder	
Name Of Registered Owner	YUEN HING LOONG
NRIC No	S7603266A
Email Address	YUENHILO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97978213
Alternative Phone No	OFFICE-97978213
Vehicle Particulars	
Manufacturer	OPEL
Model	ASTRA 5DR EASYTRONIC 1.0
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00210701
Cover Note Number	
Driver	
Name of Driver	YUEN HING LOONG
NRIC No	S7603266A
Date Of Birth	04/02/1976
Occupation	INDOOR
Date Of Driving Pass	01/06/1998
Driving Experience	20 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97978213
Fax Number	
Contact Number	OFFICE-97978213
Email Address	YUENHILO@GMAIL.COM

Address	45 KIM CHENG STREET , #04-03
Postcode	160045
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

see SEE REPORT ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGE3492J
Vehicle Make/Model/Colour	AUDI A5
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. I/We report ~~correctly~~ the details of the accident to speed up the claims process.
2. The form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Passport No.:

Sketch Plan #2

5. SKETCH PLAN

LOYANE AVE

A: SGY 5005
B: SGE 3492

6. DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WAS ALONG LOYANE AVE. MY CAR SGY 5005
WAS BEHIND SGE 3492. TRAFFIC LIGHT TURNS
GREEN, I MOVED ~~FORWARD~~ ~~HOWEVER~~ THE
CAR AHEAD WAS NOT MOVING SO I HIT
THE REAR OF SGE 3492.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Witness's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
AIRC/VIS No

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7603266A



YUEN HING LOONG
(YUAN QINGLONG)
袁庆龙
Race: CHINESE
Date of Birth: 06-02-1976 M
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE
Identity Card No. S7603266A



YUEN HING LOONG
(YUAN QINGLONG)
Date of Birth: 06 Feb 1976
Valid Until: 22 Jul 2016



Identification Card

000000



COPY NO. S78C3266A



DATE OF ISSUE
01-02-2007

(continued)

ZPT BLK CO INC CHENG STREET
#02-02
SINGAPORE 000000

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

		EXP. DATE
Unit 28	Motorcycle -- 200 cc	24 Dec 1987
Unit 23	Motorcycle Suzuki 125 cc and 400 cc	24 Dec 1988
Unit 21	Motorcycle Honda 125 cc	14 Jan 1987
Unit 9	Motor cycle with a trailer weight = 3000kg with a 7 passenger, and a trailer of 400kg. a 4 wheel trailer vehicle with a trailer weight = 2500kg	24 Dec 1988

19-04



AUTO
GERMANY
PTE LTD

Repair Estimate



Date :27/05/2019

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SGY500J

CHASSIS NO.: W0LB6EA8HG172390

ENGINE NO.: B1171497HRXX0502

Name of Insured : YUEN HING LOONG

Date of accident.: 26.05.2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	FRT BONNET <i>Deletd.</i>	\$ 1,758.00	-
2	1	FRT BONNET LOCK <i>2</i>	\$ 312.00	+
3	1	FRT BONNET LOCK CABLE <i>1 pc</i>	\$ 277.00	+
4	4	FRT BONNET STOPER <i>1 pc</i>	\$ 40.00	+
5	1	FRT BUMPER <i>Deletd</i>	\$ 1,994.00	+
6	1	FRT BUMPER TOW COVER <i>1 pc</i>	\$ 128.00	+
7	1	FRT BUMPER LOW LIP RH <i>2 pc</i>	\$ 156.00	+
8	1	FRT BUMPER LOW LIP LH <i>2 pc</i>	\$ 156.00	+
9	15	FRT BUMPER CLIP <i>1 pc</i>	\$ 97.50	+
10	1	FRT BUMPER SIDE RETAINER LH - GUIDE <i>2</i>	\$ 136.00	+
11	1	FRT BUMPER SIDE RETAINER LH - UPP <i>2</i>	\$ 106.00	+
12	1	FRT BUMPER SIDE RETAINER RH - GUIDE <i>1 pc</i>	\$ 136.00	+
13	1	FRT BUMPER SIDE RETAINER RH - UPP <i>1 pc</i>	\$ 106.00	+
14	1	FRT BUMPER BRACKET LH <i>2 pc</i>	\$ 192.00	+
15	1	FRT BUMPER BRACKET RH <i>2 pc</i>	\$ 192.00	+
16	1	FRT BUMPER UNDER DUST COVER <i>2 pc</i>	\$ 290.00	+
17	1	FRT BUMPER BRACKET TOP CENTRE <i>2 pc</i>	\$ 198.00	+
18	1	FRT BRACE BRACKET CENTRE <i>2 pc</i>	\$ 229.00	+
19	1	FRT BRACE BRACKET RH <i>2 pc</i>	\$ 118.00	+
20	1	FRT BRACE BRACKET LH <i>2 pc</i>	\$ 118.00	+
21	1	FRT BUMPER SPONGE <i>2 pc</i>	\$ 254.00	+
22	1	FRT BUMPER REINFORCEMENT UPP (metal) <i>2 pc</i>	\$ 798.00	+
23	1	FRT BUMPER REINFORCEMENT LOW (firbe) <i>2 pc</i>	\$ 374.00	+
24	2	FRT BUMPER PARKING SENSOR <i>1 piece dngd</i>	\$ 544.00	272
25	2	FRT BUMPER PARKING SENSOR SEAL <i>1 pc</i>	\$ 24.00	+
26	1	FRT BUMPER PARKING SENSOR WIRE HARNESS <i>1 pc</i>	\$ 394.00	+
27	1	FRT GRILLE ASSY <i>1 pc</i>	\$ 800.00	+
28	1	FRT GRILLE LOGO <i>1 pc</i>	\$ 160.00	+
29	1	FRT LOW CENTRE GRILLE <i>Deletd</i>	\$ 202.00	+
30	1	RH HEADLAMP <i>2 pc</i>	\$ 820.00	+
31	1	LH HEADLAMP <i>2 pc</i>	\$ 820.00	+
32	1	RH FOG LAMP <i>2 pc</i>	\$ 434.00	+

33	1	RH FOG LAMP COVER	2nd	\$	120.00	✓
34	10	FENDER INNERSHIELD CLIP	new	\$	65.00	+
35	1	FRT FENDER RH	new	\$	682.00	+
36	1	FRT FENDER INNERSHIELD RH	new	\$	138.00	+
37	1	FRT FENDER LH	new	\$	682.00	+
38	1	FRT FENDER INNERSHIELD LH	new	\$	138.00	+
39	1	RADIATOR SUPORT PANEL TOP GARNISH RH	2nd	\$	152.00	2
40	1	RADIATOR SUPORT PANEL TOP GARNISH LH	2nd	\$	152.00	2
41	1	RADIATOR SUPORT PANEL TOP	new	\$	334.00	+
42	1	FRT HEADLAMP PANEL RH	new	\$	160.00	+
43	1	FRT HEADLAMP PANEL LH	new	\$	160.00	+
44	1	RADIATOR	2nd	\$	1,424.00	2
45	1	RADIATOR COOLANT	new	\$	164.00	2
46	1	RADIATOR FAN ASSY	2nd	\$	1,806.00	2
47	1	RADIATOR TOP BRACKET LH	new	\$	124.00	2
48	1	RADIATOR TOP BRACKET RH	new	\$	124.00	2
49	1	RADIATOR TOP MOUTING	new	\$	18.00	2
50	1	RADIATOR BRACKET LOWER LH	missing	\$	162.00	2
51	1	RADIATOR BRACKET LOWER RH	missing	\$	162.00	2
52	1	A/C CONDENSER	2nd	\$	730.00	✓
53	1	A/C CONDENSER TOP SEAL	new	\$	112.00	2
54	1	A/C CONDENSOR AIR GUIDE TOP CENTRE	2nd	\$	158.00	2
55	1	A/C CONDENSER AIR GUIDE RH	2nd	\$	134.00	2
56	1	A/C CONDENSER AIR GUIDE LH	2nd	\$	138.00	2
57	1	A/C PIPE (comp to cooling coil)	new	\$	934.00	+
58	1	A/C PIPE (cooling coil to condenser)	new	\$	916.00	+
59	1	A/C AMBIENT SENSOR	2nd	\$	317.00	2
60	1	INTERCOOLER, TURBOCHARGER AIR GUIDE	2nd	\$	514.00	2
61	1	INTERCOOLER, TURBOCHARGER	2nd	\$	1,060.00	2
62	1	INTERCOOLER HOSE(turbo to intercooler), INLET	new	\$	302.00	2
63	1	INTERCOOLER HOSE(intercooler to throttle body), OUTLET	new	\$	292.00	2
64	1	ENGINE AIR INTAKE DUCT	2nd	\$	166.00	2
65	1	ENGINE AIR INTAKE DUCT HOSE	new	\$	120.00	2

Parts Total: \$ 25,023.50
Less 20%: \$ 5,004.70
Total: \$ 20,018.80

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER RH, FRT FENDER LH	\$ 2,800.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00
5	To remove and refix radiator and conduct pressure test	\$ 120.00
6	To conduct reset of engine light on	\$ 350.00
7	To conduct reset of air bag light on	\$ 350.00

Labour Total: \$ 7,740.00

Others

Other Description

No.			Price (SGD)
1		FRT NUMBER PLATE <i>cracked</i>	\$ 65.00 ✓

Other Total: \$ 65.00

TOTAL: \$ 27,823.80

GST (7%): \$ 1,947.67

GRAND TOTAL : \$ 29,771.47

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Adrian King - 28035
P/P 28/05/19.

06 Days.

Not Authorized.

Excess \$500

VEHICLE NO:

VEHICLE NO: 56Y500J

[illegible]



Date :27/05/2019

Reference: OPEL
Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SGY500J
CHASSIS NO.: W0LBE6EA8HG172390
ENGINE NO.: B1171497HRXX0502

Name of insured : YUEN HING LOONG
Date of accident.: 26.05.2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BONNET <i>Detach</i>	\$ 1,758.00
2	1	FRT BONNET LOCK	\$ 312.00
3	1	FRT BONNET LOCK CABLE	\$ 277.00
4	4	FRT BONNET STOPPED	\$ 40.00
5	1	FRT BUMPER <i>Detach</i>	\$ 1,994.00
6	1	FRT BUMPER TOW COVER	\$ 128.00
7	1	FRT BUMPER LOW LIP RH	\$ 156.00
8	1	FRT BUMPER LOW LIP LH	\$ 156.00
9	15	FRT BUMPER CLIP	\$ 97.50
10	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
11	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
12	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
13	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
14	1	FRT BUMPER BRACKET LH	\$ 192.00
15	1	FRT BUMPER BRACKET RH	\$ 192.00
16	1	FRT BUMPER UNDER DUST COVER	\$ 290.00
17	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
18	1	FRT BRACE BRACKET CENTRE	\$ 229.00
19	1	FRT BRACE BRACKET RH	\$ 118.00
20	1	FRT BRACE BRACKET LH	\$ 118.00
21	1	FRT BUMPER SPONGE	\$ 254.00
22	1	FRT BUMPER REINFORCEMENT UPP (metal)	\$ 798.00
23	1	FRT BUMPER REINFORCEMENT LOW (firbe)	\$ 374.00
24	2	FRT BUMPER PARKING SENSOR <i>1 piece damaged</i>	\$ 544.00
25	2	FRT BUMPER PARKING SENSOR SEAL	\$ 24.00
26	1	FRT BUMPER PARKING SENSOR WIRE HARNESS	\$ 394.00
27	1	FRT GRILLE ASSY	\$ 800.00
28	1	FRT GRILLE LOGO	\$ 160.00
29	1	FRT LOW CENTRE GRILLE	\$ 202.00
30	1	RH HEADLAMP	\$ 820.00
31	1	LH HEADLAMP	\$ 820.00
32	1	RH FOG LAMP	\$ 434.00

33	1	RH FOG LAMP COVER ?		\$	120.00	?
34	10	FENDER INNERSHIELD CLIP <i>alt n</i>		\$	65.00	+
35	1	FRT FENDER RH	<i>John</i>	\$	682.00	+
36	1	FRT FENDER INNERSHIELD RH		\$	138.00	+
37	1	FRT FENDER LH <i>alt n</i>		\$	682.00	+
38	1	FRT FENDER INNERSHIELD LH <i>John</i>		\$	138.00	+
39	1	RADIATOR SUPORT PANEL TOP GARNISH RH ?		\$	152.00	?
40	1	RADIATOR SUPORT PANEL TOP GARNISH LH ?		\$	152.00	?
41	1	RADIATOR SUPORT PANEL TOP	<i>Repair</i>	\$	334.00	+
42	1	FRT HEADLAMP PANEL RH	<i>Repair</i>	\$	160.00	+
43	1	FRT HEADLAMP PANEL LH		\$	160.00	+
44	1	RADIATOR ?		\$	1,424.00	?
45	1	RADIATOR COOLANT ?		\$	164.00	?
46	1	RADIATOR FAN ASSY ?		\$	1,806.00	?
47	1	RADIATOR TOP BRACKET LH ?		\$	124.00	?
48	1	RADIATOR TOP BRACKET RH ?		\$	124.00	?
49	1	RADIATOR TOP MOUTING ?		\$	18.00	?
50	1	RADIATOR BRACKET LOWER LH ?		\$	162.00	?
51	1	RADIATOR BRACKET LOWER RH ?		\$	162.00	?
52	1	A/C CONDENSER		\$	730.00	?
53	1	A/C CONDENSER TOP SEAL		\$	112.00	?
54	1	A/C CONDENSOR AIR GUIDE TOP CENTRE ?		\$	158.00	?
55	1	A/C CONDENSER AIR GUIDE RH		\$	134.00	?
56	1	A/C CONDENSER AIR GUIDE LH		\$	138.00	?
57	1	A/C PIPE (comp to cooling coil)	<i>John</i>	\$	934.00	+
58	1	A/C PIPE (cooling coil to condenser)		\$	916.00	+
59	1	A/C AMBIENT SENSOR		\$	317.00	?
60	1	INTERCOOLER, TURBOCHARGER AIR GUIDE ?		\$	514.00	?
61	1	INTERCOOLER, TURBOCHARGER ?		\$	1,060.00	?
62	1	INTERCOOLER HOSE(turbo to intercooler), INLET ?		\$	302.00	?
63	1	INTERCOOLER HOSE(intercooler to throtle body), OUTLET ?		\$	292.00	+
64	1	ENGINE AIR INTAKE DUCT ?		\$	166.00	?
65	1	ENGINE AIR INTAKE DUCT HOSE ?		\$	120.00	?

Parts Total: \$ 25,023.50

Less 20%: \$ 5,004.70

Total : \$ 20,018.80

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 3,300.00 <i>1650</i>
2	Carry out spray painting on affected area, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER RH, FRT FENDER LH	\$ 2,800.00 <i>1050</i>
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 220.00 <i>120</i>
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 600.00 ?
5	To remove and refix radiator and conduct pressure test	\$ 120.00 ?
6	To conduct reset of engine light on	\$ 350.00 ?
7	To conduct reset of air bag light on	\$ 350.00 ?

Labour Total : \$ 7,740.00

Others

Other Description

No.			Price (SGD)
1		FRT NUMBER PLATE <i>mounted</i>	\$ 65.00

Other Total: \$ 65.00

TOTAL: \$ 27,823.80
GST (7%): \$ 1,947.67

GRAND TOTAL : \$ 29,771.47

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

*Adrian King -
P/P 28/05/19*

06 Days.

Not Authorised.

Excess \$500

FINALIZE
ECICS LIMITED

GST Ref. No: 20-0000274-Z

Vehicle No: SGY500J
Chassis No: W0LBE6EABHG172390
Engine No: B1171497HRXX0502
Date of accident :26.05.2019

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	FRT BONNET	\$ 1,758.00
2	1	FRT BUMPER	\$ 1,994.00
3	15	FRT BUMPER CLIP	\$ 97.50
4	1	FRT BUMPER SIDE RETAINER LH - GUIDE	\$ 136.00
5	1	FRT BUMPER SIDE RETAINER LH - UPP	\$ 106.00
6	1	FRT BUMPER SIDE RETAINER RH - GUIDE	\$ 136.00
7	1	FRT BUMPER SIDE RETAINER RH - UPP	\$ 106.00
8	1	FRT BUMPER BRACKET LH	\$ 192.00
9	1	FRT BUMPER BRACKET RH	\$ 192.00
10	1	FRT BUMPER BRACKET TOP CENTRE	\$ 198.00
11	1	FRT BRACE BRACKET CENTRE	\$ 229.00
12	1	FRT BRACE BRACKET RH	\$ 118.00
13	1	FRT BRACE BRACKET LH	\$ 118.00
14	1	FRT BUMPER SPONGE	\$ 254.00
15	1	FRT BUMPER REINFORCEMENT UPP (metal)	\$ 798.00
16	1	FRT BUMPER REINFORCEMENT LOW (fibre)	\$ 374.00
17	1	FRT BUMPER PARKING SENSOR	\$ 272.00
18	2	FRT BUMPER PARKING SENSOR SEAL	\$ 24.00
19	1	FRT GRILLE ASSY	\$ 800.00
20	1	FRT GRILLE LOGO	\$ 160.00
21	1	FRT LOW CENTRE GRILLE	\$ 202.00
22	1	RH HEADLAMP	\$ 820.00
23	1	LH HEADLAMP	\$ 820.00
24	1	RH FOG LAMP	\$ 434.00
25	1	RH FOG LAMP COVER	\$ 120.00
26	1	RADIATOR SUPPORT PANEL TOP GARNISH RH	\$ 152.00
27	1	RADIATOR SUPPORT PANEL TOP GARNISH LH	\$ 152.00
28	1	RADIATOR	\$ 1,424.00
29	1	RADIATOR COOLANT	\$ 164.00
30	1	RADIATOR FAN ASSY	\$ 1,806.00
31	1	RADIATOR BRACKET LOWER LH	\$ 162.00

32	1	RADIATOR BRACKET LOWER RH	\$	162.00
33	1	A/C CONDENSER	\$	730.00
34	1	A/C CONDENSER AIR GUIDE TOP CENTRE	\$	158.00
35	1	A/C CONDENSER AIR GUIDE RH	\$	134.00
36	1	A/C CONDENSER AIR GUIDE LH	\$	138.00
37	1	A/C AMBIENT SENSOR	\$	317.00
38	1	INTERCOOLER , TURBOCHARGER AIR GUIDE	\$	514.00
39	1	INTERCOOLER , TURBOCHARGER	\$	1,060.00
40	1	ENGINE AIR INTAKE DUCT	\$	166.00

Supplementary

1	1	FRT BUMPER LOW GRILLE LH	\$	132.00
2	1	FRT BUMPER LOW GRILLE RH	\$	132.00

Total: \$ 17,961.50
Less 20%: \$ 3,592.30
Parts Total: \$ 14,369.20

Labour

No.		Price (SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	\$ 1,650.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA.FRT FENDER LH , FRT DOOR LH , RR DOOR LH , RR FENDER LH,ROCKER PANEL LH , RR BUMPER	\$ 1,050.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	\$ 120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR , VACUUM , REFILL AND CHECK AIR CON GAS SYSTEM	\$ 300.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00
6	TO CONDUCT RESET OF ENGINE LIGHT ON	\$ 125.00
7	TO CONDUCT RESET OF AIR BAG LIGHT ON	\$ 175.00

Labour Total: \$ 3,500.00

Other

No.		Price (SGD)
1	1 FRONT NUMBER PLATE	\$ 65.00

Other Total : \$ 65.00

Total : \$ 17,934.20

Excess: \$ 500.00

GST (7%) : \$ 1,220.39

Grand Total : \$ 18,654.59

Yours Faithfully,

Kelvin Chew
Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 May 2019 09:39 Edit Reg		28 May 2019 00:00 Edit Adj Rpt	S\$15,500.00 Edit Estimates	S\$15,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

YUEN HING LOONG, ID: S7603266A, Email: yuenhilo@gmail.com

Vehicle Reg. No.:

SGY500J

Claim Type:

OD / DMPC1900135H/JG

Repairer:

First Autoworks Pte Ltd (HQ) 23 KAKI BUKIT AVE 4 #04-01 SOUTH WING, 415933 Kaki Bukit - Tel:

Handling Insurer:

ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Janice Goh - 6303 0182]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/06/2019]

Date of Loss:

26/05/2019 14:00 - :59
[21 Months and 11 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

MPC18A00210701 [Comprehensive]

Excess:

S\$500.00

[Created by adjuster]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- ECICS (31/05/2019): Alert - Adj Mandate Approved (S\$15500.00) - SGY500J - Claim Handler: Janice Goh

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGY500J (DMPC1900135H/JG)
 OD
 May 26 2019 2:00PM
 [YUEN HING LOONG]
 First Autoworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 09:42	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 09:08	General View	Load JPG	☒
2	29/05/19 09:08	General View	Load JPG	☒
3	29/05/19 09:08	General View	Load JPG	☒
4	29/05/19 09:08	General View	Load JPG	☒
5	29/05/19 09:08	General View	Load JPG	☒
6	29/05/19 09:08	General View	Load JPG	☒
7	29/05/19 09:08	General View	Load JPG	☒
8	29/05/19 09:08	General View	Load JPG	☒
9	29/05/19 09:08	General View	Load JPG	☒
10	29/05/19 09:08	General View	Load JPG	☒
11	29/05/19 09:08	General View	Load JPG	☒
12	29/05/19 09:08	General View	Load JPG	☒
13	29/05/19 09:08	General View	Load JPG	☒
14	29/05/19 09:08	General View	Load JPG	☒
15	29/05/19 09:08	General View	Load JPG	☒
16	29/05/19 09:08	General View	Load JPG	☒
17	29/05/19 09:08	General View	Load JPG	☒
18	29/05/19 09:08	General View	Load JPG	☒
19	29/05/19 09:08	General View	Load JPG	☒
20	29/05/19 09:08	General View	Load JPG	☒
21	29/05/19 09:08	General View	Load JPG	☒
22	29/05/19 09:08	General View	Load JPG	☒
23	29/05/19 09:08	General View	Load JPG	☒
24	29/05/19 09:08	General View	Load JPG	☒
25	29/05/19 09:08	General View	Load JPG	☒
26	29/05/19 09:08	General View	Load JPG	☒
27	29/05/19 09:08	General View	Load JPG	☒
28	29/05/19 09:08	General View	Load JPG	☒
29	29/05/19 09:08	General View	Load JPG	☒
30	29/05/19 09:08	General View	Load JPG	☒
31	29/05/19 09:08	General View	Load JPG	☒
32	29/05/19 09:08	General View	Load JPG	☒
33	29/05/19 09:08	General View	Load JPG	☒
34	29/05/19 09:08	General View	Load JPG	☒
35	29/05/19 09:08	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	29/05/19 09:08	General View	 Load JPG	☒
37	29/05/19 09:08	General View	 Load JPG	☒
38	29/05/19 09:08	General View	 Load JPG	☒
39	29/05/19 09:08	General View	 Load JPG	☒
40	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
41	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
42	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
43	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
44	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
45	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
46	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
47	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
48	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
49	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
50	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
51	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
52	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
53	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
54	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
55	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
56	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
57	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
58	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
59	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
60	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
61	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
62	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
63	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
64	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
65	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
66	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
67	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
68	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
69	11/07/19 15:12	Reinspection Photo	 Load JPG	☒
70	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
71	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
72	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
73	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
74	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
75	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
76	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
77	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
78	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
79	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
80	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
81	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
82	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
83	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
84	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
85	11/07/19 15:13	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
87	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
88	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
89	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
90	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
91	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
92	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
93	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
94	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
95	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
96	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
97	11/07/19 15:13	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/05/19 09:07	ESTIMATE	 Load PDF	
2	24/07/19 16:45	Supplementary	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS19009413/ATD3E2

Date: 24/07/2019

REFERENCE

Insured/Claimant: YUEN HING LOONG Policy No: MPC18A00210701
Date of Loss: 26/05/2019 Nature of Claim: OD Claim No: DMPC1900135H/JG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGY500J**
Make & Model: OPEL ASTRA, 999cc HB (A) Engine No: B1171497HRXX0502
Reg. Date: 15/08/2017 (Man. Year: 2017) Chassis No: W0LBE6EA8HG172390
Colour: Red Odometer: 29072 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,295.00	14,434.20	5,860.80	28.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,740.00	3,500.00	4,240.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,035.00	17,934.20	10,100.80	36.03
Approved Total (Overridden) (S\$)		15,500.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	27,535.00	15,000.00	12,535.00	45.52
+ GST 7.00/7.00% (S\$)	1,927.45	1,050.00	877.45	45.52
Nett Amount (S\$)	29,462.45	16,050.00	13,412.45	45.52

INSPECTION

Date of Assignment: 28/05/2019
Date Inspected: 28/05/2019 Inspected At:

First Autoworks Pte Ltd (HQ)
23 KAKI BUKIT AVE 4 #04-01 SOUTH
WING
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2019)	
Parts: 144	OPEL ASTRA 999cc HB (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SGY500J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented	1,758.00 FL	*1,758.00 FL
2	1		*FRT BONNET LOCK	Not Necessary	312.00 FL	*- FL
3	1		*FRT BONNET LOCK CABLE	Not Necessary	277.00 FL	*- FL
4	4		*FRT BONNET STOPPED	Not Necessary	40.00 FL	*- FL
5	1		*FRT BUMPER	Deformed	1,994.00 FL	*1,994.00 FL
6	1		*FRT BUMPER TOW COVER	Not Necessary	128.00 FL	*- FL
7	1		*FRT BUMPER LOW LIP RH	Not Necessary	156.00 FL	*- FL
8	1		*FRT BUMPER LOW LIP LH	Not Necessary	156.00 FL	*- FL
9	15		*FRT BUMPER CLIP	Necessary	97.50 FL	*97.50 FL
10	1		*FRT BUMPER SIDE RETAINER LH - GUIDE	Necessary	136.00 FL	*136.00 FL
11	1		*FRT BUMPER SIDE RETAINER LH - UPP	Necessary	106.00 FL	*106.00 FL
12	1		*FRT BUMPER SIDE RETAINER RH - GUIDE	Necessary	136.00 FL	*136.00 FL
13	1		*FRT BUMPER SIDE RETAINER RH - UPP	Necessary	106.00 FL	*106.00 FL
14	1		*FRT BUMPER BRACKET LH	Bent	192.00 FL	*192.00 FL
15	1		*FRT BUMPER BRACKET RH	Bent	192.00 FL	*192.00 FL
16	1		*FRT BUMPER UNDER DUST COVER	Not Necessary	290.00 FL	*- FL
17	1		*FRT BUMPER BRACKET TOP CENTRE	Cracked	198.00 FL	*198.00 FL
18	1		*FRT BRACE BRACKET CENTRE	Bent	229.00 FL	*229.00 FL
19	1		*FRT BRACE BRACKET RH	Bent	118.00 FL	*118.00 FL
20	1		*FRT BRACE BRACKET LH	Bent	118.00 FL	*118.00 FL
21	1		*FRT BUMPER SPONGE	Cracked	254.00 FL	*254.00 FL
22	1		*FRT BUMPER REINFORCEMENT UPP (METAL)	Bent	798.00 FL	*798.00 FL
23	1		*FRT BUMPER REINFORCEMENT LOW (FIRBE)	Cracked	374.00 FL	*374.00 FL
24	1		*FRT BUMPER PARKING SENSOR (2PCS)	Damaged-1pc only	544.00 FL	*272.00 FL
25	2		*FRT BUMPER PARKING SENSOR SEAL	Necessary	24.00 FL	*24.00 FL
26	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	394.00 FL	*- FL
27	1		*FRT GRILLE ASSY	Cut	800.00 FL	*800.00 FL
28	1		*FRT GRILLE LOGO	Necessary	160.00 FL	*160.00 FL
29	1		*FRT LOW CENTRE GRILLE	Deformed	202.00 FL	*202.00 FL
30	1		*RH HEADLAMP	Cut	820.00 FL	*820.00 FL
31	1		*LH HEADLAMP	Cut	820.00 FL	*820.00 FL
32	1		*RH FOG LAMP	Cracked	434.00 FL	*434.00 FL
33	1		*RH FOG LAMP COVER	Cracked	120.00 FL	*120.00 FL
34	10		*FENDER INNERSHIELD CLIP	Not Necessary	65.00 FL	*- FL
35	1		*FRT FENDER RH	Not Necessary	682.00 FL	*- FL
36	1		*FRT FENDER INNERSHIELD RH	Not Necessary	138.00 FL	*- FL
37	1		*FRT FENDER LH	Not Necessary	682.00 FL	*- FL
38	1		*FRT FENDER INNERSHIELD LH	Not Necessary	138.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*RADIATOR SUPORT PANEL TOP GARNISH RH	Cracked	152.00 FL	*152.00 FL
40	1		*RADIATOR SUPORT PANEL TOP GARNISH LH	Cracked	152.00 FL	*152.00 FL
41	1		*RADIATOR SUPORT PANEL TOP	Repair	334.00 FL	*- FL
42	1		*FRT HEADLAMP PANEL RH	Repair	160.00 FL	*- FL
43	1		*FRT HEADLAMP PANEL LH	Repair	160.00 FL	*- FL
44	1		*RADIATOR	Bent	1,424.00 FL	*1,424.00 FL
45	1		*RADIATOR COOLANT	Necessary	164.00 FL	*164.00 FL
46	1		*RADIATOR FAN ASSY	Cracked	1,806.00 FL	*1,806.00 FL
47	1		*RADIATOR TOP BRACKET LH	Not Necessary	124.00 FL	*- FL
48	1		*RADIATOR TOP BRACKET RH	Not Necessary	124.00 FL	*- FL
49	1		*RADIATOR TOP MOUNTING	Not Necessary	18.00 FL	*- FL
50	1		*RADIATOR BRACKET LOWER LH	Missing	162.00 FL	*162.00 FL
51	1		*RADIATOR BRACKET LOWER RH	Missing	162.00 FL	*162.00 FL
52	1		*A/C CONDENSER	Dented	730.00 FL	*730.00 FL
53	1		*A/C CONDENSER TOP SEAL	Not Necessary	112.00 FL	*- FL
54	1		*A/C CONDENSOR AIR GUIDE TOP CENTRE	Cracked	158.00 FL	*158.00 FL
55	1		*A/C CONDENSER AIR GUIDE RH	Cracked	134.00 FL	*134.00 FL
56	1		*A/C CONDENSER AIR GUIDE LH	Cracked	138.00 FL	*138.00 FL
57	1		*A/C PIPE (COMP TO COOLING COIL)	Not Necessary	934.00 FL	*- FL
58	1		*A/C PIPE (COOLING COIL TO CONDENSER)	Not Necessary	916.00 FL	*- FL
59	1		*A/C AMBIENT SENSOR	Cracked	317.00 FL	*317.00 FL
60	1		*INTERCOOLER, TURBOCHARGER AIR GUIDE	Cracked	514.00 FL	*514.00 FL
61	1		*INTERCOOLER, TURBOCHARGER	Dented	1,060.00 FL	*1,060.00 FL
62	1		*INTERCOOLER HOSE (TURBO TO INTERCOOLER), INLET	Not Necessary	302.00 FL	*- FL
63	1		*INTERCOOLER HOSE (INTERCOOLER TO THROTTLE BODY), OUTLET	Not Necessary	292.00 FL	*- FL
64	1		*ENGINE AIR INTAKE DUCT	Deformed	166.00 FL	*166.00 FL
65	1		*ENGINE AIR INTAKE DUCT HOSE	Not Necessary	120.00 FL	*- FL
66	1		*FRT NUMBER PLATE	Cracked	65.00 FS	*65.00 FS
67	1		*FRT BUMPER LOW GRILLE LH	Cracked	132.00 FL	*132.00 FL
68	1		*FRT BUMPER LOW GRILLE RH	Cracked	132.00 FL	*132.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **25,352.50** **18,026.50**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 5,057.50 3,592.30

Total Parts (\$\$) **20,295.00** **14,434.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	3,300.00	1,650.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA, FRT BUMPER, FRT BONNET, FRT SUPORT PANEL, FRT FENDER RH, FRT FENDER LH	New	2,800.00	1,050.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	220.00	120.00
4	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	300.00
5	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	120.00	80.00
6	TO CONDUCT RESET OF ENGINE LIGHT ON	New	350.00	125.00
7	TO CONDUCT RESET OF AIR BAG LIGHT ON	New	350.00	175.00
Gross Labour Cost (\$\$)			7,740.00	3,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >