

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

FWD Insurance Insured's Veh No : SJU1272X

Date of Accident : 24 May 2019

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Chin Kee Wah

Date : 27 May 2019

Estimate To Repair CB7019E - Mitsubishi BE639GRMHDEA

Chassis No : BE639GD00077

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper	\$ 1,950.00
02	1 pc	rear bumper reverse lamp LH	\$ 171.00
03	1 pc	rear bumper side bracket LH	\$ 110.00
04	1 pc	rear bumper bracket LH	\$ 185.00
05	1 pc	rear licence plate lamp LH	\$ 89.00
06	1 pc	tailgate door LH	\$ 1,780.00
07	1 pc	tailgate door window glass weatherstrip LH	\$ 215.00
08	1 pc	rear lamp LH	\$ 280.00
09	1 pc	tailgate door lower garnish	\$ 150.00
10	1 pc	rear corner panel LH	\$ 325.00
11	1 pc	rear end panel	\$ 980.00
			\$ 6,235.00
<u>SPECIAL NETT ITEMS</u>			
12	1 pc	rear licence plate	\$ 50.00
13	1 set	rear door and corner panel sticker	\$ 120.00
14	1 pc	rear door 60km/h sticker	\$ 50.00
			\$ 220.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 50.00
02		To rust-proofing of the affected areas.	\$ 80.00
03		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00
04		To remove and refit tailgate door window glass weatherstrip.	\$ 100.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
06		Putty and spray painting of the affected portion.	\$ 1,200.00
			\$ 2,730.00
Total			\$ 9,185.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer