

新合利服務公司
Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

31/5/19, 2.09pm

27 May 2019

Attn: Motor Claim Department
AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower
Singapore 068811

Steve (LKK) WL Perivol
8322 8813 3 days

LIS

Ry AL SM

LIAN SENG COMPANY
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic Accident on 22 May 2019 at Loyang Way at Entrance of 23 Loyang Way involving vehicle FBP1508M/SJK1643L.

Quotation for Repair Vehicle No: SJK1643L (Third Party Claim)

Quantity	List Item	Price
1	Tail Lamp LH / DR	\$ 423.50
2	Tail Lamp Clip X	\$ 11.00
1	Rear Bumper / DR	\$ 729.55
1	Rear Bumper Reflector LH	\$ 69.30
2/1	Rear Bumper Side Retainer (LH) DR @141	\$ 282.00
6	Rear Bumper Clip / MC	\$ 30.00
		\$ 1,545.35
	Less 25%	\$ 386.34
		\$ 1,159.01
	S NETT	
	Rear Bumper Sensor / DR	\$ 220.00
		200

Labour

1	To repair Rear Fender, Rear Panel, Back Door, remove & re-fix damaged parts and realign affected areas	\$ 550.00	700
2	To spray paint on affected area.	\$ 680.00	280 400
3	To remove and refix Rear Side Trim Board, Side Garnish and other attachment parts	\$ 80.00	X
4	To install Reverse Sensor and check water seepage	\$ 60.00	70
5	To rust proof affected area	\$ 30.00	/
Total Amount		\$ 2,789.00	

Kindly arrange your surveyor to survey my vehicle.
We look forward to hear from you soon.
Thank you.

Yours Faithfully
Mr Wong
81122116

新合利服務公司
SIN HUP LEE SERVICE CO.,
Blk 1005, Bukit Merah Lane 2,
#01-20, Singapore 159761
Tel: 6278 2482 Fax: 6271 9802

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: